


Parkside Steam Wallpaper Stripper PDTA 5 A1	
Aspect	Details
Images	
Alert Number	2108-0349
Product Type	Electrical Appliances and Equipment – Steam Wallpaper Remover
Product Identifiers	IAN 332976_1907
Product Description	Parkside Steam Wallpaper Stripper PDTA 5 A1
Country of Origin	China
Counterfeit	No
Risk Level	Medium
Risk Type	Scalding
Risk Description	The lid may unexpectedly come off from the boiler container (green base) while the product is in use, resulting in a risk of scalding. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.
Corrective Measures	Recall of the product and withdrawal of the product from the market. For more information please see: https://www.lidl.co.uk/our-products/product-information/product-recalls
Online Marketplace	N/A
Notifier	Office for Product Safety and Standards

Product Description, Product Identifiers, Country of Origin, Risk level and Notifier updated 31/08 to reflect further information on product