Gazelle Makki Cargo Bike With Electrical Support	
Aspect	Details
Images	
Alert Number	2108-0063
Product Type	Hobby and Sports Equipment – Cargo Bike
Product Identifiers	N/A
Product Description	Gazelle Makki cargo bike with electrical support / assistance.
Country of Origin	Netherlands
Counterfeit	No
Risk Level	Serious
Risk Type	Injuries
Risk Description	This product poses a risk to the user because the threaded rod, positioned at the ball joint that forms part of the steering rod, can break under exceptional circumstances. The failing ball joint will lead to a complete loss of (steering) control of the front wheel on the cargo bike. In such a scenario, most riders would instinctively bring the bike to an emergency stop, in doing so, causing themselves to fall from the bike. The product does not meet the requirements of the General Product Safety Regulations 2005.
Corrective Measures	Recall of product from end users
Online Marketplace	N/A
Notifier	Office for Product Safety and Standards