




Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk



Our Reference:
FOI2022/02359
Date:
25 February 2022

Dear 

I am writing about your email of 22 February 2022, requesting the following information:

'I would like to request the military history on an EX MOD vehicle, MB 56 AA, LandRover Defender TUM GS, chassis number SALLDBA67WA142179.'

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

- Annex A - Transfer History
- Annex B - Inspection History
- Annex C - Service History
- Annex D - Modification History
- Annex E - Fault History (redacted)

It has proved necessary to withhold some information in accordance with a qualified exemption of the FOI Act. Commercially sensitive information in the Fault History (Annex E) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As this exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, the Fault History provides details of the time taken by MOD contractors to undertake modifications and rectify fault reports for the vehicle concerned. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of “would” rather than “would be likely to”.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner’s Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
MB56AA	2320998939963	NB50103101	LV2A/088DUM	TRUCK UTY MED (TUM HS) 4X4 SOFT TOP LANDROVER 2.5LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
22/04/1998	SALLDBA67WA142179	25L05529B		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
MB56AA	3		CA005A	JSCS ASHCHURCH		34034AA	22/04/1998	
MB56AA	4	09/06/1998	A3818A	33 FD HOSP	39822A	17	17/06/1998	
MB56AA	4	08/12/1998	A0554C	OP UPMINSTER COY 1 KORBR	20	0566A27	09/02/1999	
MB56AA	4	24/04/1999	A9046A	UK CSS BN (CSAT)	482	835A51	19/06/1999	
MB56AA	4	29/07/1999	A0820A	27 RLC	135	280	24/08/1999	P80
MB56AA	4	19/10/1999	A3818A	33 FD HOSP	183	458	22/11/1999	P88
MB56AA	4	21/11/2003	A9091A	UK MED GP	999	999	21/11/2003	
MB56AA	4	21/11/2003	A3818A	33 FD HOSP	141	500	24/11/2003	U29
MB56AA		08/11/2018		HQ 2 MED BDE			08/11/2018	
MB56AA		15/11/2018		22 FD HOSP			15/11/2018	
MB56AA		03/04/2019		EQUIPMENT POOL			03/04/2019	

Work Objects										
Serial Number:	MB56AA									
NSN:	2320998939963									
Criteria:										
Repair Level:	ALL									
Work Object Status:	Closed									
Mission Impact:	ALL									
Fault State:	ALL									
Escalate Work:	ALL									
Work Request ID:										
Assigned Work Status:	ALL									
Working Organisation:										
Repair Section:										
Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0015D233		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-002F9764		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1	Non-Taskworthy	CL	000:00		
000000-0015D241		No	MEI (2)	29 Nov 2016	Level 2		WiP	000:00		
000000-00489BBC		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1	Non-Taskworthy	CL	000:00		
000000-005316DD		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-001EDD09		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1		WiP	000:00		
000000-001AB2FF		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1		WiP	000:00		
000000-0016A92A		No	First Parade Insp (AR)(1)		Level 1		WiP	000:00		
000000-004568AD		No	MEI (2)	29 Nov 2016	Level 2	Non-Taskworthy	CL	000:00		
000000-0011060F		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00182FB9		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1		WiP	000:00		
000000-00708AFD		No	First Parade Insp (AR)(1)		Level 1	Fully Fit	CL	000:00		
000000-0014D23E		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-005F5C6F		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1	Non-Taskworthy	CL	000:00		
000000-0016A92B		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1		WiP	000:00		
000000-001AC280		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-006D6B03		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1			000:00		
000000-00159D92		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-000C3769		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-000B4874		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-0004761D		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-0004FE91		No	MEI (2)	29 Nov 2016	Level 2		CL	000:00		
000000-0004FE92		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-0005A242		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-000BBA87		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-005EC7D2		No	MEI (2)	29 Nov 2016	Level 2	Non-Taskworthy	CL	000:00		
000000-0019C2E3		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-001ED51C		No	MEI (2)	29 Nov 2016	Level 2		WiP	000:00		
000000-0039E5DD		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1	Fully Fit	CL	000:00		
000000-005316DC		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1			000:00		
000000-001AB802		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1		WiP	000:00		
000000-002C0E54		No	MEI (2)	29 Nov 2016	Level 2	Non-Taskworthy	CL	000:00		
000000-00253680		No	6 Monthly 6534 Insp	17 Jan 2017	Level 1	Non-Taskworthy	CL	000:00		
000000-000652F3		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time
000000-00159D91		No	Weekly (AR)(1)		Level 1			000:00
000000-00253678		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1	Non-Taskworthy	CL	000:00
000000-00213318		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	31 May 2020	Level 1			000:00
000000-00182FC7		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1		WIP	000:00
000000-003C5E49		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-003A6230		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-001AC274		No	Weekly (AR)(1)		Level 1			000:00
000000-00211C03		No	Weekly (AR)(1)		Level 1			000:00
000000-0014CAFB		No	Weekly (AR)(1)		Level 1			000:00
000000-00489B8F		No	Yearly/20000 Kms	15 Jul 2017	Level 1	Non-Taskworthy	CL	000:00
000000-0035404C		No	Weekly (AR)(1)		Level 1	Non-Taskworthy	CL	000:00
000000-0033C3ED		No	Weekly (AR)(1)		Level 1	Fully Fit	CL	000:00
000000-0039E5DC		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1	Fully Fit	CL	000:00
000000-001D1685		No	Weekly (AR)(1)		Level 1			000:00
000000-0053064B		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1	Fully Fit	CL	000:00
000000-002132DD		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	13 Nov 2016	Level 1			000:00
000000-001105F3		No	Weekly (AR)(1)		Level 1			000:00
000000-002132DE		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	13 Nov 2016	Level 1			000:00
000000-002326EB		No	Weekly (AR)(1)		Level 1	Fully Fit	CL	000:00
000000-002BBD32		No	Weekly (AR)(1)		Level 1	Fully Fit	CL	000:00
000000-002F9756		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1	Non-Taskworthy	CL	000:00
000000-0018B95D		No	Weekly (AR)(1)		Level 1			000:00
000000-00213315		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	14 Jul 2022	Level 2			000:00
000000-00218864		No	Weekly (AR)(1)		Level 1			000:00
000000-0020F7F1		No	Weekly (AR)(1)		Level 1			000:00
000000-0015D23E		No	Yearly/20000 Kms	15 Jul 2017	Level 1		WIP	000:00
000000-002C0E53		No	Yearly/20000 Kms	15 Jul 2017	Level 1	Non-Taskworthy	CL	000:00
000000-005470A0		No	Weekly (AR)(1)		Level 1	Fully Fit	CL	000:00
000000-00214FFE		No	Weekly (AR)(1)		Level 1			000:00
000000-001ECAEA		No	Yearly/20000 Kms	15 Jul 2017	Level 1		WIP	000:00
000000-00546F51		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	31 May 2020	Level 2	Fully Fit	CL	000:00
000000-003A0F31		No	Weekly (AR)(1)		Level 1	Fully Fit	CL	000:00
000000-00100511		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-0015D242		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1		WIP	000:00
000000-000BB1B6		No	2 Yearly/40000 Kms	15 Jul 2018	Level 1		CL	000:00
000000-00102EFC		No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00
000000-0005069A		No	Yearly/20000 Kms	15 Jul 2017	Level 1		CL	000:00
000000-000E26B5		No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00
000000-0005069B		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1		CL	000:00
000000-0005069C		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-0037D64D		No	Weekly (AR)(1)		Level 1	Fully Fit	CL	000:00
000000-00169877		No	Weekly (AR)(1)		Level 1			000:00
000000-0020CC26		No	Weekly (AR)(1)		Level 1			000:00
000000-0021D982		No	Weekly (AR)(1)		Level 1			000:00
000000-006D51F9		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	14 Jul 2022	Level 2	Non-Taskworthy	CL	000:00
000000-000FE456		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-000C4B4E		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-000704AC		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1		CL	000:00
000000-000720EA		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-0003E4A5		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1		CL	000:00
000000-0003E4A6		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-00045C47		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-000EC392		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-0045688D		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	13 Nov 2016	Level 1	Non-Taskworthy	CL	000:00
000000-00708AFB		No	Weekly (AR)(1)		Level 1			000:00
000000-00221C1C		No	Weekly (AR)(1)		Level 1			000:00
000000-005EC7D3		No	Yearly/20000 Kms	15 Jul 2017	Level 1	Non-Taskworthy	CL	000:00
000000-006D5718		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1	Non-Taskworthy	CL	000:00
000000-002FE858		No	Weekly (AR)(1)		Level 1	Fully Fit	CL	000:00
000000-001EA6AF		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (AR)(1)		Level 1		WIP	000:00
000000-00213317		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	31 May 2020	Level 2			000:00
000000-0031E818		No	Weekly (AR)(1)		Level 1	Non-Taskworthy	CL	000:00
000000-001DD900		No	2 Yearly/40000 Kms	15 Jul 2018	Level 1		WIP	000:00
000000-001ECAEB		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1		WIP	000:00
000000-005F5C75		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1	Non-Taskworthy	CL	000:00
000000-006D5717		No	Yearly/20000 Kms	15 Jul 2017	Level 1	Non-Taskworthy	CL	000:00
000000-002A6B60		Yes	Weekly (AR)(1)		Level 1	Fully Fit	CL	000:00
000000-0019C2E7		No	Weekly (AR)(1)		Level 1			000:00
000000-0021A0F7		No	Weekly (AR)(1)		Level 1			000:00
000000-00147799		No	Weekly (AR)(1)		Level 1			000:00
000000-0045688E		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	13 Nov 2016	Level 1	Non-Taskworthy	CL	000:00
000000-00145FF1		No	Weekly (AR)(1)		Level 1			000:00
000000-001EA6B1		No	OOPS Drain/Replenish Eng Oil And Renew Oil Filter (AR)(2)		Level 2		WIP	000:00
000000-0016EB43		No	Weekly (AR)(1)		Level 1			000:00
000000-006D520D		No	2 Yearly/40000 Kms	15 Jul 2018	Level 1	Non-Taskworthy	CL	000:00
000000-0015D22E		No	Weekly (AR)(1)		Level 1			000:00
000000-00456896		No	2 Yearly/40000 Kms	15 Jul 2018	Level 1	Non-Taskworthy	CL	000:00
000000-0022405C		No	Weekly (AR)(1)		Level 1			000:00
000000-0022A1C1		No	Weekly (AR)(1)		Level 1			000:00
000000-005470A1		No	First 1600 Kms (AR)		Level 2	Fully Fit	CL	000:00
000000-00546F4F		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	31 May 2020	Level 1	Fully Fit	CL	000:00
000000-00489B90		No	6 Monthly/10000 Kms	14 Jan 2017	Level 1	Non-Taskworthy	CL	000:00
000000-0005A15F		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-000BC24C		No	Weekly (AR)(1)		Level 1		CL	000:00

Work Objects														
Serial Number:	MB56AA													
NSN:	232098939963													
Criteria:														
Repair Level:	ALL													
Work Object Status:	Closed													
Mission Impact:	ALL													
Fault State:	ALL													
Escalate Work:	ALL													
Work Request ID:														
Assigned Work Status:	ALL													
Working Organisation:														
Repair Section:														
Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00B23403		SNVE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B	29 Mar 2019	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00AED4D0		VEH CAST	Closed	Non-Taskworthy	No	Level 4		22 Oct 2018	N/A	CAST	TUM HS GS SOFT TOP			
000000-00B2087A		SNVE 377 - SWIVEL HOUSING	Closed	Non-Taskworthy	No	Level 1	000000-0000697A	29 Mar 2019	N/A	Inspection	TUM HS GS SOFT TOP			
000000-009CB5F2		RTI DAMAGE TO FRONT DRIVERS SIDE.	Closed	Non-Taskworthy	No	Level 2		28 Sep 2016	N/A	Damage	TUM HS GS SOFT TOP			
000000-00A4322C		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-00004550	30 Jul 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-008D8DD6		REAR SEATS RIPPED	Closed	Fully Fit	No	Level 1		21 Jul 2015	N/A	Damage	TUM HS GS SOFT TOP			
000000-008DCCDB		Front Registration plate faded	Closed	Fully Fit	No	Level 1		18 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP			
000000-009B11BF		CARRY OUT 6534 INSPECTION	Closed	Non-Taskworthy	No	Level 1		30 Apr 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-009B08D7		PLEASE RECEIPT INSP	Closed	Non-Taskworthy	No	Level 2		17 Jul 2016	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00996E9E		Investigate leak at fuel tank.	Closed	Non-Taskworthy	No	Level 2		23 May 2016	N/A	Damage	TUM HS GS SOFT TOP			
000000-00960C78		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-000031EE	19 Jan 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00955008		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Fully Fit	No	Level 2		07 Jan 2016	N/A	Inspection	TUM HS GS SOFT TOP			
000000-008DCCDA		LH Rear tailgate seal perished	Closed	Fully Fit	No	Level 2		18 Nov 2015	N/A	Failure	TUM HS GS SOFT TOP			
000000-008DCCD9		Backrest of LH front seat torn	Closed	Fully Fit	No	Level 2		18 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP			
000000-008DCCD2		Tailgate severely dented and causing damage to bottom seal	Closed	Fully Fit	No	Level 2		18 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP			
000000-008DCCBF		Excessive clearance between anvil face and nose lock of towing pintle	Closed	Limited Role	No	Level 2		18 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP			
000000-008DCCD0		Play in both front door hinges	Closed	Fully Fit	No	Level 2		18 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP			
000000-008D8DE6		WIPPER DO NOT WORK WHEN JET SQUIRTS	Closed	Non-Taskworthy	No	Level 2		21 Jul 2015	N/A	Damage	TUM HS GS SOFT TOP			
000000-008D8DDC		PLEASE INSPECT N/S REAR TYRE	Closed	Fully Fit	No	Level 1		21 Jul 2015	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-008D8DDE		DRIVER DOOR DOES NOT CLOSE PROPERLY	Closed	Fully Fit	No	Level 2		21 Jul 2015	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-008D8D97		SCREW IN TYRE	Closed	Non-Taskworthy	No	Level 2		07 Oct 2015	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00893FC9		OVERDUE 6 MONTHLY 6543	Closed	Non-Taskworthy	No	Level 1		07 May 2015	N/A	Inspection	TUM HS GS SOFT TOP			
000000-007BC7D7		DVR DOOR SEAL MINOR RIP	Closed	Fully Fit	No	Level 1		15 Sep 2013	N/A	Damage	TUM HS GS SOFT TOP			
000000-0085426C		Fire Extinguisher Overdue Annual Inspection	Closed	Limited Role	No	Level 1		12 Sep 2014	N/A	Inspection	TUM HS GS SOFT TOP			
000000-0083E55F		ACID SMELL COMING FROM BATTERY BAY	Closed	Non-Taskworthy	No	Level 1		29 Sep 2014	N/A	Damage	TUM HS GS SOFT TOP			
000000-00853A35		Carry out Post Inspection of work carried out by outside agency	Closed	Non-Taskworthy	No	Level 2		14 Nov 2014	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00844680		Towing Pintle Assembly	Closed	Fully Fit	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUM HS GS SOFT TOP			
000000-007C89E5		PASSENGER SIDE SEAT BELT U/S	Closed	Fully Fit	No	Level 2		06 Nov 2013	N/A	Inspection	TUM HS GS SOFT TOP			
000000-007C87EA		ECI MONITORING INSPECTION	Closed	Fully Fit	Yes	Level 2		06 Nov 2013	N/A	Inspection	TUM HS GS SOFT TOP			
000000-007AC573		CARRY OUT MOT	Closed	Fully Fit	No	Level 2		14 Aug 2013	N/A	Inspection	TUM HS GS SOFT TOP			
000000-007AC570		INSPECTED AND RECTIFY PLAY IN WHEEL BEARING	Closed	Fully Fit	No	Level 3		14 Aug 2013	N/A	Inspection	TUM HS GS SOFT TOP			
000000-007B8C2D		CRB OUT INSPECTION	Closed	Fully Fit	No	Level 2		01 Oct 2013	N/A	Inspection	TUM HS GS SOFT TOP			
000000-0079BEF7		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00798F43		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A	23 Jun 2013	N/A	Failure	TUM HS GS SOFT TOP			
000000-007309A0	000000-002DC3A7	RENEW DOOR LOCK BARRELS	Closed	Fully Fit	No	Level 2		19 Aug 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-007506FA		HEATER SWITCH INTERMITANT	Closed	Fully Fit	No	Level 2		20 Nov 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-007216EA		RENEW REAR CANOPY BUNGEEES	Closed	Fully Fit	No	Level 1		27 Jun 2012	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-007216DC		RENEW FUEL CAP AND STRAINER	Closed	Fully Fit	No	Level 1		27 Jun 2012	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-007309A3	000000-002DC3A2	RENEW TAILGATE	Closed	Fully Fit	No	Level 2		19 Aug 2012	N/A	Damage	TUM HS GS SOFT TOP			
000000-007216BF		RENEW TAILGATE AND WIRE STRAPS	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-00721697		RECTIFY DRIVERS WINDOW LOCK INOP	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-00721691		RENEW BRAKE PIPE CLAMPS AT REAR AXLE	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0072168C		RENEW BOTH DOOR CATCHES AND LOCKS	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-00721683		RENEW INDICATOR SWITCH	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-0072167B		RECTIFY HEATER CONTROLS INOP	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-0072166C		RECTIFY OIL LEAK AT T-BOX	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-0072166A		RENEW EXHAUST TAIL PIPE	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-0072165C		RENEW FRONT R/H INNER HUB SEAL	Closed	Non-Taskworthy	No	Level 2		27 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-00721648		RENEW BOTH FRONT TRACTA SEALS	Closed	Non-Taskworthy	No	Level 2		27 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-007215FC		RENEW REAR SHOCK ABSORBER BOTTOM BUSHES	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-007215C7		FIT MISSING DUST COVER ON AIR INTAKE PIPEWORK	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Inspection	TUM HS GS SOFT TOP			
000000-007215AD		FIT MISSING BOLT @REAR OF ALTERNATOR	Closed	Fully Fit	No	Level 2		27 Jun 2012	N/A	Inspection	TUM HS GS SOFT TOP			
000000-006C0F5A		RENEW WIPER MOTOR COVER	Closed	Fully Fit	No	Level 2		09 Aug 2011	N/A	Failure	TUM HS GS SOFT TOP			
000000-00732720	000000-002DC62B	RENEW BRAKE CALIPER BOLTS	Closed	Non-Taskworthy	No	Level 2		27 Aug 2012	N/A	Failure	TUM HS GS SOFT TOP			
000000-0071E901		CARRY OUT INSPECTION OF SERVICING ON RETURN FROM CRB	Closed	Non-Taskworthy	No	Level 2		19 Jun 2012	N/A	Inspection	TUM HS GS SOFT TOP			
000000-0071E8FE		CARRY OUT L2 MAINTENANCE TASKS AS PER AESP 2320-D-128-601 TABLE 7 COL C (2 YEARLY)	Closed	Non-Taskworthy	No	Level 2		19 Jun 2012	N/A	Servicing	TUM HS GS SOFT TOP			
000000-0071E8FB		CARRY OUT L1 MAINTENANCE TASKS AS PER AESP 2320-D-128-601 TABLE 7 COL C (2 YEARLY)	Closed	Non-Taskworthy	No	Level 1		19 Jun 2012	N/A	Servicing	TUM HS GS SOFT TOP			
000000-006E69A0		CARRY OUT L2 MAINTENANCE TASKS AS PER AESP 2320-D-128-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 2		13 Dec 2011	N/A	Servicing	TUM HS GS SOFT TOP			
000000-006B2C9F		RENEW WIPER MOTOR	Closed	Limited Role	No	Level 2		29 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP			
000000-006B2BDF		RENEW L/H HEADLIGHT ACTUATOR	Closed	Fully Fit	No	Level 2		29 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP			
000000-006E6997		CARRY OUT L1 MAINTENANCE TASKS AS PER AESP 2320-D-128-601 TABLE 7 COL A	Closed	Fully Fit	No	Level 1		13 Dec 2011	N/A	Servicing	TUM HS GS SOFT TOP			
000000-006CE507		QM(M) STABLES PARADE 100 PER CENT	Closed	Fully Fit	No	Level 1		29 Sep 2011	N/A	Inspection	TUM HS GS SOFT TOP			
000000-006B2CA6		RENEW FRONT TYRES AND L/H/R TYRE (932)	Closed	Fully Fit	No	Level 2		29 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP			
000000-006B0B71		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-0000031B	22 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP			
000000-006B06F6		CARRY OUT L2 MAINT TASKS AS PER AESP 2320-D-128-601 TBL 7 COL B	Closed	Non-Taskworthy	No	Level 2		03 Jun 2011	N/A	Servicing	TUM HS GS SOFT TOP			
000000-006B06F3		CARRY OUT L1 MAINT TASKS AS PER AESP 2320-D-128-601 TBL 7 COL B	Closed	Non-Taskworthy	No	Level 1		03 Jun 2011	N/A	Servicing	TUM HS GS SOFT TOP			
000000-0060AFAB		RENEW 6 WAY LIGHTING SWITCH	Closed	Non-Taskworthy	No	Level 2		02 Jun 2011	N/A	Failure	TUM HS GS SOFT TOP			
000000-005E8AD9		FUSE BOX NEEDS REPLACING	Closed	Fully Fit	No	Level 1		18 Mar 2011	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-005E8ADC		100 PER CENT CHECK FROM SGT WRIGHT MT SNCO	Closed	Fully Fit	No	Level 1		18 Mar 2011	N/A	Inspection	TUM HS GS SOFT TOP			
000000-005E8AC8		SPARE WHEEL TYRE ADDAPTOR	Closed	Fully Fit	No	Level 1		18 Mar 2011	N/A	Damage	TUM HS GS SOFT TOP			
000000-005E8A86		BONNET CATCH NEEDS RENEWING	Closed	Fully Fit	No	Level 1		18 Mar 2011	N/A	Damage	TUM HS GS SOFT TOP			
000000-005DC53F		RENEW 6 WAY LIGHTING SWITCH	Closed	Limited Role	No	Level 2		11 Feb 2011	N/A	Failure	TUM HS GS SOFT TOP			
000000-005D298A		RENEW DRIVERS DOOR SEAL	Closed	Fully Fit	No	Level 2		18 Jan 2011	N/A	Failure	TUM HS GS SOFT TOP			
000000-005C545F	000000-002D2348	Complete L1 Unit B vehicle inspection as per AF B 6534	Closed	Non-Taskworthy	No	Level 1		24 Nov 2010			TUM HS GS SOFT TOP			
000000-005C5413	000000-002D2348	Complete L2 maintenance tasks in accordance with AESP 2320-D-128-601, Table 7, Column A	Closed	Non-Taskworthy	No	Level 2		24 Nov 2010			TUM HS GS SOFT TOP			
000000-005C5402	000000-002D2348	Complete L1 maintenance tasks in accordance with AESP 2320-D-128-601, Table 7, Column A	Closed	Non-Taskworthy	No	Level 1		24 Nov 2010			TUM HS GS SOFT TOP			
000000-005BA3EE		Spare Tyre U/S	Closed	Fully Fit	No	Level 3		16 Nov 2010			TUM HS GS SOFT TOP			
000000-004C6714	000000-002A6631	RENEW CANOPY TEAR IN BACK	Closed	Fully Fit	No	Level 1		03 Feb 2010			TUM HS GS SOFT TOP			
000000-005136F7	000000-002B62FD	VEHICLE AT DSG PROJECT REMUS	Closed	Non-Taskworthy	No	Level 3		03 Jun 2010			TUM HS GS SOFT TOP			
000000-004FCB29	000000-002B0D2F	COMPLETE L2 MAINTENANCE TASKS IN ACCORDANCE WITH AESP 2320-D-128-601 TABLE 5 SERIAL 6 (TIMING BELT)	Closed	Non-Taskworthy	No	Level 2		27 Apr 2010			TUM HS GS SOFT TOP			
000000-004FCB22	000000-002B0D2F	COMPLETE L2 MAINTENANCE TASKS IN ACCORDANCE WITH AESP 2320-D-128-601 TABLE 5 SERIAL 4 (AIR CLEANER)	Closed	Non-Taskworthy	No	Level 2		27 Apr 2010			TUM HS GS SOFT TOP			
000000-004FCB1C	00													