March 2022



Air Quality and Dust Monitoring Monthly Report - March 2022

Cherwell District Council



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2021, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/ version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

Monthly Summary


- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of dust monitoring undertaken in the Cherwell District Council (CDC) area during March 2022.
- 1.1.2 Figure 1 and 2 in Appendix A indicates the current worksites together with dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current phase of works commenced in April 2021 and is expected to be completed by December 2025. The current worksite, as presented in Appendix A, Figure 1 and 2, includes:
 - Finmere bridge installation (North and South);
 - Stone deliveries (North and South);
 - Stockpiling;
 - Compound development;
 - Access road;
 - Drainage maintenance
 - Topsoil stripping
 - A421 Temporary Bridge installation
 - Vegetation clearance
- 1.1.5 Two (2) dust monitors are installed at the worksite, where works are underway. The site returned a medium dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from the dust monitor presented in Figure 3. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level for PM₁₀ concentrations of 190 μg/m³, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)' has been applied.

Air Quality and Dust Monitoring Summary Report, March 2022 Cherwell District Council

- 1.1.8 No (0) dust trigger alerts were recorded during the March 2022 monitoring period.
- 1.1.9 Data capture was below 90% for the monitors in March 2022, due to long-term damage from Storm Eunice and power supply issues.
- 1.1.10 No (0) complaints were received during the monitoring period (March 2022).

Appendix A - Monitoring Locations

Figure 1: Worksite and monitoring locations during March 2022 within the CDC



Appendix B - Dust Monitoring Results

Table 1: Dust monitoring locations and March 2022 results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (μg/m³)	Minimum 1- hour PM ₁₀ concentration (μg/m³)	Maximum 1- hour PM ₁₀ concentration (μg/m³)	Number of 1- hour periods exceeding trigger level of 190 µg/m³	1-hour data capture (%)
Newton Purcell - Finmere	462904, 231144	Site boundary adjacent property on A4421	М	Yes	Yes	20.3	1.0	128.0	0	75.3
A421 North	462156, 233290	A421	М	Yes	Yes	12.2	3.0	37.0	0	14.9

Figure 3: Continuous dust 1-hour mean indicative PM₁₀ concentration for all dust monitors.

