

SAFETY FLYER TO THE FISHING INDUSTRY

Foundering of the whelk potter *Nicola Faith* (BS58), resulting in the loss of all three crew, in Colwyn Bay, North Wales, on 27 January 2021



Nicola Faith

Narrative

On the 27 January 2021, the 9.81m whelk potter *Nicola Faith* was fishing about 2-3 miles offshore and relocating whelk pots. Loaded with a day's catch and four strings of pots (approximately 240 in total) to be relocated, the vessel capsized and foundered with the loss of all three of its crew.

The vessel was not equipped with an Emergency Position Indicating Radio Beacon (EPIRB) nor were the crew wearing personal locator beacons (PLBs). The absence of this mandatory safety equipment meant the alarm was not raised for some 16 hours after the foundering, and the subsequent search and rescue operation found no trace of *Nicola Faith* or its crew.

The MAIB investigation found that the boat had undergone extensive modifications in the 2 years before the accident, none of which had been approved by the Maritime and Coastguard Agency (MCA). The modifications had eroded its stability safety margin and this meant that, when combined with an estimated 2090kg of catch plus a weighed 2521kg of fishing gear on board at the time of the accident, the vessel had a very small amount of positive stability. The working deck was cluttered and partially covered by a canopy made from steel tubes and plywood sheets. The vessel capsized quickly; this is likely to have trapped the crew on board and they were probably taken down with the vessel when it sank.

Safety lessons

- 1. When *Nicola Faith* was built it had adequate stability for its designed purpose. The unauthorised modifications carried out to the vessel severely compromised its stability. Thought must be given to how planned modifications will affect a vessel's stability and may involve the services of a naval architect to accurately calculate what effect the additions or changes to the vessel will have on the stability safety margin. Additionally, permission must be sought from the MCA before any significant modifications are undertaken.
- 2. Skippers should have a good understanding of their vessel's underlying stability and how this can change during fishing operations. Simple roll tests, heel tests, or a Wolfson assessment will provide skippers with the basic information. Loading a vessel heavily with catch, and then adding retrieved fishing gear, can quickly render a vessel unstable.
- EPIRBs and/or PLBs are mandatory safety equipment for very good reason. Their purpose, to transmit the location of an incident and thereby focus any search and rescue effort, undoubtedly saves lives. A personal flotation device (PFD) can keep a casualty afloat sufficiently long enough for the rescue services, or their own vessel, to find them.

This flyer and the MAIB's investigation report are posted on our website: www.gov.uk/maib

For all enquiries: Marine Accident Investigation Branch First Floor, Spring Place 105 Commercial Road Southampton SO15 1GH

Email: <u>maib@dft.gov.uk</u> Tel: +44 (0)23 8039 5500

Publication date: June 2022

Extract from The United Kingdom Merchant Shipping (Accident Reporting and Investigation) Regulations 2012 – Regulation 5:

"The sole objective of the investigation of an accident under the Merchant Shipping (Accident Reporting and Investigation) Regulations 2012 shall be the prevention of future accidents through the ascertainment of its causes and circumstances. It shall not be the purpose of an such investigation to determine liability nor, except so far as is necessary to achieve its objective, to apportion blame."

NOTE

This safety flyer is not written with litigation in mind and, pursuant to Regulation 14(14) of the Merchant Shipping (Accident Reporting and Investigation) Regulations 2012, shall be inadmissible in any judicial proceedings whose purpose, or one of whose purposes is to attribute or apportion liability or blame.

© Crown copyright, 2021

You may re-use this document/publication (not including departmental or agency logos) free of charge in any format or medium. You must re-use it accurately and not in a misleading context. The material must be acknowledged as Crown copyright and you must give the title of the source publication. Where we have identified any third party copyright material you will need to obtain permission from the copyright holders concerned.