

Defence Equipment and Support Secretariat #2043 Maple 0a Ministry of Defence Abbey Wood Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

Our Reference:FOI2022/01873Date:17 February 2022

Dear

Thank you for your email of 10 February 2022, requesting the following information:

'Hello I am making this Freedom of Information request to find out if you have any Merlin vehicle reports, vehicle registration cards or any other service history on my

DAF LEYLAND T244, VIN No. XLRS2D39EOL114412

Registration: 54KK60

year of commissioning 04 November 1992'

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search of Ministry of Defence (MOD) records has been completed and some information about the service history of your vehicle is held on the Joint Asset Management and Engineering Solutions (JAMES) system, and provided in the attached Annexes:

Annex A - Fault history Annex B - Inspection history Annex C - Modification history Annex D - Service history

Some information about your vehicle has previously been published and Section 21(1) of the FOI Act provides that information is exempt if it is reasonably available by other means. The Merlin archive was released as part of a previous FOI request and can be accessed at the Government publications website, at the following:

https://www.gov.uk/government/publications/foi-responses-published-by-mod-week-commencing-09-july-2018

Under Section 16 (Advice and Assistance) of the FOI Act, I can advise you that the database in the above link is split into seven spreadsheets. The first has a list of vehicles, while sheets two through seven include the service histories. To search for a vehicle, you must press Ctrl + F on your computer keyboard, then select 'Options' and then select 'Workbook' from the 'Within' drop down list. Information relevant to your request can be found by typing the vehicle registration number (54KK60) and pressing 'enter'.

Defence Equipment & Support

You may wish to note that when the Merlin database was archived into its current format some data may have been lost or corrupted. You should, therefore, be cautious that some of the data may be inaccurate.

I can also advise you that in order to read some of the Annexes included in this response, you may need to use the zoom feature on your pdf viewer software.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at https://ico.org.uk/.

Yours sincerely,

DE&S Secretariat

	54KK60 2320998938523								
Criteria:									
Repair Level:	ALL								
Work Object Status:	Closed								
Mission Impact:	ALL								
Fault State:	ALL								
Escalate Work:	ALL								
Work Request ID:									
Assigned Work Status:	ALL								
Working Organisation:									
Repair Section:									
	Work Request ID		Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date Mission Impact Reason I	For Work
		FIT CORRECT FRONT/REAR TOWING EYE PINS	Closed	Limited Role	No	Level 1		27 Oct 2009	
		STENCIL TYRE PRESSURES ON MUD WINGS AND ACID SPLASH ON BATTERY COVER	Closed	Fully Fit	No	Level 1		08 Sep 2008	
	000000-0029748E		Closed	Non-Taskworthy	No	Level 2		09 Sep 2009	
	000000-0029748E		Closed	Non-Taskworthy	No	Level 1		09 Sep 2009	
	000000-00296A32		Closed	Non-Taskworthy	No	Level 2		03 Sep 2009	
	000000-00296A32		Closed	Non-Taskworthy	No	Level 1		03 Sep 2009	
000000-003DD171		coolant cap missing	Closed	Non-Taskworthy	No	Level 1		06 Mar 2009	
000000-002D353C		CARRY OUT PHYSICAL INSP OF REAR LAB MOUNTING AT NEXT ROUTE MAINTERANCE EVENT	Closed	Fully Fit	No	Level 2		24 Oct 2008	
000000-0026F764		RENEW ANTI SLIP STRIPES ON BOTH FRONT MUD GUARDS	Closed	Fully Fit	No	Level 2		08 Sep 2008	
000000-0026A6DE		Torque check of top and bottom brake knuckle (Swivel Pin Housing) steering arm bolts fitted to Leyland Daf 4 tonne (all variants).	Closed	Non-Taskworthy	No	Level 2	GSV/20/40/02/06	03 Sep 2008	
000000-0026F752		TIGHTEN UP BOTH QUARTER LIGHT LOCKS	Closed	Fully Fit	No	Level 2		08 Sep 2008	
000000-0026F755		RENEW BALL JOINT NO.1	Closed	Non-Taskworthy	No	Level 2		08 Sep 2008	
000000-000CCB03		Torque RH & LH steering lever brake knuckle bolts	Closed	Non-Taskworthy	No	Level 2	GSV/8/6/5	07 Feb 2008	
				· · · · · · · · · · · · · · · · · · ·					

 Work
 Level 3 Description
 Working Organisation
 Repair Section
 Estimated Repair Time

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

 4T BULK FUEL
 4T BULK FUEL
 4T BULK FUEL

Serial Number:	54KK60				
NSN:	2320998938523				
Criteria:					
Repair Level:	ALL				
Work Object Status:	Closed				
Mission Impact:	ALL				
Fault State:	ALL				
Escalate Work:	ALL				
Work Request ID:					
Assigned Work Status:	ALL				
Working Organisation:					
Repair Section:					

000000-000A0A49 No MEI (2) 23 Oct 2010 Level 2 CL 000000-000A0A4A No 6 Monthly Safety Insp (2) 23 Apr 2010 Level 2 CL 000000-00006FCA No 6 Monthly Safety Insp (2) 23 Apr 2010 Level 2 CL	000:00 000:00
000000-00006FCA No 6 Monthly Safety Insp (2) 23 Apr 2010 Level 2 CL	
	000:00
000000-0000B7F2 No MEI (2) 23 Oct 2010 Level 2 CL	000:00
000000-00101E15 No 6 Monthly Bonding Check (2) 16 Jun 2010 Level 2 CL	000:00
000000-000B73CB No 6 Monthly Safety Insp (2) 23 Apr 2010 Level 2 CL	000:00
000000-0000E137 No MEI (2) 23 Oct 2010 Level 2 CL	000:00
000000-000BF8A5 No 6 Monthly Safety Insp (2) 23 Apr 2010 Level 2 CL	000:00
000000-0000FB1F No 6 Monthly Bonding Check (2) 16 Jun 2010 Level 2 CL	000:00
000000-0000FB20 No Annual Declaration Of Roadworthiness Europe (2) 19 May 2010 Level 2 CL	000:00
000000-0000FBAC No MLRVV Test (2) 19 May 2011 Level 2 CL	000:00
000000-000B7906 No DfT Reg 11 Certification Leak Proof Test (2) 19 May 2011 Level 2 CL	000:00
000000-0000FBAD No DfT Reg 11 Certification Pressure Test (2) 18 May 2013 Level 2 CL	000:00
000000-0000FBAB No MT Officers Certificate Of Approval (2) 19 May 2010 Level 2 CL	000:00
000000-000E0C63 No 6 Monthly Bonding Check (2) 16 Jun 2010 Level 2 CL	000:00
000000-000294C4 No MEI (2) 23 Oct 2010 Level 2 CL	000:00
000000-000294C5 No 6 Monthly Safety Insp (2) 23 Apr 2010 Level 2 CL	000:00

ne Working Organisation Repair Section

Serial Number: NSN:	54KK60 2320998938523			
Criteria:				
Repair Level: Work Object Status:				
Mission Impact:	ALL			
Fault State:	ALL			
Escalate Work: Work Request ID:	ALL			
Assigned Work Status	: ALL			
Working Organisation	:			
Repair Section:				

Modification Event ID	Modification Number	Modification Description	Work Request ID Escalate Wor	k Production Classification/In Service Classification	Modification Type Apply When Usage Equals Embody by Target Date Usage Counter Unit	s Fault State Work Status Repair Level Working Organisation Repair Section Estimated Repair Time
000000-000257EB	00003	REVISED TURBO CHARGER EXHAUST HEAT SHIELD CHASSIS MOUNTED	No	-/	UTI	Fully Fit CL
000000-0001B46B	00004	SIDE MARKER LIGHTS	No	-/	UTI	Fully Fit CL
000000-0001B3BC	00019	INJECTOR LEAK OFF PIPE NYLON-METAL	No	-/	RTI	Fully Fit CL
000000-00015C47	00018	TRAILER ABS ELECTRICAL SUPPLY TO CAB WRNG LIGHT	No	-/	RTI	Fully Fit CL
000000-0000045B	00008	FITTING OF UPRATED REAR AXLE	No	-/	Mod	Fully Fit CL
000000-000006CA	00021	PARKING BRAKE	No	-/	UTI	Fully Fit CL
000000-00001B16	00026	Height Indicators	No	-/	UTI	Fully Fit CL

Serial Number:	54KK60			
NSN:	2320998938523			
Criteria: Repair Level: Work Object Status: Mission Impact: Fault State: Escalate Work: Work Request ID: Assigned Work Status: Working Organisation: Repair Section:	ALL Closed ALL ALL ALL ALL			

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level Fault State	Work Status	Estimated Repair Time	Working Organisation
000000-0008515E		No	Battery Test		Level 1	CL	000:00	
000000-0008515F		No	Equipment Check		Level 1	CL	000:00	
000000-00087DF8		No	Battery Test		Level 1	CL	000:00	
000000-000C3E85		No	Equipment Check		Level 1	CL	000:00	
000000-0009468D		No	Battery Test		Level 1	CL	000:00	
000000-000E55E7		No	Equipment Check		Level 1	CL	000:00	
000000-000201D6		No	6 Monthly/10000 Kms	13 Jul 2010	Level 1	CL	000:00	
000000-000928CF		No	Battery Test		Level 1	CL	000:00	
000000-000C4D49		No	Equipment Check		Level 1	CL	000:00	
000000-00098CF3		No	Battery Test		Level 1	CL	000:00	
000000-000D5AD3		No	Equipment Check		Level 1	CL	000:00	
000000-000A2A36		No	2 Yearly/40000 Kms	17 Jan 2011	Level 1	CL	000:00	
000000-000A2A37		No	Yearly/20000 Kms	12 Jan 2011	Level 1	CL	000:00	
000000-000A2A38		No	6 Monthly/10000 Kms	13 Jul 2010	Level 1	CL	000:00	
000000-000A2A77		No	OOPS 4 Yearly/80000 Kms (2)		Level 2	CL	000:00	
000000-000A123E		No	Battery Test		Level 1	CL	000:00	
000000-000EF9A4		No	Equipment Check		Level 1	CL	000:00	
000000-000BFBEF		No	6 Monthly/10000 Kms	13 Jul 2010	Level 1	CL	000:00	
000000-000201D5		No	Yearly/20000 Kms	12 Jan 2011	Level 1	CL	000:00	

ation Repair Section