



Ministry  
of Defence

Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

---

[Redacted]

Our Reference:  
FOI2022/04428  
Date:  
25 April 2022

---

Dear [Redacted],

I am writing about your email of 4 April 2022, requesting the following information:

**' I recently purchased Land Rover 110 TUM FFR PS 36 AA I would any and all history and data attached to this vehicle.'**

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

- Annex A - Transfer History
- Annex B - Inspection History
- Annex C - Service History
- Annex D - Modification History
- Annex E - Fault History (redacted)

It has proved necessary to withhold some information in accordance with a qualified exemption of the FOI Act. Commercially sensitive information in the Fault History, (Annex E) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As this exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, the Fault History provides details of the time taken by MOD contractors to rectify fault reports for the vehicle concerned. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of “would” rather than “would be likely to”.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail [CIO-FOI-IR@mod.gov.uk](mailto:CIO-FOI-IR@mod.gov.uk)). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner’s Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Secretariat

### VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
PS36AA	2320998939745	NB50313100	MICH04	TRUCK UTY MED (TUM) (HS) FFR SOFT TOP LAND ROVER 2.5 LTR TURBO DSL (WITH EEGR)	

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
13/01/1999	SALLDBA67WA157467	N/A		

### VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
PS36AA	4	20/07/1998	F6675A	RAF FORCE PROTECTION FORCE HQ	16013	6702N78	13/01/1999	
PS36AA	4	19/04/1999	F4705A	3 SQN RAF REGT	280	0249P27	14/05/1999	
PS36AA	4	09/07/2001	F4569A	LSS RAF LOSSIEMOUTH	122	793	20/07/2001	S34
PS36AA	4	22/03/2005	F6675R	51 SQN RAF REGT	MCR005	MCR005	22/03/2005	MC5
PS36AA	4	05/09/2006	F4617A	RAF ODIHAM	1880	168	05/09/2006	X61
PS36AA	2	07/01/2009	F0636A	DMJDI AQ	312	675	24/01/2009	Z89
PS36AA	1		CA122A	JSCS STORE BUS STRM SP CEN		1325WW	11/07/2012	
PS36AA		17/09/2013		ERHF VAME			12/10/2013	
PS36AA		11/11/2013		DSG HXP			18/12/2013	
PS36AA		14/09/2015		SEF (UK) ASHCHURCH			15/09/2015	



PS36AA									
2320998939745									
ALL									
Closed									
ALL									
ALL									
ALL									
ALL									
Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
No		OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	17 Jun 2017	Level 1			000:00		
No		OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	16 Jun 2021	Level 2	Fully Fit	CL	000:00		
No		2 Yearly/40000 Kms	17 Jun 2017	Level 1			000:00		
No		Yearly/20000 Kms	17 Jun 2016	Level 1			000:00		
No		OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	16 Jun 2020	Level 2			000:00		
No		OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	17 Jun 2017	Level 1			000:00		
No		OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	16 Jun 2020	Level 2			000:00		
No		6 Monthly/10000 Kms	17 Dec 2015	Level 1			000:00		
No		OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Jun 2017	Level 1			000:00		
No		6 Monthly/10000 Kms	17 Dec 2015	Level 1			000:00		
No		OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	17 Jun 2017	Level 1			000:00		
No		OOPS 5 Yearly Drain/Flush And Replen Cooling System	16 Jun 2020	Level 1			000:00		
No		6 Monthly/10000 Kms	17 Dec 2015	Level 1			000:00		
No		OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Jun 2017	Level 1			000:00		
No		Yearly/20000 Kms	17 Jun 2016	Level 1	Fully Fit	CL	000:00		
No		OOPS 5 Yearly Drain/Flush And Replen Cooling System	16 Jun 2020	Level 1			000:00		
No		OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Jun 2017	Level 1			000:00		
No		6 Monthly/10000 Kms	17 Dec 2015	Level 1	Fully Fit	CL	000:00		
No		6 Monthly/10000 Kms	17 Dec 2015	Level 1	Non-Taskworthy	CL	000:00		
No		2 Yearly/40000 Kms	17 Jun 2017	Level 1			000:00		
No		Yearly/20000 Kms	17 Jun 2016	Level 1			000:00		
No		OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	16 Jun 2021	Level 2			000:00		
No		2 Yearly/40000 Kms	17 Jun 2017	Level 1	Fully Fit	CL	000:00		
No		Yearly/20000 Kms	17 Jun 2016	Level 1			000:00		

Work Objects													
Serial Number:	PS36AA												
NSN:	2320998939745												
Criteria:													
Repair Level:	ALL												
Work Object Status:	Closed												
Mission Impact:	ALL												
Fault State:	ALL												
Escalate Work:	ALL												
Work Request ID:													
Assigned Work Status:	ALL												
Working Organisation:													
Repair Section:													
Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/Modification Type	Apply When Embodied by	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-006105B9	00038	Fitting of a New Import/Export Box Mount Bracket		No	-/-	UTI		Fully Fit					
000000-006105A0	00092	Project SHOEHORN Revised Weight Data Plate		No	-/-	UTI		Fully Fit	CL				
000000-006105B5	00031	Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants		No	-/-	UTI		Fully Fit					
000000-006105B0	00020	8 Metre Mast Mount Installation Kit		No	-/-	UTI		Fully Fit					
000000-0061059A	00016	Radio Battery Isolation Switch and Power Import / Export System		No	-/-	RTI		Fully Fit	CL				
000000-00610599	00014	Fitting of Showerproof Dash Cover		No	-/-	RTI		Fully Fit					
000000-00610596	00007	TUAM Earth Bonding Improvements		No	-/-	RTI		Fully Fit	CL				
000000-00610583	00004	Fitting Emergency Lights, Siren and Harness		No	-/-	RTI		Fully Fit					
000000-00610582	00003	Helilift Vehicle Modification (Hard Top Only)		No	-/-	RTI		Fully Fit					
000000-00610581	00001	Radio Rack Fixings		No	-/-	RTI		Fully Fit	CL				
000000-006105B4	00030	Front Belt Protection Sleeves		No	1/A	UTI		Non-Taskworthy	CL	Level 2			
000000-006105B1	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/-	UTI		Fully Fit	CL	Level 2			
000000-006105B7	00039	TUM (HS) REMUS 1 - SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI		Fully Fit	CL	Level 2			
000000-006105B2	00028	FITTING OF REAR ANTI-ROLL BAR (RARB)		No	-/-	UTI		Limited Role	CL	Level 2			
000000-0061059B	00017	Introduction of Battery Retention		No	1/A	UTI		Non-Taskworthy	CL	Level 2			
000000-00610597	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI		Non-Taskworthy	CL	Level 2			
000000-0061059C	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI		Non-Taskworthy	CL	Level 2			
000000-0061059E	00027	Input/Output Porthole for Communication Cables, Cover Modification		No	-/-	UTI		Fully Fit	CL	Level 2			
000000-006105B8	00037	Fitting Glow Plug Timer Interface Harness		No	-/-	UTI		Fully Fit	CL	Level 2			
000000-006105AF	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI		Fully Fit	CL	Level 2			
000000-0061059F	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation		No	-/-	UTI		Fully Fit	CL	Level 2			
000000-006105B4	00005	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/-	RTI		Limited Role	CL	Level 2			

Work Objects														
Serial Number:	P536AA													
NSN:	232098939745													
Criteria:														
Repair Level:	ALL													
Work Object Status:	Closed													
Mission Impact:	ALL													
Fault State:	ALL													
Escalate Work:	ALL													
Work Request ID:														
Assigned Work Status:	ALL													
Working Organisation:														
Repair Section:														
Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-008B582		Asbestos Decontamination Cleaning Required	Closed	Limited Role	No	Level 1		10 Jun 2020	N/A	Ban	TUM HS FFR SOFT TOP BOWMAN			
000000-008A664		MODS HXP13-001	Closed	Fully Fit	No	Level 2		03 Nov 2014	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-008A6657		ENGINE/COMPONENT REPAIRS HXP13-001	Closed	Non-Taskworthy	No	Level 2		06 Oct 2014	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-008A6645		TRANSMISSION REPAIRS HXP13-001	Closed	Non-Taskworthy	No	Level 2		06 Oct 2014	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-008A663D		STEERING/SUSPENSION REPAIRS HXP13-001	Closed	Non-Taskworthy	No	Level 2		03 Nov 2014	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-008A6627		BODY REPAIRS HXP13-001	Closed	Non-Taskworthy	No	Level 2		03 Nov 2014	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-008A658A		ELECTRICAL REPAIRS HXP13-001	Closed	Non-Taskworthy	No	Level 2		01 Sep 2014	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-008A6582		CAB EXTERNAL REPAIRS HXP13-001	Closed	Non-Taskworthy	No	Level 2		06 Oct 2014	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-008A6577		CAB INTERNAL REPAIRS HXP13-001	Closed	Non-Taskworthy	No	Level 2		08 Sep 2014	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007C62FD		INSPECT CES WHEN ISSUED	Closed	Fully Fit	No	Level 2		29 Oct 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007C58C4		renew aux battery cables	Closed	Fully Fit	No	Level 2		28 Oct 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007B7FD0		FIT PADDING @ WEAPON RACKS.	Closed	Fully Fit	No	Level 1		13 Oct 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007B77DA		COMD LOWER AIR VENT MISSING.	Closed	Fully Fit	No	Level 1		13 Oct 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007B77D9		G/BOX TUNNEL COVER DAMAGED.	Closed	Fully Fit	No	Level 1		13 Oct 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007B77D7		ASHTRAY MISSING	Closed	Fully Fit	No	Level 1		13 Oct 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007A445F		REPLACE TAILGATE	Closed	Fully Fit	No	Level 2		20 Jul 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-00843F98		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007B7759		REPAIR TO TH EXIT STANDARDS, LAW BRITFOR SOI 207	Closed	Non-Taskworthy	No	Level 2		12 Oct 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007B6628		STN LHF WING	Closed	Fully Fit	No	Level 2		16 Sep 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007B77D7		INCORRECT MIRROR FITTED L/H.	Closed	Fully Fit	No	Level 2		13 Oct 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007B77D6		CHAIN MISSING @ FUEL CAP	Closed	Fully Fit	No	Level 1		13 Oct 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007B77D5	000000-002CA26	BLOWER CONTROL LEVER COVER INSECURE.	Closed	Fully Fit	No	Level 1		13 Oct 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN	TH ES GP	LT REDEPLOY	
000000-007B77DC	000000-002CA26	DVRS SEAT CUSHION INSECURE.	Closed	Fully Fit	Yes	Level 1		13 Oct 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN	TH ES GP	LT REDEPLOY	
000000-007B77D9	000000-002CA26	STRAIGHTEN F/R/H WING.	Closed	Fully Fit	No	Level 2		13 Oct 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN	TH ES GP	LT REDEPLOY	
000000-007B77D6	000000-002CA26	STEERING WHEEL SHROUD INSECURE.	Closed	Fully Fit	No	Level 2		13 Oct 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN	TH ES GP	LT REDEPLOY	
000000-007BA5DC		RENEW RH DOOR	Closed	Fully Fit	No	Level 2		26 Sep 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007B662D		REMOVE BONNET SPARE WHEEL CARRIER STUD	Closed	Fully Fit	No	Level 2		17 Sep 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007B6623		FIT MISSING CLUTCH MASTER CYLINDER COVER PLATE	Closed	Fully Fit	No	Level 2		17 Sep 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007B661F		FIT MISSING SPARE WHEEL EXTENSION MOD	Closed	Fully Fit	No	Level 1		17 Sep 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007B6624		RENEW NO PLATE LIGHT	Closed	Non-Taskworthy	No	Level 2		17 Sep 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007B6628		HAZARD LIGHTS INOP	Closed	Non-Taskworthy	No	Level 2		17 Sep 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007B6862		SECURE LHR WHEEL ARCH EYEBROW	Closed	Fully Fit	No	Level 2		18 Sep 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007B6866		FIT MISSING FRONT TOW PIN	Closed	Limited Role	No	Level 1		18 Sep 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-007A4460		FIT BONNET STRAPS	Closed	Limited Role	No	Level 2		20 Jul 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007A4469		FUEL FILTER BRACKET MISSING	Closed	Fully Fit	No	Level 2		20 Jul 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007A4467		FRONT O/S GREASE CAP MISSING	Closed	Fully Fit	No	Level 2		20 Jul 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007A4461		FIT FFR ALTERNATOR BELT	Closed	Limited Role	No	Level 2		20 Jul 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007A4463		FIT BONNET RUBBER BUMPER	Closed	Fully Fit	No	Level 2		20 Jul 2013	N/A	Closed No Action	TUM HS FFR SOFT TOP BOWMAN			
000000-007ARCAE		O/S BONNET BLANKING GRILLE CRACKED	Closed	Fully Fit	No	Level 2		03 Aug 2013	N/A	Damage	TUM HS FFR SOFT TOP BOWMAN			
000000-007A446C		REMOVE FOAM SEATS IN REAR	Closed	Limited Role	No	Level 2		20 Jul 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007A445C		RECTIFY PLAY IN DOOR HINGES	Closed	Fully Fit	No	Level 2		20 Jul 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007A4465		EXCESSIVE SIDEWAYS PLAY IN BRAKE PEDAL	Closed	Non-Taskworthy	No	Level 2		20 Jul 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007A4468		O/S BRAKE LAMP OUT	Closed	Non-Taskworthy	Yes	Level 2		20 Jul 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007A4476		REPAIR IGNITION	Closed	Non-Taskworthy	No	Level 2		20 Jul 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007A445E		REPLACE DRIVERS SIDE SEAT BASE	Closed	Non-Taskworthy	No	Level 2		20 Jul 2013	N/A	Damage	TUM HS FFR SOFT TOP BOWMAN			
000000-00796528		RENEW WVA BALL JOINT RUBBER	Closed	Non-Taskworthy	No	Level 2		20 Jun 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-00796599		RENEW TYRES XS	Closed	Non-Taskworthy	No	Level 1		22 Jun 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-007988A8		GODDYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-00798895		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-0078862A		STARTER MOTOR U/S	Closed	Non-Taskworthy	No	Level 2		13 May 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-00788524		RENEW WINDSCREEN	Closed	Fully Fit	No	Level 2		11 May 2013	N/A	Damage	TUM HS FFR SOFT TOP BOWMAN			
000000-00778752		NONE STARTER	Closed	Fully Fit	No	Level 2		01 Apr 2013	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-00644553		Insp Steering Drive Arm Tab Washer	Closed	Fully Fit	No	Level 2	000000-000002D0	22 Jun 2011	N/A	Inspection	TUM HS FFR SOFT TOP BOWMAN			
000000-0077822		REPLACE STARTER MOTOR	Closed	Non-Taskworthy	No	Level 2		21 May 2013	N/A	Failure	TUM HS FFR SOFT TOP BOWMAN			
000000-00409815		Initial Maintenance	Closed	Fully Fit	No	Level 1		29 Mar 2009	N/A		TUM HS FFR SOFT TOP BOWMAN			
000000-0040980E		Initial Usage	Closed	Fully Fit	No	Level 1		29 Mar 2009	N/A		TUM HS FFR SOFT TOP BOWMAN			