





<b>Nikon Monarch HG 10x42; &amp; Monarch M5 10x42</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	 <p>Strap identification No.</p> <p>Location of identification No. (reference to MONARCH 5)</p>  <p>Old strap                      Improved strap</p>
<b>Alert Number</b>	2207-0288
<b>Product Type</b>	Gadgets - Binoculars
<b>Product Identifiers</b>	See affected straps on PDF attached
<b>Product Description</b>	Black binoculars with strap
<b>Country of Origin</b>	Not specified
<b>Counterfeit</b>	No
<b>Risk Type</b>	Chemical
<b>Risk Description</b>	The product presents a chemical risk as the straps associated with a range of Nikon products have been reported as being in breach of the REACH Regulations by having excess PAH's.
<b>Corrective Measures</b>	Nikon will replace the affected straps free of charge regardless of the warranty period. For more information, please see: <a href="https://www.nikonimgsupport.com/eu/BV_article?articleNo=000044441&amp;co_nfigured=1&amp;lang=en_GB">https://www.nikonimgsupport.com/eu/BV_article?articleNo=000044441&amp;co_nfigured=1&amp;lang=en_GB</a>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards