




Wooden Toy Tractors	
Aspect	Details
Images	
Alert Number	2208-0456
Product Type	Toys – Wooden Toy
Product Identifiers	N/A
Product Description	Wooden toy tractor with no markings, warnings or identification information. Roofs are painted in blue while other surfaces are wood. Purely wooden tractors have two circular holes for windows in the sides and a small metal hook on the back. Painted roof tractors have larger wheels, a small steering wheel inside, windows/entrance and a wooden dowel vertically at the rear.
Country of Origin	Turkey
Counterfeit	No
Risk Type	Choking
Risk Level	Serious
Risk Description	The product presents a serious risk of choking as small parts, particularly the wheels and dowels, can be easily removed with minimal force and can fit into a truncated cylinder. A young child may place the small part in their mouth and the parents/carers may not notice in time, with the small part able to block a child's airways. The product does not meet the requirements of the Toys (Safety) Regulations 2011.
Corrective Measures	The products have been destroyed at the border.
Online Marketplace	N/A
Notifier	Local Authority Trading Standards