

September 2022

Air Quality and Dust Monitoring Monthly Report – September 2022 Birmingham City Council

gov.uk/hs2



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS₂ Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2021, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken within Birmingham City (BCC) during September 2022.
- 1.1.2 Figures 1-3 in Appendix A indicates the current worksites together with the dust monitoring locations for September 2022.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report monthly available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites as presented in Appendix A, Figures 1-3, include:

Washwood Heath (Sublot 4)

- Setup of the compound area and haulage routes; and
- Demolition and crushing of existing concrete foundations on site.

Bromford East Tunnel Portal (BETP) (Sublot 1B)

• On-site slurry treatment


Curzon Street Station


- Ground remediation; and
- Utility diversion works.
- 1.1.5 Seven (7) dust monitors have been installed at worksites, where works are underway. These sites returned a medium to high dust risk rating.
- 1.1.6 The dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from the dust monitor presented in Figure 4. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigations.


- 1.1.7 The trigger level for PM₁₀ concentrations of 190 μg/m³, over a 1-hour period, in accordance with the updated guidance document '*Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)*' has been applied.
- 1.1.8 There were no (0) dust trigger alerts recorded during the monitoring period (September 2022).
- 1.1.9 Data capture was below 90% for #753 Curzon monitor due to a power disconnection on site.
- 1.1.10 No (0) complaints were received in the reporting period.

Appendix A – Worksites and Monitoring Locations

Figures 1 - 3: Worksites and monitoring locations within the BCC








		Z		
	0	13 N STREET		
	5		1	2
		IL	COPSAL STREE	A
		1		t
				.1
		Easteid City Par	e k	
				AS
1				RZON STREET
			61 CU	
53 CURZON STREET				
CURZON STREE				
				-
				-
	-			- 1
				1
Sp.				
		>		
05	7			
X				
	~			
				1
///	×			
			\sim	
100				
	HS2 Ltd accept	no responsibility for	any circumstances, whic	
hs	arise from the re amendment or a incomplete in an	bbreviation or if it is	hap after alteration, s issued in part or issued	
- Common - C	on number 06704800		Scale at A3: 1:2	2 000
Registered in England. Registrati Registered office: 2 Snowhill, Qu Birmingham B4 6GA. © Crown copyright and dai		Ŷ	20 40	60 80
Ordnance Survey Licence	Number 1000491	 90.	Metres	e: 23/06/22
Boo Humber.			Date	

Appendix B – Dust Monitoring Results

Table 1: Dust monitoring locations and September 2022 results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (µg/m³)	Minimum 1-hour PM ₁₀ concentration (µg/m³)	Maximum 1- hour PM ₁₀ concentration (µg/m³)	Number of 1- hour periods exceeding trigger level of 190 µg/m ³	Data capture (%)
WHD001	411221, 289245	Washwood Heath Depot, near receptors on Drews Lane	М	Yes	No	4.7	0.2	33.8	0	99.9
WHD002	410758, 289130	Washwood Heath Depot, near receptors on Common Lane	М	Yes	No	1.2	0.1	18.1	0	96.7
BETP001	416620, 290808	Bromford East Tunnel Portal, Twisted Oak Stables	М	Yes	No	7.2	0.5	39.6	0	100.0
BETP002	417467, 290649	Bromford East Tunnel Portal, Attleboro Lane	М	Yes	No	5.0	0.7	35.1	0	100.0
Dust #530	407702, 287079	Curzon Street Station HS2 Site	н	N/A	N/A	3.7	0.1	25.8	0	93.1
Dust #753	407619, 287006	Curzon Street Station HS2 Site	н	N/A	N/A	4.3	0.1	22.2	0	85.3
Dust #552	407765, 287073	Curzon Street Station HS2 Site	н	N/A	N/A	5.6	0.3	38.0	0	100.0

Figure 4: Construction dust 1-hour mean indicative PM10 concentration for all dust monitors



Air Quality and Dust Monitoring Summary Report, September 2022 Birmingham City Council

