


Extracts from Svitzer vessel inspection report

	SVITZER VESSEL INSPECTION REPORT	
--	---	--

VESSEL NAME: <i>MERCURIUS</i> VESSEL LOCATION: <i>IMUIDEN</i>
--

STATUS:		REVISION:	
PRELIMINARY	<input checked="" type="checkbox"/>	FINAL REPORT	<input type="checkbox"/>
RESTRICTED	<input type="checkbox"/>	UNRESTRICTED	<input type="checkbox"/>
		DATE: <i>09-12-2019</i>	

AUTHOR(S): SIGNED: NAME: 	

VESSEL NAME: SVITZER
VESSEL
INSPECTION REPORT

2. LOCATION/INSPECTION CONDITIONS/STATE OF VESSEL

VESSEL EXAMINED		REMARKS
@ ANCHOR		
@ SEA		
@ QUAY	X	
@ DRYDOCK		
TOWING	YES	
	NO	

3. VESSEL DESCRIPTION AND SPECIAL FEATURES
4. PRINCIPAL PARTICULARS

Current Vessel Name	MERCURIUS
Port of Registry	ILMUIDEN B. ISKEE & ZOON B.V
Owners	SLEEDDIENST
Managers	
Builder	DAMEN - SONG SAM SHIPYARD VIETNAM
Yard Number	512533
Year of Build	2013
Date Keel Laid	2013
Date of Delivery	22 09 - 07 - 2014
Official Number	PCYS
Call Sign	PCYS
Type of Vessel	ASD TUG 3212
Classification Society	BUREAU VERITAS
Class Notations	A1 + A2 + A3 ILM A1 Escort Tug ILM ^{# IWS} UMS
Class Number	
IMO Number	9695523
Length	L.O.A. 32.70 m
Length (L) as defined in Art. 2(8)	28.83 m
Length	L.B.P.
Breadth	(m) 12.820 m

VESSEL NAME:

SVITZER
VESSEL
INSPECTION REPORT

Breadth	(extreme)	
Depth	(m)	
Draught	(maximum summer)	4.10
Displacement	(summer)	
Gross Tonnage		447
Net Tonnage		134
Deadweight		per 53
Main Engine Type and Number		cn= 3516 c # TTI00435 243
Output at RPM		2x 2525 kW 5050 RPM
Bollard Pull		ASTERN 75.0 TONNES @ 1750 RPM AHEAD 81.9 TONNES 1760
Electric Power Generation & Prime Movers.		

5. CLASSIFICATION STATUS OF VESSEL

STATUS	LAST SURVEY DATE	NEXT SURVEY DATE
ANNUAL SURVEY	Aug 2019	
BOILER SURVEY		
DOCKING SURVEY	Aug 2019	
MACHINERY SURVEY	Aug 2019	
SPECIAL SURVEY	Aug 2019	
TAILSHAFT SURVEY		

CONDITIONS OF CLASS		
PLACE	REPORT No.	REMARKS

VESSEL NAME:

**SVITZER
VESSEL
INSPECTION REPORT**

6. TRADING CERTIFICATES/MANUALS/LOG BOOKS

STATUS	ISSUED BY	DATE OF ISSUE	DATE OF EXPIRY	LAST ENDORSEMENT
CERTIFICATE OF REGISTRY		08-02-16		
INTERNATIONAL LOAD LINE		23-09-19	20-07-24	
INTERNATIONAL TONNAGE		09-04-14		
PANAMA CANAL TONNAGE				
SUEZ CANAL TONNAGE				
SAFETY CONSTRUCTION				
SAFETY EQUIPMENT		17-01-19	17-01-20	
SAFETY RADIO		22-07-14		
ISPS CERTIFICATE				
GMDSS				
PASSENGER SHIP SAFETY				
I. S. M. CODE				
MINIMUM MANNING CERTIFICATE				
SAFE MANNING				
IOPP CERTIFICATE				
CERTIFICATE OF INSURANCE IN RESPECT OF CIVIL LIABILITY FOR OIL POLLUTION				
DERATTING				
PORT STATE CONTROL				
U.S.C.G. LETTER OF COMPLIANCE				
U.S.C.G. CERTIFICATE OF FINANCIAL RESPONSIBILITY (WATER POLLUTION)				
UNATTENDED MACHINERY SPACE				
NON-CANADIAN COMPLIANCE				
R.I.N.A. CERTIFICATE				
IAPP CERTIFICATE				

MANUALS	GOVERNMENT	DATE OF APPROVAL
OPERATIONS MANUAL		
PROCEDURES & ARRANGEMENT MANUALS ANNEX I/II/VI		
SHIPBOARD OIL POLLUTION EMERGENCY PLAN		

VESSEL NAME:

**SVITZER
VESSEL
INSPECTION REPORT**

MANUALS	GOVERNMENT	DATE OF APPROVAL
TRIM & STABILITY BOOK		

LOG BOOKS EXAMINED	REMARKS
DECK: YES	
NO	
TOWING LOG YES	
NO	
ENGINE: YES	
NO	
OTHER: (SPECIFY)	

7. SURVEY RECORD SHEETS

7.1 HULL									
ITEM	GENERAL CONDITION				COATING CONDITION			REMARKS	
	1	2	3	4	1	2	3	CONTINUOUS GENERAL GOOD APART FROM FWD DR	

RUDDER IF FITTED									
GENERAL									
PINTLE UPPER	CLEARANCES*	Port			Stbd			Fwd	Aft
PINTLE LOWER	CLEARANCES*	Port			Stbd			Fwd	Aft

* Taken from Ship's Records - (mm)

SHELL PORT									
FORWARD	1								
MIDSHIP	1								
AFT	1								

SHELL STARBOARD									
FORWARD	1								

VESSEL NAME:

SVITZER
VESSEL
INSPECTION REPORT

MIDSHIP	1						
AFT	1						

SHELL BELOW WATERLINE

FORWARD P/S							
MIDSHIP P/S							
AFT P/S							

ITEM	GENERAL CONDITION				COATING CONDITION			REMARKS
	(1)	2	3	4	(1)	2	3	

FORECASTLE DECK	1	X				X	
-----------------	---	---	--	--	--	---	--

MAIN DECK

FORWARD	1					X	
MIDSHIP	1				X		
AFT	1				X		

POOP DECK	1				X		
-----------	---	--	--	--	---	--	--

FENDERS

BOW	X				X		
STBD SIDE		X			X		
PORT SIDE		X			X		
AFT	X				X		

7.2 TANKS

ITEM	GENERAL CONDITION				COATING CONDITION			REMARKS
	1	2	3	4	1	2	3	

VESSEL NAME:

SVITZER
VESSEL
INSPECTION REPORT

7.3 ACCOMMODATION & DECKHOUSES

ITEM	GENERAL CONDITION				COATING CONDITION			REMARKS
	1	2	3	4	1	2	3	

ACCOMMODATION: CREW	X							NO. OF BERTHS
ACCOMMODATION: DECORATION & FINISHES	X							
ACCOMMODATION: OFFICERS	X							NO. OF BERTHS
ACCOMMODATION: SURVIVORS	X							NO. OF BERTHS

ACCOMMODATION: STRUCTURE	X							
-----------------------------	---	--	--	--	--	--	--	--

GALLEY	X							
PROVISION	X							

STORES ROOMS								
	X							

VESSEL NAME:

**SVITZER
VESSEL
INSPECTION REPORT**

7.4 DECK OUTFIT & LIFE SAVING EQUIPMENT

ITEM	GENERAL CONDITION				COATING CONDITION			SEEN OPERATING	REMARKS
	1	2	3	4	1	2	3	YES/NO	

ACCOMMODATION GANGWAYS

PORT								
STBD								

BULWARKS & RAILINGS

PORT								
STBD								

FUNNEL

--	--	--	--	--	--	--	--	--

LIFEBOATS & DAVITS

No. 1							CERTIFIED FOR	PERSONS
No. 2							CERTIFIED FOR	PERSONS

RESCUE BOAT

							CERTIFIED FOR	PERSONS
--	--	--	--	--	--	--	---------------	---------

LIFEBUOYS

--	--	--	--	--	--	--	--	--

LIFERAFTS & HYDROSTATIC RELEASES

							CERTIFIED FOR	PERSONS
							CERTIFIED FOR	PERSONS
							CERTIFIED FOR	PERSONS
							CERTIFIED FOR	PERSONS

CRANES

VESSEL NAME:

**SVITZER
VESSEL
INSPECTION REPORT**

7.6 TOWING GEAR

ITEM	GENERAL CONDITION				COATING CONDITION			SEEN OPERATING	REMARKS
	1	2	3	4	1	2	3	YES/NO	

TOWING WINCHES FORWARD

TOWING- & ANCHOR HANDLING WINCHES AFT

CAPSTANS, TUGGER- & AUXILIARY WINCHES

OTHER TOWING EQUIPMENT

TOWING HOOK									
SHARK JAWS									
TOWING PINS									
STERN ROLLER									
CARGO RAILS									

**TOWING LINES
MAIN & SPARE**

					TYPE	DIM. / MBL mm / tons	