




Nail Dust Collector 858-5

Aspect	Details
Images	
Alert Number	2212-0028
Product Type	Electrical appliances and equipment - Nail dust collector
Product Identifiers	Model: 858-5
Product Description	White electric nail dust collector
Country of Origin	China
Counterfeit	Unknown
Risk Type	Electric shock
Risk Level	High
Risk Description	The product presents a high risk of electric shock as the plug pins are difficult to fit into a socket, due to the irregularities. Over time, from the consumer using the product, the plug pins could wear down the socket connectors. After they have worn down, it could be likely that the user plugs in the device and receives an electric shock from the damaged socket. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.
Corrective Measures	The import has been rejected and destroyed at the border
Online Marketplace	N/A
Notifier	Local Authority Trading Standards