

Product Safety Report

PIEPS and Black Diamond Avalanche Transceiver	
Aspect	Details
Images	PIEPS PRO BT PIEPS POWDER BT PIEPS DSP SPORT
Alert Number	2207-0385
Product Type	Communications and media equipment – avalanche transceiver
Product Identifiers	Affected models: PIEPS Micro BT Button, PIEPS Micro BT Race, PIEPS Micro BT Sensor, PIEPS POWDER BT, PIEPS PRO BT, PIEPS DSP PRO / SPORT, BLACK DIAMOND RECON and BLACK DIAMOND GUIDE
Product Description	Plastic units with LCD screen. A number of models, each with the manufacturer's name (PIEPS) or the Black Diamond logo printed on the front or rear of the unit. The devices are worn by skiers/snowboarders/ snowmobilers so they can be located if they are buried in an avalanche. Images of all affected models can be found on the PIEPS website.
Country of Origin	Bosnia
Counterfeit	No
Risk Type	Malfunction leading to injuries/death
Risk Description	The product has been found to present a risk to the user as certain transceivers and beacons do not pass a Safety Check. A defect in the electronics may prevent the unit from switching from SEND mode to SEARCH mode, resulting in no additional aid in the search and rescue process in the case of an avalanche.
Corrective Measures	Consumers should immediately cease use of the product and follow the instructions provided on the PIEPS website: https://www.pieps.com/safety-check-mode-failure/?lang=en_uk
Online Marketplace	N/A
Notifier	Local Authority Trading Standards