




IKEA LETTAN Mirror											
Aspect	Details										
Images	 <table border="1" data-bbox="839 472 1289 696"> <thead> <tr> <th>Article no.</th> <th>Item name</th> </tr> </thead> <tbody> <tr> <td>604.352.69</td> <td>LETTAN mirror 100x96</td> </tr> <tr> <td>004.353.14</td> <td>LETTAN mirror 40x96</td> </tr> <tr> <td>804.353.05</td> <td>LETTAN mirror 60x96</td> </tr> <tr> <td>804.353.10</td> <td>LETTAN mirror 80x96</td> </tr> </tbody> </table>	Article no.	Item name	604.352.69	LETTAN mirror 100x96	004.353.14	LETTAN mirror 40x96	804.353.05	LETTAN mirror 60x96	804.353.10	LETTAN mirror 80x96
Article no.	Item name										
604.352.69	LETTAN mirror 100x96										
004.353.14	LETTAN mirror 40x96										
804.353.05	LETTAN mirror 60x96										
804.353.10	LETTAN mirror 80x96										
Alert Number	2301-0066										
Product Type	Decorative Articles - Mirror										
Product Identifiers	Item Number: 604.352.69 LETTAN mirror 100x96, Item Number 004.353.14 LETTAN mirror 40x96, Item Number 804.353.05 LETTAN mirror 60x96, Item number 804.353.10 LETTAN mirror 80x96 Date stamps before and including 2105 (yy/ww)										
Product Description	Wall mirror with fittings sold from February 2020. Products with amended wall fittings are still available. Dates up to 2105 (yy/ww) affected.										
Country of Origin	China										
Counterfeit	No										
Risk Type	Injuries										
Risk Description	The product presents a risk of injuries as the wall fittings for the mirror may break, causing the mirror to fall. The product does not meet the requirements of the General Product Safety Regulations 2005.										
Corrective Measures	IKEA have recalled the product from end users. For further information, access the IKEA website at: https://www.ikea.com/gb/en/customer-service/product-support/recalls/lettan-mirror-pub9537a970										
Online Marketplace	N/A										
Notifier	Local Authority Trading Standards										