



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk



Our Reference:
FOI2022/09368
Date:
11 August 2022

Dear [REDACTED],

I am writing about your email of 6 August 2022, requesting the following information:

'My company has just purchased a ex mod vehicle and we would like to make a freedom of information request regarding the vehicle

It would be great if you would be able to give me any details that you hold on this vehicle

We are looking for

Service history

Deployment history

And anything of interest that you hold

The vehicle is now in "trade" and attached to this email is a picture of the V5'

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000. Using the photograph you provided we were able to determine that the military registration number of this vehicle was KA71AA, which was used to locate the information you requested.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

- Annex A – KA71AA TFR (Vehicle History)
- Annex B – Fault History (Redacted)
- Annex C – Inspection History
- Annex D – Modification History (Redacted)
- Annex E – Service History

It has proved necessary to withhold some information related to your request. This is commercially sensitive information in the Fault History (Annex B) and Modification History (Annex D) relating to contractor repair times, which has been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As this exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

Defence Equipment & Support

The Fault and Modifications Histories provide details of the time taken by MOD contractors to rectify fault reports on KA71AA. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of “would” rather than “would be likely to”.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner’s Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner’s website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
KA71AA	2320998939741	NB42203100	LV2A/088AM3	TRUCK UTY LIGHT (TUL) (HS) 4X4 GS SOFT TOP LAND ROVER 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR
Date In Service	Chassis Number	Engine No.	Cast	Cast Date	
(g)	(h)	(i)	(j)	(k)	
27/1/1997	SALLDAA67VA122585	N/K			

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KA71AA	4	27/1/1997	F6675A	RAF FORCE PROTECTION FORCE HQ	999	5321M3	27/1/1997	
KA71AA	4	07/08/2001	F4705A	3 SQN RAF REGT	1010	744	07/08/2001	S38
KA71AA	4	23/01/2008	F5005A	SHQ RAF HIGH WYCOMBE	98	903	05/02/2008	Z08
KA71AA	1	07/05/2013	CA005A	JSCS ASHGURCH	10	7239AA	09/10/2013	
KA71AA		25/1/2013		DSG COLCHESTER			02/12/2013	
KA71AA		23/10/2014		75 ENGR REGT			07/1/2014	
KA71AA		18/10/2019		75 ENGR REGT, 106 FD SQN			30/10/2019	
KA71AA		25/1/2019		OSVP HOLDINGS			10/12/2019	

Work Objects
 Serial Number: 6471AA
 NSL: 232095839741

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID: ALL
 Assigning Work Status: ALL
 Working Organisation: Working Organisation

Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID	Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00A0C415	INV TEMP AND FUEL DASH BACK LT INOP	Closed	Fully FR	No	Level 2			19 Jul 2018	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00A0C412	INV OIL LEAKAGE AT LH TRACTA SEAL	Closed	Fully FR	No	Level 2			19 Jul 2018	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B1E336	SWAGE 377 - SWIVEL HOUSING	Closed	Fully FR	No	Level 1	000000-00006978		29 Mar 2019	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B1E338	SWAGE 377 - SWIVEL HOUSING	Closed	Fully FR	No	Level 1	000000-00006978		29 Mar 2019	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00A0C417	RECT PASS WINDOW NOT OPENING	Closed	Non-Taskworthy	No	Level 2			19 Jul 2018	N/A	Closed No Action	TUL HS GS SOFT TOP		000:00	
000000-00A0C411	INV OIL LEAK AT GEARBOX	Closed	Fully FR	No	Level 2			19 Jul 2018	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00A0C410	INV MAP LT INOP	Closed	Fully FR	No	Level 1			19 Jul 2018	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00A0C413	INFLATE ALL TYRES TO CORRECT PRESSURES	Closed	Fully FR	No	Level 1			19 Jul 2018	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00A0B416	CONVOY LAMP INOP	Closed	Unlimited Role	No	Level 1			14 Jun 2018	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00A0B409	BATTERIES DISCHARGED LUS	Closed	Unlimited Role	No	Level 1			14 Jun 2018	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00A0B40F	WIPERS OPERATE ONE SPEED ONLY	Closed	Unlimited Role	No	Level 2			14 Jun 2018	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00A0B418	AF 6.654 - 17 - SPECIALISED EQUIPMENT - NO AF6530 PRESENTED	Closed	Fully FR	No	Level 2			14 Jun 2018	N/A	Closed No Action	TUL HS GS SOFT TOP		000:00	
000000-00A0B40F	THIS vehicle has been certified - fit to drive to repair facility only	Closed	Fully FR	No	Level 2			21 Jun 2018	N/A	Closed No Action	TUL HS GS SOFT TOP		000:00	
000000-00A62196	PLAY AT VISCIOUS FAN UNIT	Closed	Fully FR	No	Level 2			11 Oct 2017	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A621A8	BAAN - 20 - CARRY OUT REAR LIGHT DIAGNOSTIC CHECKS ELECTRIC LIGHTS *REVERSE LIGHT INOP	Closed	Non-Taskworthy	No	Level 2			11 Oct 2017	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B506	BAAN - 25 - RE-PAIN AS REQUIRED	Closed	Non-Taskworthy	No	Level 2			14 Jun 2018	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B40F	BAAN - 25 - WAX OIL REPAIRED AREA	Closed	Non-Taskworthy	No	Level 2			14 Jun 2018	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B409	BAAN - 25 - REMOVE AND REPAIR CORROSION IN DRIVERS SIDE FOOT WELL	Closed	Non-Taskworthy	No	Level 2			14 Jun 2018	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B4CA	BAAN - 25 - WAX OIL REPAIRED AREA	Closed	Non-Taskworthy	No	Level 2			14 Jun 2018	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B4C2	BAAN - 25 - REMOVE SECTION OF CHASSIS CORRODED AND WELD IN REPAIR PLATE	Closed	Non-Taskworthy	No	Level 2			14 Jun 2018	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B484	BAAN - 25 - R/RETT REQUIRED ITEMS TO CONDUCT REPAIR AND WELD OF OUTREGGER	Closed	Non-Taskworthy	No	Level 2			14 Jun 2018	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B49F	BAAN - 20 - 9899 - REMOVE & RETT ACCESS PANEL TO ACCESS REVERSE LIGHT SWITCH	Closed	Non-Taskworthy	No	Level 2			14 Jun 2018	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B497	BAAN - 20 - 4586 - REMOVE & RETT REVERSING LIGHT RH ELEC LIGHTS	Closed	Non-Taskworthy	No	Level 2			14 Jun 2018	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B48D	BAAN - 20 - 4590 - RENEW REVERSING LIGHT SWITCH ELEC LIGHTS	Closed	Non-Taskworthy	No	Level 2			14 Jun 2018	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A0B71E	THIS vehicle has been certified - fit to drive to repair facility only	Closed	Non-Taskworthy	No	Level 2			15 Jan 2018	N/A	Closed No Action	TUL HS GS SOFT TOP		000:00	
000000-00A62139	CONVOY LIGHT BULB MISSING	Closed	Fully FR	No	Level 1			11 Oct 2017	N/A	Closed No Action	TUL HS GS SOFT TOP		000:00	
000000-00A62134	PLAY AT FRONT PROP SHAFT	Closed	Non-Taskworthy	No	Level 2			11 Oct 2017	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00A4139D	Whing Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Unlimited Role	No	Level 2	000000-00004519		28 Jul 2017	N/A	Closed No Action	TUL HS GS SOFT TOP		000:00	
000000-00A0B2R5	Clutch pedal drops to the floor	Closed	Non-Taskworthy	No	Level 2			09 Mar 2017	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00A0B3B4	HANDBRAKE INOP	Closed	Non-Taskworthy	No	Level 2			19 Feb 2017	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B38F	REPLACE TIE DOWNIS ON BONNET	Closed	Fully FR	No	Level 1			11 Nov 2015	N/A	Refurbishment	TUL HS GS SOFT TOP		000:00	
000000-00B0B38B	REPLACE REAR TAILGATE STRAPS	Closed	Fully FR	No	Level 1			11 Nov 2015	N/A	Refurbishment	TUL HS GS SOFT TOP		000:00	
000000-00B0B386	CARRY OUT AF66524 RE INSPECTION.	Closed	Non-Taskworthy	No	Level 1			11 Nov 2015	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3D2C	REPLACE COOLANT AS SPEC GRAVITY INCORRECT AT -15	Closed	Fully FR	No	Level 1			12 Nov 2015	N/A	Service	TUL HS GS SOFT TOP		000:00	
000000-00B0B3D2C	REPLACE COOLANT HEADER TANK CAP AS NOT SECURE	Closed	Fully FR	No	Level 1			12 Nov 2015	N/A	Refurbishment	TUL HS GS SOFT TOP		000:00	
000000-00B0B3080	Check No2 ball joint torque tightness as per safety notice LE SNAC 00063	Closed	Non-Taskworthy	No	Level 2	000000-0000320A		20 Jun 2016	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	REPLACE DOOR LOCKS WITH NEW BARRELS AND KEYS	Closed	Unlimited Role	No	Level 2			11 Nov 2015	N/A	Refurbishment	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	carry out 316.6334 inspection	Closed	Non-Taskworthy	No	Level 2			22 Sep 2015	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	CARRY OUT IN INSP	Closed	Fully FR	No	Level 2			13 Aug 2015	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	000000-00320299 VEHICLE JACK CERT OUT OF DATE	Closed	Unlimited Role	No	Level 2			24 Nov 2014	N/A	Closed No Action	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	000000-00320299 TOW STRAP CERT OUT OF DATE	Closed	Unlimited Role	No	Level 2			24 Nov 2014	N/A	Closed No Action	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	DAMAGE TO WINDSCREEN	Closed	Unlimited Role	No	Level 2			24 Feb 2015	N/A	Damage	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	THIS VEHICLE MAY BE DRIVEN TO REPAIR FACILITY ONLY	Closed	Non-Taskworthy	No	Level 2			12 Nov 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	CARRYOUT FIRE EXTINGUISHER CHECK	Closed	Non-Taskworthy	No	Level 1			12 Nov 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	CARRY OUT VEHICLE JACK INSPECTION	Closed	Non-Taskworthy	No	Level 1			12 Nov 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	CARRY OUT 53Z RECEIPT INSPECTION	Closed	Non-Taskworthy	No	Level 2			12 Nov 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	CARRY OUT 53ZW RECEIPT INSPECTION	Closed	Non-Taskworthy	No	Level 2			12 Nov 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	Towing 2 axle Assembly	Closed	Unlimited Role	No	Level 2	000000-00001158		09 Oct 2014	Degraded	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	GOODREAD C90 tyres manufactured in South Africa cracking File Ref	Closed	Non-Taskworthy	No	Level 1	000000-0000031A		24 Jun 2013	N/A	Failure	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	05976540/06/09	Closed	Fully FR	No	Level 2	000000-00000395		25 Jun 2013	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	Inspect tyres for damage	Closed	Fully FR	No	Level 2			03 Apr 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	Full Repray	Closed	Fully FR	No	Level 1			03 Apr 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	Front Shock Towers Rusted	Closed	Fully FR	No	Level 1			03 Apr 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	Rear Pylons Insure Along RH Side Of Chassis	Closed	Fully FR	No	Level 1			03 Apr 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	Conroy Light Sacerd	Closed	Fully FR	No	Level 1			03 Apr 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	Change Rings Shared	Closed	Fully FR	No	Level 1			03 Apr 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	5000 Fan Missing	Closed	Fully FR	No	Level 1			03 Apr 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	
000000-00B0B3089	Bonnet Straps Broken	Closed	Fully FR	No	Level 1			03 Apr 2014	N/A	Inspection	TUL HS GS SOFT TOP		000:00	

Work Objects

Serial Number: KA71AA
 NSN: 2320998939741

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-005E2BDA		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00BACD77		No	FMT934 Functional Check (1)*	29 Apr 2020	Level 1	Fully Fit	CL	000:00		
000000-003C7D87		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-006C278B		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-0083DD88		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-0098D29A		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-0083DD9E		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-006C27F7		No	First Parade Insp (AR)(1)		Level 1	Non-Taskworthy	CL	000:00		
000000-00A90A78		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-004DD973	000000-00302B99	No	MEI (2)		Level 1	Fully Fit	CL	000:00		
000000-006C27F6		No	6 Monthly 6534 Insp		Level 2	Non-Taskworthy	CL	000:00		
000000-003C7D72		No	MEI (2)		Level 1	Non-Taskworthy	CL	000:00		
000000-0092B88F		No	6 Monthly 6534 Insp		Level 2	Non-Taskworthy	CL	000:00		
000000-005E2BD9		No	MEI (2)		Level 1	Fully Fit	CL	000:00		
000000-00437A52		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-00502AB4		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-00502AB5	000000-00302B99	No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-00210D98		No	First Parade Insp (AR)(1)		Level 1	Non-Taskworthy	CL	000:00		
000000-0077CAE0		No	6 Monthly 6534 Insp		Level 1	Wip		000:00		
000000-00B4CE1D		No	MEI (2)		Level 1	Fully Fit	CL	000:00		
000000-00B4CE55		No	6 Monthly 6534 Insp		Level 2	Fully Fit	CL	000:00		
000000-00BAE868		No	First Parade Insp (AR)(1)		Level 1	Fully Fit	CL	000:00		
000000-0077CBFC		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		

Work Objects
Serial Number: 1471AA
NSN: 231098939741

Criteria:
Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault Status: ALL
Escalate Work: ALL
Work Request ID: ALL
Assigned Work Status: ALL
Working Organisation: ALL
Repair Section:

Work Request ID	Modification Number	Modification Description	Escalate Work	Production Classification	Modification Type	Apply When Usage Equals	Embodiment by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-00622566	00046	FITTING OF WHEELMUT INDICATORS TO LAMB ROVER HS PLATFORMS	No	L/A	Mod				Fully Fit	CL	Level 2			
000000-00685471	00004	The instruction details the removal of the existing 16 way lighting switch and the fitting of a seven way lighting switch to all variants including winter water valves.	No	3/A	RT				Fully Fit	CL	Level 2			
000000-00629168	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension	No	-/-					Fully Fit	CL	Level 2			
000000-00629164	00031	Cover for Blower Flashing Beacons (Battlefield Ambulance & RMP TULUM HS) Variants	No	-/-	UT				Fully Fit	CL	Level 2			
000000-00629165	00004	Fitting of Spare Wheel Tyre Inflation Valve Extension	No	-/-	RT				Fully Fit	CL	Level 2			
000000-0062914C	00004	Fitting of Spare Wheel Tyre Inflation Valve Extension	No	-/-	RT				Fully Fit	CL	Level 2			
000000-00629161	00019	Blankout Cover for Warning Light Panel	No	-/-	UT				Fully Fit	CL	Level 2			
000000-00629150	00037	Fitting Glow Plug Timer Interface Harness	No	-/-	UT				Fully Fit	CL	Level 2			
000000-00629160	00017	Introduction of Battery Retention	No	L/A	UT				Non-Taskworthy	CL	Level 2			
000000-00629163	00025	Fitting of Spare Wheel Lifting Aid Harness	No	L/A	UT				Non-Taskworthy	CL	Level 2			
000000-0062914F	00030	Front Bulk Protection Sleeves	No	L/A	UT				Non-Taskworthy	CL	Level 2			
000000-00629162	00024	Fitting of Trailer Breakaway Attachment Plate	No	-/-	UT				Fully Fit	CL	Level 2			
000000-00618004	00039	TUM HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME	No	-/-	RT				Fully Fit	CL	Level 2			

Work Objects

Serial Number: KA71AA
 NSN: 2320998939741

Criteria:

Repair Level: ALL
 Work Object Status: Closed

Mission Impact: ALL

Fault State: ALL

Escalate Work: ALL

Work Request ID:

Assigned Work Status: ALL

Working Organisation:

Repair Section:

Maintenance Event ID	Escalate Work	Maintenance Event Name	Work Request ID	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-00437A55	No	6 Monthly/10000 Kms	000000-00302B99	29 Apr 2020	Level 1			000:00		
000000-003C7D6C	No	2 Yearly/40000 Kms		25 Mar 2021	Level 1			000:00		
000000-0088D929	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Fully Fit	CL	000:00		
000000-007A1EAB	No	2 Yearly/40000 Kms		25 Mar 2021	Level 1	Fully Fit	CL	000:00		
000000-003C7D6F	No	Yearly/20000 Kms		02 Jul 2020	Level 1			000:00		
000000-008AE710	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1			000:00		
000000-00AC1569	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)		25 Mar 2021	Level 1	Fully Fit	CL	000:00		
000000-009A5193	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-004E86FD	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-004DD918	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-009A37F9	No	Yearly/20000 Kms		02 Jul 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-007AEZAB	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)		25 Mar 2021	Level 1	Fully Fit	CL	000:00		
000000-007CE980	No	OOPS 5 Yearly/150000 Kms Drain And Replen Gearbox Oil (2)		20 Mar 2022	Level 2	Non-Taskworthy	CL	000:00		
000000-004E86FB	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-003C7D6D	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-004E86FA	No	2 Yearly/40000 Kms		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-005B4811	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-00210D8A	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Non-Taskworthy	WIP	000:00		
000000-0068E2B1	No	Yearly/20000 Kms		02 Jul 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-00AC156A	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)		25 Mar 2021	Level 1	Fully Fit	CL	000:00		
000000-004DD972	No	Yearly/20000 Kms		02 Jul 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-0080AAB4	No	Yearly/20000 Kms		02 Jul 2020	Level 1	Fully Fit	CL	000:00		
000000-007CF577	No	Yearly/20000 Kms		02 Jul 2020	Level 1	Fully Fit	CL	000:00		
000000-0077CAAD	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-005CB468	No	First 1600 Kms (AR)		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-00AC1502	No	2 Yearly/40000 Kms		29 Apr 2020	Level 1	Fully Fit	CL	000:00		
000000-004E86F9	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)		25 Mar 2021	Level 2	Non-Taskworthy	CL	000:00		
000000-00A29678	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Fully Fit	CL	000:00		
000000-005CB467	No	Weekly (AR)(1)		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-007CE9C0	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-007CF576	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Fully Fit	CL	000:00		
000000-003C7D70	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-00AF87C2	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)		25 Mar 2021	Level 1	Fully Fit	CL	000:00		
000000-004F87C2	No	6 Monthly/10000 Kms		29 Apr 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-006C26BA	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)		25 Mar 2021	Level 1	Fully Fit	CL	000:00		
000000-0052C204	No	OOPS 5 Yearly/Drain/Flush And Replen Cooling System		20 Mar 2022	Level 1	Fully Fit	CL	000:00		
000000-007CE98F	No	Weekly (AR)(1)		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-0052CE9E	No	Weekly (AR)(1)		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-004E86FC	No	Weekly (AR)(1)		25 Mar 2021	Level 1	Non-Taskworthy	CL	000:00		