



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[Redacted]
[Redacted]

Our Reference:
FOI2022/09455
Date:
1 September 2022

Dear [Redacted]

I am writing about your email of 10 August 2022, requesting the following information:

'I wish to make a freedom of information request for any unrestricted information you have on MJ77AA A general service Landrover Wolf TUM'

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

- Annex A - Transfer History
- Annex B - Inspection History
- Annex C - Service History
- Annex D - Modification History
- Annex E - Fault History (redacted)

It has proved necessary to withhold some information in accordance with a qualified exemption of the FOI Act. Some of the information in the Fault History (Annex E) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As this exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, the Fault History provides details of the time taken by MOD contractors to rectify fault reports for the vehicle concerned. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of “would” rather than “would be likely to”.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner’s Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
MJ77AA	2320998939940	NB50173100	LV2A/088DUM	TRUCK UTY MED (TUM)(HS) 4X4 GS (HARD TOP) LAND ROVER 2.5LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
21/04/1998	SALLDBA67WA138857	25L05038B		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
MJ77AA	3		CA005A	JSCS ASHCHURCH		33919AA	21/04/1998	
MJ77AA	4	06/07/1998	A0419A	30 SIG REGT	40502A	2939	15/07/1998	
MJ77AA	4	02/09/2005	A3419A	251 (UK OPS) SIG SQN	7189	31	08/09/2005	W44
MJ77AA	2	04/09/2009	A3428A	10 SIG REGT RHQ	999	999	04/09/2009	MC9
MJ77AA		21/08/2017		OP TANGHAM			21/08/2017	
MJ77AA		13/09/2018		SSO			13/09/2018	
MJ77AA		13/09/2018		DSG WARMINSTER			08/10/2018	

Work Objects		Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
Serial Number:	MIJ7AA		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
NSN:	2320998939940		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
Criteria:			No	6 Monthly 6534 Insp	04 Dec 2018	Level 1	Fully Fit	CL	000:00		
Repair Level:	ALL		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1	Fully Fit	CL	000:00		
Work Object Status:	Closed		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1	Fully Fit	CL	000:00		
Mission Impact:	ALL		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1	Fully Fit	CL	000:00		
Fault State:	ALL		No	MEI (2)	17 Jan 2019	Level 2	Fully Fit	CL	000:00		
Escalate Work:	ALL		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
Work Request ID:			No	MEI (2)	17 Jan 2019	Level 2			000:00		
Assigned Work Status:	ALL		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1	Fully Fit	CL	000:00		
Working Organisation:			No	6 Monthly 6534 Insp	04 Dec 2018	Level 1	Fully Fit	CL	000:00		
Repair Section:			No	MEI (2)	17 Jan 2019	Level 2			000:00		
Maintenance Event ID	000000-0025C065	000000-00319DA7	No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-001FF479		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-00998E39		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-003ABF55		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-00634B76		No	MEI (2)	17 Jan 2019	Level 2			000:00		
	000000-0018411B		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-001C0325		No	MEI (2)	17 Jan 2019	Level 2			000:00		
	000000-004D9883		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1	Fully Fit	CL	000:00		
	000000-00998E3D		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-00998DFB		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-003ABF37		No	MEI (2)	17 Jan 2019	Level 2	Fully Fit	CL	000:00		
	000000-006C95A5		No	MEI (2)	17 Jan 2019	Level 2	Fully Fit	CL	000:00		
	000000-0058E8FF		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-00998E16		No	MEI (2)	17 Jan 2019	Level 2	Fully Fit	CL	000:00		
	000000-00665A8A		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1	Fully Fit	CL	000:00		
	000000-006CE7DE		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1	Fully Fit	CL	000:00		
	000000-00458F9D		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-001C0323		No	6 Monthly 6534 Insp	04 Dec 2018	Level 1			000:00		
	000000-0025C064		No	MEI (2)	17 Jan 2019	Level 2			000:00		
	000000-000394D3		No	MEI (2)	17 Jan 2019	Level 2			000:00		
	000000-004D5A23		No	MEI (2)	17 Jan 2019	Level 2	Fully Fit	CL	000:00		
	000000-000BDC84		No	MEI (2)	17 Jan 2019	Level 2			000:00		
	000000-000876F3		No	MEI (2)	17 Jan 2019	Level 2			000:00		
	000000-000D50C2		No	MEI (2)	17 Jan 2019	Level 2			000:00		
	000000-00005FC0		No	MEI (2)	17 Jan 2019	Level 2			000:00		

Work Objects	Serial Number:	NSN:	Criteria:	Repair Level:	Work Object Status:	Mission Impact:	Fault State:	Escalate Work:	Work Request ID:	Assigned Work Status:	Working Organisation:	Repair Section:	Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
	MJ77AA	232098939940		ALL	Closed	ALL	ALL			ALL																	
000000-008B7C34																					13 Aug 2015	N/A	Closed No Action	TUM HS GS HARD TOP			
000000-00ACFEDA																					04 Aug 2018	N/A	No Fault Found	TUM HS GS HARD TOP			000:00
000000-00A42C5A																				000000-0000452C	30 Jul 2017	N/A	Inspection	TUM HS GS HARD TOP			000:00
000000-0096D669																					11 Feb 2016	N/A	Closed No Action	TUM HS GS HARD TOP			
000000-0096D666																					11 Feb 2016	N/A	Closed No Action	TUM HS GS HARD TOP			
000000-009A7411																					01 Jun 2016	N/A	Closed No Action	TUM HS GS HARD TOP			
000000-009ADF79																					11 Jul 2016	N/A	Inspection	TUM HS GS HARD TOP			
000000-0096D64C																					11 Feb 2016	N/A	Inspection	TUM HS GS HARD TOP			
000000-00873041																					11 Feb 2015	N/A	Inspection	TUM HS GS HARD TOP			
000000-0096D662																					11 Feb 2016	N/A	Closed No Action	TUM HS GS HARD TOP			
000000-0096D65E																					11 Feb 2016	N/A	Inspection	TUM HS GS HARD TOP			
000000-0096D658																					11 Feb 2016	N/A	Failure	TUM HS GS HARD TOP			
000000-0096D656																					11 Feb 2016	N/A	Failure	TUM HS GS HARD TOP			
000000-0096D652																					11 Feb 2016	N/A	Failure	TUM HS GS HARD TOP			
000000-0096D644																					11 Feb 2016	N/A	Failure	TUM HS GS HARD TOP			
000000-0096D63D																					11 Feb 2016	N/A	Failure	TUM HS GS HARD TOP			
000000-0096D63C																					11 Feb 2016	N/A	Failure	TUM HS GS HARD TOP			
000000-0096D648																					11 Feb 2016	N/A	Inspection	TUM HS GS HARD TOP			
000000-0096D647																					11 Feb 2016	N/A	Failure	TUM HS GS HARD TOP			
000000-0096D642																					11 Feb 2016	N/A	Failure	TUM HS GS HARD TOP			
000000-0096D640																					11 Feb 2016	N/A	Failure	TUM HS GS HARD TOP			
000000-0096F06C																					19 Jan 2016	N/A	Inspection	TUM HS GS HARD TOP			
000000-008D0315																					20 Oct 2015	N/A	Inspection	TUM HS GS HARD TOP			
000000-008D0322																					20 Oct 2015	N/A	Inspection	TUM HS GS HARD TOP			
000000-0087304B																					11 Feb 2015	N/A	Closed No Action	TUM HS GS HARD TOP			
000000-00873056																					11 Feb 2015	N/A	Closed No Action	TUM HS GS HARD TOP			
000000-008B7254																					17 Aug 2015	N/A	Inspection	TUM HS GS HARD TOP			
000000-0084223A																					09 Oct 2014	Degraded	Inspection	TUM HS GS HARD TOP			
000000-00873039																					11 Feb 2015	N/A	Failure	TUM HS GS HARD TOP			
000000-00873036																					11 Feb 2015	N/A	Failure	TUM HS GS HARD TOP			
000000-0083A823																					22 Sep 2014	N/A	Failure	TUM HS GS HARD TOP			
000000-0083A821																					22 Sep 2014	N/A	Failure	TUM HS GS HARD TOP			
000000-0083A81C																					22 Sep 2014	N/A	Failure	TUM HS GS HARD TOP			
000000-0083A818																					22 Sep 2014	N/A	Failure	TUM HS GS HARD TOP			
000000-0083A80B																					24 Sep 2014	N/A	Inspection	TUM HS GS HARD TOP			
000000-0079D010																					05 Jun 2013	N/A	Failure	TUM HS GS HARD TOP			
000000-0079D009																					05 Jun 2013	N/A	Failure	TUM HS GS HARD TOP			
000000-0072DAB8																					06 Aug 2012	N/A	Failure	TUM HS GS HARD TOP			
000000-00796CE7																					24 Jun 2013	N/A	Quarantine	TUM HS GS HARD TOP			
000000-0072DAB4	000000-002DC2AD																				07 Aug 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-0072DAB2	000000-002DC2AD																				07 Aug 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-0072DAAE	000000-002DC2AD																				07 Aug 2012	N/A	Service	TUM HS GS HARD TOP			
000000-0071A438	000000-002E76A4																				06 Jun 2012	N/A	Modification	TUM HS GS HARD TOP			
000000-00770155																					05 Mar 2013	N/A	Service	TUM HS GS HARD TOP			
000000-0077015F																					05 Mar 2013	N/A	Service	TUM HS GS HARD TOP			
000000-0077016A																					05 Mar 2013	N/A	Inspection	TUM HS GS HARD TOP			
000000-00565EBB																					01 Sep 2010	N/A	Failure	TUM HS GS HARD TOP			
000000-006F25FA																					02 Feb 2012	N/A	Service	TUM HS GS HARD TOP			
000000-006F25F1																					02 Feb 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-006F25ED																					02 Feb 2012	N/A	Service	TUM HS GS HARD TOP			
000000-006F25E4																					02 Feb 2012	N/A	Service	TUM HS GS HARD TOP			
000000-006FB25B																					28 Feb 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-006FB253																					28 Feb 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-006FB250																					28 Feb 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-006FB24B																					28 Feb 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-006FB244																					28 Feb 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-006FB1F4																					28 Feb 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-006FB1DF																					28 Feb 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-006FB1DB																					28 Feb 2012	N/A	Inspection	TUM HS GS HARD TOP			
000000-006A4DB																					30 May 2011	N/A	Accident	TUM HS GS HARD TOP			
000000-006C4355																					24 Aug 2011	N/A	Service	TUM HS GS HARD TOP			
000000-006C4357																					24 Aug 2011	N/A	Service	TUM HS GS HARD TOP			
000000-006C435A																					24 Aug 2011	N/A	Service	TUM HS GS HARD TOP			
000000-006C435E																					24 Aug 2011	N/A	Modification	TUM HS GS HARD TOP			
000000-006C4360																					24 Aug 2011	N/A	Service	TUM HS GS HARD TOP			