



Ministry  
of Defence

Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]

Our Reference:  
FOI2022/10350  
Date:  
16 September 2022

Dear [REDACTED]

I am writing about your email of 5 September 2022, requesting the following information:

*I have recently purchased an ex-military Land rover defender 90*

*I have checked the released MERLIN database and the vehicle service history is not contained in the available published MERLIN extract . Therefore I submit a FOI request for the following information:*

- 1) Vehicle military service history (Units served etc, as contained in MERLIN/James)*
- 2) Any Maintenance Records / Work objects related to this vehicle.*

*Vehicle Registration: kb80aa*

*VIN number: SALLdaa67va127016*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

- Annex A - Ownership History of KB80AA
- Annex B - Fault History of KB80AA (redacted)
- Annex C – Inspection History of KB80AA
- Annex D – Modification History of KB80AA
- Annex E – Servicing History of KB80AA

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the Fault History (Annex B) of KB80AA relating to classified equipment or upgrades has been redacted in accordance with Sections 26(1) (a) and (b) (Defence) and Section 38(1) (a) and (b) (Health and Safety). Section 26 applies to information that if disclosed would or would likely; prejudice the defence of the British

Defence Equipment & Support

Islands or any colony; and/or the capability, effectiveness or security of the Armed Forces of the Crown or any forces cooperating with them. Section 38 applies to information that if disclosed would or would likely; endanger the physical or mental health of any individual; or endanger the safety of any individual.

In addition, commercially sensitive information in the Fault History of KB80AA (Annex B) relates to contractor repair times, which has been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As these exemptions are qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, releasing the information redacted under Sections 26 and 38 in the Fault History (Annex B) would divulge information that could be used to compromise the ability of UK Armed Forces to carry out operations safely. Namely, by revealing information about classified equipment and vehicle modifications which could assist adversaries to plan attacks against the vehicle and endanger the lives of personnel.

The Fault History (Annex B) provides details of the time taken by MOD contractors to rectify fault reports. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

Defence Equipment & Support

**VEHICLE DETAILS**

<b>ERM</b>	<b>NATO Stock Number</b>	<b>Asset Code</b>	<b>Contract Number</b>	<b>Description</b>	<b>Colour</b>
<b>(a)</b>	<b>(b)</b>	<b>(c)</b>	<b>(d)</b>	<b>(e)</b>	<b>(f)</b>
KB80AA	2320998939742	NB42253100	LV2A/088DUM	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

<b>Date In Service</b>	<b>Chassis Number</b>	<b>Engine No.</b>	<b>Cast</b>	<b>Cast Date</b>
<b>(g)</b>	<b>(h)</b>	<b>(i)</b>	<b>(j)</b>	<b>(k)</b>
30/10/1997	SALLDAA67VA127016	25L3293A		

**VEHICLE HISTORY**

<b>ERM</b>	<b>Key No.</b>	<b>RIV Date</b>	<b>UIN</b>	<b>Unit Title</b>	<b>RIV No.</b>	<b>RCP No.</b>	<b>RCP Date</b>	<b>Batch</b>
<b>(a)</b>	<b>(b)</b>	<b>(c)</b>	<b>(d)</b>	<b>(e)</b>	<b>(f)</b>	<b>(g)</b>	<b>(h)</b>	<b>(i)</b>
KB80AA	3	29/10/1997	CA005A	JSCS ASHCHURCH	CAPITA	29822AA	30/10/1997	
KB80AA	4	09/12/1997	A1259A	2 PWRR	35558A	552	12/12/1997	
KB80AA	4	12/07/2002	A0573A	R WELSH CO ORD CELL	151	1	29/07/2002	H/T
KB80AA	4	12/07/2006	A0510A	1 IG	999	999	12/07/2006	
KB80AA	4	19/05/2008	A0580A	2 MERC	23342	58390	31/07/2008	Z46
KB80AA	2	23/10/2012	A3703A	156 RLC	58804	44513	31/10/2012	D03
KB80AA		02/07/2019		OSVP HOLDINGS			08/07/2019	

Work Objects

Serial Number: KB80AA  
 NSN: 2320998939742

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00A321D1		Vehicle requires respray topside/underside	Closed	Fully Fit	No	Level 3		01 Jun 2017	N/A	Refurbishment	TUL HS FFR HARD TOP			000:00
000000-00A8354F		TOWING PINTLE SWIVEL LOCK PIN WILL NOT LOCK IN PINTLE SWIVELLING POSITION.	Closed	Fully Fit	No	Level 2		18 Dec 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00ABA088		IDENTIFY FRONT TRACTA HOUSING LUBRIANT COMODITY TYPE OIL/GRAPHITE GREASE.	Closed	Fully Fit	No	Level 2		05 Jun 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00ABA081		SLIGHT COOLANT LEAK @ THERMOSTAT HOUSING (OBSERVE)	Closed	Fully Fit	No	Level 2		05 Jun 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00A321C4		R/h front tyre showing signs of perishing (OBS)	Closed	Fully Fit	No	Level 2		31 May 2017	N/A	Non Specific	TUL HS FFR HARD TOP			000:00
000000-00A83E46		TOWING STROP BIRTH CERTIFICATE MISSING ITEM QUARANTINED	Closed	Fully Fit	No	Level 1		05 Jan 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00ABA08D		SPARE WHEEL TYRE INFLATION EXTENSION PIPE LEAKING	Closed	Fully Fit	No	Level 2		05 Jun 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00ADDC5		ALTERNATOR/FAN DRIVE BELTS WORN	Closed	Fully Fit	No	Level 2		17 Sep 2018	N/A	Refurbishment	TUL HS FFR HARD TOP			000:00
000000-00ADDC7A		WATER PUMP SPINDLE BEARINGS COLLAPSED	Closed	Fully Fit	No	Level 2		17 Sep 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00ABA08A		WIPER BLADES SHOWING SIGNS OF WEAR (RENEW)	Closed	Fully Fit	No	Level 1		05 Jun 2018	N/A	Inspection	TUL HS FFR HARD TOP		235LAD	000:00
000000-00ABA090		L/H/R SIDELIGHT BRIGHTER THAN R/H/R SIDELIGHT	Closed	Non-Taskworthy	No	Level 2		05 Jun 2018	N/A	Inspection	TUL HS FFR HARD TOP		235LAD	000:00
000000-00A83E52		MAP READING LIGHT FLEXI DAMAGED OPERABLE.	Closed	Fully Fit	No	Level 2		20 May 2018	N/A	Inspection	TUL HS FFR HARD TOP		235LAD	000:00
000000-008E4069		Slight leakage at both front tracta housing seals.	Closed	Fully Fit	No	Level 2		09 Dec 2015	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00ABA07D		BONNET HINGE BUSHES WORN	Closed	Fully Fit	No	Level 2		05 Jun 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00

000000-00ABD1DE	Replace spare wheel valve extension	Closed	Fully Fit	No	Level 1	14 Jun 2018	N/A	Failure	TUL HS FFR HARD TOP	000:00
000000-009972EA	Slight oil leakage evident at turbo (OBS)	Closed	Fully Fit	No	Level 2	24 May 2016	N/A	Closed No Action	TUL HS FFR HARD TOP	
000000-00AB3E58	FUEL CAP TO FILLER/FILTER NECK CHAIN DETACHED	Closed	Fully Fit	No	Level 2	20 May 2018	N/A	Closed No Action	TUL HS FFR HARD TOP	
000000-00A32175	Clutch bite very low investigate	Closed	Fully Fit	No	Level 2	01 Jun 2017	N/A	Non Specific	TUL HS FFR HARD TOP	000:00
000000-00AB3E4E	BONNET LOCK WILL NOT ENGAGE CORRECTLY INTERMITTENT	Closed	Fully Fit	No	Level 2	20 May 2018	N/A	Inspection	TUL HS FFR HARD TOP	000:00
000000-00AB9314	RENEW FRONT BRAKE PADS	Closed	Fully Fit	No	Level 2	05 Jun 2018	N/A	Inspection	TUL HS FFR HARD TOP	000:00
000000-00853AF7	Renew rear door. CARRY OUT CONFIRMATION BRAKE TEST OF DRIVER/OPERATOR FAULT REPORT FMT	Closed	Fully Fit	No	Level 2	14 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	000:00
000000-00AB27EB	1005 DATED 15/05/2018	Closed	Fully Fit	No	Level 2	15 May 2018	N/A	No Fault Found	TUL HS FFR HARD TOP	235LAD 000:00
000000-009972FE	Radiator cooling fins damaged.	Closed	Fully Fit	No	Level 2	23 May 2016	N/A	Damage	TUL HS FFR HARD TOP	235LAD 000:00
000000-00A63793	Indicator and fog lamp lens faded.	Closed	Fully Fit	No	Level 1	12 Oct 2017	N/A	Damage	TUL HS FFR HARD TOP	235LAD 000:00
000000-00895957	R/H/R x-member accident damaged.	Closed	Fully Fit	No	Level 2	13 May 2015	N/A	Damage	TUL HS FFR HARD TOP	235LAD 000:00
000000-00A4513D	Carryout Mod Inst' No 46	Closed	Fully Fit	No	Level 1	01 Aug 2017	N/A	Modification	TUL HS FFR HARD TOP	235LAD 000:00
000000-00A3167B	NATO Socket 24v wng sign damaged	Closed	Fully Fit	No	Level 2	01 Jun 2017	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00A3167F	Both rear red reflectors slight damage Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Fully Fit	No	Level 1	01 Jun 2017	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00A41525		Closed	Limited Role	No	Level 2	000000-000C 28 Jul 2017	N/A	Inspection	TUL HS FFR HARD TOP	238LAD
000000-00A2F940	2 YEARLY SERVICE	Closed	Fully Fit	No	Level 2	15 Jun 2017	N/A	Servicing	TUL HS FFR HARD TOP	238LAD
000000-00A321A6	L/H/R Half shaft/Stub axle seal leaking into hub.	Closed	Non- Taskworthy	No	Level 2	01 Jun 2017	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-009E0E5D	Renew l/h wiper blade	Closed	Fully Fit	No	Level 1	15 Nov 2016	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-009E13CB	Slight play at viscous fan unit.(OBS)	Closed	Fully Fit	No	Level 2	14 Nov 2016	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-009972DD	L/H rear damper lower rubbers showing signs of wear.	Closed	Fully Fit	No	Level 2	23 May 2016	N/A	Failure	TUL HS FFR HARD TOP	
000000-009972FB	Coolant btm hose chaffed .	Closed	Fully Fit	No	Level 2	24 May 2016	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-009972E3	R/H rear axle bump stop missing	Closed	Fully Fit	No	Level 2	24 May 2016	N/A	Failure	TUL HS FFR HARD TOP	238LAD

000000-009972D6	R/H Air vent flap inoperative	Closed	Fully Fit	No	Level 2	24 May 2016	N/A	Failure	TUL HS FFR HARD TOP	
000000-008E2CBA	Passenger door will not lock with key.	Closed	Fully Fit	No	Level 2	07 Dec 2015	N/A	Failure	TUL HS FFR HARD TOP	
000000-008E4123	Exhaust tailpipe corroded.	Closed	Fully Fit	No	Level 2	08 Dec 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-008E2D7B	Key can be removed from ignition switch whilst engine running.	Closed	Fully Fit	No	Level 2	07 Dec 2015	N/A	Failure	TUL HS FFR HARD TOP	
000000-008E2D17	Indicator switch does not stay on.L/H side.	Closed	Fully Fit	No	Level 2	07 Dec 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00895972	L/H Window lock inoperative	Closed	Fully Fit	No	Level 2	13 May 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-009436F3	Replace number 2 and 3 balljoints.	Closed	Fully Fit	No	Level 2	04 Jan 2016	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00962267	Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Fully Fit	No	Level 2	000000-000C20 Jan 2016	N/A	Inspection	TUL HS FFR HARD TOP	238LAD
000000-008959D9	1 x battery retaining screw missing	Closed	Fully Fit	No	Level 1	13 May 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00895992	L/H Heater ventcover missing	Closed	Fully Fit	No	Level 1	13 May 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00895965	R/H Brake caliper bleed nipple rounded.	Closed	Fully Fit	No	Level 2	13 May 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-0089594D	R/H Track rod end boot starting to perish (OBS)	Closed	Fully Fit	No	Level 2	13 May 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00895927	Slight oil seepage at t/box rear output flange seal.	Closed	Fully Fit	No	Level 2	12 May 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00895906	Slight play in both rear shock absorber top bushes	Closed	Fully Fit	No	Level 2	13 May 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00895982	Both btm engine mtg bolts loose.	Closed	Non-Taskworthy	No	Level 2	14 May 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-008958FE	T/Box drain plug sheared.	Closed	Non-Taskworthy	No	Level 2	04 May 2015	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00853B80	Headlamp guard clip missing.	Closed	Fully Fit	No	Level 1	14 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00853B1D	Oil leakage from engine oil cooler pipes.	Closed	Fully Fit	No	Level 2	14 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00872333	FANBELT TORN AND PULLEY WHEEL HAS COME OFF	Closed	Fully Fit	No	Level 2	10 Feb 2015	N/A	Damage	TUL HS FFR HARD TOP	238LAD
000000-00853C21	Radio terminal box cover missing.	Closed	Fully Fit	No	Level 1	14 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00853BB3	1 x negative lead FFR damaged.	Closed	Fully Fit	No	Level 2	14 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-00853865	Fuse box damaged.	Closed	Fully Fit	No	Level 2	14 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	238LAD
000000-0082FF20	R/H Door starting to corrode.	Closed	Fully Fit	No	Level 2	21 Aug 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-007CBD39	Rear door frame starting to corrode.(OBS)	Closed	Fully Fit	No	Level 2	14 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP	

000000-007CBD78	2 x Oil cooler pipes to oil filter head suspect slight oil leakage (OBS).	Closed	Fully Fit	No	Level 2	14 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-00806919	L/H and R/H door hinges worn.	Closed	Fully Fit	No	Level 2	01 May 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-00806925	1xMtg brkt broken fuse box l/h bulkhead.	Closed	Fully Fit	No	Level 2	01 May 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-00806934	Slight oil leakage at front diff pinion oil seal (OBS)	Closed	Fully Fit	No	Level 2	01 May 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-00806952	1xRadio terminal box cover missing rear compartment.	Closed	Fully Fit	No	Level 1	01 May 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-0084E273	Carryout B6534 6 mthly insp'	Closed	Non-Taskworthy	No	Level 1	03 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP
000000-00844266	Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-000C 09 Oct 2014	Degraded	Inspection	TUL HS FFR HARD TOP
000000-00817FBC	Oil pressure switch defective	Closed	Non-Taskworthy	No	Level 2	16 Jun 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-00788594	FUSE BOARD MELTING	Closed	Fully Fit	No	Level 2	12 May 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007CBD72	Slight oil leakage at rear diff pinion oil seal.(OBS)	Closed	Fully Fit	No	Level 2	14 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-0080691F	1xtool stowage brkt on bonnet snapped.	Closed	Fully Fit	No	Level 2	01 May 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-00806947	Rear door seal torn.	Closed	Fully Fit	No	Level 2	01 May 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-007CBD83	Suspect slight oil leakage from fuel pump mtg gasket (OBS).	Closed	Fully Fit	No	Level 2	14 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-008068F4	Carryout Annual MEI i.a.w JSP 930 (micat)	Closed	Non-Taskworthy	No	Level 2	01 May 2014	N/A	Inspection	TUL HS FFR HARD TOP
000000-007CBD69	1 x tool mtg brkt on bonnet snapped.	Closed	Fully Fit	No	Level 1	14 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-008068E9	Carryout yearly maintenance tasks i.a.w AESP 2320-D-128-601 Table 7 Col B	Closed	Non-Taskworthy	No	Level 2	01 May 2014	N/A	Servicing	TUL HS FFR HARD TOP
000000-0080693B	L/H draglink end worn to excess.	Closed	Non-Taskworthy	No	Level 2	01 May 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-0080693D	1xFuel return pipe leaking fuel.	Closed	Non-Taskworthy	No	Level 2	01 May 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-00806943	2KG Fire extinguisher 5 year life span expired.	Closed	Non-Taskworthy	No	Level 1	01 May 2014	N/A	Failure	TUL HS FFR HARD TOP
000000-007B86E8	Renew damaged r/h sill panels.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Damage	TUL HS FFR HARD TOP
000000-007CA228	Carryout 6 monthly MT and VM tasks i.a.w AESP 2320-D-128-601 Table 7 col A	Closed	Non-Taskworthy	No	Level 2	11 Nov 2013	N/A	Servicing	TUL HS FFR HARD TOP

000:00

000000-007CA230	Carryout B1 Drivers B6534 inspection.	Closed	Non-Taskworthy	No	Level 1	11 Nov 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-007CBD2C	Indicator switch wont lock in position l/h mode.	Closed	Fully Fit	No	Level 2	14 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007CBD2E	Re-affix positive battery lead grommet in battery box.	Closed	Fully Fit	No	Level 1	14 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007CBD35	Rear door check strap mtg detached.	Closed	Fully Fit	No	Level 2	14 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007CBD88	Replenish coolant/antifreeze mixture.	Closed	Fully Fit	No	Level 2	14 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B86FC	Renew temperature gauge.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Damage	TUL HS FFR HARD TOP
000000-007B877C	Renew weak clutch slave cylinder.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B867F	Renew windscreen washer pump.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B870C	Upper alternator 2 x rear cover bolts missing.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B876C	Renew speedometer head.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Damage	TUL HS FFR HARD TOP
000000-0078519F	RADIO BATTERY BOX COVER U/S (LOWER LOCATING PINS BROKEN)	Closed	Limited Role	No	Level 1	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-00785243	SLIGHT OIL LEAK @ ENGINE OIL FILTER.	Closed	Fully Fit	No	Level 1	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-007851C1	SLIGHT OIL LEAK @ ENGINE SUMP GASKET	Closed	Fully Fit	No	Level 2	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-00751FF8	REAR BRAKE PADS NEAR WEAR LIMIT (RENEW).	Closed	Fully Fit	No	Level 2	26 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP
000000-00785245	DUST CAPS MISSING @ TYRE VALVES.	Closed	Fully Fit	No	Level 1	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-00785253	ENGINE OIL LEVEL LOW	Closed	Fully Fit	No	Level 1	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-0078524E	POWER STEERING FLUID (OX 75) LEVEL LOW @ RESIVOIR.	Closed	Fully Fit	No	Level 1	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-0078524A	CLUTCH HYDRAULIC FLUID (OX 8) LEVEL LOW @ RESIVOIR.	Closed	Fully Fit	No	Level 1	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-00785153	EXHAUST PIPE FOULING REAR SUSPENSION 'A' FRAME.	Closed	Fully Fit	No	Level 2	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-0078514E	R/H WASHER JET AIM LOW	Closed	Fully Fit	No	Level 1	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-00785148	REAR AXLE BRAKE PIPE PLASTIC CLIPS WORN (TEMP REPAIR).	Closed	Fully Fit	No	Level 2	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-00785143	TRANSMISSION BRAKE LININGS NEAR WEAR LIMIT	Closed	Fully Fit	No	Level 2	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-00785138	REAR AXLE BRAKE DISCS SLIGHTLY PITTED	Closed	Fully Fit	No	Level 2	30 Apr 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-00751FF5	REAR DOOR KEYS MISSING (NO ACCESS).	Closed	Fully Fit	No	Level 2	26 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP



000000-0071CA82	TRACTOR SEAL L/H SEEPAGE (OBSERVE). PLEASE TIGHTEN RUBBER BUNG AT THERMOSTAT HOUSING	Closed	Fully Fit	No	Level 2	12 Jun 2012	No Effect	Inspection	TUL HS FFR HARD TOP
000000-006B1BDA		Closed	Fully Fit	No	Level 1	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-007B8713	Carryout roller brake test after fitment of 2 x rear brake calipers.	Closed	Non- Taskworthy	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B871E	Renew l/h window frame runner felt.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B8759	Renew both rear brake calipers.	Closed	Non- Taskworthy	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B8719	Steering column lower u/j loose on steering box sector shaft.	Closed	Non- Taskworthy	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B8764	Strip and repack rear hub wheel bearings.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-007B8695	Headlight warning light inop'.	Closed	Non- Taskworthy	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B869D	Steering wheel out of alignment.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B86A9	Steering column shroud adrift.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B86B6	Heater controls very stiff in operation.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B86C0	Re-write tyre pressures	Closed	Fully Fit	No	Level 1	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B86EF	Fog lamp warning lamp inop'.	Closed	Non- Taskworthy	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B8700	Tighten all propshaft bolts.	Closed	Non- Taskworthy	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B8729	Replace l/h/f tyre with spare tyre.	Closed	Fully Fit	No	Level 1	23 Sep 2013	N/A	No Fault Found	TUL HS FFR HARD TOP
000000-007B8748	Tighten all heater plug electrical connections.	Closed	Fully Fit	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-007B8778	Renew leaking clutch master cylinder.	Closed	Non- Taskworthy	No	Level 2	23 Sep 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-00798B56	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non- Taskworthy	No	Level 1	000000-000C 24 Jun 2013	N/A	Failure	TUL HS FFR HARD TOP
000000-0079BB2E	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-000C 25 Jun 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-007851CF	SLIGHT OIL LEAK @ ENGINE SUMP GASKET.	Closed	Fully Fit	No	Level 2	30 Apr 2013	N/A	Closed No Action	TUL HS FFR HARD TOP
000000-0078523D	SLIGHT OIL LEAK @ ENGINE SUMP GASKET.	Closed	Fully Fit	No	Level 2	30 Apr 2013	N/A	Closed No Action	TUL HS FFR HARD TOP


000000-00784008	CARRY OUT 24 MONTHLY TIME/USAGE MAINT (BRAKE FLUID CHANGE), IAW AESP 2320-D-128-601, TABLE 7, MAINT INTERVAL 'C', SERIAL 52.	Closed	Non-Taskworthy	No	Level 2	29 Apr 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-0071CA87	REAR DOOR BLACK OUT BLIND (FFR VARIANT ONLY). MOD INST No 33.	Closed	Fully Fit	No	Level 2	11 Jun 2012	No Effect	Inspection	TUL HS FFR HARD TOP
000000-006B1BDC	PLEASE RENEW DIESEL DECAL AT FUEL FILLER	Closed	Fully Fit	No	Level 1	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-0075BBD7	FUEL LEAK @ MAIN FUEL FILTER HOUSING (BLEED SCREW STRIPPED)	Closed	Non-Taskworthy	No	Level 2	11 Jan 2013	N/A	Damage	TUL HS FFR HARD TOP
000000-00756252	CARRY OUT 6 MONTHLY UNIT 'B' VEHICLE INSPECTION & REPORT AF B6534.	Closed	Non-Taskworthy	No	Level 1	06 Dec 2012	N/A	Inspection	TUL HS FFR HARD TOP
000000-0075624F	CARRY OUT 6 MONTHLY (10,000 Kms) SERVICE VMs TASKS, IAW AESP 2320-D-128-601, TABLE 7, MAINT INTERVAL 'A'.	Closed	Non-Taskworthy	No	Level 2	06 Dec 2012	N/A	Servicing	TUL HS FFR HARD TOP
000000-0075624A	CARRY OUT 6 MONTHLY (10,000 kms) SERVICE MT TASKS, IAW AESP 2320-D-128-601, TABLE 7, MAINT INTERVAL 'A'.	Closed	Non-Taskworthy	No	Level 1	06 Dec 2012	N/A	Servicing	TUL HS FFR HARD TOP
000000-00751FE8	R/H SIDELIGHT INOPERATIVE.	Closed	Non-Taskworthy	No	Level 2	26 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B1BD6	PLEASE RENEW REAR DOOR SEAL	Closed	Fully Fit	No	Level 1	25 Jun 2011	N/A	Damage	TUL HS FFR HARD TOP
000000-006B1BD8	PLEASE SECURE O/S/R REFLECTOR	Closed	Fully Fit	No	Level 2	25 Jun 2011	N/A	Refurbishment	TUL HS FFR HARD TOP
000000-006B1BD9	PLEASE SECURE BOTH BOLTS AT SPARE WHEEL CARRIER	Closed	Fully Fit	No	Level 1	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B1BDB	PLEASE SECURE DIESEL STRAINER TO FUEL CAP	Closed	Fully Fit	No	Level 1	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-00750294	CARRY OUT HEADLIGHT ALIGNMENT TEST, IAW WHEELED VEHICLE MEI STANDARDS MANUAL.	Closed	Non-Taskworthy	No	Level 2	20 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP
000000-00751FEE	REAR SEATBELTS NOT INSPECTED (NO ACCESS TO REAR OF VEHICLE KEYS MISSING).	Closed	Non-Taskworthy	No	Level 2	26 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP
000000-00750291	CARRY OUT SMOKE EMISSIONS TEST, IAW WHEELED VEHICLE MEI STANDARDS MANUAL.	Closed	Non-Taskworthy	No	Level 2	20 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP
000000-0075028F	CARRY OUT ROLLING ROAD BRAKE TEST (RRBT), IAW WHEELED VEHICLE MEI STANDARDS MANUAL.	Closed	Non-Taskworthy	No	Level 2	20 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP
000000-0075028E	CARRY OUT RECEIPT INSPECTION FMT 933 INSPECTION & REPORT, IAW WHEELED VEHICLE ROLE STANDARDS MANUAL.	Closed	Non-Taskworthy	No	Level 2	20 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP

000000-0075028B	CARRY OUT RECEIPT INSPECTION FMT 932W INSPECTION & REPORT, IAW WHEELED VEHICLE MEI STANDARDS MANUAL.	Closed	Non- Taskworthy	No	Level 2	20 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP
000000-007251AF	PLEASE CARRY OUT REMUS	Closed	Non- Taskworthy	No	Level 2	11 Jul 2012	N/A	Modification	TUL HS FFR HARD TOP
000000-00721CE4	PLEASE INVESTIGATE FLASHER UNIT	Closed	Non- Taskworthy	No	Level 2	29 Jun 2012	N/A	Failure	TUL HS FFR HARD TOP
000000-0071BFEC	PLEASE CARRY OUT REACTIVATION MEI IAW 2300-A-050-013	Closed	Non- Taskworthy	No	Level 2	12 Jun 2012	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18D3	PLEASE RENEW FFR DRIVE BELT	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18D1	RENEW COOLANT PIPE FROM THERMOSTAT TO HEADER TANK	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18D0	PLEASE TIGHTEN TRANSMISSION BRAKE	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18CF	PLEASE RENEW FRONT STEERING DAMPER AND BUSHES	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18CD	RENEW STEERING DROP ARM AND BALL JOINT	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18CC	PLEASE RENEW METAL BRAKE PIPES ON BOTH FRONT CALIPERS	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18CB	PLEASE RENEW FRONT BRAKE DISKS AND PADS	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18CA	PLEASE RENEW O/S/F TRACTA HOUSING OIL SEAL	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18C9	PLEASE RENEW CLUTCH FLUID (CONTAMINATION)	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B18C8	PLEASE RENEW BRAKE FLUID (CONTAMINATED)	Closed	Non- Taskworthy	No	Level 2	25 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006B1858	PLEASE RENEW PASSENGER SEAT BELTS	Closed	Non- Taskworthy	No	Level 2	24 Jun 2011	N/A	Damage	TUL HS FFR HARD TOP
000000-006B1854	PLEASE RENEW DRIVERS SEAT BELT	Closed	Non- Taskworthy	No	Level 2	24 Jun 2011	N/A	Damage	TUL HS FFR HARD TOP

000000-0060BAS5C		PLEASE RECTIFY INTERMITENT TEMPERATURE GAUGE FAULT	Closed	Fully Fit	No	Level 2	03 Jun 2011	N/A	Failure	TUL HS FFR HARD TOP
000000-0060BA50		PLEASEADJUST CLUTCH PEDAL	Closed	Fully Fit	No	Level 2	03 Jun 2011	N/A	Failure	TUL HS FFR HARD TOP
000000-0060BA46		PLEASE RECTIFY COOLANT LEAK AT TOP HOSE	Closed	Fully Fit	No	Level 2	03 Jun 2011	N/A	Failure	TUL HS FFR HARD TOP
000000-006098AC		CARRY OUT MEI IAW 2300-A-050-013	Closed	Fully Fit	No	Level 3	26 May 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-006098A9		CARRY OUT 1 YEAR VM TASKS IAW 2320-D-128-601 TABLE 7 COL B	Closed	Fully Fit	No	Level 3	26 May 2011	N/A	Servicing	TUL HS FFR HARD TOP
000000-006098A4		CARRY OUT 1 YEAR SERVICE IAW 2320-D-128-601 TABLE 7 COL B	Closed	Non-Taskworthy	No	Level 3	26 May 2011	N/A	Servicing	TUL HS FFR HARD TOP
000000-0051857E		FIT REAR DOOR CHECK STRAP	Closed	Fully Fit	No	Level 1	09 Jun 2010	N/A	Failure	TUL HS FFR HARD TOP
000000-00518576		FIT RUBBER GROMMETS TO LEFT & RIGHT SIDES OF HARDTOP	Closed	Fully Fit	No	Level 1	09 Jun 2010	N/A	Failure	TUL HS FFR HARD TOP
000000-006B0663		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-000C22 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-0060E0A4		PLEASE RENEW 1 X BATTERY	Closed	Fully Fit	No	Level 1	10 Jun 2011	N/A	Failure	TUL HS FFR HARD TOP
000000-00617215		PLEASE RENEW 1X BATTERY	Closed	Fully Fit	No	Level 1	16 Jun 2011	N/A	Failure	TUL HS FFR HARD TOP
000000-005CCDBF		REPAIR RTA DAMAGE TO R/H/F ON VEHICLE	Closed	Non-Taskworthy	No	Level 3	16 Dec 2010	N/A	Accident	TUL HS FFR HARD TOP
000000-005CCDB5		RAISE DAMAGE REPORT	Closed	Non-Taskworthy	No	Level 3	16 Dec 2010	N/A	Damage	TUL HS FFR HARD TOP
000000-005AF9E7	000000-002CF589	PLEASE INVESTIGATE NON-STARTER CARRY OUT OOP MAINTENANCE AS PER AESP 2320-D-128-601 TABLE 5 SERIAL 6	Closed	Limited Role	No	Level 2	02 Nov 2010			TUL HS FFR HARD TOP
000000-00595846	000000-002C750D	(CAMBELT)	Closed	Fully Fit	No	Level 3	28 Sep 2010			TUL HS FFR HARD TOP
000000-00566531	000000-002C750D	PLEASE INVESTIGATE NON STARTER	Closed	Limited Role	No	Level 2	02 Sep 2010			TUL HS FFR HARD TOP
000000-004CA133	000000-002C289C	REPLACE OFFSIDE REAR REFLECTOR	Closed	Fully Fit	No	Level 1	09 Feb 2010			TUL HS FFR
000000-00518577	000000-002BCDBE	FIT REAR DOOR HANDLE (MISSING)	Closed	Fully Fit	No	Level 1	09 Jun 2010			TUL HS FFR
000000-004FB697	000000-002BCDBE	FIT DASH BLANKING PLUG	Closed	Fully Fit	No	Level 1	26 Apr 2010			TUL HS FFR
000000-00533AA0		Monitor Inspection (Before Use Check carried out in accordance with relevant AESP Cat ) carried out by 24809650 Sgt Brow HQLF ECIT (NI)	Closed	Non-Taskworthy	No	Level 2	13 Jul 2010			TUL HS FFR HARD TOP
000000-00529697		932(B) MEI RE-CERTIFICATION	Closed	Fully Fit	No	Level 2	30 Jun 2010			TUL HS FFR
000000-00518590	000000-002B718A	RENEW BOTH RADIUS ARMS	Closed	Non-Taskworthy	No	Level 2	09 Jun 2010			TUL HS FFR HARD TOP

000000-0051858F	000000-002B718A	RENEW PANARD ROD	Closed	Non- Taskworthy	No	Level 2	09 Jun 2010	TUL HS FFR HARD TOP
000000-0051858C	000000-002B718A	RECTIFY TEMP. GAUGE INOP	Closed	Fully Fit	No	Level 2	09 Jun 2010	TUL HS FFR TUL HS FFR
000000-0051858B	000000-002B718A	RECTIFY MAIN BEAM LIGHT ON DASH INOP	Closed	Fully Fit	No	Level 2	09 Jun 2010	HARD TOP
000000-0051857A	000000-002B83D9	FIT REAR VIEW MIRROR (MISSING)	Closed	Fully Fit	No	Level 1	09 Jun 2010	TUL HS FFR TUL HS FFR
000000-004FB693	000000-002B7F70	RENEW 2X BATTS	Closed	Limited Role	No	Level 1	26 Apr 2010	HARD TOP
000000-0051445B	000000-002B65EA	RENEW BRAKE FLUID	Closed	Fully Fit	No	Level 2	04 Jun 2010	TUL HS FFR TUL HS FFR
000000-00512F0A	000000-002B65EA	PLEASE CARRY OUT MEI	Closed	Limited Role	No	Level 2	02 Jun 2010	HARD TOP
000000-00512F09	000000-002B65EA	PLEASE CARRY OUT 2YRLY VM'S	Closed	Limited Role	No	Level 2	02 Jun 2010	TUL HS FFR HARD TOP
000000-00512F08	000000-002B6151	PLEASE CARRY OUT 2YRLY SERVICE	Closed	Limited Role	No	Level 1	02 Jun 2010	HARD TOP
000000-001B2E95	000000-002B102F	SECURE H/BRAKE BOOT	Closed	Fully Fit	No	Level 2	12 Jun 2008	TUL HS FFR
000000-004FB2B1	000000-002B078C	PLEASE CARRY OUT 6M VM'S	Closed	Fully Fit	No	Level 2	25 Apr 2010	TUL HS FFR
000000-004FB2B0	000000-002B06CD	PLEASE CARRY OUT 6534	Closed	Fully Fit	No	Level 1	25 Apr 2010	TUL HS FFR
000000-004FB2AF	000000-002B06CD	PLEASE CARRY OUT 6M SERVICE	Closed	Fully Fit	No	Level 1	25 Apr 2010	TUL HS FFR
000000-004D039F	000000-002A84A8	adjust engine idle (too fast)	Closed	Non- Taskworthy	No	Level 2	17 Feb 2010	TUL HS FFR HARD TOP
000000-004D039D	000000-002A84A8	Rectify coolant leak around coolant pump area	Closed	Non- Taskworthy	No	Level 2	17 Feb 2010	TUL HS FFR HARD TOP
000000-00499FB0	000000-0029E19F	CARRY OUT COMPLETE VEHICLE RESPRAY	Closed	Fully Fit	No	Level 3	12 Nov 2009	TUL HS FFR HARD TOP
000000-0048F7E7	000000-0029C4A5	RECTIFY VARIOUS LIGHTS INOP	Closed	Non- Taskworthy	No	Level 3	28 Oct 2009	TUL HS FFR HARD TOP
000000-0048F7E1	000000-0029C4A5	RENEW No 1 BALL JOINT	Closed	Non- Taskworthy	No	Level 3	28 Oct 2009	TUL HS FFR HARD TOP
000000-0048F7E0	000000-0029C4A5	RENEW FRONT AND REAR PADS	Closed	Non- Taskworthy	No	Level 3	28 Oct 2009	TUL HS FFR HARD TOP
000000-0048F7DE	000000-0029C4A5	RENEW OS SEAT BELT	Closed	Non- Taskworthy	No	Level 3	28 Oct 2009	TUL HS FFR HARD TOP
000000-0048F7DA	000000-0029C4A5	RENEW ENGINE	Closed	Non- Taskworthy	No	Level 3	28 Oct 2009	TUL HS FFR HARD TOP
000000-001B2ED1	000000-0029C4A5	RENEW STEERING WHEEL	Closed	Fully Fit	No	Level 2	12 Jun 2008	TUL HS FFR
000000-001B2EBC	000000-0029C4A5	BOTH DOOR SILLS DAMAGED	Closed	Fully Fit	No	Level 2	12 Jun 2008	TUL HS FFR
000000-001B2E94	000000-0029C4A5	SECURE WIRING@R/H CHASSIS	Closed	Fully Fit	No	Level 2	12 Jun 2008	TUL HS FFR
000000-001B2E80	000000-0029C4A5	ACCIDENT DAMAGE TO R/H/R CHASSIS	Closed	Fully Fit	No	Level 2	12 Jun 2008	TUL HS FFR
000000-001B2E5A	000000-0029C4A5	RENEW DRVRS DOOR SEAL	Closed	Fully Fit	No	Level 2	12 Jun 2008	TUL HS FFR
000000-001B2E44	000000-0029C4A5	RENEW R/H HEADLIGHT UNIT COMP	Closed	Fully Fit	No	Level 2	12 Jun 2008	TUL HS FFR
000000-001B2E1C	000000-0029C4A5	RENEW FUEL FILLER NECK RUBBER	Closed	Fully Fit	No	Level 2	12 Jun 2008	TUL HS FFR

000000-00451C75	000000-00292277	CARRY OUT MEI	Closed	Non- Taskworthy	No	Level 2	07 Jul 2009	TUL HS FFR HARD TOP
000000-00451C73	000000-00292277	CARRY OUT 12 MONTH VM TASKS	Closed	Non- Taskworthy	No	Level 2	07 Jul 2009	TUL HS FFR HARD TOP
000000-00451C70	000000-00292277	CARRY OUT 12 MONTH SERVICE	Closed	Non- Taskworthy	No	Level 2	07 Jul 2009	TUL HS FFR HARD TOP
000000-001B3025	000000-0027CC0C	FIT DIFFY DVRS PASS SEAT BACK STOPS	Closed	Fully Fit	No	Level 1	12 Jun 2008	TUL HS FFR
		HEAD LIGHT MAIN BEAM AND SIDE LIGHT						TUL HS FFR
000000-001B3010	000000-0027CC0C	WARNING LIGHT BULBS BLOWN	Closed	Fully Fit	No	Level 1	12 Jun 2008	HARD TOP
000000-001B2FEB	000000-0027CC0C	DVRS DOOR LOCK STICKER DIFFY	Closed	Fully Fit	No	Level 1	12 Jun 2008	TUL HS FFR
000000-001B2FD5	000000-0027CC0C	SECURE RADIO RACKS	Closed	Fully Fit	No	Level 1	12 Jun 2008	TUL HS FFR
								TUL HS FFR
000000-001B2FAC	000000-0027CC0C	FIT DIFFY REAR DOOR INSIDE GRAB HANDLE	Closed	Fully Fit	No	Level 1	12 Jun 2008	HARD TOP
000000-001B2F9C	000000-0027CC0C	FIT DIFFY REAR VIEW MIRROR	Closed	Fully Fit	No	Level 1	12 Jun 2008	TUL HS FFR
								TUL HS FFR
000000-001B2F99	000000-0027CC0C	FIT DIFFY R/H/R SIDE MARKER REFLECTOR	Closed	Fully Fit	No	Level 1	12 Jun 2008	HARD TOP
000000-001B2F84	000000-0027CC0C	SECURE R/L/H MAST MOUNT	Closed	Fully Fit	No	Level 1	12 Jun 2008	TUL HS FFR
		PATCH PAINT F/L/H WING AND REAR TOW						TUL HS FFR
000000-001B2F34	000000-0027CC0C	EYE	Closed	Fully Fit	No	Level 1	12 Jun 2008	HARD TOP
								TUL HS FFR
000000-001B2F21	000000-0027CC0C	RENEW DRIVERS RIFLE RACK HEAD GUARD	Closed	Fully Fit	No	Level 1	12 Jun 2008	HARD TOP
000000-001B2F15	000000-0027CC0C	F/L/H TYRE APPROACHING LEGAL LIMIT	Closed	Fully Fit	No	Level 1	12 Jun 2008	TUL HS FFR
000000-001B2F12	000000-0027CC0C	[REDACTED]	Closed	Fully Fit	No	Level 1	12 Jun 2008	TUL HS FFR
000000-001B2F0E	000000-0027CC0C	SECURE BONNET PICK HEAD MOUNT	Closed	Fully Fit	No	Level 1	12 Jun 2008	TUL HS FFR
000000-001B2EF8	000000-0027CC0C	RENEW BONNET STAY BAR GROMMET	Closed	Fully Fit	No	Level 1	12 Jun 2008	TUL HS FFR
								TUL HS FFR
000000-00216045		Insufficient Data	Closed	Non- Taskworthy	No	Level 1	21 Jul 2008	HARD TOP
000000-00161707	000000-0027B77E	RECTIFY LACK OF POWER	Closed	Fully Fit	No	Level 2	01 May 2008	TUL HS FFR
000000-0003C343		Initial Usage	Closed	Fully Fit	No	Level 1	27 Nov 2006	TUL HS FFR
000000-0003C35A		Initial Maintenance	Closed	Fully Fit	No	Level 1	27 Nov 2006	TUL HS FFR



Work Objects

Serial Number: KB80AA  
 NSN: 2320998939742

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request		Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated		Repair Section
	ID	Escalate Work						Repair Time	Working Organisation	
000000-008030A4		No	MEI (2)	05 Jun 2019	Level 2	Fully Fit	CL	000:00		238LAD
000000-0074ED42		No	6 Monthly 6534 Insp	05 Dec 2018	Level 1			000:00		
000000-00175138		No	MEI (2)	05 Jun 2019	Level 2			000:00		
000000-003DAA26		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00235B46		No	6 Monthly 6534 Insp	05 Dec 2018	Level 1			000:00		
000000-001E83B9		No	MEI (2)	05 Jun 2019	Level 2			000:00		
000000-0097B839		No	MEI (2)	05 Jun 2019	Level 2	Fully Fit	CL	000:00		235LAD
000000-0050A443		No	MEI (2)	05 Jun 2019	Level 2	Fully Fit	CL	000:00		238LAD
000000-0032C8F0		No	6 Monthly 6534 Insp	05 Dec 2018	Level 1			000:00		
000000-0053408C		No	6 Monthly 6534 Insp	05 Dec 2018	Level 1	Fully Fit	CL	000:00		238LAD
000000-0098C441		No	First Parade Insp (AR)(1)		Level 1	Fully Fit	CL	000:00		235LAD
000000-00276788		No	6 Monthly 6534 Insp	05 Dec 2018	Level 1			000:00		
000000-008E2E0F		No	6 Monthly 6534 Insp	05 Dec 2018	Level 1	Fully Fit	CL	000:00		235LAD
000000-0082C8DD		No	6 Monthly 6534 Insp	05 Dec 2018	Level 1	Fully Fit	CL	000:00		238LAD



000000-003DAA25	No	6 Monthly 6534 Insp	05 Dec 2018	Level 1		000:00		
000000-0032C8F1	No	First Parade Insp (AR)(1)		Level 1		000:00		
000000-00175152	No	6 Monthly 6534 Insp	05 Dec 2018	Level 1		000:00		
000000-005E7570	No	6 Monthly 6534 Insp	05 Dec 2018	Level 1		000:00		
000000-001E83CB	No	6 Monthly 6534 Insp	05 Dec 2018	Level 1		000:00		
000000-000C5481	No	MEI (2)	05 Jun 2019	Level 2		CL	000:00	
000000-000277F2	No	MEI (2)	05 Jun 2019	Level 2		CL	000:00	
000000-00052AE4	No	MEI (2)	05 Jun 2019	Level 2		CL	000:00	
000000-008E2E01	No	First Parade Insp (AR)(1)		Level 1	Fully Fit	CL	000:00	235LAD
000000-003DAA24	No	MEI (2)	05 Jun 2019	Level 2			000:00	
000000-006A0DD7	No	MEI (2)	05 Jun 2019	Level 2	Fully Fit	CL	000:00	238LAD
000000-0026905D	No	MEI (2)	05 Jun 2019	Level 2	Non-Taskworthy	CL	000:00	
000000-00486675	No	6 Monthly 6534 Insp	05 Dec 2018	Level 1			000:00	
000000-0098C440	No	6 Monthly 6534 Insp	05 Dec 2018	Level 1	Fully Fit	CL	000:00	235LAD
000000-006A0E5A	No	6 Monthly 6534 Insp	05 Dec 2018	Level 1	Fully Fit	CL	000:00	238LAD

Work Objects

Serial Number: KB80AA  
 NSN: 2320998939742

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification / In Service Classification	Modification Type	Apply When Usage Equals	Embodied by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-00702947	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			000:00
000000-007179C6	00020	8 Metre Mast Mount Installation Kit		No	-/-	UTI				Fully Fit	CL	Level 2		235LAD	000:00
000000-00719E93	00033	Rear Door Blackout Blind (FFR Variants) Only		No	-/-	UTI				Fully Fit	CL	Level 2		235LAD	000:00
000000-00694CA7	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2		235LAD	000:00
000000-0062A283	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-00009061	00003	Heli-lift Vehicle Modification (Hard Top Only)	000000-002DD73B	No	-/	RTI				Fully Fit	CL	Level 1	2 YORKS LIGHT AID DETACHMENT	INSPECTIONS	
000000-00012F9A	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL				
000000-00019DCD	00027	Input/Output Porthole for Communication Cables, Cover Modification		No	-/	UTI				Fully Fit	CL				
000000-000153CF	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL				

000000-00010DF2	00030	Front Belt Protection Sleeves	No	1/A	UTI	Fully Fit	CL
000000-0000D36D	00035	Fitting of Emergency Hammer	No	1/A	UTI	Fully Fit	CL
000000-00024415	00025	Fitting of Spare Wheel Lifting Aid Harness	No	1/A	UTI	Fully Fit	CL
000000-0000D87A	00037	Fitting Glow Plug Timer Interface Harness	No	-/	UTI	Fully Fit	CL
000000-000249B7	00017	Introduction of Battery Retention	No	1/A	UTI	Fully Fit	CL
000000-0000AFAD	00007	TUAAM Earth Bonding Improvements	No	-/	RTI	Fully Fit	CL
000000-00015654	00001	Radio Rack Fixings Fitting Radio Frequency Radiated Hazard (RADHAZ)	No	-/	RTI	Fully Fit	CL
000000-000155B3	00012	Protection Kit	No	1/A	RTI	Fully Fit	CL
000000-0000A328	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension	No	-/	RTI	Fully Fit	CL
000000-0001EA55	00008	Input / Output Porthole for Comms / Power Cable Installation	No	-/	RTI	Fully Fit	CL

Work Objects

Serial Number: KB80AA  
 NSN: 2320998939742

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-002693B2		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	02 Jun 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-00274469		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	02 Jun 2019	Level 1	Fully Fit	CL	000:00		
000000-0082C8DA		No	Yearly/20000 Kms	05 Jun 2019	Level 1	Fully Fit	CL	000:00		238LAD
000000-00274855		No	6 Monthly/10000 Kms	05 Dec 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-006A0DD5		No	Yearly/20000 Kms	05 Jun 2019	Level 1	Fully Fit	CL	000:00		238LAD
000000-0010D057		No	6 Monthly/10000 Kms	05 Dec 2018	Level 1			000:00		
000000-003DAA2B		No	Yearly/20000 Kms	05 Jun 2019	Level 1			000:00		
000000-0098C439		No	First 1600 Kms (AR)		Level 2	Fully Fit	CL	000:00		235LAD
000000-0032C8F4		No	6 Monthly/10000 Kms	05 Dec 2018	Level 1			000:00		

		OOPS 5 Yearly Drain/Flush And							
000000-00202E09	No	Replen Cooling System	28 Mar 2020	Level 1			000:00		
000000-00175143	No	Yearly/20000 Kms	05 Jun 2019	Level 1			000:00		
000000-005E7447	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1	Fully Fit	CL	000:00		238LAD
		OOPS 2 Yearly/40000 Kms							
000000-0050A455	No	Replace Air Cleaner Element (1)	02 Jun 2019	Level 1	Fully Fit	CL	000:00		238LAD
000000-0050A3E0	No	2 Yearly/40000 Kms	02 Jun 2019	Level 1	Fully Fit	CL	000:00		238LAD
000000-003DAA2C	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1			000:00		
000000-008E2DFF	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1	Fully Fit	CL	000:00		235LAD
000000-0097B83B	No	Yearly/20000 Kms	05 Jun 2019	Level 1	Fully Fit	CL	000:00		235LAD
					Non-				
000000-0047A8CC	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1	Taskworthy	CL	000:00		
					Non-				
000000-0026905C	No	2 Yearly/40000 Kms	02 Jun 2019	Level 1	Taskworthy	CL	000:00		
000000-0074ED4F	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1	Fully Fit	CL	000:00		238LAD
000000-0082C8D9	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1	Fully Fit	CL	000:00		238LAD
000000-0009B9E6	No	Yearly/20000 Kms	05 Jun 2019	Level 1		CL	000:00		
000000-0001E233	No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00		
000000-000CEBDF	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1		CL	000:00		
000000-0009B241	No	2 Yearly/40000 Kms	02 Jun 2019	Level 1		CL	000:00		
000000-006A0E14	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1	Fully Fit	CL	000:00		238LAD
000000-00027C86	No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00		
000000-00027C84	No	Yearly/20000 Kms	05 Jun 2019	Level 1		CL	000:00		
000000-00027C85	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1		CL	000:00		
000000-000AC1BA	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1		CL	000:00		
000000-00048ED5	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1		CL	000:00		
000000-00052C42	No	2 Yearly/40000 Kms	02 Jun 2019	Level 1		CL	000:00		
000000-00052C43	No	Yearly/20000 Kms	05 Jun 2019	Level 1		CL	000:00		
000000-00052C44	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1		CL	000:00		
		OOPS 2 Yearly/20000 Kms Drain							
000000-0050A42D	No	Engine Oil And Filter Change (1)	02 Jun 2019	Level 1	Fully Fit	CL	000:00		238LAD

000000-0098C43A	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1	Fully Fit	CL	000:00	235LAD
000000-00534133	No	Yearly/20000 Kms	05 Jun 2019	Level 1	Fully Fit	CL	000:00	238LAD
		OOPS 5 Yearly/155000 Kms Drain						
000000-00202E5B	No	And Replen Gearbox Oil (2)	13 Oct 2020	Level 2			000:00	
000000-0017515E	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1			000:00	
					Non-			
000000-00274856	No	Yearly/20000 Kms	05 Jun 2019	Level 1	Taskworthy	CL	000:00	
		OOPS 2 Yearly/40000 Kms						
000000-00803091	No	Replace Air Cleaner Element (1)	02 Jun 2019	Level 1	Fully Fit	CL	000:00	238LAD
000000-00534136	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1	Fully Fit	CL	000:00	238LAD
		OOPS 6 Yearly/120000 Kms						
000000-0070C4CC	No	Camshaft Timing Belt (2)	13 Sep 2022	Level 2	Fully Fit	CL	000:00	238LAD
		OOPS 2 Yearly/40000 Kms						
000000-00202E0D	No	Replace Air Cleaner Element (1)	02 Jun 2019	Level 1			000:00	
		OOPS 5 Yearly Drain/Flush And						
000000-0050A3AF	No	Replen Cooling System	28 Mar 2020	Level 1	Fully Fit	CL	000:00	238LAD
		OOPS 5 Yearly/155000 Kms Drain						
000000-005C641F	No	And Replen Gearbox Oil (2)	13 Oct 2020	Level 2	Fully Fit	CL	000:00	238LAD
000000-00235B38	No	6 Monthly/10000 Kms	05 Dec 2018	Level 1			000:00	
		OOPS 6 Yearly/120000 Kms						
000000-00202E08	No	Camshaft Timing Belt (2)	13 Sep 2022	Level 2			000:00	
		OOPS 2 Yearly/20000 Kms Drain						
000000-00202E11	No	Engine Oil And Filter Change (1)	02 Jun 2019	Level 1			000:00	
000000-007BA5BB	No	2 Yearly/40000 Kms	02 Jun 2019	Level 1	Fully Fit	CL	000:00	238LAD
		OOPS 2 Yearly/20000 Kms Drain						
000000-0080309F	No	Engine Oil And Filter Change (1)	02 Jun 2019	Level 1	Fully Fit	CL	000:00	238LAD

