



Ministry  
of Defence

[REDACTED]  
Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]

Our Reference:  
FOI2022/11127  
Date:  
07 October 2022

Dear [REDACTED]

I am writing about your email of 20 September 2022, requesting the following information:

*I have recently purchased an ex military defender 110. I have checked the release MERLIN data base and the vehicle service history is not contained in the available published MERLIN extract (the vehicle has recently just come out of service).*

*Therefore I submit a FOI request for the following information;*

- 1) Vehicle military service history (units served etc as contained in the MERLIN/James).*
- 2) Any maintenance records / work objects related to this vehicle.*

*Vehicle registration: KN 40 AA*

*VIN number: SALLDBA67VA116039*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History (redacted)
- Annex E – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault History (Annex B) and Modification History (Annex D) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

**Defence Equipment & Support**

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,





DE&S Policy Secretariat

**VEHICLE DETAILS**

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
KN40AA	2320999086912	NB50203190	LV2A/088DUM	TRUCK UTY MED (HS) 4X4 FFR HARD TOP LAND ROVER 2.5LTR TURBO DSL W/EEGR BOWMAN FF LAS	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
06/05/1997	SALLDBA67VA116039	N/A		

**VEHICLE HISTORY**

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KN40AA	3	05/05/1997	CA005A	JSCS ASHCHURCH	CAPITA	26235AA	06/05/1997	
KN40AA	4	27/06/1997	A0211A	16 REGT RA	31666A	363	15/07/1997	
KN40AA	3	03/02/2005	CA005A	JSCS ASHCHURCH	380	66201AA	03/02/2005	
KN40AA	4	22/06/2005	A5826A	2 ITB	72339A	2488	06/07/2005	
KN40AA	4	14/05/2007	A4359A	ITC QM DEPT	774	1931	14/05/2007	H/T
KN40AA	4	07/05/2010	A5738A	WAR SPT UNIT & GAR	199445	51881	13/05/2010	A91
KN40AA	2	23/08/2010	A0989A	HQ SUPPORT WEAPONS SCHOOL	199445	51881	23/08/2010	B09
KN40AA		21/03/2017		AFV FLEET			21/03/2017	
KN40AA		21/03/2017		TRANSPORT FLEET			21/03/2017	
KN40AA		20/08/2020		CMC HQ			20/08/2020	
KN40AA		03/11/2020		OSVP CVS HOLDINGS			05/11/2020	

Work Objects

Serial Number: KN40AA  
 NSN: 2320999086912

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Fault ID	Work Request ID	Work Fault Description	Work Status	Work Fault State	Escalate Work	Repair Level	Batch Fault Group ID	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00C06945	000000-00352EFF	PT Reclamation Task	Closed	Fully Fit	No	Level 2		22 Feb 2021	N/A	Reclamation	TUM HS FFR HARD TOP	14 REGT RA, WKSP	RSAPRECLA MATION	000:00
000000-00AC6353		Replace Tuff Lift	Closed	Fully Fit	No	Level 1		09 Jul 2018	N/A	Refurbishment	TUM HS FFR HARD TOP			000:00
000000-00ACA21E	000000-00337288	FIT UMS	Closed	Limited Role	No	Level 2		18 Jul 2018	N/A	Servicing	TUM HS FFR HARD TOP			000:00
000000-00AC6D3F		DRIVE BELTS SQUEALING	Closed	Fully Fit	No	Level 1		10 Jul 2018	N/A	Inspection	TUM HS FFR			
000000-00AC6C7B		AFB 6534 UNIT INSPECTION	Closed	Limited Role	No	Level 1		10 Jul 2018	N/A	Inspection	TUM HS FFR			000:00
000000-00AC6576		O/S WINDOW FELTS WORN	Closed	Fully Fit	No	Level 1		09 Jul 2018	N/A	Inspection	TUM HS FFR			
000000-00AC656B		BRAKE PEDAL RUBBER WORN	Closed	Fully Fit	No	Level 1		09 Jul 2018	N/A	Inspection	TUM HS FFR			
000000-00AC6554		WIPER BLADES U/S	Closed	Fully Fit	No	Level 1		09 Jul 2018	N/A	Inspection	TUM HS FFR			
000000-00AC6538		NUMBER PLATE LIGHT NOT WORKING	Closed	Fully Fit	No	Level 1		09 Jul 2018	N/A	Inspection	TUM HS FFR			
000000-00AC6529		CONVOY LIGHT SEIZED	Closed	Fully Fit	No	Level 1		09 Jul 2018	N/A	Inspection	TUM HS FFR			
000000-00AB6400		Re Furbish Bonnet Bks & Straps	Closed	Fully Fit	No	Level 1		25 May 2018	N/A	Refurbishment	TUM HS FFR			000:00
000000-00AAF6D2		Re certifie Veh Fire Extn	Closed	Fully Fit	No	Level 1		09 May 2018	N/A	Inspection	TUM HS FFR			000:00
000000-00A790EA		RECOVER VEHICLE FROM SALISBURY PLAIN	Closed	Fully Fit	No	Level 2		22 Nov 2017	N/A	Failure	TUM HS FFR HARD TOP			000:00
000000-00A8C686		SU00344773 TO WARMINSTER DSG	Closed	Fully Fit	No	Level 1		29 Jan 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A69162	000000-0032FD40	Investigate Grumble on Clutch pedal operation'Obs'	Closed	Fully Fit	No	Level 2		26 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A8B7F1		DIAGNOSTIC CHECKS ON TRANSMISSION, FREE OFF DIFF LOCK MECHANISM	Closed	Fully Fit	No	Level 2		25 Jan 2018	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00A8B7F6		DIAGNOSTIC CHECK FRONT LIGHTS, ROAD TEST, FINAL OUT INSP	Closed	Fully Fit	No	Level 2		25 Jan 2018	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00A83608	000000-0032FC95	Please investigate & rectify head gasket	Closed	Fully Fit	No	Level 2		03 Jan 2018	N/A	Failure	TUM HS FFR HARD TOP			000:00

000000-00A8357B	000000-0032FC8F	Please recover from Warminster to Lulworth BDSG	Closed	Non-Taskworthy	No	Level 2	03 Jan 2018	N/A	Failure	TUM HS FFR HARD TOP BOWMAN	000:00
000000-00A60A85 000000-00A564EC	000000-0032CDD8	Investigate re-occurring Battery Drain ( Sept 17) Refit Vehicle Batteries	Closed Closed	Fully Fit Fully Fit	No No	Level 2 Level 1	09 Oct 2017 14 Sep 2017	N/A N/A	Inspection Inspection	TUM HS FFR HARD TOP BOWMAN	000:00
000000-00A48423	000000-0032AD96	Clutch fluid leak slave cyl	Closed	Fully Fit	No	Level 2	11 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP BOWMAN	
000000-00A4841D	000000-0032AD96	Fuse box in Engine Bay broken	Closed	Fully Fit	No	Level 2	11 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP BOWMAN	
000000-00A48411	000000-0032AD96	Rear Engine oil leak	Closed	Fully Fit	No	Level 2	11 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP BOWMAN	
000000-00A3796B	000000-0032AD96	Confirm charging system correct Battery Drain	Closed	Fully Fit	No	Level 2	05 Jul 2017	N/A	Inspection	TUM HS FFR HARD TOP BOWMAN	
000000-00A43D47	000000-0032AD96	Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Fully Fit	No	Level 2	000000-00004573 31 Jul 2017	N/A	Inspection	TUM HS FFR HARD TOP BOWMAN	
000000-00A48987		AESP-2320-D-128-601 7TH ED MAY 17 TABLE 7 COL A 6 M	Closed	Limited Role	No	Level 1	14 Aug 2017	N/A	Servicing	TUM HS FFR HARD TOP	
000000-00A488B7		AFB 6534 UNIT INSPECTION	Closed	Limited Role	No	Level 1	14 Aug 2017	N/A	Inspection	TUM HS FFR	
000000-00A483DF		Wiper blades replaced	Closed	Fully Fit	No	Level 1	11 Aug 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A483E4		Seat grip handles missing	Closed	Fully Fit	No	Level 1	11 Aug 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A483EA		N/S & Rear Doors earth strap replaced	Closed	Fully Fit	No	Level 1	11 Aug 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A483F3		Bonnet bump stops & stay grommet replaced	Closed	Fully Fit	No	Level 1	11 Aug 2017	N/A	Inspection	HARD TOP	000:00
000000-00A483FC		Tyre decalls fitted	Closed	Fully Fit	No	Level 1	11 Aug 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A48401		Reg plate light insecure	Closed	Fully Fit	No	Level 1	11 Aug 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A48404		N/S DOOR PANNEL INSECURE	Closed	Fully Fit	No	Level 1	11 Aug 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A4840C		N/S Door riv nut replaced	Closed	Fully Fit	No	Level 1	11 Aug 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A4841A		Sed bowl seals replaced	Closed	Fully Fit	No	Level 1	11 Aug 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A34064		MOD 46 Wheel Nut Indicator	Closed	Fully Fit	No	Level 1	27 Jun 2017	N/A	Modification	TUM HS FFR	000:00
000000-00A378DC		Replaced Vehicle Batteries	Closed	Fully Fit	No	Level 1	05 Jul 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A3791A		Battery terminal cover /bolt & nut replaced	Closed	Fully Fit	No	Level 1	05 Jul 2017	N/A	Inspection	HARD TOP	000:00
000000-00A20051		Rear Seat Mount required	Closed	Fully Fit	No	Level 1	08 May 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A1F9C0		Replaced Veh Batteries	Closed	Fully Fit	No	Level 1	08 May 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A10F7A		O/S/F Hub leak	Closed	Fully Fit	No	Level 2	24 Mar 2017	N/A	Inspection	TUM HS FFR	000:00
000000-00A10F78	000000-003250CE	Power steering leak	Closed	Fully Fit	No	Level 2	24 Mar 2017	N/A	Inspection	TUM HS FFR HARD TOP BOWMAN	
000000-00A10F74	000000-003250CE	Oil leak Engine	Closed	Fully Fit	No	Level 2	24 Mar 2017	N/A	Inspection	TUM HS FFR HARD TOP BOWMAN	

										TUM HS FFR		
										HARD TOP		
000000-009E1413	000000-003250CE	INV SEAT BELT RETAINERS MISSING	Closed	Fully Fit	No	Level 2	15 Nov 2016	N/A	Non Specific	BOWMAN		
000000-00A0F35D		Replace Fuel Cap	Closed	Fully Fit	No	Level 1	21 Mar 2017	N/A	Inspection	TUM HS FFR	Armccen	000:00
000000-00A0F837		Emergency Hammer not fitted	Closed	Fully Fit	No	Level 1	22 Mar 2017	N/A	Inspection	TUM HS FFR	Armccen	000:00
000000-00A0F849		Vehicle Insecure	Closed	Fully Fit	No	Level 1	22 Mar 2017	N/A	Inspection	TUM HS FFR	Armccen	000:00
000000-00A0F850		Replace Number plates	Closed	Fully Fit	No	Level 1	22 Mar 2017	N/A	Inspection	TUM HS FFR		000:00
000000-00A1B551		Replace Fuel ID Plate	Closed	Fully Fit	No	Level 1	25 Apr 2017	N/A	Inspection	TUM HS FFR		000:00
000000-00A1B55B		Drv's seat tilt lever cover missing	Closed	Fully Fit	No	Level 1	25 Apr 2017	N/A	Inspection	TUM HS FFR		000:00
000000-00A1B55E		Pas side window felt replaced	Closed	Fully Fit	No	Level 1	25 Apr 2017	N/A	Inspection	TUM HS FFR		000:00
000000-00A0F82B		Replace Fire Extinguisher	Closed	Fully Fit	No	Level 1	22 Mar 2017	N/A	Inspection	TUM HS FFR	Armccen	000:00
000000-00A0F358		Certifie Vehicle Jack	Closed	Fully Fit	No	Level 1	21 Mar 2017	N/A	Inspection	TUM HS FFR		000:00
		RENEW HEATER AIR INTAKE GRILLE ON TOP OF								TUM HS FFR		
000000-00A01214		L/H WING	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Damage	HARD TOP		
000000-00A01210		RNEW O/S STOWAGE LOCKER DOOR	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Damage	TUM HS FFR		
		RENEW WIPER MOTOR. RENEW ENGINE								TUM HS FFR		
000000-00A0129A		BREATHER PIPES	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Failure	HARD TOP		
000000-009FF070		RENEW L/H SIDE DASH FINISHER	Closed	Fully Fit	No	Level 2	08 Feb 2017	N/A	Modification	TUM HS FFR		
		REMOVE TACHO AND REFIT ORIGINAL SPEEDO								TUM HS FFR		
000000-009E407F		CABLE	Closed	Fully Fit	No	Level 2	21 Nov 2016	N/A	Modification	HARD TOP		
000000-00A0120D		RENEW BOTH BATTERIES	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Failure	BOWMAN		
		RENEW N/S TRACK ROD END / RNEW N/S								TUM HS FFR		
000000-00A0120A		LOWER SHOCK ABSORBER BUSH	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Damage	HARD TOP		
		RENEW REAR ANTI-ROLL BAR LINKS								TUM HS FFR		
000000-00A01207		ARMS/BUSHES	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Damage	HARD TOP		
000000-00A01202		RENEW RADIATOR ASSY	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Damage	TUM HS FFR		
										TUM HS FFR		
000000-009DF8F6		CLUTCH SLIPPING	Closed	Taskworthy	No	Level 2	09 Nov 2016	N/A	Failure	HARD TOP		
										TUM HS FFR		
000000-009E141C		CARRY OUT FIBRE GLASS REPAIRS TO ROOF	Closed	Fully Fit	No	Level 2	15 Nov 2016	N/A	Damage	HARD TOP		
000000-009DE151		CARRY OUT SIX MONTHLY INSP	Closed	Fully Fit	No	Level 2	09 Nov 2016	N/A	Inspection	TUM HS FFR		
		CARRY OUT 6 MONTHLY 6534 INSPECTION								TUM HS FFR		
000000-009DDD79		IAW JSP 930	Closed	Fully Fit	No	Level 2	09 Nov 2016	N/A	Inspection	HARD TOP		
000000-009949A4		RENEW DRIVERS SEAT	Closed	Fully Fit	No	Level 2	18 May 2016	N/A	Damage	TUM HS FFR		
000000-00990CBE		RENEW REAR DOOR & SEALS	Closed	Fully Fit	No	Level 2	10 May 2016	N/A	Damage	TUM HS FFR		
		INV FAN BELT HAS COME OFF - POSS COOLANT								TUM HS FFR		
000000-00980D7A		PUMP FAILURE	Closed	Taskworthy	No	Level 2	23 Mar 2016	N/A	Failure	HARD TOP		
										TUM HS FFR		
										HARD TOP		
000000-0095E4ED		Check No2 ball joint torque tightness as per								TUM HS FFR		
000000-008DD902		safety notice LE SNvE 00063	Closed	Fully Fit	No	Level 2	14 Jan 2016	N/A	Inspection	BOWMAN		
		REFIT HEATER MOTOR AFTER DRS REPAIR	Closed	Fully Fit	No	Level 2	24 Nov 2015	N/A	Failure	TUM HS FFR		
		CARRY OUT 6 MONTHLY 6534 INSPECTION								TUM HS FFR		
000000-008DBEFA		IAW JSP 930	Closed	Taskworthy	No	Level 2	19 Nov 2015	N/A	Inspection	HARD TOP		
										TUM HS FFR		
000000-008DD867		REMOVE HEATER MOTOR FOR DRS REPAIR	Closed	Taskworthy	No	Level 2	24 Nov 2015	N/A	Failure	HARD TOP		
000000-00897370		RENEW REAR AXLE "A" FRAME BALLOINT	Closed	Fully Fit	No	Level 2	20 May 2015	N/A	Failure	TUM HS FFR		
000000-0089736A		REPAIR GLOW PLUG WIRING	Closed	Fully Fit	No	Level 2	20 May 2015	N/A	Damage	TUM HS FFR		
										TUM HS FFR		
000000-0088EA4D		RENEW VEH BATTERIES	Closed	Taskworthy	No	Level 2	08 Apr 2015	N/A	Failure	HARD TOP		

000000-0088742D	RENEW CLUTCH SLAVE CYLINDER	Closed	Non-Taskworthy	No	Level 2	17 Feb 2015	N/A	Failure	TUM HS FFR HARD TOP TUM HS FFR	
000000-00843D38	Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	HARD TOP BOWMAN TUM HS FFR
000000-0079B325	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	HARD TOP BOWMAN TUM HS FFR
000000-0079831D	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	HARD TOP BOWMAN TUM HS FFR
000000-006AF28D	Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-000002CE	22 Jun 2011	N/A	Inspection	HARD TOP BOWMAN
000000-001CBD62	Initial Usage	Closed	Fully Fit	No	Level 1		06 May 1997			TUM HS FFR
000000-001CBD63	Initial Maintenance	Closed	Fully Fit	No	Level 1		06 May 1997			TUM HS FFR



## Work Objects

Serial Number: KN40AA  
 NSN: 2320999086912

### Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated		Working Organisation	Repair Section
								Repair Time			
000000-008E7073	0032FD40	No	MEI (2)	11 Jan 2019	Level 2	Fully Fit Non-	CL	000:00			
000000-0053A431		No	MEI (2)	11 Jan 2019	Level 2	Taskworthy	CL	000:00			
000000-0037E0F6		No	6 Monthly 6534 Insp	08 Jan 2019	Level 1			000:00			
000000-0053A7D1		No	6 Monthly 6534 Insp	08 Jan 2019	Level 1			000:00			
000000-0079C01E		No	MEI (2)	11 Jan 2019	Level 2	Fully Fit	CL	000:00			
000000-003F7D75		No	6 Monthly 6534 Insp	08 Jan 2019	Level 1			000:00			
000000-003F7D6A		No	MEI (2)	11 Jan 2019	Level 2			000:00			
000000-0048D390		No	6 Monthly 6534 Insp	08 Jan 2019	Level 1			000:00			
000000-0037E0C7		No	MEI (2)	11 Jan 2019	Level 2			000:00			
000000-0068ECCC		No	MEI (2)	11 Jan 2019	Level 2	Fully Fit	CL	000:00			
000000-0085F045		No	6 Monthly 6534 Insp	08 Jan 2019	Level 1			000:00			
000000-0069620A		No	6 Monthly 6534 Insp	08 Jan 2019	Level 1			000:00			



000000-009ABCCE	No	6 Monthly 6534 Insp	08 Jan 2019	Level 1			000:00
000000-007AC5BC	No	6 Monthly 6534 Insp	08 Jan 2019	Level 1	Fully Fit	CL	000:00
000000-008FFC14	000000- 0032FD40 No	6 Monthly 6534 Insp	08 Jan 2019	Level 1	Fully Fit	CL	000:00
000000-005EE4D3	No	6 Monthly 6534 Insp	08 Jan 2019	Level 1			000:00
000000-0074C1F9	No	6 Monthly 6534 Insp	08 Jan 2019	Level 1			000:00

Work Objects

Serial Number: KN40AA  
 NSN: 2320999086912

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work		Production	Modification Type	Apply	Embodiment	Usage Counter	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
			Request ID	Escalate Work	In Service Classification		When Usage Equals								
000000-0068BA45	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 1		Armcen TPT	
000000-006881A0	00014	Fitting of Showerproof Dash Cover		No	-/-	RTI				Fully Fit					
000000-0068583F	00003	Heli-lift Vehicle Modification (Hard Top Only) Fitting of Front Windscreen and Side and Rear Window Protection Screens		No	-/	RTI				Fully Fit					
000000-006456FC	00018			No	-/-	UTI				Fully Fit					
000000-006456FB	00004	Fitting Emergency Lights, Siren and Harness TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-0063FCEB	00039	Fitting of a New Import/Export Box Mount Bracket		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-006881A6	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-006881A7	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0063FCD8	00025	Fitting of Spare Wheel Lifting Aid Harness Spare Wheel Adaptor Plates; Left and Right Hand Installation		No	1/A	UTI				Non-	CL	Level 2			
000000-006881A4	00029			No	-/-	UTI				Fully Fit	CL	Level 2			
000000-006881A5	00033	Rear Door Blackout Blind (FFR Variants) Only		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-0068818F	00020	8 Metre Mast Mount Installation Kit		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-0063FCE0	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0063FCCF	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0063FCBB	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			

000000-0063FCC7	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension	No	-/	RTI	Limited Role	CL	Level 2
000000-0063FCB3	00017	Introduction of Battery Retention Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit	No	1/A	UTI	Non-Taskworthy	CL	Level 2
000000-0068818E	00012		No	1/A	RTI	Non-Taskworthy	CL	Level 2

Work Objects

Serial Number: KN40AA  
 NSN: 2320999086912

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated		Working Organisation	Repair Section
								Repair Time			
			OOPS 2 Yearly/20000 Kms Drain								
000000-0079BFFA		No	Engine Oil And Filter Change (1)	17 Feb 2019	Level 1	Fully Fit	CL	000:00			
000000-00746FD3		No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1	Fully Fit	CL	000:00			
	000000-0032FD40	No	Yearly/20000 Kms	24 Jan 2019	Level 1	Fully Fit	CL	000:00			
			OOPS 2 Yearly/40000 Kms			Non-					
000000-0053A43E		No	Replace Air Cleaner Element (1)	17 Feb 2019	Level 1	Taskworthy	CL	000:00			
000000-0048D37F		No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1			000:00			
			OOPS 5 Yearly/155000 Kms Drain								
000000-003F7D3C		No	And Replen Gearbox Oil (2)	22 May 2019	Level 2			000:00			

000000-0037DEFB	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	17 Feb 2019	Level 1			000:00	
000000-0053A449	No	2 Yearly/40000 Kms	17 Feb 2019	Level 1	Non- Taskworthy	CL	000:00	
000000-0037DEF9	No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1			000:00	
000000-009ABDEF	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	09 Jul 2023	Level 1			000:00	
000000-0037DEFC	No	Weekly (AR)(1)		Level 1			000:00	
000000-005EA845	No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1	Non- Taskworthy	CL	000:00	
000000-007AC644	No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1	Fully Fit	CL	000:00	
000000-0048D380	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	11 Nov 2020	Level 2			000:00	
000000-0053A714	No	Yearly/20000 Kms	24 Jan 2019	Level 1	Non- Taskworthy	CL	000:00	
000000-0037DFF9	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	22 May 2019	Level 2			000:00	
000000-0037DF3C	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	11 Nov 2020	Level 2			000:00	
000000-0079BFFB	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Feb 2019	Level 1	Fully Fit	CL	000:00	
000000-008FFC1C	000000- 0032FD40	No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1	Fully Fit	CL	000:00
000000-006961E3	No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1	Non- Taskworthy	CL	000:00	
000000-0037DFFA	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	09 Jul 2023	Level 1			000:00	
000000-0037E0B8	No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1			000:00	
000000-007AC645	No	Yearly/20000 Kms	24 Jan 2019	Level 1	Fully Fit	CL	000:00	
000000-0037DEFA	No	Yearly/20000 Kms	24 Jan 2019	Level 1			000:00	

000000-0085ED74	000000-0032AD96	No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1	Fully Fit	CL	000:00
						Non-		
000000-0053A715		No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1	Taskworthy	CL	000:00
000000-003F7D3D		No	6 Monthly/10000 Kms (1)	26 Jul 2018	Level 1			000:00
000000-0037DEF7		No	2 Yearly/40000 Kms	17 Feb 2019	Level 1			000:00
000000-003F7D3B		No	Yearly/20000 Kms	24 Jan 2019	Level 1			000:00
			OOPS 2 Yearly/20000 Kms Drain			Non-		
000000-0053A454		No	Engine Oil And Filter Change (1)	17 Feb 2019	Level 1	Taskworthy	CL	000:00
000000-0079C014		No	2 Yearly/40000 Kms	17 Feb 2019	Level 1	Fully Fit	CL	000:00
			OOPS 2 Yearly/40000 Kms					
000000-0037DEF8		No	Replace Air Cleaner Element (1)	17 Feb 2019	Level 1			000:00
						Non-		
000000-0068EC98		No	Yearly/20000 Kms	24 Jan 2019	Level 1	Taskworthy	CL	000:00