



Ministry
of Defence

[REDACTED]
Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]

Our Reference:
FOI2022/10427
Date:
07 October 2022

Dear [REDACTED],

I am writing about your email of 10 August 2022, requesting the following information:

I have recently purchased an ex military defender 110. I have checked the release MERLIN data base and the vehicle service history is not contained in the available published MERLIN extract (the vehicle has recently just come out of service).

Therefore I submit a FOI request for the following information;

- 1) Vehicle military service history (units served etc as contained in the MERLIN/James).*
- 2) Any maintenance records / work objects related to this vehicle.*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

Following your subsequent email of 12 September 2022 in which you provided a photograph of the vehicle chassis plate confirming the vehicle registration as MV25AA and the chassis number as SALLDBA68VA130886 another search for the information has been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

- Annex A – Owner History
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History (redacted)
- Annex E – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault and Modification Histories (Annexes B and D) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43

Defence Equipment & Support

concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

[Redacted signature]

[Redacted name]

DE&S Policy Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
MV25AA	2320999086919	NB50208170	LV2A/088DUM	TRUCK UTY MED (HS) 4X4 FFR HARD TOP LHD LAND ROVER 2.5LTR TURBO DSL W/EEGR BOWMAN SH	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
06/04/1998	SALLDBA68VA130886	25LO3454A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
MV25AA	3		CA005A	JSCS ASHCHURCH		33542AA	06/04/1998	
MV25AA	4	10/07/1998	A3719A	6 TLR RLC	40678A	228	07/09/1998	
MV25AA	4	18/01/2000	A9046A	UK CSS BN (CSAT)	184	2916	26/01/2000	A95
MV25AA	4	16/07/2000	A3719A	6 TLR RLC	1513	157	20/09/2000	B31
MV25AA	3	05/07/2004	CA005A	JSCS ASHCHURCH	999999	61799AA	05/07/2004	
MV25AA	2	29/03/2005	A0135A	QM (T) DEPT ARMOUR CENTRE	71064A	86592	28/04/2005	
MV25AA		18/12/2019		CMC HQ			18/12/2019	
MV25AA		03/11/2020		OSVP CVS HOLDINGS			05/11/2020	

Work Objects

Serial Number: MV25AA
 NSN: 2320998939968

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00C069A5	000000-00352F0D	PT Reclamation Task	Closed	Fully Fit	No	Level 2		22-Feb-21	N/A	Reclamation	TUM HS FFR HARD TOP	14 REGT RA, WKSP	RSAPRECL AMATION	000:00
000000-00B20FFF		SNve 377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 2	000000-0000697A	29-Mar-19	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AE7AC1		Replaced Reg Light Unit	Closed	Fully Fit	No	Level 1		11-Oct-18	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AC4029		BAAN - 72 - 0001 - INITIAL INSPECTION/ ASSESSMENT	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AB8D69	000000-0033586B	Bottom Belt Idler pulley bearing worn	Closed	Limited Role	No	Level 2		05-Jun-18	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AC401E		BAAN - 372 - 0002 - INSP FINAL OUT	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AC4018		BAAN - 372 - 0008 - INSP VEH RECOVERY/ COUPLING/ STARTING	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AC400E		BAAN - 372 - 0004 - INSP INT/ EXT ROAD TEST	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AC4005		BAAN - 372 - 0003 - INSP SHOP FLOOR INSP/ASSESSMENT	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AC3FFC		BAAN - 372 - 0007 - INSP ROADWORTHY INSPECTION	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AC3FF1		BAAN - 372 - 0015 - INSP COMPRESSION TEST	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AC3FE3		BAAN - 300 - 0470 - RENEW ALT DRIVE BELT	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AC3FDE		BAAN - 300 - 0424 - RENEW WATERPUMP DRIVE BELT TENSION PULLEY	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AC3FD9		BAAN - 300 - 0425 - C&A WATERPUMP DRIVE BELTS	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AC3FD1		BAAN - 300 - 0426 - RENEW WATERPUMP DRIVE BELTS	Closed	Fully Fit	No	Level 2		04-Jul-18	N/A	Inspection	TUM HS FFR HARD TOP			

000000-00AC3FCD	BAAN - 300 - 0470 - RENEW FFR BELTS ADJ ASSY	Closed	Fully Fit	No	Level 2	04-Jul-18 N/A	Inspection	TUM HS FFR HARD TOP	
000000-00AC3FBA	BAAN - 300 - 0224 - C&A ALT DRIVE BELTS RADIO	Closed	Fully Fit	No	Level 2	04-Jul-18 N/A	Inspection	TUM HS FFR HARD TOP	
000000-00AC3FAF	BAAN - 300 - 0225 - R&R ALT DRIVE BELTS RADIO	Closed	Fully Fit	No	Level 2	04-Jul-18 N/A	Inspection	TUM HS FFR HARD TOP	
000000-00AC3F99	BAAN - 300 - 0226 - RENEW ALT DRIVE BELTS RADIO	Closed	Fully Fit	No	Level 2	04-Jul-18 N/A	Inspection	TUM HS FFR HARD TOP	
000000-00AC3F6E	BAAN - 300 - 0219 - C&A ALT DRIVE BELTS	Closed	Fully Fit	No	Level 2	04-Jul-18 N/A	Inspection	TUM HS FFR HARD TOP	
000000-00AC3F4D	BAAN - 300 - 0222 - R&R ALT DRIVE BELTS VEH	Closed	Fully Fit	No	Level 2	04-Jul-18 N/A	Inspection	TUM HS FFR HARD TOP	
000000-00AC3F48	BAAN - 300 - 0223 - RENEW ALT DRIVE BELTS VEH	Closed	Fully Fit	No	Level 2	04-Jul-18 N/A	Inspection	TUM HS FFR HARD TOP	
000000-00AB786F	ADVISORY VEHICLE JACK EXPIRES 25/05/2018 (OBSERVATION SLIGHT WEEP ON VALVE)	Closed	Fully Fit	No	Level 1	25-Apr-18 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AA729A	000000-0033388E Transfer Box Oil leak	Closed	Limited Role	No	Level 2	17-Apr-18 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AA6FDD	Replaced Both Drive Belts	Closed	Fully Fit	No	Level 1	16-Apr-18 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AA72BE	Re Furbish Bonnet Tool Furniture	Closed	Fully Fit	No	Level 1	17-Apr-18 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AA729F	Replaced Sediment bowl seals	Closed	Fully Fit	No	Level 1	17-Apr-18 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AA729B	Wiper blades replaced	Closed	Fully Fit	No	Level 1	17-Apr-18 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AA7299	Tow pintle R clip missing	Closed	Fully Fit	No	Level 1	17-Apr-18 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AA7298	Clutch pedal rubber missing	Closed	Fully Fit	No	Level 1	17-Apr-18 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A67104	000000-0032D6D1 Oil leak between G/Box & T/Box	Closed	Fully Fit	No	Level 2	23-Oct-17 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A670D2	000000-0032D6D1 Top Radiator coolant hose leaking	Closed	Fully Fit	No	Level 2	23-Oct-17 N/A	Inspection	TUM HS FFR HARD TOP	
000000-00A670D8	Fog light SW replaced	Closed	Fully Fit	No	Level 1	23-Oct-17 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A670F5	Map LIGHT SW replaced	Closed	Fully Fit	No	Level 1	23-Oct-17 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A436C0	Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Fully Fit	No	Level 2	000000-00004560 31-Jul-17 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A341E0	MOD 46 Wheel Nut Indicator	Closed	Fully Fit	No	Level 1	27-Jun-17 N/A	Modification	TUM HS FFR HARD TOP	000:00
000000-00A27568	Re-certifie Veh Jack	Closed	Fully Fit	No	Level 1	25-May-17 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A23CEE	Fit Rear Seat Belt	Closed	Fully Fit	No	Level 1	17-May-17 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A26C9D	Replaced Emeg Hammer Bracket	Closed	Fully Fit	No	Level 1	24-May-17 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A1BCEE	000000-0032625A Power steering pump leak	Closed	Fully Fit	No	Level 2	26-Apr-17 N/A	Inspection	TUM HS FFR HARD TOP	

000000-00A18CE1	000000-0032625A	Steering Pump pulley not aligned	Closed	Fully Fit	No	Level 2	26-Apr-17 N/A	Inspection	TUM HS FFR HARD TOP		
000000-00A214EC		RNW PANHARD ROD BUSHES	Closed	Limited Role	No	Level 2	10-May-17 N/A	Inspection	TUM HS FFR HARD TOP		
000000-00A18B45		Replace Both Drive Belts	Closed	Fully Fit	No	Level 1	26-Apr-17 N/A	Inspection	TUM HS FFR HARD TOP	Armccen TPT	000:00
000000-00A18F82		Replace Service Filters	Closed	Fully Fit	No	Level 1	18-Apr-17 N/A	Servicing	TUM HS FFR HARD TOP	Armccen TPT	000:00
000000-00A18CDD		Bonnet Bump stops deteriorated	Closed	Fully Fit	No	Level 1	26-Apr-17 N/A	Inspection	TUM HS FFR HARD TOP		000:00
000000-00A1BCE8		Drivers seat insecure	Closed	Fully Fit	No	Level 1	26-Apr-17 N/A	Inspection	TUM HS FFR HARD TOP		000:00
000000-00A1BCEA		Rear reg light dim	Closed	Fully Fit	No	Level 1	26-Apr-17 N/A	Inspection	TUM HS FFR HARD TOP		000:00
000000-00A1BCF4		Wiper blades replaced	Closed	Fully Fit	No	Level 1	26-Apr-17 N/A	Inspection	TUM HS FFR HARD TOP		000:00
000000-00A17460		O/S Headlight not working	Closed	Fully Fit	No	Level 1	11-Apr-17 N/A	Inspection	TUM HS FFR HARD TOP		000:00
000000-00A17465		Number plate light not working	Closed	Fully Fit	No	Level 1	11-Apr-17 N/A	Inspection	TUM HS FFR HARD TOP		000:00
000000-00A0CF51	000000-003249FF	FUEL TANK SPLIT	Closed	Fully Fit	No	Level 2	14-Mar-17 N/A	Failure	TUM HS FFR HARD TOP		
000000-00A0CF52	000000-003249FE	RECOVER VEHICLE FROM BOV MT FUEL TANK SPLIT	Closed	Limited Role	No	Level 2	14-Mar-17 N/A	Failure	TUM HS FFR HARD TOP		
000000-009DA316	000000-0031F034	Oil Feed Pipe to Turbo Leaking	Closed	Fully Fit	No	Level 2	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP		
000000-009DA31D	000000-0031F034	Steering Box Oil Leak	Closed	Fully Fit	No	Level 2	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP		
000000-009DA325	000000-0031F034	Oil cooler pipe leaking	Closed	Fully Fit	No	Level 2	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP		
000000-009DA32C	000000-0031F034	Coolant hose chaffed Top of engine(marked with yellow crayon)	Closed	Fully Fit	No	Level 2	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP		
000000-009DA30E	000000-0031F034	N/S/F Seat Back damaged	Closed	Fully Fit	No	Level 2	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP		
000000-009DEADD		R+R RAD & INTERCOOLER ASSY, INTERCOOLER PIPE L/H WING FOR ACCESS	Closed	Fully Fit	No	Level 2	10-Nov-16 N/A	Servicing	TUM HS FFR HARD TOP		
000000-009DEAE6		RENEW ALT DRIVE BELTS VEH + RADIO	Closed	Fully Fit	No	Level 2	10-Nov-16 N/A	Servicing	TUM HS FFR HARD TOP		
000000-009DEAF1		RENEW ENGINE BREATHER PIPE, CYCLONE BREATHER + AIRDUCT TUBE	Closed	Fully Fit	No	Level 2	10-Nov-16 N/A	Servicing	TUM HS FFR HARD TOP		
000000-009DEAF9		DIAG/FUNC CHECKS, ROAD TEST, FINAL OUT INSP	Closed	Fully Fit	No	Level 2	10-Nov-16 N/A	Servicing	TUM HS FFR HARD TOP		
000000-009DEB01		RENEW EXHAUST MANIFOLD DOWNPIPE NUTS	Closed	Fully Fit	No	Level 2	10-Nov-16 N/A	Servicing	TUM HS FFR HARD TOP		
000000-009DEAD7		INITIAL ASSESMENT OIL LEAKS	Closed	Fully Fit	No	Level 2	10-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP		
000000-009DA34F		Tyre pressures corrected	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP		000:00
000000-009DA356		Hatch Seals Replaced	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP		000:00
000000-009DA35B		Fuel Plate ID Replaced	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP		000:00

000000-009DA362		Air Filter Dump Valve replaced	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-009DA368		Rocker Gasket replaced	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-009DA372		Oil Breather leaking	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-009DA37C		Power steering oil topped up	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-009DA383		Batt Terminal cover replaced	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-009DA38B		Door Trim Fasteners missing	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-009DA399		Vehicle Jack Re-Certified	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-009DA3A0		Fire Extinguisher Re-Certified	Closed	Fully Fit	No	Level 1	02-Nov-16 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-0098FEAB		Fuel Cap not secure	Closed	Fully Fit	No	Level 1	09-May-16 N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-0098FEBF	000000-00316D3B	Front Diff Oil Contaminated Inner seals U/S	Closed	Fully Fit	No	Level 2	09-May-16 N/A	Inspection	TUM HS FFR HARD TOP	[REDACTED]
000000-0098FECF	000000-00316D3B	Both Front Shock Abs bushes Top&Bottom worn	Closed	Fully Fit	No	Level 2	09-May-16 N/A	Inspection	TUM HS FFR HARD TOP	
000000-0098FEDA	000000-00316D3B	Steering Box Lower seal leak	Closed	Fully Fit	No	Level 2	09-May-16 N/A	Inspection	TUM HS FFR HARD TOP	
000000-0098FEF9	000000-00316D3B	O/S/F Flexible Brake Pipe protector split rubs on spring	Closed	Fully Fit	No	Level 2	09-May-16 N/A	Inspection	TUM HS FFR HARD TOP	
000000-0098FF00	000000-00316D3B	Storage Bin straps mounts corroded	Closed	Fully Fit	No	Level 2	09-May-16 N/A	Inspection	TUM HS FFR HARD TOP	
000000-009941BD		RENEW HAND HELD FIRE EXTINGUISHER	Closed	Fully Fit	No	Level 2	12-May-16 N/A	Inspection	TUM HS FFR HARD TOP	
000000-009941C0		DIAG LACK OF ENGINE POWER INCL EXCESS SMOKE	Closed	Fully Fit	No	Level 2	12-May-16 N/A	Inspection	TUM HS FFR HARD TOP	
000000-009941BA		FUNC/TECH CHECKS ROAD TEST, FINAL OUT INSP	Closed	Fully Fit	No	Level 2	12-May-16 N/A	Inspection	TUM HS FFR HARD TOP	
000000-0098FEF0	000000-00316D3B	Rear Lower Link bush worn	Closed	Limited Role	No	Level 2	09-May-16 N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0098FEEA	000000-00316D3B	Rear Upper Link Balljoint play	Closed	Limited Role	No	Level 2	09-May-16 N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0098FEE6	000000-00316D3B	Panhard Rod bushes worn	Closed	Limited Role	No	Level 2	09-May-16 N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0098FEDF	000000-00316D3B	Both Front Radius Arm bushes worn	Closed	Limited Role	No	Level 2	09-May-16 N/A	Action	TUM HS FFR HARD TOP	
000000-00961438		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Limited Role	No	Level 1	000000-00003206 19-Jan-16 N/A	Inspection	TUM HS FFR HARD TOP	[REDACTED]
000000-008D6B2D		Vehicle Jack not working	Closed	Limited Role	No	Level 1	09-Nov-15 N/A	Inspection	TUM HS FFR HARD TOP	[REDACTED]
000000-008E974D		Confirm No Nylock Nuts Fitted to Ball Joints	Closed	Fully Fit	No	Level 1	15-Dec-15 N/A	Inspection	TUM HS FFR HARD TOP	[REDACTED]
000000-008D6CBC	000000-0030ED0D	OIL LEAK FROM POWER STEERING PIPE	Closed	Fully Fit	No	Level 2	09-Nov-15 N/A	Failure	TUM HS FFR HARD TOP	[REDACTED]
000000-008D6CB7	000000-0030ED0D	TX BOX OIL LEAK	Closed	Fully Fit	No	Level 2	09-Nov-15 N/A	Failure	TUM HS FFR HARD TOP	[REDACTED]

Armccn
TPT

000000-008E6BA9		D+R COOLANT SYSTEM, RENEW, TIGHTEN JUBILEE CLIPS, PRESSURE TEST	Closed	Fully Fit	No	Level 2	16-Dec-15	N/A	Inspection	TUM HS FFR HARD TOP
000000-008D6CC1	000000-0030ED0D	AFB 6534 UNIT INSPECTION	Closed	Limited Role	No	Level 1	09-Nov-15	N/A	Inspection	TUM HS FFR HARD TOP
000000-008B4655	000000-0030A5C3	INVESTIGATE NON CHARGING OF BATTERIES	Closed	Fully Fit	No	Level 2	05-Aug-15	N/A	Failure	TUM HS FFR HARD TOP
000000-0089645B	000000-00303F20	BROKEN FLANGE BOLTS RETAP ALL THREADS	Closed	Fully Fit	No	Level 2	15-Apr-15	N/A	Inspection	TUM HS FFR HARD TOP
000000-00896455	000000-00303F20	UNSEIZE REAR CALIPER TOP BOLTS	Closed	Fully Fit	No	Level 2	15-Apr-15	N/A	Inspection	TUM HS FFR HARD TOP
000000-0089644F	000000-00303F20	RETORQUE WHEEL NUTS	Closed	Fully Fit	No	Level 2	15-Apr-15	N/A	Inspection	TUM HS FFR HARD TOP
000000-0087F9E3	000000-00303F20	TRACK ROD RUBS ON BRACKET	Closed	Fully Fit	No	Level 2	12-Mar-15	N/A	Failure	TUM HS FFR HARD TOP
000000-0087F9E0	000000-00303F20	COOLANT LEAK FROM PUMP AREA	Closed	Fully Fit	No	Level 2	12-Mar-15	N/A	Failure	TUM HS FFR HARD TOP
000000-0084D907		AFB 6534 UNIT INSPECTION	Closed	Limited Role	No	Level 1	30-Oct-14	N/A	Inspection	TUM HS FFR HARD TOP
000000-0084D8A9	000000-002FE6EF	INNER FRONT HUB SEAL LEAKING	Closed	Fully Fit	No	Level 2	30-Oct-14	N/A	Failure	TUM HS FFR HARD TOP
000000-0084D8B0	000000-002FE6EF	CHECK DROP ARM BALL JOINT	Closed	Fully Fit	No	Level 2	30-Oct-14	N/A	Failure	TUM HS FFR HARD TOP
000000-0084D8B6	000000-002FE6EF	CHECK DRAG LINK BALL JOINT	Closed	Fully Fit	No	Level 2	30-Oct-14	N/A	Failure	TUM HS FFR HARD TOP
000000-0084D8BB	000000-002FE6EF	TRACK ROD BALL JOINT RUBBER	Closed	Fully Fit	No	Level 2	30-Oct-14	N/A	Failure	TUM HS FFR HARD TOP
000000-0084D8C0	000000-002FE6EF	PAN HARD ROD BUSHES	Closed	Fully Fit	No	Level 2	30-Oct-14	N/A	Failure	TUM HS FFR HARD TOP
000000-0084D8C3	000000-002FE6EF	CHECK REAR UPPER LINK BALL JOINT	Closed	Fully Fit	No	Level 2	30-Oct-14	N/A	Failure	TUM HS FFR HARD TOP
000000-00843158		Towing Pintle Assembly	Closed	Limited Role	No	Level 1	09-Oct-14	Degraded	Inspection	TUM HS FFR HARD TOP
000000-00813AFD		COMMS 857	Closed	Fully Fit	No	Level 1	04-Jun-14	N/A	Inspection	TUM HS FFR HARD TOP
000000-00802AA8	000000-002F5DD8	REAR EXHAUST PIPE	Closed	Fully Fit	No	Level 2	17-Apr-14	N/A	Failure	TUM HS FFR HARD TOP
000000-007F60E7	000000-002F451A	INSPECT AND REPAIR ACCIDENT DAMAGE	Closed	Limited Role	No	Level 2	14-Mar-14	N/A	Accident	TUM HS FFR HARD TOP
000000-007DEB23	000000-002F1156	CHECK ALL PULLY BEARINGS	Closed	Limited Role	No	Level 2	20-Jan-14	N/A	Failure	TUM HS FFR HARD TOP
000000-0079AA0B		Inspect tyres for damage	Closed	Fully Fit	No	Level 1	25-Jun-13	N/A	Inspection	TUM HS FFR HARD TOP
000000-007C30EE		COMMS 857	Closed	Fully Fit	No	Level 1	22-Oct-13	N/A	Inspection	TUM HS FFR HARD TOP
000000-007979B5		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	24-Jun-13	N/A	Quarantine	TUM HS FFR HARD TOP
000000-00782513		VIDS-247/LS GPS CABLE AWAY FOR REPAIR	Closed	Fully Fit	No	Level 4	24-Apr-13	N/A	Damage	TUM HS FFR HARD TOP
000000-007824FA		COMMS 857	Closed	Limited Role	No	Level 1	24-Apr-13	N/A	Failure	TUM HS FFR HARD TOP

000000-0076CCCF	AESP-2320-D-128-601 6TH EDITION MAY 10 TABLE 7 COL C 24 Monthly	Closed	Non- Taskworthy	No	Level 2	25-Feb-13 N/A	Servicing	TUM HS FFR HARD TOP
000000-0076CCEB	FMT 932W & FMT 933 MEI	Closed	Non- Taskworthy	No	Level 2	25-Feb-13 N/A	Inspection	TUM HS FFR HARD TOP
000000-0076CCCA	AESP-2320-D-128-601 6TH EDITION MAY 10 TABLE 7 COL C 24 Monthly	Closed	Non- Taskworthy	No	Level 1	25-Feb-13 N/A	Servicing	TUM HS FFR HARD TOP
000000-0076CCDD	TABLE 5 SER 1 Engine Oil	Closed	Non- Taskworthy	No	Level 1	25-Feb-13 N/A	Servicing	TUM HS FFR HARD TOP
000000-0076CCE6	TABLE 5 SER 4 Air Cleaner	Closed	Non- Taskworthy	No	Level 1	25-Feb-13 N/A	Servicing	TUM HS FFR HARD TOP
000000-0076CCE9	AFB 6534 UNIT INSPECTION	Closed	Non- Taskworthy	No	Level 1	25-Feb-13 N/A	Inspection	TUM HS FFR HARD TOP
000000-0073E139	COMMS 857	Closed	Fully Fit	No	Level 1	01-Oct-12 N/A	Inspection	TUM HS FFR HARD TOP
000000-007323D5	AESP-2320-D-128-601 6TH EDITION MAY 10 TABLE 7 COL A 6 Monthly	Closed	Non- Taskworthy	No	Level 2	28-Aug-12 N/A	Servicing	TUM HS FFR HARD TOP
000000-0073340A	N/S/F HUB LEAK	Closed	Non- Taskworthy	No	Level 2	30-Aug-12 N/A	Failure	TUM HS FFR HARD TOP
000000-007323D4	AESP-2320-D-128-601 6TH EDITION MAY 10 TABLE 7 COL A 6 Monthly	Closed	Non- Taskworthy	No	Level 1	28-Aug-12 N/A	Servicing	TUM HS FFR HARD TOP
000000-007323D6	AFB 6534 UNIT INSPECTION	Closed	Non- Taskworthy	No	Level 1	28-Aug-12 N/A	Inspection	TUM HS FFR HARD TOP
000000-0070ADA4	WATER PUMP LEAK	Closed	Non- Taskworthy	No	Level 2	18-Apr-12 N/A	Failure	TUM HS FFR HARD TOP
000000-0070ADAA	NOISEY ALTANATOR	Closed	Non- Taskworthy	No	Level 2	18-Apr-12 N/A	Failure	TUM HS FFR HARD TOP
000000-006EBE1D	comms	Closed	Limited Role	No	Level 4	16-Jan-12 N/A	Failure	TUM HS FFR HARD TOP
000000-006FD80E	COMMS 857	Closed	Fully Fit	No	Level 1	06-Mar-12 N/A	Inspection	TUM HS FFR HARD TOP
000000-006FB649	AESP-2320-D-128-601 6TH EDITION MAY 10 TABLE 7 COL B 12 Monthly	Closed	Non- Taskworthy	No	Level 2	29-Feb-12 N/A	Servicing	TUM HS FFR HARD TOP
000000-006FB64E	FMT 932W & FMT 933 MEI	Closed	Non- Taskworthy	No	Level 2	29-Feb-12 N/A	Inspection	TUM HS FFR HARD TOP
000000-006FB645	AESP-2320-D-128-601 6TH EDITION MAY 10 TABLE 7 COL B 12 Monthly	Closed	Non- Taskworthy	No	Level 1	29-Feb-12 N/A	Servicing	TUM HS FFR HARD TOP
000000-006FB651	AFB 6534 UNIT INSPECTION	Closed	Non- Taskworthy	No	Level 1	29-Feb-12 N/A	Inspection	TUM HS FFR HARD TOP
000000-006CB90F	COMMS 857	Closed	Fully Fit	No	Level 1	20-Sep-11 N/A	Inspection	TUM HS FFR HARD TOP
000000-006C9978	PAN HARD ROD BUSH	Closed	Non- Taskworthy	No	Level 2	14-Sep-11 N/A	Failure	TUM HS FFR HARD TOP
000000-006C9064	AESP-2320-D-128-601 6TH EDITION MAY 10 TABLE 7 COL A 6 Monthly	Closed	Non- Taskworthy	No	Level 2	13-Sep-11 N/A	Servicing	TUM HS FFR HARD TOP
000000-005E6411	STEERING DAMPER BUSHES	Closed	Fully Fit	No	Level 2	11-Mar-11 N/A	Failure	TUM HS FFR HARD TOP
000000-005E4779	TABLE 5 SER 6 Cam Belt	Closed	Fully Fit	No	Level 2	08-Mar-11 N/A	Servicing	TUM HS FFR HARD TOP
000000-005E4774	TABLE 5 SER 3 Cooling System	Closed	Fully Fit	No	Level 2	08-Mar-11 N/A	Servicing	TUM HS FFR HARD TOP
000000-005E4772	AFG 932(B) MEI	Closed	Fully Fit	No	Level 2	08-Mar-11 N/A	Servicing	TUM HS FFR HARD TOP

000000-005E476E	AESP-2320-D-128-601 5 ED JUN 08 TABLE 7 COL C 24 Monthly	Closed	Fully Fit	No	Level 2	08-Mar-11	N/A	Servicing	TUM HS FFR HARD TOP	
000000-005E6418	PANHARD ROD BUSHES	Closed	Fully Fit	No	Level 2	11-Mar-11	N/A	Failure	TUM HS FFR HARD TOP	
000000-005ECCE4	ALL LEVEL 2 FAULTS COMPLETED AS PER LEVEL 2 WORK SHEETS	Closed	Fully Fit	No	Level 1	30-Mar-11	N/A	No Fault Found	TUM HS FFR HARD TOP	
000000-006C9063	AESP-2320-D-128-601 6TH EDITION MAY 10 TABLE 7 COL A 6 Monthly	Closed	Non-Taskworthy	No	Level 1	13-Sep-11	N/A	Servicing	TUM HS FFR HARD TOP	
000000-006C9066	AFB 6534 UNIT INSPECTION	Closed	Taskworthy	No	Level 1	13-Sep-11	N/A	Inspection	TUM HS FFR HARD TOP	
000000-006AF6E2	Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-000002D1	22-Jun-11	N/A	Inspection	TUM HS FFR HARD TOP
000000-005ED47A	COMMS 857	Closed	Fully Fit	No	Level 1	31-Mar-11	N/A	Failure	TUM HS FFR HARD TOP	
000000-005E476F	AFB 6534 UNIT INSPECTION	Closed	Fully Fit	No	Level 1	08-Mar-11	N/A	Inspection	TUM HS FFR HARD TOP	
000000-005E476D	AESP-2320-D-128-601 5 ED JUN 08 TABLE 7 COL C 24 Monthly	Closed	Fully Fit	No	Level 1	08-Mar-11	N/A	Servicing	TUM HS FFR HARD TOP	
000000-005E123B	Repair leaking water pump	Closed	Fully Fit	No	Level 2	25-Feb-11	N/A	Failure	TUM HS FFR HARD TOP	
000000-005BAF1E	000000-002D085B COMMS 857	Closed	Fully Fit	No	Level 1	16-Nov-10			TUM HS FFR HARD TOP	
000000-005B64AF	AFB 6534 UNIT INSPECTION	Closed	Taskworthy	No	Level 1	10-Nov-10			TUM HS FFR HARD TOP	
000000-005B64AD	000000-002CF55D AESP-2320-D-128-601 5 ED JUN 08 TABLE 7 COL A Monthly	Closed	Non-Taskworthy	No	Level 2	10-Nov-10			TUM HS FFR HARD TOP	
000000-005B64AB	000000-002CF55A AESP-2320-D-128-601 5 ED JUN 08 TABLE 7 COL A Monthly	Closed	Non-Taskworthy	No	Level 1	10-Nov-10			TUM HS FFR HARD TOP	
000000-004E2F57	000000-002ABC02 REMUS UPGRADE LV 2	Closed	Fully Fit	No	Level 2	15-Mar-10			TUM HS FFR HARD TOP	
000000-0052DF9C	ALTERNATOR BELT BROKEN. FMT1005 RAISED. BOV MT0027.	Closed	Fully Fit	No	Level 1	24-Jun-10			TUM HS FFR HARD TOP	
000000-0050A4C4	000000-002B4090 COMMS 857	Closed	Fully Fit	No	Level 1	19-May-10			TUM HS FFR HARD TOP	
000000-004F119C	000000-002AE982 AFG 932(B) MEI LV 2 TASK	Closed	Fully Fit	No	Level 2	07-Apr-10			TUM HS FFR HARD TOP	
000000-004F1187	000000-002AE982 AESP-2320-D-128-601 5 ED JUN 08 TABLE 7 COL B LV 2 TASKS	Closed	Fully Fit	No	Level 2	07-Apr-10			TUM HS FFR HARD TOP	
000000-004F119E	000000-002AE97F AFB 6534 UNIT INSPECTION LV 1 TASK	Closed	Fully Fit	No	Level 1	07-Apr-10			TUM HS FFR HARD TOP	
000000-004F1170	000000-002AE97F AESP-2320-D-128-601 5 ED JUN 08 TABLE 7 COL B LV 1 TASKS	Closed	Fully Fit	No	Level 1	07-Apr-10			TUM HS FFR HARD TOP	
000000-004845A1	000000-0029A01F AESP-2320-D-128-601 5 ED JUN 08 TABLE 7 COL A LV 2 TASKS	Closed	Non-Taskworthy	No	Level 2	07-Oct-09			TUM HS FFR HARD TOP	
000000-004845A5	000000-0029A01B AFB 6534 UNIT INSPECTION	Closed	Non-Taskworthy	No	Level 1	07-Oct-09			TUM HS FFR HARD TOP	
000000-004845A0	000000-0029A01B AESP-2320-D-128-601 5 ED JUN 08 TABLE 7 COL A LV 1 TASKS	Closed	Non-Taskworthy	No	Level 1	07-Oct-09			TUM HS FFR HARD TOP	
000000-00487F9E	000000-0029AD75 comms 857	Closed	Limited Role	No	Level 1	14-Oct-09			TUM HS FFR HARD TOP	

000000-0021573C	000000-0027E82E	VHF RADIO INOP	Closed	Limited Role	No	Level 4	18-Jul-08	TUM HS FFR HARD TOP
000000-00125D36		Initial Usage	Closed	Fully Fit	No	Level 1	03-Apr-08	TUM HS FFR HARD TOP
000000-00125DBF		Initial Maintenance	Closed	Fully Fit	No	Level 1	03-Apr-08	TUM HS FFR HARD TOP

Work Objects

Serial Number: MV25AA
 NSN: 2320998939968

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-00150AF9		No	MEI (2)	25-Apr-19	Level 2			000:00		
	000000-									
000000-005365F8	00303F20	No	6 Monthly 6534 Insp	12-Apr-19	Level 1	Fully Fit	CL	000:00		
000000-00487799		No	6 Monthly 6534 Insp	12-Apr-19	Level 1			000:00		
000000-001C1908		No	MEI (2)	25-Apr-19	Level 2			000:00		
	000000-									
000000-007EF2C4	0032625A	No	MEI (2)	25-Apr-19	Level 2	Fully Fit	CL	000:00		
000000-0016C199		No	6 Monthly 6534 Insp	12-Apr-19	Level 1			000:00		
000000-00A0DF1A		No	6 Monthly 6534 Insp	12-Apr-19	Level 1	Limited Role	CL	000:00		
000000-002704E6		No	MEI (2)	25-Apr-19	Level 2			000:00		
	000000-					Non-				
000000-003D02E3	002F5DD8	No	MEI (2)	25-Apr-19	Level 2	Taskworthy	CL	000:00		
000000-001C1909		No	6 Monthly 6534 Insp	12-Apr-19	Level 1			000:00		
000000-0073E617		No	6 Monthly 6534 Insp	12-Apr-19	Level 1	Limited Role	CL	000:00		


000000-0095267E		No	6 Monthly 6534 Insp	12-Apr-19 Level 1	Limited Role	CL	000:00
000000-002704E8		No	6 Monthly 6534 Insp	12-Apr-19 Level 1			000:00
000000-0068F086		No	6 Monthly 6534 Insp	12-Apr-19 Level 1			000:00
000000-000F2D40		No	MEI (2)	25-Apr-19 Level 2		CL	000:00
	000000-						
000000-0068E4B0	00316D3B	No	MEI (2)	25-Apr-19 Level 2	Fully Fit	CL	000:00
000000-008A0D4D		No	6 Monthly 6534 Insp	12-Apr-19 Level 1	Limited Role	CL	000:00
					Non-		
000000-003D02E4		No	6 Monthly 6534 Insp	12-Apr-19 Level 1	Taskworthy	CL	000:00
000000-005DE340		No	6 Monthly 6534 Insp	12-Apr-19 Level 1			000:00
000000-001860D3		No	6 Monthly 6534 Insp	12-Apr-19 Level 1			000:00
000000-0010AA21		No	MEI (2)	25-Apr-19 Level 2		CW	000:00
	000000-						
000000-004F93C7	00303F20	No	MEI (2)	25-Apr-19 Level 2	Fully Fit	CL	000:00
000000-00217806		No	6 Monthly 6534 Insp	12-Apr-19 Level 1			000:00
000000-007EF299		No	6 Monthly 6534 Insp	12-Apr-19 Level 1	Limited Role	CL	000:00
000000-00306B81		No	6 Monthly 6534 Insp	12-Apr-19 Level 1	Fully Fit	CL	000:00
	000000-						
000000-00952648	0033388E	No	MEI (2)	25-Apr-19 Level 2	Limited Role	CL	000:00
000000-00010E3B		No	MEI (2)	25-Apr-19 Level 2		CL	000:00
000000-0009A8C6		No	MEI (2)	25-Apr-19 Level 2		CL	000:00

Work Objects

Serial Number: MV25AA
 NSN: 2320998939968

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification / In Service Classification	Modification Type	Apply When Usage Equals	Embodiment by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0068BADC	46	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS Installation of 12/24 volt sockets.(Installation Instruction 8 (2320-D-128-411 Installations Instructions and 8 Index))	000000-0032D6D1	No	1/A	Mod				Non-Taskworthy	CL	Level 2			
000000-0068860A		Spare Wheel Adaptor Plates; Left and Right Hand Installation		No	3/A	STI				Fully Fit	CL	Level 1		Armccen	
000000-00687DF6	29	Fitting Glow Plug Timer Interface		No	-/-	UTI				Fully Fit	CL	Level 2		TPT	
000000-00687F7B	37	Harness		No	-/-	UTI				Fully Fit	CL	Level 2		Armccen	
000000-00687DF4	12	Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Non-Taskworthy	CL	Level 2		TPT	
000000-00687DF7	33	Rear Door Blackout Blind (FFR Variants) Only		No	-/-	UTI				Fully Fit	CL	Level 2		Armccen	
000000-00687F7A	35	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2		TPT	
000000-00686CDD	14	Fitting of Showerproof Dash Cover		No	-/-	RTI				Fully Fit					
000000-006434FB	6	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/-	RTI				Limited Role	CL	Level 1		Armccen	
000000-00643509	19	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 1		TPT	
000000-00643508	17	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 1		Armccen	
000000-0064350A	24	Fitting of Trailer Breakaway Attachment Plate		No	-/-	UTI				Fully Fit	CL	Level 1		TPT	
000000-0064350B	30	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 1		Armccen	

000000-006434FC	Fitting of Spare Wheel Lifting Aid 25 Harness	No	1/A	UTI	Non- Taskworthy	CL	Level 1	Armccen TPT	
000000-00643381	Fitting of Front Windscreen and Side 18 and Rear Window Protection Screens	No	-/-	UTI	Fully Fit				
000000-00643380	Fitting Emergency Lights, Siren and 4 Harness	No	-/-	RTI	Fully Fit				
000000-0000225A	FITTING OF REAR ANTI-ROLL BAR 28 (RARB)	No	-/	UTI	Fully Fit	CL			

Work Objects

Serial Number: MV25AA
 NSN: 2320998939968

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Estimated		Working Organisation	Repair Section
							Work Status	Repair Time		
000000-00537EC0		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	26-Apr-19	Level 1			000:00		
000000-0080E5BD	000000-0032625A	No	6 Monthly/10000 Kms	10-Aug-19	Level 1	Fully Fit	CL	000:00		
000000-0068E49C	000000-00316D3B	No	Yearly/20000 Kms	23-May-19	Level 1	Fully Fit	CL	000:00		
000000-008A0D4E	000000-0032D6D1	No	6 Monthly/10000 Kms	10-Aug-19	Level 1	Fully Fit	CL	000:00		
000000-00536651	000000-00303F20	No	6 Monthly/10000 Kms	10-Aug-19	Level 1	Fully Fit	CL	000:00		
000000-00150ADF		No	5 Yearly/100000 Kms (1)		Level 1			000:00		

000000-00537EC1		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	26-Apr-19 Level 1			000:00
000000-005C25CE	000000- 0030ED0D	No	6 Monthly/10000 Kms	10-Aug-19 Level 1	Fully Fit	CL	000:00
000000-006C19BE	000000- 00316D3B	No	6 Monthly/10000 Kms	10-Aug-19 Level 1	Fully Fit	CL	000:00
000000-00217802		No	6 Monthly/10000 Kms	10-Aug-19 Level 1			000:00
000000-0020090E		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	30-Nov-21 Level 1			000:00
000000-0027051A		No	Yearly/20000 Kms	23-May-19 Level 1			000:00
000000-00270518		No	2 Yearly/40000 Kms	10-May-19 Level 1			000:00
000000-00150ADE		No	6 Yearly/120000 Kms (2)	Level 2			000:00
000000-00664FD3		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	23-Mar-21 Level 2	Fully Fit	CL	000:00
000000-00150ADC		No	2 Yearly/40000 Kms	10-May-19 Level 1			000:00
000000-0027052F		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	26-Apr-19 Level 1			000:00
000000-002008F9		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	23-Mar-21 Level 2			000:00
000000-0080E5D2	000000- 0032625A	No	Yearly/20000 Kms	23-May-19 Level 1	Fully Fit	CL	000:00
000000-004F93B2		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	26-Apr-19 Level 1	Fully Fit	CL	000:00
000000-003F96FD	000000- 002F5DD8	No	6 Monthly/10000 Kms	10-Aug-19 Level 1	Non- Taskworthy	CL	000:00
000000-00A0DECB		No	6 Monthly/10000 Kms	10-Aug-19 Level 1	Limited Role	CL	000:00

000000-00664FFB		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	30-Nov-21 Level 1	Fully Fit	CL	000:00
000000-007686B4	000000-0031F034	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	30-Nov-21 Level 1	Fully Fit	CL	000:00
000000-004F93C5		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	26-Apr-19 Level 1	Fully Fit	CL	000:00
000000-001860D7		No	6 Monthly/10000 Kms	10-Aug-19 Level 1			000:00
000000-004DEA25		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	26-Apr-19 Level 1			000:00
000000-0009A88D		No	Yearly/20000 Kms	23-May-19 Level 1		CL	000:00
000000-000DF38A		No	6 Monthly/10000 Kms	10-Aug-19 Level 1		CL	000:00
000000-000A39DC		No	6 Monthly/10000 Kms	10-Aug-19 Level 1		CL	000:00
000000-000452E3		No	6 Monthly/10000 Kms	10-Aug-19 Level 1		CL	000:00
000000-00012EFA		No	2 Yearly/40000 Kms	10-May-19 Level 1		CL	000:00
000000-00012EFB		No	6 Monthly/10000 Kms	10-Aug-19 Level 1		CL	000:00
000000-00012EFC		No	Yearly/20000 Kms	23-May-19 Level 1		CL	000:00
000000-000F1318		No	6 Monthly/10000 Kms	10-Aug-19 Level 1		CL	000:00
000000-0004E937		No	Yearly/20000 Kms	23-May-19 Level 1		CL	000:00
000000-000BAFFD		No	6 Monthly/10000 Kms	10-Aug-19 Level 1		CL	000:00
000000-0047B537	000000-002FE6EF	No	6 Monthly/10000 Kms	10-Aug-19 Level 1	Fully Fit	CL	000:00
000000-00985430		No	6 Monthly/10000 Kms	10-Aug-19 Level 1	Fully Fit	CL	000:00
000000-003D02DC	000000-002F5DD8	No	Yearly/20000 Kms	23-May-19 Level 1	Non-Taskworthy	CL	000:00
000000-00150AEO		No	6 Monthly/10000 Kms	10-Aug-19 Level 1			000:00
000000-00270533		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	26-Apr-19 Level 1			000:00
000000-00952649		No	Yearly/20000 Kms	23-May-19 Level 1	Fully Fit	CL	000:00

000000-00306B91	000000-002ECC7E	No	6 Monthly/10000 Kms	10-Aug-19 Level 1	Limited Role	CL	000:00
000000-001C18F8		No	6 Monthly/10000 Kms	10-Aug-19 Level 1			000:00
000000-007EF2B2		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	26-Apr-19 Level 1	Limited Role	CL	000:00
000000-007EF2A9		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	26-Apr-19 Level 1	Limited Role	CL	000:00
000000-00200910		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	26-Apr-19 Level 1			000:00
000000-001A954F		No	OOPS 3 Monthly/5000 Kms	Level 2			000:00
000000-00270519		No	6 Monthly/10000 Kms	10-Aug-19 Level 1			000:00
000000-001159F9		No	6 Yearly/120000 Kms (2)	Level 2			000:00
000000-002008F8		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	30-Nov-22 Level 2			000:00
000000-0073E619	000000-0031F034	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	30-Nov-22 Level 2	Fully Fit	CL	000:00
000000-00537EBF		No	Yearly/20000 Kms	23-May-19 Level 1			000:00
000000-001159FF		No	5 Yearly/100000 Kms (1)	Level 1			000:00
000000-007EF295	000000-0032625A	No	2 Yearly/40000 Kms	10-May-19 Level 1	Fully Fit	CL	000:00
000000-00150ADD		No	Yearly/20000 Kms	23-May-19 Level 1			000:00
000000-0020090F		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	26-Apr-19 Level 1			000:00
000000-001C18F9		No	Yearly/20000 Kms	23-May-19 Level 1			000:00
000000-004F93C3	000000-00303F20	No	2 Yearly/40000 Kms	10-May-19 Level 1	Fully Fit	CL	000:00
000000-0073E618	000000-0031F034	No	6 Monthly/10000 Kms	10-Aug-19 Level 1	Fully Fit	CL	000:00

000000-004DEA24

No

OOPS 2 Yearly/40000 Kms
Replace Air Cleaner Element
(1)

26-Apr-19 Level 1

000:00