



Ministry
of Defence



DE&S Secretariat



DES SEC-PolSec LE-JSC-WPNS@mod.gov.uk



Defence Equipment & Support
Maple 0a, #2043
MOD Abbey Wood
Bristol BS34 8JH



1 July 2022

Our Reference: FOI2022/07066

Dear [REDACTED]

I am writing about your request for the following information:

"I am seeking the military unit history, service & maintenance history for a Landrover Defender Wolf TUL military reg. no. LT 93 AA, Chassis number SALLDAA67WA146082, Date into Service 15/06/1998."

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search of Ministry of Defence (MOD) records has concluded that some information is held about your vehicle and copies of the following documents are attached:

Annex A - Vehicle History
Annex B - Fault History (Redacted)
Annex C - Modification History
Annex D - Service History
Annex E – Inspection History

Some of the Fault History (Annex B), relating to commercially sensitive information, has been withheld in accordance with Section 43(2) (Commercial Interests) which concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As Section 43 is a qualified exemption, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, releasing some of the Fault History would provide details of the time taken by MOD contractors to rectify fault reports. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of “would” rather than “would be likely to”.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner’s Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner’s website at <https://ico.org.uk/>.

Yours sincerely

DE&S Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
LT93AA	2320998939742	NB42253100	LV2A/088DUM	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
15/06/1998	SALLDAA67WA146082	25L06014B		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LT93AA	3		CA005A	JSCS ASHCHURCH		35283AA	15/06/1998	
LT93AA	4	01/12/2003	A3720B	35 HQ SQN RLC	63835A	45186	09/01/2004	
LT93AA	4	02/03/2004	A3720C	21 GS SQN RLC	30753	49006	11/03/2004	U65
LT93AA	4	18/03/2004	A9108A	QM DEPT UK LOG BN	31338	4465	09/05/2004	U89
LT93AA	4	13/10/2004	A3720B	35 HQ SQN RLC	1889	60157	18/01/2005	V69
LT93AA	4	15/06/2008	A0227A	40 REGT RA (THE LOWLAND GUNNERS)	66104	74801	18/06/2008	Z34
LT93AA	4	30/06/2008	A3720B	35 HQ SQN RLC	1091	107814	31/07/2008	Z53
LT93AA	4	26/01/2009	A0580A	2 MERC	70278	2	03/02/2009	Z88
LT93AA	2	13/02/2009	A3313A	LTF(W)	4	30	13/02/2009	Z90
LT93AA		09/12/2020		OSVP HOLDINGS			03/01/2021	

Work Objects

Serial Number: LT93AA
NSN: 2320998939742

Criteria:
Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL
Escalate Work: ALL
Work Request ID:
Assigned Work Status: ALL
Working Organisation:
Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00B22019		SNvE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B	29 Mar 2019	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-00AA1B13		MEI - 932W(1) - ADVISORY - INFORMATION - UNDER SIDE OF VEHICLE NEEDS WASHING OFF	Closed	Fully Fit	No	Level 1		19 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA1230		MEI 933 - DEFECTS - 45 VEHICLE JACK NOT PRESENTED FOR INSP	Closed	Limited Role	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA1214		MEI 933 - ADVISORY - 46 - BRIDGE CASSIFICATION SIGNS	Closed	Fully Fit	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA11DC		MEI 933 - DEFECTS - 49 NO ROAD TEST, NO BRAKE TEST DUE TO BRAKE FAULT	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA114B		MEI 932 - DEFECTS - 7.4 EMISSION NOT TESTED	Closed	Non-Taskworthy	No	Level 2		19 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA1143		MEI 932 - DEFECTS - 3.5 N/S/F BRAKE CALIPER LEAKING BRAKE FLUID	Closed	Non-Taskworthy	No	Level 2		19 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA111F		MEI 932 - DEFECTS - 1.9 BATTERIES U/S	Closed	Non-Taskworthy	No	Level 2		19 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA10C3		RL_TARE IN PASSENGER SEAT	Closed	Fully Fit	No	Level 1		31 Jul 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA1487		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-0000451A	28 Jul 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA1880		WORK CARRIED OUT AS PER CUSTOMER REQUEST - SALES ORDER 8B14875	Closed	Fully Fit	No	Level 2		26 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA15AC		BAAAN - 25 - 2 - 0261 - RENEW CRANKSHAFT FRONT OIL SEAL ENGINE	Closed	Non-Taskworthy	No	Level 2		23 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA1584		BAAAN - 25 - 4 - 0048 DIAGNOS OIL LEAKS INSPECTION	Closed	Non-Taskworthy	No	Level 2		23 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA13B5		BAAAN - 20 - 4 - 6717 RENEW PASSENGER SEAT CUSHION	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA13AF		BAAAN - 20 - 4 - 6613 RENEW DOOR APERTURE SEAL RH	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA13AA		BAAAN - 20 - 2 - 6565 RENEW DOOR LH APERTURE SEAL	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA13A8		BAAAN - 20 - 1 - 5850 SECURE	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA139C		BAAAN - 15 - 5 - 0223 RENEW VEHICLE ALTERNATOR DRIVE BELTS	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA1395		BAAAN - 15 - 4 - 0426 RENEW WATER PUMP DRIVE BELTS	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA137F		BAAAN - 15 - 3 - 4114 RENEW BATTERY POSITIVE TERMINAL COVER	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA13B8		BAAAN - 15 - 2 - 4114 RENEW BATTERY NEG TERMINAL COVER	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA132D		BAAAN - 15 - 1 - 0070 CARRY OUT 12 MONTHLY SERVICE SERVICING	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA1319		BAAAN - 5 - 1 - 8 VEHICLE RECOVERY, COUPLING & STARTING	Closed	Non-Taskworthy	No	Level 2		22 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00AA1161		MEI 933 - DEFECTS - 45 VEHICLE JACK NOT PRESENTED FOR INSP	Closed	Non-Taskworthy	No	Level 2		19 Mar 2018	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00A65570		AUX DRIVE BELT CRACKING TEETH	Closed	Non-Taskworthy	No	Level 2		18 Oct 2017	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00A45485		RL_LAD_INV OIL SEAPAGE FROM SUMP GASKET	Closed	Fully Fit	No	Level 2		01 Aug 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00A4547C		RL_LAD_RENEW PASSENGER DOOR SEAL	Closed	Fully Fit	No	Level 2		01 Aug 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00A45477		RL_LAD_FIT RUBBER BATTERY TERMINAL COVER	Closed	Fully Fit	No	Level 1		01 Aug 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00A4546E		RL_TARE IN PASSENGER SEAT	Closed	Fully Fit	No	Level 1		01 Aug 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00A45465		RL_LAD_RENEW DVRS DOOR SEAL	Closed	Fully Fit	No	Level 2		01 Aug 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00A4545F		RL_LAD_FIT MISSING SCREWS @ DVRS SEAT BASE	Closed	Fully Fit	No	Level 2		01 Aug 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00A0ACA7		ENGINE OIL LEAK	Closed	Non-Taskworthy	No	Level 2		10 Mar 2017	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-00A0301F	000000-00321FEA	Renew A frame ball joint	Closed	Non-Taskworthy	No	Level 2		20 Feb 2017	N/A	Inspection	TUL HS FFR HARD TOP		LTF IBES	000:00
000000-009F87B9	000000-00321FEA	Renew both front tractor seals	Closed	Non-Taskworthy	No	Level 2		23 Jan 2017	N/A	Inspection	TUL HS FFR HARD TOP		LTF IBES	000:00
000000-009F87B6	000000-00321FEA	Renew windscreen washer jets	Closed	Non-Taskworthy	No	Level 2		23 Jan 2017	N/A	Inspection	TUL HS FFR HARD TOP		LTF IBES	000:00
000000-009F87B3	000000-00321FEA	Renew windscreen wipers	Closed	Non-Taskworthy	No	Level 2		23 Jan 2017	N/A	Inspection	TUL HS FFR HARD TOP		LTF IBES	000:00
000000-009F87B1	000000-00321FEA	Renew Fan Belt	Closed	Non-Taskworthy	No	Level 2		28 Feb 2017	N/A	Closed No Action	TUL HS FFR HARD TOP		LTF IBES	000:00
000000-00962188		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003210	20 Jan 2016	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00830810		CLUTCH INOP.	Closed	Non-Taskworthy	No	Level 2		26 Aug 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-008441E4		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUL HS FFR HARD TOP			000:00
000000-0079B8BD		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00798AE3		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Fully Fit	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-006B0723		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-00000312	22 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-0035AEC0	000000-00286851	AESP 2320-D-128-601 Table 5 Ser 1 Engine Oil and Filter change	Closed	Fully Fit	No	Level 3		10 Dec 2008			TUL HS FFR HARD TOP			000:00
000000-0035AE8	000000-00286851	AESP 2320-D-128-601 Table 5 Ser 4 Air Filter Element Change	Closed	Fully Fit	No	Level 3		10 Dec 2008			TUL HS FFR HARD TOP			000:00
000000-0035AE70	000000-00286851	Reqs 6 Monthly Service	Closed	Fully Fit	No	Level 3		10 Dec 2008			TUL HS FFR HARD TOP			000:00
000000-0035AE86	000000-00286851	Reqs 6 Monthly VM Tasks	Closed	Fully Fit	No	Level 3		10 Dec 2008			TUL HS FFR HARD TOP			000:00
000000-0035AE98	000000-00286851	Reqs 6534	Closed	Fully Fit	No	Level 3		10 Dec 2008			TUL HS FFR HARD TOP			000:00
000000-000971A1		Investigate gap on passenger door	Closed	Fully Fit	No	Level 2		24 Oct 2007			TUL HS FFR HARD TOP			000:00
000000-000971A2		Rectify holes in body work	Closed	Fully Fit	No	Level 2		24 Oct 2007			TUL HS FFR HARD TOP			000:00
000000-000554D9	000000-0027757D	R/H/F BRAKE BACK PLATE REQ'S WELDING	Closed	Fully Fit	No	Level 3		27 Feb 2007			TUL HS FFR HARD TOP			000:00
000000-000554DC	000000-0027757D	RENEW VEHICLE ALTERNATOR BELT	Closed	Fully Fit	No	Level 2		27 Feb 2007			TUL HS FFR HARD TOP			000:00
000000-000D1A64	000000-0027757D	ALTERNATOR MAKES WHINING NOISE	Closed	Non-Taskworthy	No	Level 2		15 Feb 2008			TUL HS FFR HARD TOP			000:00
000000-0002B05B		Initial Usage	Closed	Fully Fit	No	Level 1		06 Sep 2006			TUL HS FFR HARD TOP			000:00
000000-0002B062		Initial Maintenance	Closed	Fully Fit	No	Level 1		06 Sep 2006			TUL HS FFR HARD TOP			000:00

Work Objects

Serial Number: LT93AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embodiment Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0069223E	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-0062A1D3	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-005D6F9E	00001	Radio Rack Fixings		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-005D6FA1	00008	Input / Output Porthole for Comms / Power Cable Installation		No	-/-	RTI				Limited Role	CL	Level 2			
000000-005D6FB1	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-005D6FB2	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-005D6F9F	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/-	RTI				Limited Role	CL	Level 2			
000000-005D6FAE	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-005D6FB0	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-005D6FA0	00007	TUAAM Earth Bonding Improvements		No	-/-	RTI				Limited Role	CL	Level 2			
000000-005D6FA2	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-005D6FB9	00037	Fitting Glow Plug Timer Interface Harness		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-005D6FB8	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-005D6FAD	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Non-Taskworthy	CL	Level 2			

Work Objects

Serial Number: LT93AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-007B66E1	000000-00321FEA	No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		LTF IBES
000000-003C0528		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-0099BA23		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00694CBD		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-009412AB		No	MEI (2)		Level 2			000:00		
000000-0083A521		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-009412AC		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-009B8479		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00986E11		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00842B34		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0056BABB		No	MEI (2)		Level 2			000:00		
000000-00163835		No	MEI (2)		Level 2			000:00		
000000-005C6EE1		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-005DD4C6		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00163836		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-006B0E7C		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-002354DE		No	MEI (2)		Level 2			000:00		
000000-00958A67		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-009E214C		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0096F1A0		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-005BA37C		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-002E0357		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00995450		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0056BABC		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00598160		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0069B3B1		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-002354DF		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00950098		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0067F09D		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-000BD7B3		No	MEI (2)		Level 2		CL	000:00		
000000-0009061F		No	MEI (2)		Level 2		CL	000:00		
000000-000CF302		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-000B5AEC		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-000A861B		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-000D7212		No	MEI (2)		Level 2		CL	000:00		
000000-0000F466		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-0003C9DB		No	MEI (2)		Level 2		CL	000:00		
000000-006BED6C		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-009EBF16		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0095FA61		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-005A58D1		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00848761		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0086B3BC		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-003C0527		No	MEI (2)		Level 2			000:00		
000000-009CB678		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0064C8C5		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-004DC915		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00784A1A	000000-00321FEA	No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		LTF IBES
000000-006596F0		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00968557		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-007C335E		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-009A87C4		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0064C8C6		No	MEI (2)		Level 2			000:00		
000000-0068CDB2		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0098E18C		No	First Parade Insp (AR)(1)		Level 1			000:00		