



<b>Dancing Cactus Plush Toy YY7</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>Alert Number</b>	2301-0186
<b>Product Type</b>	Toys – Dancing cactus plush toy
<b>Product Identifiers</b>	Barcode: X001KF42EH
<b>Product Description</b>	Battery operated dancing cactus toy
<b>Country of Origin</b>	China
<b>Counterfeit</b>	Unknown
<b>Risk Type</b>	Asphyxiation
<b>Risk Level</b>	High
<b>Risk Description</b>	The product packaging presents a high risk of asphyxiation as the flexible plastic bag used for packaging has an area greater than 100mm x 100mm and the bag thickness measured as 0.031 ± 0.002mm. This less than the minimum 0.038mm specified. The packaging itself causes the danger and it should be removed from the product immediately and kept away from children. The product does not meet the requirements of the Toys (Safety) Regulations 2011.
<b>Corrective Measures</b>	Import rejected at the border and destruction of the product.
<b>Online Marketplace</b>	Amazon – the listing has been removed by the online marketplace.
<b>Notifier</b>	Local Authority Trading Standards.