Product Safety Report

MX-135 LED STAR LIGHTING CHAIN	
Aspect	Details
Images	
Alert Number	2212-0152
Product Type	Electrical appliances and equipment – Lighting chain
Product Identifiers	Barcode: 8935003201357 Item code: MX-135
Product Description	LED star lighting chain packaged in a see through plastic box
Country of Origin	China
Counterfeit	No
Risk Type	Electric shock
Risk Level	Serious risk
Risk Description	The product presents a risk of electric shock as it has inadequate protection. The cover on the flasher unit was easily removed without the use of a tool, which gave access to live parts. The plug fitted to this sample was a non-UK type plug. It had not been fitted with a suitable conversion plug, which presents a further risk of electric shock to the user. There product was not supplied with any instructions to ensure the safe and correct assembly, installation, use and maintenance of the equipment. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.
Corrective Measures	Withdrawal of the product from the market
Online Marketplace	N/A
Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <u>https://www.gov.uk/guidance/product-recalls-and-alerts</u>