




<b>Mammut Alugator Ride 3.0 Hoe and Alugator Ride SE avalanche shovels</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>Alert Number</b>	2304-0051
<b>Product Type</b>	Handtools – Shovels
<b>Product Identifiers</b>	Brand: Mammut Alugator Ride 3.0 hoe affected production lots: 1121 Alugator Ride SE production lots: 1221 & 0322 (sold as part of Barryvox Package, Barryvox S Package and Barryvox Package Tour)
<b>Product Description</b>	Two variations of aluminium shovels with orange handles, one with a black finish and one with a silver finish. Designed for digging out avalanche victims. The product name and production lot number are printed on shovel shaft near the handle.
<b>Country of Origin</b>	Taiwan
<b>Counterfeit</b>	Genuine
<b>Risk Type</b>	Asphyxiation, injuries, and death.
<b>Risk Description</b>	<p>The products have been recalled as the spring locking mechanism on the shovels can fail in an emergency excavation of a person buried by an avalanche. This is due to the pin joint that connects the shovel shaft to the shovel blade not being positioned correctly in every case, which can cause the shovel blade to detach from the shaft. This therefore poses a risk of injury or death for the buried person.</p> <p>The affected batches of the products do not comply with the General Product Safety Regulations 2005.</p>
<b>Corrective Measures</b>	The product has been recalled from end users. For further information, please see the Mammut recall site here: <a href="https://mammut.prezly.com/recall-notice-for-a-call-for-inspection-shovel-locking-mechanism">https://mammut.prezly.com/recall-notice-for-a-call-for-inspection-shovel-locking-mechanism</a>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards.