



Lithium Battery Charger szYB-100W-42V2A	
Aspect	Details
Images	
Alert Number	2304-0144
Product Type	Electrical appliances and equipment - Lithium Battery Charger
Product Identifiers	Other product identifiers: Carton details: Seller SKUID: S000001 OC SKUID: 0C000001639 4083 0CC043988090022 & 23 RN: 22/43 & 23/43
Product Description	Power charger with wall plug and power 'brick'
Country of Origin	China
Counterfeit	No
Risk Type	Electric shock
Risk Level	Serious
Risk Description	<p>The product presents a serious risk of electric shock as it failed the electric strength test. The insulation between the input and output circuits broke down when a 2.92 kV test voltage was applied between the circuits. The plug did not comply with BSEN 1361-1 and the fuse did not comply with BS1362. The fuse had not been supplied with any granular filler. The filler is required to ensure the safe operation of the fuse under fault conditions.</p> <p>The dimensions of the sleeved parts of the pins differed from the metal parts of the pins. This resulted in a distinct step between the two. This could cause damage to the socket and undue wear and tear to the sleeve, which presents a risk of electric shock to users. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.</p>
Corrective Measures	The import has been rejected at the border and destroyed
Online Marketplace	N/A
Notifier	Local Authority Trading Standards