



| Wooden Baby High Chair | |
|-------------------------------|--|
| Aspect | Details |
| Images | |
| Alert Number | 2303-0016 |
| Product Type | Childcare Articles and Children's Equipment – Baby High Chair |
| Product Identifiers | SKU: EZ1179245A1 |
| Product Description | A fixed position wooden baby highchair with black webbed harness. |
| Country of Origin | Unknown |
| Counterfeit | Unknown |
| Risk Type | Entrapment |
| Risk Level | Serious |
| Risk Description | <p>The product presents a serious risk of entrapment as the gaps between the seat and the sides, and the seat and the back, are too large. This can cause the young child's head or torso to become trapped in the gaps on the high chair.</p> <p>The product does not meet the requirements of the General Product Safety Regulations 2005.</p> |
| Corrective Measures | The product has been destroyed at the border. |
| Online Marketplace | N/A |
| Notifier | Local Authority Trading Standards |