




| <b>Sauna Heating Mat</b>   |  |
|----------------------------|--|
| <b>Aspect</b>              | <b>Details</b>   |
| <b>Images</b>              |    |
| <b>Alert Number</b>        | 2305-0158  |
| <b>Product Type</b>        | Electrical appliances and equipment – Sauna heating mat  |
| <b>Product Identifiers</b> | Model: XC-RZT02  |
| <b>Product Description</b> | Sauna heating mat supplied with a white controller.  |
| <b>Country of Origin</b>   | China  |
| <b>Counterfeit</b>         | No   |
| <b>Risk Type</b>           | Electric shock   |
| <b>Risk Level</b>          | High   |
| <b>Risk Description</b>    | The product presents a high risk of electric shock as the internal build quality is poor. There is inadequate separation between the primary and secondary circuits and the creepage requirements of the standard are not met. The internal components of the flexible part are accessed by cutting open the casing. The transformer is of a poor build quality because there is inadequate separation between the primary and secondary windings. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. |
| <b>Corrective Measures</b> | Destruction of the product.  |
| <b>Online Marketplace</b>  | N/A  |
| <b>Notifier</b>            | Local Authority Trading Standards  |