




<b>VEVOR Sealing Machine</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>Alert Number</b>	2301-0042
<b>Product Type</b>	Electrical appliances and equipment – Sealing machine
<b>Product Identifiers</b>	The product was not marked with a model or serial number.
<b>Product Description</b>	Processing machine with micro-computer on the side for weighing and programming.
<b>Country of Origin</b>	China
<b>Counterfeit</b>	No
<b>Risk Type</b>	Electric Shock
<b>Risk Level</b>	Serious
<b>Risk Description</b>	The product presents a high risk of electric shock as the dimensions of the plug do not meet the requirements of the relevant standard. The pins are too close to the edge of the plug, meaning the user could touch the live pins when inserting or removing the plug from the socket, receiving an electric shock. The appliance was also inadequately earthed, with insufficient securing against accidental loosening and an insufficient cross-sectional area of the earth wire, and was supplied with a noncompliant fuse. The product also required improvements to marking, labelling and documentation. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.
<b>Corrective Measures</b>	The import has been rejected at the border and destroyed.
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards