




| Philips Avent Digital Video Baby Monitor | |
|---|--|
| Aspect | Details |
| Images |  |
| Alert Number | 2306-0004 |
| Product Type | Electrical Appliances and Equipment – Baby Monitor |
| Product Identifiers | List of affected product type numbers: SCD620, SCD625, SCD630, SCD831, SCD833, SCD841, SCD843, and SCD845. This can be found printed on the bottom of the parent unit of the baby monitor. Affected models were produced and sold between January 2016 and January 2020. |
| Product Description | White and grey video baby monitor consisting of camera/microphone and separate video viewing device. |
| Country of Origin | China |
| Counterfeit | No |
| Risk Type | Fire |
| Risk Description | The product has been identified as presenting a risk of fire as the battery in the parent unit may overheat while plugged into the electrical outlet. This could cause the unit to ignite. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. |
| Corrective Measures | The product has been recalled from end users by Philips. For further information, including on how to check if your baby monitor is affected, access the Philips recall page at: https://www.philips.co.uk/c-w/support-home/recall/avent-digital-video-baby-monitors |
| Online Marketplace | N/A |
| Notifier | Local Authority Trading Standards |