

## **Product Safety Report**

Vevor wood turning lathe model MC1080 (900)	
Aspect	Details
Images	
Alert Number	2204-0199
Product Type	Machinery - Wood turning lathe
Product Identifiers	Brand: Vevor Model: MC1080 (900) Barcode: MGCCMC1018DZK0001V2
Product Description	A blue coloured wood turning lathe.
Country of Origin	China
Counterfeit	Genuine
Risk Type	Other
Risk Level	Serious
Risk Description	The product presents a serious risk as the earth stud was found to be unreliable and no declaration of conformity was supplied. During testing, it was identified that the protective earth connection used a standard cross head screw to hold two crimp terminals connecting the earths together. An earth connection must not use a standard screw that can be undone from outside of the product. The screw could be undone, and the protective earth could be removed. Also, a screw connection cannot hold two earth connections together for the same reason. Additionally, the product supply voltage requirements are not compatible with the UK power system. Some of the required documentation and markings were not present.  The product does not meet the requirement of the Supply of Machinery (Safety) Regulations 2008.
Corrective Measures	Destruction of the product.
Online Marketplace	N/A
Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <a href="https://www.gov.uk/guidance/product-recalls-and-alerts">https://www.gov.uk/guidance/product-recalls-and-alerts</a>