

Air Quality and Dust Monitoring Monthly Report – April 2023 London Borough of Camden



Department for Transport

High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited,
Two Snowhill
Snow Hill Queensway
Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2021, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-government-licence/version/2 **OGI** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in the London Borough of Camden (LBC) during March 2023 and April 2023 respectively.
- 1.1.2 Figure 1 to Figure 5 in Appendix A indicate the current worksites together with air quality and dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current phase of works commenced in November 2019 and is expected to be completed by 2025. The current worksites, as presented in Appendix A, Figure 1 to Figure 5 include:

Skanska Costain Strabag Joint Venture (SCSjv)

- Adelaide Road Vent Shaft – piling operations and groundworks.
- Euston Scissor Cut – groundworks, piling operations and materials management.
- Euston Throat Retained Cut - groundworks, piling operations and materials management
- Hampstead Road Bridge –Utilities diversion works.
- Euston Cavern – piling operations, groundworks and materials management

Mace Dragados Joint Venture (MDjv)

Utilities

- Backfilled all the manholes due to demobilisation.
- Installed main water pipe from MH3 to MH5 location.
- Started various arrangements for demobilisation.

TSS

- Completed slipform set up and started sliding.
- Completed blockwork & screeding on B3.
- Started blockwork & screeding on B2.
- Completed installation of second lifting hoists.
- Started installing pre-cast staircase.

Maria Fidelis

- Drainage works completed.
- Margarete Centre backfill removal commenced.
- Plasterboard removal.
- Installation of roof parapets.
- Installation of roof plant.
- Cladding work including windows.
- MEP first fix install.

Maria Fidelis Old School

- HAZMAT surveys to old school building commenced.

NTH

- Continued demob of site.

ITR

- Landscaping trees planted.
- Surface finishing tarmac installed.
- Street furniture installed.
- Drainage works completed.
- CCTV duct route completed.
- Lighting columns installed.

Surveys

- Kilnbridge and Emico completed demobilisation works.
- One of Emico team, responsible for panels reinstallation still on site at Euston station.
- Demobilisation of all team from the sites completed.
- Monthly SenSat drone surveys of HS2 Area stopped until further notice.
- Noise Insulation core team made redundant. But there are some ongoing works within reduced scope of maintenance on Starcross/Drummond/Euston streets.

1.1.5 Twenty-two (22) dust monitors are installed around worksites, where works are underway. These sites returned a medium to high dust risk rating.

1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 2, together with line charts of monthly data from each dust monitor in Figure 6. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.


- 1.1.7 The trigger level for PM₁₀ concentrations of 190 µg/m³, over a 1-hour period, in accordance with the updated guidance document '*Guidance on Monitoring in the Vicinity of Demolition and Construction Sites – (October 2018)*' has been applied.
- 1.1.8 No (0) dust trigger alerts were recorded during the monitoring period (April 2023).
- 1.1.9 Data capture was below 90% for multiple monitors in April 2023 due to monitor faults and power supply issues.
- 1.1.10 Diffusion tube monitoring of Nitrogen Dioxide (NO₂) is undertaken at sixty-four (64) locations around highways within the LBC as part of the management of air quality where significant effects August occur as a result of the scheme.
- 1.1.11 Diffusion tube monitoring results are as provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on the results to date, no unexpected values were recorded during the monitoring period.
- 1.1.12 NO₂ monitoring locations and results are presented in Appendix C, Table 3, together with the 2023 running mean.
- 1.1.13 Table 1 provides a summary of the complaint information related to dust or air quality received during the reporting period, together with the findings of any related investigations.

Table 1: Summary of complaints received during April 2023

Complaint Reference No.	Worksite Reference	Description of complaint	Results of investigation
HS2-23-44548-C		Complaint raised by local authority on behalf of resident concerning dust levels.	Contractor spoke directly with resident, who advised they had not raised a complaint and did not have any issues at that time. Confirmed this to local authority.

Appendix A – Worksites and Monitoring Locations

Figure 1 to Figure 5: Worksites and monitoring locations within the LBC



Legend
■ Diffusion Tube
 District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number
 Map Name
**Monitoring Locations
 In LBC (Sheet 1)**
 London Borough of Camden

hs2
 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.


Registered in England. Registration number 06791686.
 Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2022.
 Ordnance Survey Licence Number 100049190.

Scale at A3: 1:10,000

0 100 200 300 400
 Metres

Doc Number: Date: 25/10/22



- Legend**
- Diffusion Tube
 - Dust Monitor
 - Worksite
 - District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name
**Worksite and Monitoring Locations
 In LBC (Sheet 2)**

London Borough of Camden


hs2

Registered in England. Registration number 06791686.
 Registered office: 2 Snowhill, Queensway,
 Birmingham B4 6GA.

Scale at A3: 1:7,000

0 70 140 210 280
 Metres

Doc Number: _____ Date: 25/10/22



Legend

- Dust Monitor
- District Borough Unitary Boundaries
- Worksite

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name
**Worksite & Monitoring Locations
 In LBC (Sheet 3)**

London Borough of Camden


hs2

Registered in England. Registration number 06791686.
 Registered office: 2 Snowhill, Queensway,
 Birmingham B4 6GA.

Scale at A3: 1:7,000

0 70 140 210 280
 Metres


Doc Number: **Date: 18/05/23**




Legend
■ Diffusion Tube District Borough Unitary Boundaries
 Worksite

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number
 Map Name
**Worksite & Monitoring Locations
 In LBC (Sheet 4)**
 London Borough of Camden



 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
 Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

Scale at A3: 1:7,000


© Crown copyright and database rights 2023.
 Ordnance Survey Licence Number 100049190.


Doc Number: Date: 18/05/23




- Legend**
- Diffusion Tube
 - District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


Map Number
 Map Name
**Worksite and Monitoring Locations
 In LBC (Sheet 5)**
 London Borough of Camden


 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.



Registered in England. Registration number 06791686.
 Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

Scale at A3: 1:4,000



© Crown copyright and database rights 2022.
 Ordnance Survey Licence Number 100049190.

Doc Number: _____ Date: 25/10/22


Appendix B – Dust Monitoring Results

Table 2: Dust monitoring locations and April 2023 Results


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (µg/m ³)	Minimum 1-hour PM ₁₀ concentration (µg/m ³)	Maximum 1-hour PM ₁₀ concentration (µg/m ³)	Number of 1- hour periods exceeding trigger level of 190 µg/m ³	Data capture (%)
AQ001	529016, 183049	Junction of Park Village East, Stanhope Street and Granby Terrace	M	Yes	N	9.6	0.8	27.8	0	100.0
AQ002	528924, 183130	Park Village East	M	Yes	N	10.3	0.6	40.6	0	71.3
AQ003	529273, 182698	St James' Gardens	M	Yes	N/A	21.0	1.0	159.8	0	7.6
AQ004	529533, 182519	Melton Street	H	Yes	N/A	8.7	0.7	33.7	0	100.0
AQ005	529498, 182502	Stephenson Way	H	Yes	N/A	13.4	1.0	67.8	0	100.0
AQ006	529388, 182524	Euston Street	H	Yes	N/A	15.3	1.2	47.3	0	100.0
AQ007	529361, 182574	Drummond Street	H	Yes	N/A	4.8	0.3	11.6	0	100.0
AQ008	529372, 182657	Cobourg Street	H	Yes	N/A	11.8	0.7	54.9	0	100.0
AQ009	529707, 182730	Eversholt Street	H	Yes	N/A	6.1	0.4	117.7	0	100.0
AQ010	529223, 182746	Hampstead Road South	M	Yes	N/A	12.1	0.9	111.5	0	100.0
AQ011	529176, 182922	Hampstead Road	M	Yes	N	15.2	1.0	141.5	0	100.0

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (µg/m ³)	Minimum 1-hour PM ₁₀ concentration (µg/m ³)	Maximum 1-hour PM ₁₀ concentration (µg/m ³)	Number of 1- hour periods exceeding trigger level of 190 µg/m ³	Data capture (%)
AQ012	529144, 182941	Rear of Coniston House	M	Yes	N	10.2	0.8	35.0	0	99.9
AQ013	529066, 182990	Regents Park Estate	M	Yes	N	11.5	0.8	35.6	0	100.0
AQ016	528820, 183498	Mornington Terrace North	M	Yes	N	8.8	0.6	43.9	0	100.0
AQ017	528962, 183274	Mornington Terrace South	M	Yes	N	8.0	0.6	19.7	0	100.0
AQ018	529192, 183071	Hampstead Road North	M	Yes	N	8.6	0.8	46.4	0	100.0
AQ019	528689, 183500	Park Village East (North)	M	Yes	N	9.9	0.7	60.9	0	100.0
AQ020	529109, 182605	Netley School	n/a	Yes	N/A	9.6	0.8	45.6	0	100.0
AQ021	529136, 183086	Site compound at the Junction of Hampstead Road & Granby Terrace Bridge	M	Yes	N	11.1	1.0	54.8	0	100.0
AQ044	527725, 184369	Adelaide Road 1	M	Yes	N	12.2	0.6	149.9	0	100.0
AQ045	527826, 184375	Adelaide Road 2	M	Yes	N	10.0	0.8	34.3	0	100.0
AQ054	529266, 183076	Ampthill Estate, Hampstead Road	M	Yes	N	8.6	0.9	27.5	0	81.8


Figure 6: Construction dust 1-hour mean indicative PM₁₀ concentration for dust monitors




AQ005




AQ006




AQ007




AQ008




AQ009




AQ010







AQ011




AQ012







AQ019




AQ020




AQ021




AQ044



AQ045



AQ054



Appendix C – Air Quality Monitoring Results

Table 3: NO₂ monitoring locations around highways, NO₂ concentrations and monthly monitoring results with running mean for 2023 (µg/m³)

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹
HS2-000020BM5	Junction of St Chad's Street and Grays Inn Road	530436, 182929	45	46	37										43
HS2-000020BM7	Chalton Street	529894, 182702	50	53	48										50
HS2-000020BM8	Junction of Euston Square and Grafton Place	529737, 182641	48	62	41										50
HS2-000020BM9	Junction of Endsleigh Gardens and Upper Woburn Place	529785, 182529	43	50	25										39
HS2-000020BMA	Junction of Euston Road and Gower Street	529429, 182375	51	59	37										49
HS2-000020BMB	Whitfield Street	529273, 182114	38	43	33										38
HS2-000020BMC	Hampstead Road	529232, 182511	56	69	63										63
HS2-000020BMF	Junction of Polygon Road and Ossulston Street	529715, 183123	36	34	24										31
HS2-000020BMH	Nash Street	528861, 182717	37	30	24										31

¹ Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹
HS2-000020BMJ	Junction on Robert Street and Stanhope Street	529080, 182698	37	37	14										29
HS2-000020BMK	Junction of Plender Street and Bayham Street	529196, 183546	47	52	38										46
HS2-000020BML	Junction of Arlington Road and Mornington Crescent	529093, 183356	35	37	Tube Missing										36
HS2-000020BMM	Junction of Bayham Street and Pratt Street	529084, 183722	57	59	35										50
HS2-000020BMN	Junction of Delancey Street and Albert Street	528850, 183573	41	46	23										37
HS2-000020BMQ	Junction of Parkway and Delancey Street	528662, 183604	42	42	30										38
HS2-000020BMR	Junction of Oval Road and Jamestown Road	528548, 183967	32	38	27										32
HS2-000020BMS	Junction of Chalk Farm Road and Castlehaven Road	528685, 184188	43	45	36										41
HS2-000020BMT	Junction of Camden Road and Camden Street	529079, 184043	48	50	31										43
HS2-000020BMU	Junction of Southampton Road and Fleet Road	527783, 185407	44	45	38										42
HS2-000020BMV	Primrose Hill Road	527538, 184250	35	44	29										36

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹
HS2-000020BMW	Junction of Finchley Road and Hilgrove Road	526619, 184081	Tube Missing	50	33										42
HS2-000020BMZ	Junction of Finchley Road and Hendon Way	525102, 186042	71	67	53										64
HS2-000020BNA	Junction of Regent's Park Road and Rothwell Street	527884, 183980	36	37	25										32
HS2-000020BNC	Junction of Outer Circle and Gloucester Gate	528528, 183443	27	27	21										25
HS2-000020BNH	Junction of Parkway and Albert Street	528763, 183720	32	40	30										34
HS2-000020BNN	Lincoln's Inn Fields	530744, 181308	36	36	24										32
HS2-000020BNQ	Camley Street	529735, 183737	25	41	26										31
HS2-000020BNY	Junction of Mill Lane and Hillfield Road	524839, 185136	35	32	Tube Missing										33
HS2-000020BNZ	Mansfield Road	528050, 185508	40	44	27										37
HS2-000020BP0	Junction of Camden Road and Torriano Avenue	529708, 184871	46	56	42										48
HS2-000020BP2	Junction of Grays Inn Road and Holborn	531149, 181616	41	40	32										38
HS2-000020BPB	Camden High Street	528966, 183735	60	65	40										55
HS2-000020BPC	Castlehaven Road	528788, 184591	39	39	30										36

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹
HS2-000020BPD	Prince of Wales Road	528571, 184683	31	35	16										27
HS2-000020BPE	Haverstock Hill	527710, 184749	36	39	27										34
HS2-000020BPF	Junction of Primrose Gardens and England's Lane	527549, 184640	42	42	33										39
HS2-000020BPU	Junction of Gower Street and Grafton Way	529476, 182267	51	47	36										45
HS2-000020BPW	Junction of Delancey Street and Arlington Road	528939, 183637	40	45	30										38
HS2-000020BPX	Netley Street	529177, 182625	32	Tube Missing	21										27
HS2-000020BPY	Stanhope Street	529060, 182947	31	37	19										29
HS2-000020BPZ	Albany Street	528790, 182923	27	40	25										30
HS2-000020BQ0	Werrington Street	529493, 183113	34	35	19										29
HS2-000020BQ1	Polygon Road	529574, 183045	30	36	22										29
HS2-000020BQ2	Alexandra Place	526320, 183980	32	35	23										30
HS2-000020BQ3	Harrington Square	529228, 183172	42	38	26										35
HS2-000020BQ4	Junction of North Gower Street and Starcross Street	529290, 182572	43	41	28										37
HS2-000020BQ5	Adelaide Road	527713, 184392	35	41	17										31
HS2-000020BQ6	Mornington Terrace	528836, 183474	34	34	26										31

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹
HS2-000020BQ7	Arlington Road	529009, 183479	33	35	24										30
HS2-000020BQ8	Clarkson Row	529024, 183213	39	39	25										34
HS2-000020BQ9	Park Village East	528923, 183121	30	33	17										27
HS2-000020BQA	Eversholt Street	529386, 183132	52	45	34										44
HS2-000020BQB	Junction of Harrington Street and Varndell Street	529147, 182816	30	34	27										30
HS2-000020BQC	Junction of Robert Street and Hampstead Road	529199, 182704	40	40	33										38
HS2-000020BQD	Drummond Crescent	529648, 182856	38	33	Tube Missing										35
HS2-000020BQJ	Grafton Way	529380, 182225	56	56	38										50
HS2-000020BQL	Delancey Street	528768, 183581	46	50	Tube Missing										48
HS2-000020BQR	Lamp post on Park Village East	528682, 183505	36	40	26										34
HS2-000020BQS	Opposite Maria fidelis school on Phoenix Road	529670, 182982	37	36	25										33
HS2-000020BQT	Drummond Street	529385, 182581	42	46	29										39
HS2-000020BQX	Lamp post on Brunswick Square	530344, 182236	44	46	32										41
HS2-000020BP4	Triplicate site on Finchley Road next to Swiss Cottage kerbside automatic monitoring station	526633, 184392	51	54	45										50

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹
HS2-000020BP5	Triplicate site next to the Euston Road roadside automatic monitoring stations	529895, 182657	46	64	59										57
HS2-000020BP9	Triplicate site in Russell Square next to Bloomsbury urban background automatic monitoring station	530120, 182034	39	40	30										36