

## Air Quality and Dust Monitoring Monthly Report – June 2023 London Borough of Camden



## Department for Transport

High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited,  
Two Snowhill  
Snow Hill Queensway  
Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: [HS2enquiries@hs2.org.uk](mailto:HS2enquiries@hs2.org.uk)

Website: [www.gov.uk/hs2](http://www.gov.uk/hs2)

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2021, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit [www.nationalarchives.gov.uk/doc/open-government-licence/version/2](http://www.nationalarchives.gov.uk/doc/open-government-licence/version/2) **OGI** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: [psi@nationalarchives.gsi.gov.uk](mailto:psi@nationalarchives.gsi.gov.uk). Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

# Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in the London Borough of Camden (LBC) during May 2023 and June 2023 respectively.
- 1.1.2 Figure 1 to Figure 5 in Appendix A indicate the current worksites together with air quality and dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from [www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2](http://www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2), which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current phase of works in December 2017 and is expected to be completed by 2025. The current worksites, as presented in Figure 1 to Figure 5, include:

## **Skanska Costain Strabag Joint Venture (SCSjv)**

### Adelaide Road Vent Shaft

- Piling operations; and
- Groundworks.

### Euston Scissor Cut

- Groundworks;
- Piling operations; and
- Materials management.

### Euston Throat Retained Cut

- Groundworks;
- Piling operations; and
- Materials management.

### Hampstead Road Bridge

- Utilities diversion works.

### Euston Cavern

- Piling operations;
- Groundworks; and
- Materials management.

## **Mace Dragados Joint Venture (MDjv)**

### Utilities North

- Coburg Street North remedials (kerb reinstatement, backfill and concrete slab feed patches)

### Utilities, Non-Constable works

- Vodafone – Doric Way Duct excavation and Install

### Interim Taxi Rank

- Completion of north canopy roof;
- Completion of south canopy including roof edge protections and rain screen;
- Eversholt Street signals – Siemens pulling cables;
- Surfacing and road markings;
- Resin installed to footpath and entrance; and
- Water main supply testing and chlorination.

### Maria Fidelis Accommodation Building

- Ceiling reinstatements – First Floor to Level 5;
- Wall reinstatements – Ground Floor to Level 4;
- MEP First Fix – Ground Floor to Third Floor;
- Screeding to Ground Floor – completed 30/6/23;
- Continuation of roof plant and MEP install;
- Continuation of parapets and pediments install;
- External corrugated cladding installation to South First Floor;
- External corrugated cladding installed to North and West Elevations; and
- Corrugated cladding to Switch Room and CSC External Area.

### Maria Fidelis Substructure:

- Landscaping of Magaret Centre Garden;
- Brick wall commencement around Magaret Centre; and
- UKPN West Substation fit out.

### NTH Western:

- Installation of north concrete blocks;
- Type 1 laid and water drainage install Phase 1; and
- Installation of new BT Duct.

### TSS:


- Level 2 slab poured;
- Level 3 slab poured;
- PPC Stair 2 GF to FL 2 installed;
- Level 4 slab poured;
- Continue fit out of substructure of TSS – blockwork, screeding & down pipe install; and
- MEP Works commenced in tunnels – brackets and ductwork installation.

- 1.1.5 Twenty-two (22) dust monitors are installed around worksites, where demolition, groundworks and materials management are underway. These sites returned a medium to high dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor in Figure 6. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level for PM<sub>10</sub> concentrations of 190 µg/m<sup>3</sup>, over a 1-hour period, in accordance with the updated guidance document '*Guidance on Monitoring in the Vicinity of Demolition and Construction Sites – (October 2018)*' has been applied.
- 1.1.8 Dust trigger alerts were recorded during the monitoring period (June 2023) and are reported in Appendix B, Table 2.
- 1.1.9 Data capture was below 90% for multiple monitors in June 2023 due to power supply issues, as well as annual calibration and service.
- 1.1.10 Diffusion tube monitoring of Nitrogen Dioxide (NO<sub>2</sub>) is undertaken at sixty-four (64) locations around highways within the LBC as part of the management of air quality where significant effects August occur as a result of the scheme.
- 1.1.11 Diffusion tube monitoring results are as provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on the results to date, no unexpected values were recorded during the monitoring period.
- 1.1.12 NO<sub>2</sub> monitoring locations and results are presented in Appendix C, Table 3, together with the 2023 running mean.
- 1.1.13 There were no (0) complaints received during this reporting period (June 2023).

# Appendix A – Worksites and Monitoring Locations

Figure 1 to Figure 5: Worksites and monitoring locations within the LBC





**Legend**  
 Diffusion Tube  
 District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number  
 Map Name  
**Monitoring Locations  
 In LBC (Sheet 1)**  
 London Borough of Camden

**hs2**  
 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.


Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2022.  
 Ordnance Survey Licence Number 100049190.

Scale at A3: 1:10,000

Doc Number: Date: 25/10/22





- Legend**
- Diffusion Tube
  - Worksite
  - Dust Monitor
  - District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name  
**Worksite and Monitoring Locations  
 In LBC (Sheet 2)**

**London Borough of Camden**

**hs2**

Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway,  
 Birmingham B4 6GA.


© Crown copyright and database rights 2022.  
 Ordnance Survey Licence Number 100049190.

Scale at A3: 1:7,000

0 70 140 210 280  
 Metres

Doc Number: Date: 25/10/22







**Legend**  
 ● Dust Monitor □ District Borough Unitary Boundaries  
 ■ Worksite

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number  
 Map Name  
**Worksite & Monitoring Locations  
 In LBC (Sheet 3)**  
 London Borough of Camden


 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.


Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

Scale at A3: 1:7,000  


© Crown copyright and database rights 2023.  
 Ordnance Survey Licence Number 100049190.

Doc Number: \_\_\_\_\_ Date: 18/05/23







**Legend**  
■ Diffusion Tube  District Borough Unitary Boundaries  
 Worksite

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number  
 Map Name  
**Worksite & Monitoring Locations  
 In LBC (Sheet 4)**  
 London Borough of Camden


 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.


Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

Scale at A3: 1:7,000  


© Crown copyright and database rights 2023.  
 Ordnance Survey Licence Number 100049190.

Doc Number: Date: 18/05/23





- Legend**
- Diffusion Tube
  - District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number  
 Map Name  
**Worksite and Monitoring Locations  
 In LBC (Sheet 5)**  
 London Borough of Camden



HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.



Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway,  
 Birmingham B4 6GA.

Scale at A3: 1:4,000

© Crown copyright and database rights 2022.  
 Ordnance Survey Licence Number 100049190.



Doc Number:

Date: 25/10/22



## Appendix B – Dust Monitoring Results

Table 1: Dust monitoring locations and June 2023 Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Minimum 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Maximum 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Number of 1- hour periods exceeding trigger level of 190 µg/m <sup>3</sup>	Data capture (%)
AQ001	529016, 183049	Junction of Park Village East, Stanhope Street and Granby Terrace	M	Yes	N	11.4	1.0	64.4	0	96.5
AQ002	528924, 183130	Park Village East	M	Yes	N	12.9	0.8	38.1	0	96.5
AQ003	529273, 182698	St James' Gardens	M	Yes	N/A	11.3	0.8	133.5	0	100.0
AQ004	529533, 182519	Melton Street	H	Yes	N/A	12.2	2.0	47.2	0	100.0
AQ005	529498, 182502	Stephenson Way	H	Yes	N/A	12.2	1.0	64.8	0	100.0
AQ006	529388, 182524	Euston Street	H	Yes	N/A	14.0	2.4	85.8	0	100.0
AQ007	529361, 182574	Drummond Street	H	Yes	N/A	7.5	0.7	55.6	0	61.7
AQ008	529372, 182657	Cobourg Street	H	Yes	N/A	20.9	2.1	165.6	0	98.2
AQ009	529707, 182730	Eversholt Street	H	Yes	N/A	11.6	1.2	280.6	2	100.0
AQ010	529223, 182746	Hampstead Road South	M	Yes	N/A	14.0	2.1	88.8	0	95.1
AQ011	529176, 182922	Hampstead Road	M	Yes	N	13.9	1.9	395.4	1	90.5




Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Minimum 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Maximum 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Number of 1-hour periods exceeding trigger level of 190 µg/m <sup>3</sup>	Data capture (%)
AQ012	529144, 182941	Rear of Coniston House	M	Yes	N	17.3	3.9	143.2	0	90.5
AQ013	529066, 182990	Regents Park Estate	M	Yes	N	9.7	2.1	58.0	0	60.1
AQ016	528820, 183498	Mornington Terrace North	M	Yes	N	7.4	0.6	24.0	0	96.5
AQ017	528962, 183274	Mornington Terrace South	M	Yes	N	10.7	1.7	34.6	0	96.4
AQ018	529192, 183071	Hampstead Road North	M	Yes	N	11.1	2.0	37.5	0	96.5
AQ019	528689, 183500	Park Village East (North)	M	Yes	N	14.7	1.5	266.6	2	96.5
AQ020	529109, 182605	Netley School	n/a	Yes	N/A	12.5	1.4	43.0	0	100.0
AQ021	529136, 183086	Site compound at the Junction of Hampstead Road & Granby Terrace Bridge	M	Yes	N	11.7	3.5	47.0	0	87.1
AQ044	527725, 184369	Adelaide Road 1	M	Yes	N	14.8	2.0	192.5	1	93.2
AQ045	527826, 184375	Adelaide Road 2	M	Yes	N	14.3	4.5	52.7	0	93.3
AQ054	529266, 183076	Amphill Estate, Hampstead Road	M	Yes	N	8.5	4.6	12.7	0	3.5





Table 2: Summary of exceedances of trigger level in June 2023

Monitoring site ID	Period exceeding trigger level	Investigation	Outcomes / Resolution / Remedial measures implemented
AQ044	02/06/2023 16:01 – 17:00; 192.5 µg/m <sup>3</sup>	At the time of the trigger alert there were no dusty works underway as the site was shutting down on the Friday afternoon/evening. It is considered the elevated level was due to a temporary power loss to the monitor leaving it operating on the internal battery. This left the monitor's pump and heater with limited power and elevated readings for a short period. AQ045 nearby showed no elevated reading over the same period.	n/a
AQ019	05/06/2023 10:01 – 11:00; 251.5 µg/m <sup>3</sup>  09/06/2023 09:01 – 10:00; 266.6 µg/m <sup>3</sup>	At the time of the trigger alert there were third party utilities work taking place directly beneath the monitor which is located outside Park Village East Studios.	n/a
AQ011	07/06/2023 09:01 – 10:00; 395.4 µg/m <sup>3</sup>	At the time of the trigger, lifting operations were taking place in the vicinity and the area had already been thoroughly damped down. Given the relatively high reading it is considered the trigger was due to a tiny piece of loose debris within the monitor's inlet and not HS2 works.	n/a







Figure 4: Construction dust 1-hour mean indicative PM<sub>10</sub> concentration for dust monitors












Air Quality and Dust Monitoring Summary Report, June 2023  
 London Borough of Camden









AQ019




AQ020




AQ021




AQ044



AQ045



AQ054





## Appendix C – Air Quality Monitoring Results

Table 3: NO<sub>2</sub> monitoring locations around highways, NO<sub>2</sub> concentrations and monthly monitoring results with running mean for 2023 (µg/m<sup>3</sup>)

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2-000020BM5	Junction of St Chad's Street and Grays Inn Road	530436, 182929	45	46	37	40	36								41
HS2-000020BM7	Chalton Street	529894, 182702	50	53	48	41	36								46
HS2-000020BM8	Junction of Euston Square and Grafton Place	529737, 182641	48	62	41	Tube Missing	42								48
HS2-000020BM9	Junction of Endsleigh Gardens and Upper Woburn Place	529785, 182529	43	50	25	47	49								43
HS2-000020BMA	Junction of Euston Road and Gower Street	529429, 182375	51	59	37	Tube Missing	37								46
HS2-000020BMB	Whitfield Street	529273, 182114	38	43	33	33	29								35
HS2-000020BMC	Hampstead Road	529232, 182511	56	69	63	52	52								58
HS2-000020BMF	Junction of Polygon Road and Ossulston Street	529715, 183123	36	34	24	28	30								30
HS2-000020BMH	Nash Street	528861, 182717	37	30	24	24	21								27
HS2-000020BMJ	Junction on Robert Street and Stanhope Street	529080, 182698	37	37	14	29	25								28

<sup>1</sup> Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.

Air Quality and Dust Monitoring Summary Report, June 2023  
London Borough of Camden

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2-000020BMK	Junction of Plender Street and Bayham Street	529196, 183546	47	52	38	40	38								43
HS2-000020BML	Junction of Arlington Road and Mornington Crescent	529093, 183356	35	37	Tube Missing	26	25								31
HS2-000020BMM	Junction of Bayham Street and Pratt Street	529084, 183722	57	59	35	39	32								44
HS2-000020BMN	Junction of Delancey Street and Albert Street	528850, 183573	41	46	23	24	21								31
HS2-000020BMQ	Junction of Parkway and Delancey Street	528662, 183604	42	42	30	Tube Missing	35								37
HS2-000020BMR	Junction of Oval Road and Jamestown Road	528548, 183967	32	38	27	28	25								30
HS2-000020BMS	Junction of Chalk Farm Road and Castlehaven Road	528685, 184188	43	45	36	35	38								39
HS2-000020BMT	Junction of Camden Road and Camden Street	529079, 184043	48	50	31	38	40								42
HS2-000020BMU	Junction of Southampton Road and Fleet Road	527783, 185407	44	45	38	36	33								39
HS2-000020BMV	Primrose Hill Road	527538, 184250	35	44	29	25	25								31
HS2-000020BMW	Junction of Finchley Road and Hilgrove Road	526619, 184081	Tube Missing	50	33	41	42								41



Air Quality and Dust Monitoring Summary Report, June 2023  
London Borough of Camden

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2-000020BMZ	Junction of Finchley Road and Hendon Way	525102, 186042	71	67	53	62	53								61
HS2-000020BNA	Junction of Regent's Park Road and Rothwell Street	527884, 183980	36	37	25	25	19								28
HS2-000020BNC	Junction of Outer Circle and Gloucester Gate	528528, 183443	27	27	21	21	21								23
HS2-000020BNH	Junction of Parkway and Albert Street	528763, 183720	32	40	30	29	27								32
HS2-000020BNN	Lincoln's Inn Fields	530744, 181308	36	36	24	Tube Missing	21								29
HS2-000020BNQ	Camley Street	529735, 183737	25	41	26	29	24								29
HS2-000020BNY	Junction of Mill Lane and Hillfield Road	524839, 185136	35	32	Tube Missing	32	Tube Missing								33
HS2-000020BNZ	Mansfield Road	528050, 185508	40	44	27	23	19								31
HS2-000020BP0	Junction of Camden Road and Torriano Avenue	529708, 184871	46	56	42	43	40								45
HS2-000020BP2	Junction of Grays Inn Road and Holborn	531149, 181616	41	40	32	30	27								34
HS2-000020BPB	Camden High Street	528966, 183735	60	65	40	49	50								53
HS2-000020BPC	Castlehaven Road	528788, 184591	39	39	30	26	21								31
HS2-000020BPD	Prince of Wales Road	528571, 184683	31	35	16	27	19								26
HS2-000020BPE	Haverstock Hill	527710, 184749	36	39	27	24	22								30

Air Quality and Dust Monitoring Summary Report, June 2023  
London Borough of Camden

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2-000020BPF	Junction of Primrose Gardens and England's Lane	527549, 184640	42	42	33	27	25								34
HS2-000020BPU	Junction of Gower Street and Grafton Way	529476, 182267	51	47	36	Tube Missing	34								42
HS2-000020BPW	Junction of Delancey Street and Arlington Road	528939, 183637	40	45	30	28	26								34
HS2-000020BPX	Netley Street	529177, 182625	32	Tube Missing	21	31	30								29
HS2-000020BPY	Stanhope Street	529060, 182947	31	37	19	25	19								26
HS2-000020BPZ	Albany Street	528790, 182923	27	40	25	27	25								29
HS2-000020BQ0	Werrington Street	529493, 183113	34	35	19	24	20								26
HS2-000020BQ1	Polygon Road	529574, 183045	30	36	22	25	23								27
HS2-000020BQ2	Alexandra Place	526320, 183980	32	35	23	24	20								27
HS2-000020BQ3	Harrington Square	529228, 183172	42	38	26	33	41								36
HS2-000020BQ4	Junction of North Gower Street and Starcross Street	529290, 182572	43	41	28	26	27								33
HS2-000020BQ5	Adelaide Road	527713, 184392	35	41	17	Tube Missing	25								29
HS2-000020BQ6	Mornington Terrace	528836, 183474	34	34	26	25	22								28
HS2-000020BQ7	Arlington Road	529009, 183479	33	35	24	25	Tube Missing								29
HS2-000020BQ8	Clarkson Row	529024, 183213	39	39	25	25	Tube Missing								32



Air Quality and Dust Monitoring Summary Report, June 2023  
London Borough of Camden

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2-000020BQ9	Park Village East	528923, 183121	30	33	17	22	20								24
HS2-000020BQA	Eversholt Street	529386, 183132	52	45	34	38	35								41
HS2-000020BQB	Junction of Harrington Street and Varndell Street	529147, 182816	30	34	27	24	21								27
HS2-000020BQC	Junction of Robert Street and Hampstead Road	529199, 182704	40	40	33	25	34								34
HS2-000020BQD	Drummond Crescent	529648, 182856	38	33	Tube Missing	Tube Missing	31								34
HS2-000020BQJ	Grafton Way	529380, 182225	56	56	38	34	36								44
HS2-000020BQL	Delancey Street	528768, 183581	46	50	Tube Missing	34	31								40
HS2-000020BQR	Lamp post on Park Village East	528682, 183505	36	40	26	29	Tube Missing								33
HS2-000020BQS	Opposite Maria fidelis school on Phoenix Road	529670, 182982	37	36	25	26	23								30
HS2-000020BQT	Drummond Street	529385, 182581	42	46	29	31	28								35
HS2-000020BQX	Lamp post on Brunswick Square	530344, 182236	44	46	32	30	24								35
HS2-000020BP4	Triplicate site on Finchley Road next to Swiss Cottage kerbside automatic monitoring station	526633, 184392	51	54	45	42	47								48

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2-000020BP5	Triplicate site next to the Euston Road roadside automatic monitoring stations	529895, 182657	46	64	59	Tubes Missing	59								57
HS2-000020BP9	Triplicate site in Russell Square next to Bloomsbury urban background automatic monitoring station	530120, 182034	39	40	30	30	27								33