



Ministry  
of Defence

Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

---

[REDACTED]  
[REDACTED]

Our Reference:  
FOI2023/09966  
Date:  
23 August 2023

---

Dear [REDACTED]

I am writing about your email of 14 August 2023, requesting the following information:

*Could you please provide Merlin Report and / or details of vehicle history for my 1995 Defender 110 Ex-Mod. I confirm that I am the registered keeper of this vehicle.*

*The details from the VIN plate are as follows:  
SALLDHAC7MA958186*

*If you require further details, or if there is a charge payable, then please let me know. I will be very grateful for any information that you can give me that will help me to restore and maintain this vehicle for the future.*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Fault History (redacted)
- Annex B – Inspection History
- Annex C – Modification History
- Annex D – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault History (Annex A) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure.

**Defence Equipment & Support**

General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

Some information about your vehicle has previously been published; Section 21(1) of the FOI Act provides that information is exempt if it is reasonably available by other means. The chassis number you have provided corresponds to a Land Rover Defender with the military Equipment Registration Mark CE97AA. The MERLIN archive was released as part of a previous FOI request and can be accessed at the Government publications website via the following link:

<https://www.gov.uk/government/publications/foi-responses-published-by-mod-week-commencing-09-july-2018>

Under Section 16 (Advice and Assistance) of the FOI Act, I can advise you that the MERLIN database in the above link is split into seven spreadsheets. The first has a list of vehicles, while spreadsheets 2 through 7 include the vehicle service histories. To search for a vehicle, you must press Ctrl + F on your computer keyboard, then type in the vehicle registration number (CE97AA) and press 'enter'. For ease of reference, the published information concerning your vehicle is available from MERLIN 2.0 attachment 1, Row 178776, and MERLIN 2.0 attachment 6, Rows 67746 – 67754.

You may wish to note that when the MERLIN database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

**Defence Equipment & Support**

DE&S Policy Secretariat

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

Work Objects

Serial Number: CE97AA  
 NSN: 2320998939106

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault		Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
							Group ID Number	Occurrence Date						
000000-007172D1		RENEW SPARE WHEEL	Closed	Non-Taskworthy	No	Level 1		24 May 2012	N/A	Damage	TUM FFR SOFT TOP			
000000-007172D0		RENEW STEERING BOX	Closed	Non-Taskworthy	No	Level 2		24 May 2012	N/A	Damage	TUM FFR SOFT TOP			
000000-0071739C		FIT MISSING L/H REAR FOG LIGHT SECURING SCREW	Closed	Fully Fit	No	Level 2		24 May 2012	N/A	Failure	TUM FFR SOFT TOP			
000000-00717396		RECTIFY INOP R/H REAR BRAKE LIGHT	Closed	Non-Taskworthy	No	Level 2		24 May 2012	N/A	Failure	TUM FFR SOFT TOP			
000000-0071738D		RECTIFY INOP L/H REAR TAIL LIGHT	Closed	Non-Taskworthy	No	Level 2		24 May 2012	N/A	Failure	TUM FFR SOFT TOP			
000000-00717386		RECTIFY INOP R/H DIPPED HEADLIGHT	Closed	Non-Taskworthy	No	Level 2		24 May 2012	N/A	Failure	TUM FFR SOFT TOP			
000000-007111AD		COMPLETE ROLLING ROAD BRAKE TEST IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2		08 May 2012	N/A	Inspection	TUM FFR SOFT TOP			
000000-007111AB		COMPLETE UNIT B VEHICLE INSPECTION (AFB6534) IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2		08 May 2012	N/A	Inspection	TUM FFR SOFT TOP			
000000-007111A8		COMPLETE L2 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 6	Closed	Non-Taskworthy	No	Level 2		08 May 2012	N/A	Servicing	TUM FFR SOFT TOP			
000000-007111A7		COMPLETE L1 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 6	Closed	Non-Taskworthy	No	Level 1		08 May 2012	N/A	Servicing	TUM FFR SOFT TOP			
000000-006DE762		TABLE 7, SERIAL 64(DUE 16-11-2013 OR 154940 ACCUMULATIVE KMS)	Closed	Fully Fit	No	Level 2		17 Nov 2011	N/A	Servicing	TUM FFR SOFT TOP			
000000-00711188		COMPLETE ANNUAL INSPECTION (FMT 933) IAW AESP 2300-A-050-013	Closed	Fully Fit	No	Level 2		08 May 2012	N/A	Closed No Action	TUM FFR SOFT TOP			
000000-007111B1		COMPLETE ANNUAL INSPECTION (FMT 932W) IAW AESP 2300-A-050-013	Closed	Fully Fit	No	Level 2		08 May 2012	N/A	Closed No Action	TUM FFR SOFT TOP			
000000-006DE741		RENEW BOTH STEERING SHAFT U/J	Closed	Fully Fit	No	Level 2		17 Nov 2011	N/A	Damage	TUM FFR SOFT TOP			
000000-006DE73A		RENEW SUSPENSION PANHARD BUSHES	Closed	Fully Fit	No	Level 2		17 Nov 2011	N/A	Damage	TUM FFR SOFT TOP			

000000-006DDE5A	RENEW REAR EXHAUST SILENCER BOX	Closed	Fully Fit	No	Level 2	16 Nov 2011	N/A	Damage	TUM FFR SOFT TOP
000000-006DDE09	RENEW L/H REAR SHOCK ABSORBER BUSHES	Closed	Fully Fit	No	Level 2	16 Nov 2011	N/A	Damage	SOFT TOP TUM FFR
000000-006DD53A	RENEW REAR PROP SHAFT, REAR U/J	Closed	Fully Fit	No	Level 2	15 Nov 2011	N/A	Damage	SOFT TOP TUM FFR
000000-006DA00F	COMPLETE ANNUAL INSPECTION (AFG932B) IAW AESP 2300-A-050-013	Closed	Fully Fit	No	Level 2	03 Nov 2011	N/A	Inspection	SOFT TOP TUM FFR
000000-006DA003	COMPLETE UNIT B VEHICLE INSPECTION (AFB6534) IAW AESP 2300-A-050-013	Closed	Fully Fit	No	Level 1	03 Nov 2011	N/A	Inspection	SOFT TOP TUM FFR
000000-006DA00B	COMPLETE ROLLING ROAD BRAKE TEST IAW AESP 2300-A-050-013	Closed	Fully Fit	No	Level 2	03 Nov 2011	N/A	Inspection	SOFT TOP TUM FFR
000000-006D9FFE	COMPLETE L2 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 8	Closed	Fully Fit	No	Level 2	03 Nov 2011	N/A	Servicing	SOFT TOP TUM FFR
000000-006D9FF5	COMPLETE L1 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 8	Closed	Fully Fit	No	Level 1	03 Nov 2011	N/A	Servicing	SOFT TOP
000000-004A2473	CHANGE BRAKE FLUID IAW AESP 2320-D-122-601, TABLE 7, SERIAL 64(DUE 25-11-2011 OR 146608 ACCUMLATIVE KMS)	Closed	Fully Fit	No	Level 2	25 Nov 2009	N/A	Servicing	TUM FFR SOFT TOP
000000-0049FB68	OOPS 2 YEARLY/20000 KMS, CHANGE ENGINE OIL AND FILTER IAW AESP 2320-D-122-601, TABLE 5, SERIAL 2(DUE 20-11-2011 OR 126608 ACCUMLATIVE KMS)	Closed	Fully Fit	No	Level 1	20 Nov 2009	N/A	Servicing	TUM FFR SOFT TOP TUM FFR
000000-006D3D33	INSPECT STEERING DROP ARM TAB WASHER	Closed	Fully Fit	No	Level 2	17 Oct 2011	N/A	Inspection	SOFT TOP TUM FFR
000000-0060B495	REPAIR DAMAGE TO FRONT WINDSCREEN	Closed	Fully Fit	No	Level 2	02 Jun 2011	N/A	Damage	SOFT TOP TUM FFR
000000-0060B4D8	RENEW SPLIT FRONT L/H RADIUS ARM BUSH	Closed	Non-Taskworthy	No	Level 2	02 Jun 2011	N/A	Failure	SOFT TOP TUM FFR
000000-0060BC88	ADJUST TAILBOARD	Closed	Fully Fit	No	Level 2	06 Jun 2011	N/A	Failure	SOFT TOP TUM FFR
000000-005F3CB1	COMPLETE UNIT B VEHICLE INSPECTION (AFB6534) IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 1	03 May 2011	N/A	Inspection	SOFT TOP TUM FFR
000000-005F3CAA	COMPLETE ROLLING ROAD BRAKE TEST IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2	03 May 2011	N/A	Servicing	SOFT TOP TUM FFR
000000-005F3CA1	COMPLETE L2 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 6	Closed	Non-Taskworthy	No	Level 2	03 May 2011	N/A	Servicing	SOFT TOP TUM FFR
000000-005F3C99	COMPLETE L1 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 6	Closed	Non-Taskworthy	No	Level 1	03 May 2011	N/A	Servicing	SOFT TOP TUM FFR
000000-005C6625	RENEW HAZARD SWITCH HOLDER	Closed	Fully Fit	No	Level 2	25 Nov 2010	N/A	Damage	SOFT TOP TUM FFR
000000-005C6634	000000-002D2869 RECTIFY INOP BATTERY CHARGING WARNING LIGHT	Closed	Fully Fit	No	Level 2	25 Nov 2010			SOFT TOP TUM FFR
000000-005C6621	000000-002D2869 RENEW CLUTCH PEDAL PAD	Closed	Fully Fit	No	Level 1	25 Nov 2010			SOFT TOP TUM FFR
000000-004A15B6	000000-002D2869 RENEW R/H CHASSIS TO ENGINE EARTH STRAP	Closed	Fully Fit	No	Level 2	24 Nov 2009			SOFT TOP TUM FFR
000000-005AEE43	002CD552 COMPLETE UNIT B VEHICLE INSPECTION (AFB6534) IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 1	01 Nov 2010			SOFT TOP

000000-005AEE42	000000-002CD552	COMPLETE ANNUAL INSPECTION (AFG932B) IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2	01 Nov 2010	TUM FFR SOFT TOP
000000-005AEE3F	000000-002CD552	COMPLETE ROLLING ROAD BRAKE TEST IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2	01 Nov 2010	TUM FFR SOFT TOP
000000-005AEE3C	000000-002CD552	COMPLETE L2 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 7	Closed	Non-Taskworthy	No	Level 2	01 Nov 2010	TUM FFR SOFT TOP
000000-005AEE37	000000-002CD552	COMPLETE L1 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 7	Closed	Non-Taskworthy	No	Level 1	01 Nov 2010	TUM FFR SOFT TOP
000000-00595688	000000-002C7430	RENEW EXHAUST MANIFOLD	Closed	Fully Fit	No	Level 2	28 Sep 2010	TUM FFR SOFT TOP
000000-0054570D	000000-002C7430	OVERHAUL ENGINE CYLINDER HEAD	Closed	Non-Taskworthy	No	Level 2	04 Aug 2010	TUM FFR SOFT TOP
000000-005441AF	000000-002C7430	RECTIFY SLIGHT EXHAUST MANIFOLD LEAK	Closed	Fully Fit	No	Level 2	02 Aug 2010	TUM FFR SOFT TOP
000000-00236771	000000-002C7430	OOPS 5 YEARLY, COOLING SYSTEM: DRAIN, FLUSH AND REPLENISH IAW AESP 2320-D-122-601, TABLE 5, SERIAL	Closed	Fully Fit	No	Level 1	04 Aug 2008	TUM FFR SOFT TOP
000000-004E8E87	000000-002C016D	RENEW BOTH LOWER DOOR SEALS	Closed	Fully Fit	No	Level 2	23 Mar 2010	TUM FFR SOFT TOP
000000-005441A5	000000-002BFE6F	FIT MISSING REAR CANOPY STRAP	Closed	Fully Fit	No	Level 1	02 Aug 2010	TUM FFR SOFT TOP
000000-0054419E	000000-002BEFF9	FIT MISSING ACCELERATOR PEDAL PAD	Closed	Fully Fit	No	Level 1	02 Aug 2010	TUM FFR SOFT TOP
000000-00544199	000000-002BEFF9	REMOVE WATER FROM R/H HEADLIGHT	Closed	Non-Taskworthy	No	Level 1	02 Aug 2010	TUM FFR SOFT TOP
000000-00532F9A	000000-002BB996	RENEW 90 AMP ALTERNATOR BELT	Closed	Fully Fit	No	Level 2	12 Jul 2010	TUM FFR SOFT TOP
000000-0050D817	000000-002B4D1D	RENEW R/H WIPER BLADE (RDI)	Closed	Fully Fit	No	Level 1	24 May 2010	TUM FFR SOFT TOP
000000-0050D816	000000-002B4D1D	ADJUST FAN BELT (RDI)	Closed	Fully Fit	No	Level 2	24 May 2010	TUM FFR SOFT TOP
000000-0050021F	000000-002B18A8	COMPLETE ROLLING ROAD BRAKE TEST IAW AESP 2300-A-050-013	Closed	Fully Fit	No	Level 2	04 May 2010	TUM FFR SOFT TOP
000000-00500205	000000-002B18A8	COMPLETE L2 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 6	Closed	Fully Fit	No	Level 2	04 May 2010	TUM FFR SOFT TOP
000000-00500204	000000-002B18A8	COMPLETE UNIT B VEHICLE INSPECTION (AFB6534) IAW AESP 2300-A-050-013	Closed	Fully Fit	No	Level 1	04 May 2010	TUM FFR SOFT TOP
000000-005001FF	000000-002B18A8	COMPLETE L1 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 6	Closed	Fully Fit	No	Level 1	04 May 2010	TUM FFR SOFT TOP
000000-004F6DAA	000000-002AF851	TIGHTEN L/H MIRROR ARM	Closed	Fully Fit	No	Level 2	19 Apr 2010	TUM FFR SOFT TOP
000000-004E9EDC	000000-002AD3C1	REPAIR FUEL LEAKS FROM THE FIP	Closed	Non-Taskworthy	No	Level 2	24 Mar 2010	TUM FFR SOFT TOP
000000-004E8DDF	000000-002ACFBF	RENEW FLASHER UNIT	Closed	Fully Fit	No	Level 2	23 Mar 2010	TUM FFR SOFT TOP
000000-004C27FE	000000-002A8235	FIT MISSING REAR CANOPY RAIL HEAD PROTECTION PAD	Closed	Fully Fit	No	Level 1	28 Jan 2010	TUM FFR SOFT TOP
000000-004A72EF	000000-002A0A56	REPAIR LEAKING FIP	Closed	Non-Taskworthy	No	Level 2	03 Dec 2009	TUM FFR SOFT TOP
000000-0023675B	000000-002A0A56	REPLACE CAMSHAFT TIMING BELT IAW AESP 2320-D-122-601, TABLE 5, SERIAL 3(DUE 20-11-2012 OR 175507	Closed	Fully Fit	No	Level 2	04 Aug 2008	TUM FFR SOFT TOP

000000-004807C4	000000-002A23C2	RENEW 24V ALTERNATOR ADJUSTING ROD	Closed	Fully Fit	No	Level 2	18 Dec 2009	TUM FFR SOFT TOP
000000-004A4214	000000-0029FEA0	RENEW STEERING LINKAGE No. 2 BALL JOINT	Closed	Non-Taskworthy	No	Level 2	27 Nov 2009	TUM FFR SOFT TOP
000000-004A420F	000000-0029FEA0	RENEW STEERING BOX DROP ARM BALL JOINT	Closed	Non-Taskworthy	No	Level 2	27 Nov 2009	TUM FFR SOFT TOP
000000-004A420B	000000-0029FEA0	ADJUST HANDBRAKE CABLE	Closed	Fully Fit	No	Level 2	27 Nov 2009	TUM FFR SOFT TOP
000000-004A27AA	000000-0029FEA0	ADJUST STEERING BOX FREEPLAY	Closed	Fully Fit	No	Level 2	25 Nov 2009	TUM FFR SOFT TOP
000000-004A15BD	000000-0029FEA0	RENEW TRANSMISSION BRAKE SHOES SPRINGS	Closed	Fully Fit	No	Level 2	24 Nov 2009	TUM FFR SOFT TOP
000000-004A15BC	000000-0029FEA0	RENEW TRANSMISSION BRAKE SHOES	Closed	Fully Fit	No	Level 2	24 Nov 2009	TUM FFR SOFT TOP
000000-004A15BA	000000-0029FEA0	RENEW ENGINE FUEL INJECTORS	Closed	Fully Fit	No	Level 2	24 Nov 2009	TUM FFR SOFT TOP
000000-004A0ACF	000000-0029FEA0	RENEW ENGINE ROCKER SHAFT ARMS	Closed	Fully Fit	No	Level 2	23 Nov 2009	TUM FFR SOFT TOP
000000-0049203B	000000-0029CB09	COMPLETE ANNUAL INSPECTION (AFG932B) IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2	02 Nov 2009	TUM FFR SOFT TOP
000000-00492038	000000-0029CB09	COMPLETE ROLLING ROAD BRAKE TEST IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2	02 Nov 2009	TUM FFR SOFT TOP
000000-00492036	000000-0029CB09	COMPLETE L2 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 8	Closed	Non-Taskworthy	No	Level 2	02 Nov 2009	TUM FFR SOFT TOP
000000-00492034	000000-0029CB09	COMPLETE L1 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 8	Closed	Non-Taskworthy	No	Level 1	02 Nov 2009	TUM FFR SOFT TOP
000000-002367AB	000000-0029CB09	CHANGE BRAKE FLUID IAW AESP 2320-D-122-601, TABLE 7, SERIAL 64(DUE 20-11-2009 OR 135507	Closed	Non-Taskworthy	No	Level 2	04 Aug 2008	TUM FFR SOFT TOP
000000-00236720	000000-0029CB09	CHANGE ENGINE OIL AND FILTER IAW AESP 2320-D-122-601, TABLE 5, SERIAL 2(DUE 20-11-2009 OR 115507	Closed	Non-Taskworthy	No	Level 1	04 Aug 2008	TUM FFR SOFT TOP
000000-004A05EE	000000-0029F26E	RENEW TRANSFERE BOX OIL LEVEL PLUG	Closed	Fully Fit	No	Level 1	23 Nov 2009	TUM FFR SOFT TOP
000000-004A05ED	000000-0029F26E	RENEW No. 3 & 4 STEERING BALL JOINTS	Closed	Fully Fit	No	Level 2	23 Nov 2009	TUM FFR SOFT TOP
000000-0049E32A	000000-0029F095	RENEW FRONT SUSPENSION RADIUS ARM BUSHES	Closed	Fully Fit	No	Level 2	18 Nov 2009	TUM FFR SOFT TOP
000000-0049E325	000000-0029F095	RENEW ENGINE SUMP GASKET	Closed	Fully Fit	No	Level 2	18 Nov 2009	TUM FFR SOFT TOP
000000-0049A335	000000-0029E206	RENEW ENGINE BREATHER PIPE, OIL FILLER CAP TO CYCLONE VALVE	Closed	Fully Fit	No	Level 2	12 Nov 2009	TUM FFR SOFT TOP
000000-0049A32F	000000-0029E206	RENEW R/H DOOR TOP SLIDING GLASS FELTS	Closed	Fully Fit	No	Level 2	12 Nov 2009	TUM FFR SOFT TOP
000000-001A8D79	000000-0029BD8D	RENEW SPARE WHEEL RIM	Closed	Non-Fully Fit	No	Level 1	09 Jun 2008	TUM FFR SOFT TOP
000000-003DE9A7		Insufficient Data	Closed	Non-Taskworthy	No	Level 1	10 Mar 2009	TUM FFR SOFT TOP
000000-0018CA78	000000-00286DAA	RENEW HEATER SELECTOR CONTROL	Closed	Fully Fit	No	Level 2	22 May 2008	TUM FFR SOFT TOP
000000-00339697	000000-00286DAA	RENEW BRAKE PEDAL BUSHES	Closed	Fully Fit	No	Level 2	25 Nov 2008	TUM FFR SOFT TOP

000000-0033986A	000000-00286797	FIT MISSING REAR CANOY SECURING STRAP	Closed	Fully Fit	No	Level 1	26 Nov 2008	TUM FFR SOFT TOP
000000-002E5544	000000-00284484	COMPLETE L1 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 7	Closed	Non-Taskworthy	No	Level 1	03 Nov 2008	TUM FFR SOFT TOP
000000-002E82BC	000000-00284484	COMPLETE L2 MAINTENANCE IAW AESP 2320-D-122-601, TABLE 7,COLUMN 7	Closed	Non-Taskworthy	No	Level 2	04 Nov 2008	TUM FFR SOFT TOP
000000-002E82D1	000000-00284484	COMPLETE ROLLING ROAD BRAKE TEST IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2	04 Nov 2008	TUM FFR SOFT TOP
000000-002E82E7	000000-00284484	COMPLETE ANNUAL INSPECTION (AFG932B) IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2	04 Nov 2008	TUM FFR SOFT TOP
000000-00339691	000000-00285903	ADJUST L/H FRONT HUB BEARINGS	Closed	Fully Fit	No	Level 2	25 Nov 2008	TUM FFR SOFT TOP
000000-00339692	000000-00285903	ADJUST L/H REAR HUB BEARINGS	Closed	Fully Fit	No	Level 2	25 Nov 2008	TUM FFR SOFT TOP
000000-003396C9	000000-002857BF	RENEW L/H FRONT TYRE	Closed	Non-Taskworthy	No	Level 1	25 Nov 2008	TUM FFR SOFT TOP
000000-002D1338	000000-00283444	RENEW L/H WINDSCREEN WIPER ARM	Closed	Non-Taskworthy	No	Level 1	23 Oct 2008	TUM FFR SOFT TOP
000000-0018CADC	000000-002836B5	RENEW WINDSCREEN WASHER BOTTLE CAP	Closed	Fully Fit	No	Level 1	22 May 2008	TUM FFR SOFT TOP
000000-0021590C	000000-0027E959	DRIVER SIDE WINDSCREEN WIPER ARM DISCONNECTED FROM MOTOR SHAFT	Closed	Non-Taskworthy	No	Level 2	18 Jul 2008	TUM FFR SOFT TOP
000000-00216217	000000-0027E959	RENEW R/H WINDSCREEN WIPER ARM	Closed	Non-Taskworthy	No	Level 1	21 Jul 2008	TUM FFR SOFT TOP
000000-0018CA28	000000-0027C51C	INVESTIGATE CLUTCH MECHANISM	Closed	Non-Taskworthy	No	Level 3	22 May 2008	TUM FFR SOFT TOP
000000-0018CA50	000000-0027C7B4	RENEW REAR PROP SHAFT, FRONT UJ	Closed	Non-Taskworthy	No	Level 2	22 May 2008	TUM FFR SOFT TOP
000000-0018CA64	000000-0027C7B4	RENEW REAR BRAKE PADS	Closed	Non-Taskworthy	No	Level 2	22 May 2008	TUM FFR SOFT TOP
000000-0018CAA0	000000-0027C51A	OVERHAUL RADIO BATTERY BOX	Closed	Fully Fit	No	Level 2	22 May 2008	TUM FFR SOFT TOP
000000-0018BEFC		Initial Usage	Closed	Fully Fit	No	Level 1	22 May 2008	TUM FFR SOFT TOP
000000-0018BF85		Initial Maintenance	Closed	Fully Fit	No	Level 1	22 May 2008	TUM FFR SOFT TOP



Work Objects

Serial Number: CE97AA  
 NSN: 2320998939106

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0019C473		No	MEI (2)	16 Nov 2012	Level 2			000:00		
000000-0019C58A		No	6 Monthly 6534 Insp	23 Nov 2012	Level 1			000:00		
000000-00164ACE		No	6 Monthly 6534 Insp	23 Nov 2012	Level 1			000:00		
000000-001E1589		No	6 Monthly 6534 Insp	23 Nov 2012	Level 1			000:00		
000000-000B6671		No	MEI (2)	16 Nov 2012	Level 2		CL	000:00		
000000-000E118A		No	MEI (2)	16 Nov 2012	Level 2		CL	000:00		
000000-000720CD		No	MEI (2)	16 Nov 2012	Level 2		CL	000:00		

Work Objects

Serial Number: CE97AA  
 NSN: 2320998939106

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service	Modification Type	Apply When Usage Equals	Embodiment Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0001A81F	00026	Wheel Rim Change		No	-/	RTI				Fully Fit	CL				

Work Objects

Serial Number: CE97AA  
 NSN: 2320998939106

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated	Working Organisation	Repair Section
								Repair Time		
000000-0010BB02		No	80000 Kms (2)	11 Aug 2030	Level 1			000:00		
000000-0016124E		No	6 Monthly/10000 Kms	23 Nov 2012	Level 1			000:00		
000000-001E1478		No	6 Monthly/10000 Kms	23 Nov 2012	Level 1			000:00		
000000-0019C46B		No	2 Yearly/40000 Kms	16 Nov 2013	Level 1			000:00		
000000-000720CA		No	Yearly/20000 Kms	16 Nov 2012	Level 1		CL	000:00		
000000-000720CB		No	6 Monthly/10000 Kms	23 Nov 2012	Level 1		CL	000:00		
000000-000A9FD6		No	Yearly/20000 Kms	16 Nov 2012	Level 1		CL	000:00		
000000-000EFD6B		No	6 Monthly/10000 Kms	23 Nov 2012	Level 1		CL	000:00		
000000-00025A77		No	6 Monthly/10000 Kms	23 Nov 2012	Level 1		CL	000:00		
000000-0002E446		No	2 Yearly/40000 Kms	16 Nov 2013	Level 1		CL	000:00		
000000-0002E447		No	6 Monthly/10000 Kms	23 Nov 2012	Level 1		CL	000:00		
000000-0002E448		No	Yearly/20000 Kms	16 Nov 2012	Level 1		CL	000:00		
000000-000EBB18		No	6 Monthly/10000 Kms	23 Nov 2012	Level 1		CL	000:00		
000000-0010BAEA		No	36000 Kms (2)	18 Jul 2026	Level 2			000:00		

000000-0019C46C	No	Yearly/20000 Kms	16 Nov 2012	Level 1	000:00
000000-0019C46D	No	6 Monthly/10000 Kms	23 Nov 2012	Level 1	000:00