



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]

Our Reference:
FOI2023/09791
Date:
23 August 2023

Dear [REDACTED]

I am writing about your email of 09 August 2023, requesting the following information:

Could you please supply me with the operational and service history for the following Land Rover Defender:

*ERM: KB05AA
Chassis Number: SALLDAA67VA125255
TRUCK UTILITY LIGHT TUL H 4X4
LAND ROVER FFR HARD TOP 2.5LTR TURBO DSL*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History
- Annex E – Servicing History (redacted)

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault and Modification Histories (annexes B and D) relate to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the

Defence Equipment & Support

MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
KB05AA	2320998939742	NB42253100	LV2A/088AM3	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
16/10/1997	SALLDAA67VA125255	25L03035A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KB05AA	3	15/10/1997	CA005A	JSCS ASHCHURCH	CAPITA	29501AA	16/10/1997	
KB05AA	4	20/11/1997	A0203A	7 RHA	35018A	1978	27/01/1998	
KB05AA	4	15/05/2006	A8314A	CSAT-OP HERRICK ACCOUNTS	181	1388	02/07/2006	H/T
KB05AA	4	26/07/2006	A8313A	CF BURMA - (CSAT OP HERRICK)	999	2603	26/07/2006	X43
KB05AA	2	22/01/2007	A0203A	7 RHA	999	1844	22/01/2007	Y04
KB05AA		28/07/2015		RAF ODIHAM STN MT			28/07/2015	
KB05AA		30/06/2020		OSVP HOLDINGS			06/07/2020	

Work Objects

Serial Number: KB05AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00B61F38		REPLACE REAR LOWER LINK BUSHES	Closed	Non-Taskworthy	No	Level 2		09 Sep 2019	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00B61F30		REPLACE BOTH FRONT RADIUS ARM BUSHES	Closed	Non-Taskworthy	No	Level 2		09 Sep 2019	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00B41CF1		Post Mod 1	Closed	Fully Fit	No	Level 2		06 Jun 2019	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00B2B5BE		Restore surface finish to F/N/S panel	Closed	Fully Fit	No	Level 2		23 Apr 2019	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00B2D95C		non start	Closed	Fully Fit	No	Level 2		30 Apr 2019	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00B220DC		SNvE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B	29 Mar 2019	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00B1F4E6		SNvE 377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697A	29 Mar 2019	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00AF7D52		Replace U/S Front shock absorbers	Closed	Fully Fit	No	Level 2		22 Nov 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00AEDEBA		Post MEI faults	Closed	Fully Fit	No	Level 2		29 Oct 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00AF7D56		Replace track arm	Closed	Fully Fit	No	Level 2		22 Nov 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00ACAD9E		Front wings damaged	Closed	Fully Fit	No	Level 2		20 Jul 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00ACADA4		Front number plate faded	Closed	Fully Fit	No	Level 2		20 Jul 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00ACADAC		O/S bottom sill damaged	Closed	Fully Fit	No	Level 2		20 Jul 2018	N/A	Damage	TUL HS FFR HARD TOP			000:00
000000-00ACAD8A		Front N/S tyre worn	Closed	Fully Fit	No	Level 2		20 Jul 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00ACADB3		Viscous fan excessive play	Closed	Fully Fit	No	Level 2		20 Jul 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00ACADAD		O/S mudguards loose	Closed	Fully Fit	No	Level 2		20 Jul 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00

000000-00ACADB4	Cowling incorrectly fitted	Closed	Fully Fit	No	Level 2	20 Jul 2018	N/A	Failure	TUL HS FFR HARD TOP	000:00	
000000-00ACADA8	Header tank loose	Closed	Fully Fit	No	Level 2	20 Jul 2018	N/A	Failure	TUL HS FFR HARD TOP	000:00	
000000-00ACADA3	A frame ball joint perished	Closed	Fully Fit	No	Level 2	20 Jul 2018	N/A	Failure	TUL HS FFR HARD TOP	000:00	
000000-00ACAD9C	N/S & O/S mirrors loose	Closed	Fully Fit	No	Level 2	20 Jul 2018	N/A	Failure	TUL HS FFR HARD TOP	000:00	
000000-00AE6FF3	Post GSMOD 1 faults	Closed	Fully Fit	No	Level 2	10 Oct 2018	N/A	Failure	TUL HS FFR HARD TOP	000:00	
000000-00ACADB8	Rear springs excessively compressed	Closed	Non- Taskworthy	No	Level 2	20 Jul 2018	N/A	Closed No Action	TUL HS FFR HARD TOP	000:00	
000000-00A0F241	HEATER ASSEMBLY U/S	Closed	Fully Fit	No	Level 2	21 Mar 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00873EE5	REQUIRES MODs 41, 42, 44 EMBODIMENT.	Closed	Fully Fit	No	Level 2	11 Feb 2015	N/A	Closed No Action	TUL HS FFR HARD TOP		
000000-007B0A54	FFR BATTERIES NOT FITTED	Closed	Limited Role	No	Level 1	30 Aug 2013	N/A	Closed No Action	TUL HS FFR HARD TOP		
000000-00A263E5	RECTIFY DAMAGE TO FRONT N/S BODY PANEL	Closed	Fully Fit	No	Level 2	23 May 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A263E3	SECURE FFR BATTERIES IN REAR OF VEHICLE	Closed	Fully Fit	No	Level 2	23 May 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A263E1	RECTIFY PLAY IN PASS DOOR TOP HINGE	Closed	Fully Fit	No	Level 2	23 May 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A263DF	RECTIFY PLAY IN DVRS DOOR HINGES	Closed	Fully Fit	No	Level 2	23 May 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A263DD	RENEW F/L/H HEADLIGHT GRILL	Closed	Fully Fit	No	Level 2	23 May 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A263D9	RENEW F/R/H MUDGUARD	Closed	Fully Fit	No	Level 2	23 May 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A263D7	RENEW F/R/H TRACTA SEAL	Closed	Non- Taskworthy	No	Level 2	23 May 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A263D5	RECTIFY SLIGHT OIL LEAK ON R/H/S ENGINE	Closed	Non- Taskworthy	No	Level 2	23 May 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A263D3	RECTIFY F/R/H SIDE LIGHT INOP	Closed	Taskworthy	No	Level 2	23 May 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A414E4	Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field	Closed	Limited Role	No	Level 2	000000- 0000451A	28 Jul 2017	N/A	Closed No Action	TUL HS FFR HARD TOP	
000000-009CCEA0	PLEASE CARRYOUT RE-SPRAY	Closed	Fully Fit	No	Level 2	02 Oct 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00A0B2B2	RECTIFY DAMAGED FUEL PIPE CONNECTOR TO SEDIMENTER	Closed	Non- Taskworthy	No	Level 2	09 Mar 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A02A0D	ADJUST H/BRAKE	Closed	Non- Taskworthy	No	Level 2	15 Feb 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-009FAA57	O/S/F SUSPENSION KNOCKING	Closed	Limited Role Non-	No	Level 2	27 Jan 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-009CCE9D	FRH SHOCK BUSH DAMAGED	Closed	Non- Taskworthy	No	Level 2	03 Oct 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-009CCE98	FRH TYRE DAMAGED	Closed	Non- Taskworthy	No	Level 2	03 Oct 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-009A877A	BOTH FRONT SHOCKS U/S	Closed	Non- Taskworthy	No	Level 2	22 Jun 2016	N/A	Damage	TUL HS FFR HARD TOP		

000000-0098E2D8	COOLANT HOSE LEAK	Closed	Non-Taskworthy	No	Level 2	28 Apr 2016	N/A	Failure	TUL HS FFR	
000000-0098C2A1	VEHICLE BATTERIES NOT CHARGING	Closed	Non-Taskworthy	No	Level 2	27 Apr 2016	N/A	Failure	HARD TOP TUL HS FFR	
000000-0098ACAF	WIRE BEHIND N/S HEADLIGHT SHEERED OFF	Closed	Non-Taskworthy	No	Level 2	22 Apr 2016	N/A	Failure	HARD TOP TUL HS FFR	
000000-009822DD	VEH JACK NOT PRESENTED - CAMP USE ONLY	Closed	Fully Fit	No	Level 1	30 Mar 2016	N/A	Inspection	HARD TOP TUL HS FFR	
000000-009822DB	FIRE EXT EXPIRED - CAMP USE ONLY	Closed	Fully Fit	No	Level 1	30 Mar 2016	N/A	Inspection	HARD TOP TUL HS FFR	
000000-009822E0	RECERT INSP REP UPON COMP OF NTW FAULTS (BY 27/04/16)	Closed	Fully Fit	No	Level 2	30 Mar 2016	N/A	Inspection	HARD TOP TUL HS FFR	
000000-009822D8	RECTIFY HEADLIGHT ALIGNMENT	Closed	Fully Fit	No	Level 2	30 Mar 2016	N/A	Inspection	HARD TOP TUL HS FFR	
000000-009822D6	RECTIFY POOR REAR BRAKE PERFORMANCE	Closed	Non-Taskworthy	No	Level 2	30 Mar 2016	N/A	Inspection	HARD TOP TUL HS FFR	
000000-008ADA8A	Vehicle Re-Spray	Closed	Fully Fit	No	Level 2	19 Jul 2015	N/A	Closed No Action	TUL HS FFR HARD TOP	
000000-00962225	Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003210	20 Jan 2016	N/A	Closed No Action	TUL HS FFR HARD TOP
000000-00960104	Inspect No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	18 Jan 2016	No Effect	Inspection	TUL HS FFR HARD TOP	
000000-008BD0F4	FRONT SUSPENSION LEANING	Closed	Fully Fit	No	Level 2	01 Sep 2015	N/A	Inspection	TUL HS FFR HARD TOP	
000000-008BD0EB	RADIATOR DAMAGED	Closed	Fully Fit	No	Level 2	01 Sep 2015	N/A	Damage	TUL HS FFR HARD TOP	
000000-008C85FE	P/S FLUID LEAKING	Closed	Non-Taskworthy	No	Level 2	21 Sep 2015	N/A	Inspection	TUL HS FFR HARD TOP	
000000-008BFE53	SPARE WHEEL MOUNT SUPPORT STRAP U/S	Closed	Fully Fit	No	Level 2	09 Sep 2015	N/A	Failure	TUL HS FFR HARD TOP	
000000-0088B378	O/S REAR TYRE REQUIRES REPLACING.	Closed	Non-Taskworthy	No	Level 2	26 Aug 2015	N/A	Failure	TUL HS FFR HARD TOP	
000000-00855A6F	EGR NOT WORKING	Closed	Fully Fit	No	Level 2	01 Aug 2014	N/A	Closed No Action	TUL HS FFR HARD TOP	
000000-00873EDF	R CLIP MISSING FROM TOWING SWIVEL PIN	Closed	Fully Fit	No	Level 1	11 Feb 2015	N/A	Action	TUL HS FFR HARD TOP	
000000-00873EDB	FUEL CAP REQUIRES PAINTING YELLOW.	Closed	Fully Fit	No	Level 1	11 Feb 2015	N/A	Closed No Action	TUL HS FFR HARD TOP	
000000-00873EDA	DRIVER DOOR EARTH STRAP U/S	Closed	Fully Fit	No	Level 2	11 Feb 2015	N/A	Action	TUL HS FFR HARD TOP	
000000-00855A69	EXHAUST SYSTEM FOULING BODY AND FRAME	Closed	Non-Taskworthy	No	Level 2	01 Aug 2014	N/A	Closed No Action	TUL HS FFR HARD TOP	
000000-00855A65	FAILED SERVICE BRAKES	Closed	Non-Taskworthy	No	Level 2	01 Aug 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00855A5F	O/S/R REFLECTOR MISSING	Closed	Non-Taskworthy	No	Level 2	01 Aug 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00855A64	EXCESSIVE PLAY IN BRAKE PEDAL PIVOT SHAFT/BUSH	Closed	Non-Taskworthy	No	Level 2	01 Aug 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-0079BB78	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUL HS FFR HARD TOP
000000-008442B9	Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUL HS FFR HARD TOP

000000-00855A63		O/S/F SUSPENSION TURRET RUSTY	Closed	Non- Taskworthy	No	Level 2	01 Aug 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00854E7E	000000- 002FF4C7	INVESTIGATE STEERING BOX KNOCKING	Closed	Non- Taskworthy	No	Level 2	18 Nov 2014	N/A	Closed No Action	TUL HS FFR HARD TOP	DSG COLCHESTER		
000000-00855A6B		N/S/F SUSPENSION TUREET STARTING TO RUST	Closed	Fully Fit	No	Level 2	01 Aug 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00771B2E	000000- 002E4F07	EARTHING WIRE SNAPPED FROM DOOR O/S O/S/F SUSPENSION TURRET STARTING TO RUST (OBS)	Closed	Fully Fit	No	Level 2	07 Mar 2013	N/A	Closed No Action	TUL HS FFR HARD TOP	7 RHA	PRODUCTION	
000000-007B0A49			Closed	Fully Fit	No	Level 2	29 Aug 2013	N/A	Damage	TUL HS FFR HARD TOP			
000000-007B0A59		FRONT TOWING PIN NOT PRESENT	Closed	Limited Role	No	Level 1	29 Aug 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007A2613	000000- 002E88F6	MEI	Closed	Fully Fit	No	Level 2	14 Jul 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007B0A57		EMERGENCY HAMMER MOD NOT FITTED	Closed	Limited Role	No	Level 2	30 Aug 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007A2612	000000- 002E88F6	2 YEARLY VM TASKS	Closed	Fully Fit	No	Level 2	15 Jul 2013	N/A	Servicing	TUL HS FFR HARD TOP			
000000-007A2611	000000- 002E88F6	2 YEARLY SERVICE	Closed	Fully Fit	No	Level 1	15 Jul 2013	N/A	Servicing	TUL HS FFR HARD TOP			
000000-0079DADF		KEYS DONT WORK IN THE INGNITION	Closed	Fully Fit	No	Level 2	01 Jul 2013	N/A	Damage	TUL HS FFR HARD TOP			
000000-00798BA3		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Fully Fit	No	Level 1	000000- 0000081A	24 Jun 2013	N/A	Failure	TUL HS FFR HARD TOP		
000000-00781DBA	000000- 002E4F07	NEW FANBELT PUT ON,IT IMMEDIATELY STARTED DESTROYING THE NEW ONE.	Closed	Non- Taskworthy	No	Level 2	23 Apr 2013	N/A	Servicing	TUL HS FFR HARD TOP	7 RHA	PRODUCTION	
000000-0078D835		RENEW WATER PUMP	Closed	Non- Taskworthy	No	Level 2	28 May 2013	N/A	Failure	TUL HS FFR HARD TOP			

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
KB05AA	2320998939742	NB42253100	LV2A/088AM3	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
16/10/1997	SALLDAA67VA125255	25L03035A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KB05AA	3	15/10/1997	CA005A	JSCS ASHCHURCH	CAPITA	29501AA	16/10/1997	
KB05AA	4	20/11/1997	A0203A	7 RHA	35018A	1978	27/01/1998	
KB05AA	4	15/05/2006	A8314A	CSAT-OP HERRICK ACCOUNTS	181	1388	02/07/2006	H/T
KB05AA	4	26/07/2006	A8313A	CF BURMA - (CSAT OP HERRICK)	999	2603	26/07/2006	X43
KB05AA	2	22/01/2007	A0203A	7 RHA	999	1844	22/01/2007	Y04
KB05AA		28/07/2015		RAF ODIHAM STN MT			28/07/2015	
KB05AA		30/06/2020		OSVP HOLDINGS			06/07/2020	

Work Objects

Serial Number: KB05AA
 NSN: 2320998939742

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work		Maintenance Event Name	Next Due Date	Repair		Estimated		Working Organisation	Repair Section
	Request ID	Escalate Work			Level	Fault State	Work Status	Repair Time		
000000-00595261		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	WiP	000:00		
000000-00954DE4		No	Ad Hoc Insp (AR)		Level 1	Fully Fit	CL	000:00		
			FMT932 (W) 6 Monthly							
000000-00B75F72		No	Safety Inspection (2)	12 Mar 2020	Level 2	Fully Fit	CL	000:00		
000000-0071BCCB		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	WiP	000:00		
000000-00A6247C		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
			Annual Smoke Emissions							
000000-00B75F6F		No	Test(2)	11 Oct 2020	Level 2	Fully Fit	CL	000:00		
000000-003E2528		No	MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-0063FB59		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-00A1121D		No	MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-00BAAAD2		No	Ad Hoc Insp (AR)		Level 1	Fully Fit	CL	000:00		
000000-007C4AAD		No	MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-00B9A530		No	Ad Hoc Insp (AR)		Level 1	Fully Fit	CL	000:00		

		Annual Headlight Alignment					
000000-00B75F71	No	Check (2)	11 Oct 2020	Level 2	Fully Fit	CL	000:00
000000-003E24FF	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
		FMT933 (W) Role Equipment					
000000-00B74CFD	No	(2)*	11 Sep 2020	Level 2	Fully Fit	CL	000:00
000000-00259E80	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-00377BA7	No	6 Monthly 6534 Insp		Level 1	Limited Role	CL	000:00
000000-00B74D01	No	FMT931 Comms (2)*	12 Mar 2020	Level 2	Limited Role	CL	000:00
000000-0034E066	No	MEI (2)		Level 2			000:00
000000-00669DFB	No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00
000000-0093E871	No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00
		FMT932 (W) Mandatory					
000000-00B74D06	No	Equipment Inspection (2)*	11 Sep 2020	Level 2	Fully Fit	CL	000:00
000000-009B8465	No	Ad Hoc Insp (AR)		Level 1	Non-Taskworthy	CL	000:00
000000-00B75F70	No	Annual Brake Test (2)	11 Oct 2020	Level 2	Fully Fit	CL	000:00
000000-0034E067	No	6 Monthly 6534 Insp		Level 1			000:00
		FMT934 Functional Check					
000000-00B74D8C	No	(1)*	12 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-0087AF6E	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00

Work Objects

Serial Number: KB05AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embodiment Date	Usage Counter	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-00701458	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-0071A7AD	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Limited Role	CL	Level 2			
000000-007168C5	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Limited Role	CL	Level 2			
000000-00702667	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-00719E91	00033	Rear Door Blackout Blind (FFR Variants) Only		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-006CD47D	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-006F7A14	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F52C2	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F61FD	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F45FC	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F69D3	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-0062A1AB	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-00617CC6	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			

Work Objects

Serial Number: KB05AA
 NSN: 2320998939742

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request		Maintenance Event Name	Next Due Date	Repair		Estimated		Working Organisation	Repair Section
	ID	Escalate Work			Level	Fault State	Work Status	Repair Time		
000000-00595261		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	WiP	000:00		
000000-00954DE4		No	Ad Hoc Insp (AR)		Level 1	Fully Fit	CL	000:00		
			FMT932 (W) 6 Monthly							
000000-00875F72		No	Safety Inspection (2)	12 Mar 2020	Level 2	Fully Fit	CL	000:00		
000000-0071BCCB		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	WiP	000:00		
000000-00A6247C		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
			Annual Smoke Emissions							
000000-00B75F6F		No	Test(2)	11 Oct 2020	Level 2	Fully Fit	CL	000:00		
000000-003E2528		No	MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-0063FB59		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-00A1121D		No	MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-00BAAAD2		No	Ad Hoc Insp (AR)		Level 1	Fully Fit	CL	000:00		
000000-007C4AAD		No	MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-0089A530		No	Ad Hoc Insp (AR)		Level 1	Fully Fit	CL	000:00		
			Annual Headlight Alignment							
000000-00875F71		No	Check (2)	11 Oct 2020	Level 2	Fully Fit	CL	000:00		
000000-003E24FF		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
			FMT933 (W) Role Equipment							
000000-00B74CFD		No	(2)*	11 Sep 2020	Level 2	Fully Fit	CL	000:00		
000000-00259EB0		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-00377BA7		No	6 Monthly 6534 Insp		Level 1	Limited Role	CL	000:00		
000000-00B74D01		No	FMT931 Comms (2)*	12 Mar 2020	Level 2	Limited Role	CL	000:00		
000000-0034E066		No	MEI (2)		Level 2			000:00		
000000-00669DFB		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-0093E871		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
			FMT932 (W) Mandatory							
000000-00B74D06		No	Equipment Inspection (2)*	11 Sep 2020	Level 2	Fully Fit	CL	000:00		
000000-009B8465		No	Ad Hoc Insp (AR)		Level 1	Non-Taskworthy	CL	000:00		
000000-00B75F70		No	Annual Brake Test (2)	11 Oct 2020	Level 2	Fully Fit	CL	000:00		
000000-0034E067		No	6 Monthly 6534 Insp		Level 1			000:00		
			FMT934 Functional Check							
000000-00B74D8C		No	{1)*	12 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-0087AF6E		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		

Work Objects

Serial Number: KB05AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

	Work Request	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-00B6F006	2 ID	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-00249A6F		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	08 Sep 2021	Level 1	Fully Fit	CL	000:00		
000000-0085C4E4		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	08 Sep 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-0085C4D3		No	2 Yearly/40000 Kms	08 Sep 2021	Level 1	Taskworthy	CL	000:00		
000000-004D921E		No	Weekly (AR)(1)		Level 1			000:00		
000000-007B3D19		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	08 Sep 2021	Level 1	Non-Taskworthy	CL	000:00		

000000-006E937E	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	10 Aug 2021	Level 2	Fully Fit	CL	000:00
000000-00591CC5	No	2 Yearly/40000 Kms	08 Sep 2021	Level 1	Non- Taskworthy	CL	000:00
000000-0063FB58	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Taskworthy	CL	000:00
000000-00A11342	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-00863CC3	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	08 Sep 2021	Level 1	Non- Taskworthy	CL	000:00
000000-00B2D083	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	08 Sep 2021	Level 1	Fully Fit	CL	000:00
000000-007B3D1C	No	Yearly/20000 Kms	08 Sep 2020	Level 1	Non- Taskworthy	CL	000:00
000000-007B3D1B	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	08 Sep 2021	Level 1	Non- Taskworthy	CL	000:00
000000-00259EB1	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1		CW	
000000-0085C4E3	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	08 Sep 2021	Level 1	Fully Fit	CL	000:00
000000-00B6EFD2	No	Yearly/20000 Kms	08 Sep 2020	Level 1	Non- Taskworthy	CL	000:00
000000-003E2525	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-00377B9F	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Limited Role	CL	000:00
000000-00257942	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-002491F5	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	10 Feb 2020	Level 1	Fully Fit	CL	000:00

		OOPS 2 Yearly/40000 Kms					
000000-00B2D082	No	Replace Air Cleaner Element (1)	08 Sep 2021	Level 1	Fully Fit	CL	000:00
000000-00A1121E	No	Yearly/20000 Kms	08 Sep 2020	Level 1	Fully Fit	CL	000:00
					Non-		
000000-00863CC6	No	Yearly/20000 Kms	08 Sep 2020	Level 1	Taskworthy	CL	000:00
000000-00B2D098	No	2 Yearly/40000 Kms	08 Sep 2021	Level 1	Fully Fit	CL	000:00
000000-002CF6FC	No	2 Yearly/40000 Kms	08 Sep 2021	Level 1			000:00
		OOPS 2 Yearly/40000 Kms					
000000-00249A6E	No	Replace Air Cleaner Element (1)	08 Sep 2021	Level 1	Fully Fit	CL	000:00
000000-003F671F	No	Weekly (AR)(1)		Level 1			000:00
		OOPS 5 Yearly Drain/Flush And					
000000-003E252C	No	Replen Cooling System	10 Feb 2020	Level 1	Fully Fit	CL	000:00
000000-00907C38	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Fully Fit	CL	000:00
		OOPS 2 Yearly/40000 Kms					
000000-004D8E96	No	Replace Air Cleaner Element (1)	08 Sep 2021	Level 1			000:00
					Non-		
000000-00863CC4	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Taskworthy	CL	000:00
000000-003E2505	No	Yearly/20000 Kms	08 Sep 2020	Level 1	Fully Fit	CL	000:00
		OOPS 6 Yearly/120000 Kms					
000000-00A9E561	No	Camshaft Timing Belt (2)	14 Apr 2025	Level 2	Fully Fit	CL	000:00
		OOPS 2 Yearly/20000 Kms Drain					
000000-002491F4	No	Engine Oil And Filter Change (1)	08 Sep 2021	Level 1	Fully Fit	CL	000:00
					Non-		
000000-007B3D1A	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Taskworthy	CL	000:00
		OOPS 2 Yearly/20000 Kms Drain			Non-		
000000-00863CC5	No	Engine Oil And Filter Change (1)	08 Sep 2021	Level 1	Taskworthy	CL	000:00

000000-003E252B	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	08 Sep 2021	Level 1	Fully Fit Non-	CL	000:00
000000-007B3D24	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Taskworthy	CL	000:00
000000-002CFCFD	No	Yearly/20000 Kms	08 Sep 2020	Level 1			000:00
000000-002491F6	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	10 Aug 2021	Level 2	Non- Taskworthy	CL	000:00
000000-002491F1	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	08 Sep 2021	Level 1	Fully Fit Non-	CL	000:00
000000-0059521F	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Taskworthy	CL	000:00
000000-00A9E56B	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-006E937D	No	Yearly/20000 Kms	08 Sep 2020	Level 1	Fully Fit Non-	CL	000:00
000000-0059521E	No	Yearly/20000 Kms	08 Sep 2020	Level 1	Taskworthy Non-	CL	000:00
000000-007B3CFD	No	2 Yearly/40000 Kms OOPS 6 Yearly/120000 Kms	08 Sep 2021	Level 1	Taskworthy	CL	000:00
000000-00249A70	No	Camshaft Timing Belt (2)	14 Apr 2025	Level 2	Fully Fit	CL	000:00
000000-006ED6FF	No	6 Monthly/10000 Kms	09 Mar 2020	Level 1	Fully Fit	CL	000:00