



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[Redacted]

email: [Redacted]

Our Reference:
FOI2023/10174
Date:
23 August 2023

Dear [Redacted]

I am writing about your email of 21 August 2023, requesting the following information:

I would like to trace the history of these vehicles and learn more about their Army service record and maintenance history.

*Service registration number: PJ 98 AA
Model: Defender Wolf (LWB)
Description: TUM HS FFR SOFT TOP*

*Service registration number: KK 69 AA
Model: Defender Wolf (LWB)
Description: TUM HS FFR HARD TOP*

Any information or photographs you can provide me will be greatly appreciated.

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History of KK69AA
- Annex B – Fault History of KK69AA (redacted)
- Annex C – Inspection History of KK69AA
- Annex D – Modification History of KK69AA (redacted)
- Annex E – Servicing History of KK69AA
- Annex F – Owner History of PJ98AA
- Annex G – Fault History of PJ98AA (redacted)
- Annex H – Inspection History of PJ98AA
- Annex I – Servicing History of PJ98AA

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault History (Annex B) and Modification History (Annex D) of KK69AA and the Fault History of PJ98AA (Annex G) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

Defence Equipment & Support

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
KK69AA	2320998939744	NB50203100	LV2A/088DUM	TRUCK UTY MED (TUM) (HS) 4X4 FFR HARD TOP LAND ROVER 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
30/07/1997	SALLDBA67VA112726	25LO1346A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KK69AA	3	29/07/1997	CA005A	JSCS ASHCHURCH	CAPITA	28095AA	30/07/1997	
KK69AA	4	11/09/1997	A0419A	30 SIG REGT	33295A	1101	16/09/1997	
KK69AA	4	08/03/2010	A0413C	1SIG-200SQN	131	40608	15/04/2010	A85
KK69AA	4	01/09/2010	A0565A	1YORKS-MUNSTER	25612	104976	15/09/2010	B16
KK69AA	2	18/07/2013	A5992D	TFSU (G)	999	999	18/07/2013	
KK69AA		26/04/2018		2 SIG REGT 215 SIG SQN			22/05/2018	
KK69AA		23/05/2018		21 SIG REGT			23/05/2018	
KK69AA		16/01/2019		AI BDE MT			16/01/2019	
KK69AA		20/01/2019		21 SIG REGT			30/01/2019	
KK69AA		20/01/2020		OSVP HOLDINGS			28/01/2020	

Work Objects

Serial Number: KK69AA
 NSN: 2320998939744

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault	Fault	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated
							Group ID	Occurrence Date						Repair Time
000000-00B200EB		SNve 377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697A	29 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AB7A51		FIRE EXTINGUISHER OUT OF DATE	Closed	Limited Role	No	Level 1		31 May 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AB79D3		Left hand shock absorbers worn excessively	Closed	Fully Fit	No	Level 2		30 May 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AB7134		PLEASE CARRY OUT ADHOC INSPECTION	Awaiting Labour	Non-Taskworthy	No	Level 2		30 May 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AA1D92		RHR & SPARE TYRES U/S	Closed	Taskworthy	No	Level 2		25 Mar 2018	N/A	Failure	TUM HS FFR HARD TOP			000:00
000000-00A4A966		R/H/R BUMPER BENT	Closed	Fully Fit	No	Level 2		20 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A4A981		CLEAN BOTTOM OF VEHICLE	Closed	Fully Fit	No	Level 1		20 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A4A972		FIT MISSING SPACERS TO SUN VISORS	Closed	Fully Fit	No	Level 2		20 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A4A96B		FIT MISSING RUBER GROMMETS TO BATTERY BOX	Closed	Fully Fit	No	Level 1		20 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A4A970		FIT MISSING BOLT TO ALTERNATOR BACK COVER	Closed	Fully Fit	No	Level 2		20 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A4A964		TIGHTEN L/H/R BOTTOM SHOCK ABSORBER BUSH	Closed	Fully Fit	No	Level 2		20 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A60287		CARRY OUT AESP CAT 421 INSTR NO 4	Closed	Fully Fit	No	Level 2	000000-00004726	05 Oct 2017	N/A	Modification	TUM HS FFR HARD TOP			000:00
000000-00A4A975		FIT MISSING SPACERS TO SUN VISORS	Closed	Fully Fit	No	Level 2		20 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A4A97D		C.E.S. AND FIRE EXTINGUISHER NOT PRESENTED	Closed	Limited Role	No	Level 1		20 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A4A97A		BOWMAN SYSTEM REQ.CHECKING BY OPERATOR	Closed	Limited Role	No	Level 1		20 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			

000000-00A4213E	000000-	Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-0000451D	28 Jul 2017	N/A	Inspection	HARD TOP	TUM HS FFR	
000000-00A10301	00324F5A	INSPECT AND REPAIR TO BETTERMENT STANDARD IAW SO2 ES HQ BFG INSTRUCTIONS	Closed	Taskworthy	No	Level 2	000000-0000418C	22 Mar 2017	N/A	Inspection	HARD TOP	TUM HS FFR	
000000-00962B5F	00324F5A	Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Taskworthy	No	Level 2	000000-0000321C	19 Jan 2016	N/A	Inspection	HARD TOP	TUM HS FFR	
000000-008806F6		CARRY OUT ALL LIMITED ROLE REPAIR ACTIONS	Closed	Limited Role	No	Level 2		16 Mar 2015		Degrade	Failure	HARD TOP	000:00
000000-008806F0		CARRY OUT ALL FULLY FIT REPAIR ACTIONS	Closed	Fully Fit	No	Level 2		16 Mar 2015		Effect	Failure	HARD TOP	000:00
000000-00802067		CARRY OUT MOD 27	Closed	Fully Fit	No	Level 2		14 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	000:00
000000-008806FC		CARRY OUT JAMES ACTIVITY	Closed	Fully Fit	No	Level 2		16 Mar 2015	Effect	Failure	HARD TOP	TUM HS FFR	
000000-00859022		CARRY OUT ALL NON TASKWORTHY REPAIR ACTIONS	Closed	Taskworthy	No	Level 2		27 Nov 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-0080206B		CARRY OUT MOD 38	Closed	Fully Fit	No	Level 2		14 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-00802069		CARRY OUT MOD 35	Closed	Fully Fit	No	Level 2		14 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-00802066		MOD 2	Closed	Fully Fit	No	Level 2		14 Apr 2014	N/A	Closed No Action	HARD TOP	TUM HS FFR	
000000-00801DAF		STEAM CLEAN UNDERSIDE OF VEHICLE	Closed	Fully Fit	No	Level 1		13 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-00801DAC		STEAM CLEAN ENGINE	Closed	Fully Fit	No	Level 2		13 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-00801DA7		SECURE FRONT LEFT OUTER FENDER	Closed	Fully Fit	No	Level 2		13 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-00801DA6		REPLACE RUBBER SEAL AT FUEL CANISTER STORAGE COMPARTMENT	Closed	Fully Fit	No	Level 2		13 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-00801DA2		ADJUST ENGINE COOLANT FROM -27' TO -37' DEGREES	Closed	Fully Fit	No	Level 2		13 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-00842F31		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014		Degrade	Inspection	HARD TOP	
000000-00801DA8		NO VEHICLE JACK PRESENTED AT MEI TEST	Closed	Limited Role	No	Level 2		13 Apr 2014	N/A	Closed No Action	HARD TOP	TUM HS FFR	
000000-0082EFBC		RENEW INDICATOR SWITCH (SELF CANCELS WHEN IT SHOULDN'T)	Closed	Taskworthy	No	Level 2		18 Aug 2014	N/A	Inspection	HARD TOP	TUM HS FFR	
000000-00801DAA		REPLACE REAR STABILIZER RUBBER MOUNTS LEFT AND RIGHT EXCESSIVE PLAY	Closed	Taskworthy	No	Level 2		13 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-00801DA4		FIT AND SECURE RADIO BATTERIES	Closed	Limited Role	No	Level 2		13 Apr 2014	N/A	Failure	HARD TOP	TUM HS FFR	
000000-007C440A	000000-002ED558	out inspect from CRB(G)	Closed	Fully Fit	No	Level 2		23 Oct 2013	N/A	Closed No Action	HARD TOP	TUM HS FFR	
000000-00792953		FIT BREATHER PIPES TO AUX BATTERIES	Closed	Fully Fit	No	Level 2		09 Jun 2013	N/A	Inspection	HARD TOP	TUM HS FFR	
000000-00792946		CLEAN UNDER SIDE OF VEH	Closed	Fully Fit	No	Level 1		09 Jun 2013	N/A	Inspection	HARD TOP	TUM HS FFR	

000000-00792936	AJD COOLANT SG READING TO CORRECT LEVEL	Closed	Fully Fit	No	Level 1	09 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0079292F	REPAIR OIL LEAK AT FRONT DIFF INPUT SEAL	Closed	Fully Fit	No	Level 2	09 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00792928	RENEW SUMP GASKET	Closed	Fully Fit	No	Level 2	09 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00792924	REPAIR OIL SEEPAGE AT CRANKCASE BREATHER AT ROCKER COVER	Closed	Fully Fit	No	Level 2	09 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00792917	RENEW FFR ALT	Closed	Fully Fit	No	Level 2	09 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00792913	RENEW FFR BELT	Closed	Fully Fit	No	Level 2	09 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00792911	RENEW FAN BELT	Closed	Fully Fit	No	Level 2	09 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00797827	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non- Taskworthy	No	Level 1	000000- 0000081A	23 Jun 2013	N/A	Failure	TUM HS FFR HARD TOP
000000-0079A884	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000- 00000835	25 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP
000000-00780484	000000- 002E4BD3 FIT REAR SEATBELT	Closed	Fully Fit	No	Level 1		17 Apr 2013	N/A	Inspection	TUM HS FFR HARD TOP
000000-0078047B	000000- 002E4BD3 CHECK CRACKS ON SPARE TYRE FOR SERVICE ABILITY	Closed	Fully Fit	No	Level 1		17 Apr 2013	N/A	Inspection	TUM HS FFR HARD TOP
000000-00715EC8	CARRY OUT 1 YEARLY SERVICE AS PER AESP 2320-D-128-601	Closed	Fully Fit	No	Level 1		22 May 2012	N/A	Servicing	TUM HS FFR HARD TOP
000000-00715EC9	CARRY OUT 1 YEARLY VM TASKS AS PER AESP 2320-D-128-601	Closed	Fully Fit	No	Level 2		22 May 2012	N/A	Servicing	TUM HS FFR HARD TOP
000000-00715EC7	CARRY OUT MEI PLEASE CHECK THIS VEHICLE IS SAFE TO BE DRIVEN TO THE UNIT OR REPAIR AGENCY AND RETURNED FOR RE-INSPECTION ONLY	Closed	Fully Fit	No	Level 2		22 May 2012	N/A	Inspection	TUM HS FFR HARD TOP
000000-0071CB3E		Closed	Non- Taskworthy	No	Level 2		13 Jun 2012	N/A	Inspection	TUM HS FFR HARD TOP
000000-004A0A96	Carry out Mod 29	Closed	Fully Fit	No	Level 2		23 Nov 2009	N/A	Failure	TUM HS FFR HARD TOP
000000-006E92BC	CARRY OUT REEMUS FIT	Closed	Fully Fit	No	Level 2		09 Jan 2012	N/A	Modification	TUM HS FFR HARD TOP
000000-006E92B7	CARRY OUT CLEANLINESS INSPECTION-PRE REEMUS	Closed	Fully Fit	No	Level 2		09 Jan 2012	N/A	Inspection	TUM HS FFR HARD TOP
000000-006E1BEF	CARRY OUT 6 MONTHLY LEVEL 2 MAINT AS PER AESP 2320-D-128-601	Closed	Fully Fit	No	Level 2		29 Nov 2011	N/A	Servicing	TUM HS FFR HARD TOP
000000-006E1BEB	CARRY OUT 6 MONTHLY LEVEL 1 MAINT AS PER AESP 2320-D-128-601	Closed	Fully Fit	No	Level 1		29 Nov 2011	N/A	Servicing	TUM HS FFR HARD TOP
000000-006E1BE2	CARRY OUT 6 MONTHLY 6534 AS PER AESP 2320-D-128-601	Closed	Fully Fit	No	Level 1		29 Nov 2011	N/A	Servicing	TUM HS FFR HARD TOP
000000-004EB30E	Obs LH radius arm bushes	Closed	Fully Fit	No	Level 2		25 Mar 2010	N/A	Failure	TUM HS FFR HARD TOP
000000-006C521E	FIT REAR VIEW MIRROR	Closed	Fully Fit	No	Level 1		30 Aug 2011	N/A	No Fault Found	TUM HS FFR HARD TOP
000000-006C512A	REPLACE REAR VIEW MIRROR	Closed	Fully Fit	No	Level 1		30 Aug 2011	N/A	No Fault Found	TUM HS FFR HARD TOP

000:00

000:00

000000-004EB335	Fire extinguishers require certifying	Closed	Fully Fit	No	Level 1	25 Mar 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-006BA921	CARRY OUT MOD 37	Closed	Fully Fit	No	Level 2	19 Jul 2011	N/A	Modification	TUM HS FFR HARD TOP	
000000-006B4125	RECTIFY FAILED EMMISIONS TEST	Closed	Non- Taskworthy	No	Level 2	04 Jul 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-006B19F3	Insp Steering Drop Arm Tab Washer	Closed	Non- Taskworthy	No	Level 2	24 Jun 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-0060D439	CARRY OUT 2 YEARLY SERVICE AS PER AESP 2320-D-128-601	Closed	Non- Taskworthy	No	Level 1	09 Jun 2011	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-0060D43A	CARRY OUT 2 YEARLY VM TASKS AS PER AESP 2320-D-128-601	Closed	Non- Taskworthy	No	Level 2	09 Jun 2011	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-0060D43B	CARRY OUT MEI	Closed	Non- Taskworthy	No	Level 2	09 Jun 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006AECDD	Insp Steering Drop Arm Tab Washer	Closed	Taskworthy	No	Level 2	000000- 000002C3 22 Jun 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-005D5BDD	VIP PANEL NOT FITTED	Closed	Fully Fit	No	Level 2	25 Jan 2011	N/A	Failure	TUM HS FFR HARD TOP	
000000-005CDCAC	RENEW REAR SHOCK ABSORBER BUSHES	Closed	Fully Fit	No	Level 2	04 Jan 2011	N/A	Failure	TUM HS FFR HARD TOP	
000000-004EB346	Fit modification No 35 Emergency Hammer, No passengers in rear	Closed	Fully Fit	No	Level 2	25 Mar 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-004EB327	Obs oil seepage at rocker cover gasket	Closed	Fully Fit	No	Level 2	25 Mar 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-004EB31D	No plate light needs securing	Closed	Fully Fit	No	Level 1	25 Mar 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-004EB315	renew tow pintle bottom 'R' clip	Closed	Fully Fit	No	Level 1	25 Mar 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-004EB2EF	Fit rubber cap to battery terminal x2	Closed	Fully Fit	No	Level 1	25 Mar 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-004EB2E6	Renew bonnet stay clip	Closed	Fully Fit	No	Level 1	25 Mar 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-005DED4F	CARRY OUT BRAKE FLUID CHANGE AS PER AESP 2320-D-128-601 TABLE 7	Closed	Non- Taskworthy	No	Level 2	18 Feb 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-005DED4E	CARRY OUT 5 YEARLY OOPM GEARBOX OIL CHANGE AS PER AESP 2320-D-128-601 TABLE 5	Closed	Non- Taskworthy	No	Level 1	18 Feb 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-005DED4D	CARRY OUT 5 YEARLY OOPM COOLANT CHANGE AS PER AESP 2320-D-128-601 TABLE 5	Closed	Non- Taskworthy	No	Level 1	18 Feb 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-005DED4C	CARRY OUT 2 YEARLY ENGINE OIL AND FILTER CHANGE AS PER AESP 2320-D-128-601	Closed	Non- Taskworthy	No	Level 1	18 Feb 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-005CDCA6	RENEW R/H/R SHOCK ABSORBER BUSHES	Closed	Fully Fit	No	Level 2	04 Jan 2011	N/A	Failure	TUM HS FFR HARD TOP	
000000-005CB55B	CARRY OUT 6 MTH LEVEL 2 MAINT IAW AESP 2320-D-122-601 TABLE 7 COL A	Closed	Fully Fit	No	Level 2	03 Dec 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-005CB55A	CARRY OUT 6 MTH LEVEL 1 MAINT IAW AESP 2320-D-122-601 TABLE 7 COL A	Closed	Fully Fit	No	Level 1	03 Dec 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-004EB303	000000- 002AD7DE Tighten RH radius arm bolt	Closed	Fully Fit	No	Level 2	25 Mar 2010			TUM HS FFR HARD TOP	
000000-004EB2F8	000000- 002AD7DE Renew steering damper	Closed	Non- Taskworthy	No	Level 2	25 Mar 2010			TUM HS FFR HARD TOP	

000000-004EB2E1	000000-002AD7DE	Remove spare wheel from LHS, carry in back of vehicle	Closed	Non-Taskworthy	No	Level 1	25 Mar 2010	TUM HS FFR HARD TOP
000000-004EB2C3	000000-002AD7DE	Change to european headlights	Closed	Non-Taskworthy	No	Level 2	25 Mar 2010	TUM HS FFR HARD TOP
000000-004D8BA4	000000-002A9CE1	CARRY OUT 6 MTHLY SERV	Closed	Fully Fit	No	Level 1	01 Mar 2010	TUM HS FFR HARD TOP
000000-004D8BA0	000000-002A9CE1	CARRY OUT 6534	Closed	Fully Fit	No	Level 1	01 Mar 2010	TUM HS FFR HARD TOP
000000-004D8B9A	000000-002A9CE1	CARRY OUT 6 MTHLY VM TASKS	Closed	Fully Fit	No	Level 2	01 Mar 2010	TUM HS FFR HARD TOP
000000-004D0247		rect wiper motor inop	Closed	Non-Taskworthy	No	Level 2	17 Feb 2010	TUM HS FFR HARD TOP
000000-004A0A98		Both Brake pipes fowling at full lock	Closed	Non-Taskworthy	No	Level 2	23 Nov 2009	TUM HS FFR HARD TOP
000000-0049CAF3	000000-0029E86E	6 Monthly VM Task	Closed	Fully Fit	No	Level 2	17 Nov 2009	TUM HS FFR HARD TOP
000000-0049CAE7	000000-0029E86E	6 Monthly Serv and Inspection	Closed	Fully Fit	No	Level 1	17 Nov 2009	TUM HS FFR HARD TOP
000000-00080737	000000-0027181C	RENEW REAR DOOR BOTTOM SEAL	Closed	Fully Fit	No	Level 2	REAR 01 Aug 2007	TUM HS FFR HARD TOP
000000-004346DC	000000-00290C80	PLEASE CARRY OUT ANNUAL MEI	Closed	Fully Fit	No	Level 2	22 Jun 2009	TUM HS FFR HARD TOP
000000-004346D9	000000-00290C80	PLEASE CARRY OUT 2YR VM TASKS	Closed	Fully Fit	No	Level 2	22 Jun 2009	TUM HS FFR HARD TOP
000000-004346D4	000000-00290C80	PLEASE CARRY OUT 2YR SERVICE	Closed	Fully Fit	No	Level 1	22 Jun 2009	TUM HS FFR HARD TOP
000000-000B4E62	000000-0026EBAC	SEATBELT MODIFICATION INCORRECTLY FITTED	Closed	Fully Fit	No	Level 2	15 Jan 2008	TUM HS FFR HARD TOP
000000-001F4117	000000-0027DBDD	RENEW EXHAUST END SECTION	Closed	Fully Fit	No	Level 2	04 Jul 2008	TUM HS FFR HARD TOP
000000-003D4B38	000000-00287CEC	RENEW END SECTION OF EXHURST	Closed	Non-Taskworthy	No	Level 2	19 Feb 2009	TUM HS FFR HARD TOP
000000-0036A7E4	000000-0026C406	CARRY OUT 6 MONTHLY VM TASKS	Closed	Non-Taskworthy	No	Level 2	05 Jan 2009	TUM HS FFR HARD TOP
000000-0036A7BC	000000-0026C406	CARRY OUT 6 MONTHLY SERVICE	Closed	Non-Taskworthy	No	Level 1	05 Jan 2009	TUM HS FFR HARD TOP
000000-0036A7D0	000000-0026C406	CARRY OUT 6 MONTHLY INSPECTION	Closed	Taskworthy	No	Level 1	05 Jan 2009	TUM HS FFR HARD TOP
000000-0003A4CE	000000-0027181C	RENEW L/H DOOR EARTH STRAP	Closed	Fully Fit	No	Level 2	17 Nov 2006	TUM HS FFR HARD TOP
000000-00080735	000000-0027181C	SECURE PIPE @ EGR VALVE	Closed	Fully Fit	No	Level 2	SECURE PIPE @ 01 Aug 2007	TUM HS FFR HARD TOP
000000-00080736	000000-0027181C	RENEW CLUTCH FLUID	Closed	Fully Fit	No	Level 2	RENEW CLUTCH 01 Aug 2007	TUM HS FFR HARD TOP
000000-0008073C	000000-0027181C	FIT LH DOOR GLASS SLIDER FELT	Closed	Fully Fit	No	Level 2	FIT LH DOOR 01 Aug 2007	TUM HS FFR HARD TOP
000000-00080761	000000-0027181C	DAMAGE TO RHR OF VEHICLE	Closed	Fully Fit	No	Level 2	DAMAGE TO RHR OF 01 Aug 2007	TUM HS FFR HARD TOP
000000-002899B8	000000-00281603	CARRY OUT 6 YRLY	Closed	Fully Fit	No	Level 2	22 Sep 2008	TUM HS FFR HARD TOP

000000-001F5733	000000-0027FA20	SPARE WHEEL FLAT	Closed	Limited Role	No	Level 1	07 Jul 2008	TUM HS FFR HARD TOP
000000-001F40EF	000000-0027DBDD	STRAIGHTON & RENEW BUMPERRETTE & CROSS MEMBER	Closed	Fully Fit	No	Level 2	04 Jul 2008	TUM HS FFR HARD TOP
000000-001F4103	000000-0027DBDD	FIT SEAT BELT MOD CORRECTLY	Closed	Fully Fit	No	Level 2	04 Jul 2008	TUM HS FFR HARD TOP
000000-001EA60B	000000-0027D775	CARRY OUT 1 YEARLY SERVICE	Closed	Fully Fit	No	Level 1	30 Jun 2008	TUM HS FFR HARD TOP
000000-001EA60E	000000-0027D775	CARRY OUT MEI	Closed	Fully Fit	No	Level 2	30 Jun 2008	TUM HS FFR HARD TOP
000000-001EA613	000000-0027D775	CARRY OUT 1 YEARLY VM TASKS	Closed	Fully Fit	No	Level 2	30 Jun 2008	TUM HS FFR HARD TOP
000000-000AE3AD	000000-0026C512	6 MONTHLY VM TASK	Closed	Non-Taskworthy	No	Level 2	09 Jan 2008	TUM HS FFR HARD TOP
000000-000AE3AA	000000-0026C509	6 MONTHLY SERVICING	Closed	Non-Taskworthy	No	Level 1	09 Jan 2008	TUM HS FFR HARD TOP
000000-000AE3C0	000000-0026C517	6 MONTHLY SEVICING	Closed	Non-Taskworthy	No	Level 1	09 Jan 2008	TUM HS FFR HARD TOP
000000-000AE3FF	000000-0026C53D	6 MONTHLY INSPECTION	Closed	Non-Taskworthy	No	Level 2	09 Jan 2008	TUM HS FFR HARD TOP
000000-0003BABE	000000-	1 X FIRE EXTINUSHER REQUIRES NEW SAFETY TAGS	Closed	Fully Fit	No	Level 1	23 Nov 2006	TUM HS FFR HARD TOP
000000-00079A5A	000000-00270990	RENEW RHR LOWERLINK ARM BUSH @ AXLE END	Closed	Non-Taskworthy	No	Level 2	RENEW RHR 10 Jul 2007	TUM HS FFR HARD TOP
000000-00079A60	000000-00270990	REQ RE-TEST (VOR)	Closed	Non-Taskworthy	No	Level 2	REQ RE-TEST (VOR) 10 Jul 2007	TUM HS FFR HARD TOP
000000-000735C0	000000-0026FF8D	2 YRLY SERVICING	Closed	Non-Taskworthy	No	Level 1	2 YRLY SERVICING 19 Jun 2007	TUM HS FFR HARD TOP
000000-000735C1	000000-0026FF8D	2 YRLY MEI	Closed	Non-Taskworthy	No	Level 2	2 YRLY MEI 19 Jun 2007	TUM HS FFR HARD TOP
000000-000735BF	000000-0026FF8D	2 YRLY VM TASK	Closed	Non-Taskworthy	No	Level 2	2 YRLY VM TASK 19 Jun 2007	TUM HS FFR HARD TOP
000000-0003A27A	000000-0026E944	6 MONTHLY SERVICE	Closed	Fully Fit	No	Level 2	16 Nov 2006	TUM HS FFR HARD TOP
000000-0003A279	000000-0026E944	6 MONTHLY VM TASKS	Closed	Fully Fit	No	Level 2	16 Nov 2006	TUM HS FFR HARD TOP
000000-0002ACC6		Initial Usage	Closed	Fully Fit	No	Level 1	05 Sep 2006	TUM HS FFR HARD TOP
000000-0002AD10		Initial Maintenance	Closed	Fully Fit	No	Level 1	05 Sep 2006	TUM HS FFR HARD TOP

Work Objects

Serial Number: KK69AA
 NSN: 2320998939744

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated	Working Organisation	Repair Section
								Repair Time		
000000-00863B2C	000000-00324F5A	No	First Parade Insp (AR)(1)		Level 1	Non-Taskworthy	CL	000:00		
000000-00495553		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-001E8515		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy		000:00		
000000-00946196		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-004FD079		No	MEI (2)		Level 2	Non-Taskworthy		000:00		
000000-001E8514		No	MEI (2)		Level 2	Non-Taskworthy		000:00		
000000-0043B384		No	6 Monthly 6534 Insp FMT933 (W) Role Equipment		Level 1	Non-Taskworthy	WiP	000:00		
000000-00BCA570		No	(2)*	20 Nov 2020	Level 2	Non-Taskworthy	CL	000:00		
000000-00277BAC		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		

000000-0028C649	000000-002E7159	No	MEI (2)		Level 2	Fully Fit	CL	000:00
000000-003CF8F3		No	6 Monthly 6534 Insp		Level 1			000:00
000000-0016C31B		No	MEI (2)		Level 2			000:00
000000-000C3925		No	MEI (2)		Level 2		CL	000:00
000000-000DE1BB		No	MEI (2)		Level 2		CL	000:00
000000-0008AF65		No	MEI (2)		Level 2		CL	000:00
000000-0009C02D		No	MEI (2)		Level 2		CL	000:00
000000-00052E18		No	First Parade Insp (AR)(1)		Level 1		CL	000:00
000000-000FC63D		No	First Parade Insp (AR)(1)		Level 1		CL	000:00
000000-000D2275		No	First Parade Insp (AR)(1)		Level 1		CL	000:00
000000-0005A7D1		No	MEI (2)		Level 2		CL	000:00
			FMT932 (W) Mandatory			Non-		
000000-00BCA1FA		No	Equipment Inspection (2)*	20 Nov 2020	Level 2	Taskworthy	CL	000:00
						Non-		
000000-007D810E	000000-00324F5A	No	MEI (2)		Level 2	Taskworthy	CL	000:00
000000-004FD07A		No	6 Monthly 6534 Insp		Level 1			000:00
000000-001A20AE		No	6 Monthly 6534 Insp		Level 1			000:00
000000-0022D359		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-002748C2	000000-002E54D9	No	MEI (2)		Level 2	Fully Fit	CL	000:00
000000-00985F0A		No	Ad Hoc Insp (AR)		Level 1	Fully Fit	CL	000:00
000000-00863B1E		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-0016C2F6		No	6 Monthly 6534 Insp		Level 1			000:00
			FMT932 (W) 6 Monthly Safety			Non-		
000000-00BCA550		No	Inspection (2)	22 May 2020	Level 2	Taskworthy	CL	000:00
000000-00985F09		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-00985B99		No	MEI (2)		Level 2	Fully Fit	CL	000:00
000000-000C828D		No	MEI (2)		Level 2		CL	000:00
						Non-		
000000-00BCAAFE		No	FMT934 Functional Check (1)*	22 May 2020	Level 1	Taskworthy	CL	000:00
000000-000EB336		No	MEI (2)		Level 2		CL	000:00

Work Objects

Serial Number: KK69AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-00695715	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS Installation of 12/24 volt sockets.(Installation Instruction 8 (2320-D-128-411 Installations Instructions and Index))	000000-00324F5A	No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-00688E9D	00008	8 Metre Mast Mount Installation Kit	000000-002D7C66	No	3/A	STI				Fully Fit	CL	Level 3			
000000-0061B39A	00020	Fitting of Trailer Breakaway Attachment Plate	000000-002D7C66	No	-/-	UTI				Fully Fit	CL	Level 2			
000000-0061B38E	00024	Introduction of Battery Retention	000000-002D7C66	No	-/-	UTI				Fully Fit	CL	Level 2			
000000-0002481B	00017	Fitting of Spare Wheel Lifting Aid Harness	000000-002D7C66	No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0001255C	00025	Fitting Glow Plug Timer Interface Harness	000000-002D7C66	No	1/A	UTI				Non-Taskworthy	CL	Level 1			
000000-0002144C	00037	Radio Battery Isolation Switch and Power Import / Export System	000000-002D7C66	No	-/-	UTI				Fully Fit	CL	Level 1			
000000-0001EE5E	00016	Input/Output Porthole for Communication Cables, Cover Modification	000000-002D7C66	No	-/-	RTI				Fully Fit	CL	Level 1			
000000-00011D26	00027	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit	000000-002D7C66	No	-/-	UTI				Fully Fit	CL	Level 1			
000000-00025F4F	00012	Blackout Cover for Warning Light Panel	000000-002D7C66	No	1/A	RTI				Non-Taskworthy	CL	Level 2			
000000-00013498	00019	Rear Door Blackout Blind (FFR Variants) Only	000000-002D7C66	No	-/-	UTI				Fully Fit	CL	Level 1			
000000-000200FA	00033	Radio Rack Fixings	000000-002D7C66	No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00018BE0	00001	Roof Mounted Communication Installation (Blanking Plate Only)	000000-002D7C66	No	-/-	RTI				Fully Fit	CL	Level 1			
000000-00021A26	00002	TUAAM Earth Bonding Improvements	000000-002D7C66	No	-/-	RTI				Fully Fit	CL	Level 2			
000000-00020543	00007		000000-002D7C66	No	-/-	RTI				Fully Fit	CL	Level 2			

000000-00019D3B	00032	Project SHOEHORN Revised Weight Data Plate	000000-002D7C66	No	-/	UTI	Fully Fit	CL	Level 1
000000-000244FE	00035	Fitting of Emergency Hammer Input / Output Porthole for Comms / Power Cable Installation	000000-002D7C66	No	1/A	UTI	Non-Taskworthy	CL	Level 2
000000-00014EB5	00008	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME	000000-002D7C66	No	-/	RTI	Fully Fit	CL	Level 1
000000-00013BAD	00039	Spare Wheel Adaptor Plates; Left and Right Hand Installation	000000-002D7C66	No	-/-	RTI	Fully Fit	CL	Level 1
000000-00011824	00029	Fitting of a New Import/Export Box Mount Bracket	000000-002D7C66	No	-/-	UTI	Fully Fit	CL	Level 2
000000-00024F81	00038	Front Belt Protection Sleeves	000000-002D7C27	No	1/A	UTI	Non-Taskworthy	CL	Level 1
000000-0000A47D	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension	000000-002D7C16	No	-/	RTI	Fully Fit	CL	Level 2
000000-00013D10	00040	Fitting of Additional Lashing Eyes		No	-/	RTI	Fully Fit	CL	
000000-000180DD	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI	Fully Fit	CL	
000000-00016D0D	00028	FITTING OF REAR ANTI-ROLL BAR (RARB)		No	-/	UTI	Fully Fit	CL	

Work Objects

Serial Number: KK69AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Estimated		Working Organisation	Repair Section
							Work Status	Repair Time		
000000-002748A2		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	04 Apr 2020	Level 1	Fully Fit	CL	000:00		
000000-0043B36B		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1	Fully Fit	CL	000:00		
000000-0093FF6D		No	Equipment Check		Level 1			000:00		
000000-00180B21		No	5 Yearly/100000 Kms (1)		Level 1			000:00		
000000-0022F352	000000-002DEFD7	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	04 Apr 2020	Level 1	Fully Fit	CL	000:00		
000000-0028C64A	000000-002E7159	No	Yearly/20000 Kms	08 Sep 2019	Level 1	Fully Fit	CL	000:00		
000000-0010F937		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1			000:00		
000000-0043C482		No	Equipment Check		Level 1			000:00		
000000-004AAC9E		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	17 Nov 2023	Level 2	Fully Fit	CL	000:00		
000000-002748DC		No	2 Yearly/40000 Kms	04 Apr 2020	Level 1	Fully Fit	CL	000:00		

			OOPS 5 Yearly/155000 Kms Drain					
000000-0020AF19		No	And Replen Gearbox Oil (2)	01 Jul 2019	Level 2			000:00
000000-001E8501		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1			000:00
	000000-							
000000-0022D30F	002DEDB6	No	6 Monthly/10000 Kms	04 Oct 2018	Level 1	Fully Fit	CL	000:00
			OOPS 2 Yearly/20000 Kms Drain					
000000-0020AF1F		No	Engine Oil And Filter Change (1)	04 Apr 2020	Level 1			000:00
000000-001E8500		No	Yearly/20000 Kms	08 Sep 2019	Level 1			000:00
			OOPS 2 Yearly/40000 Kms Replace					
000000-002748CA		No	Air Cleaner Element (1)	04 Apr 2020	Level 1	Fully Fit	CL	000:00
000000-008978B9		No	Battery Test		Level 1			000:00
000000-0095C95B		No	Battery Test		Level 1			000:00
000000-00277AEB		No	Yearly/20000 Kms	08 Sep 2019	Level 1	Fully Fit	CL	000:00
000000-000838F3		No	2 Yearly/40000 Kms	04 Apr 2020	Level 1		CL	000:00
000000-000D3F36		No	2 Yearly/40000 Kms	04 Apr 2020	Level 1		CL	000:00
000000-000CDC80		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		CL	000:00
000000-000E4380		No	Yearly/20000 Kms	08 Sep 2019	Level 1		CL	000:00
000000-00087D8A		No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00
000000-0008F003		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		CL	000:00
000000-000DF1D5		No	Yearly/20000 Kms	08 Sep 2019	Level 1		CL	000:00
000000-0009B5AF		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		CL	000:00
000000-000A59E1		No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00
000000-0007A7B1		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		CL	000:00
000000-000AC03F		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		CL	000:00
000000-0002CE61		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		CL	000:00
000000-000FC80D		No	Weekly (AR)(1)		Level 1		CL	000:00
000000-00277AEA		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1	Fully Fit	CL	000:00
						Non-		
000000-00863B34		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1	Taskworthy	CL	000:00
	000000-		OOPS 2 Yearly/20000 Kms Drain					
000000-002748D5	002E54D9	No	Engine Oil And Filter Change (1)	04 Apr 2020	Level 1	Fully Fit	CL	000:00
000000-0001A47C		No	2 Yearly/40000 Kms	04 Apr 2020	Level 1		CL	000:00
000000-000E07E3		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		CL	000:00

000000-0001A4A3	No	Yearly/20000 Kms	08 Sep 2019	Level 1		CL	000:00
000000-000DAA66	No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		CL	000:00
000000-0005AD98	No	Yearly/20000 Kms	08 Sep 2019	Level 1		CL	000:00
000000-0005AD99	No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		CL	000:00
000000-008978BA	No	Equipment Check		Level 1			000:00
000000-001A21AE	No	6 Monthly/10000 Kms	04 Oct 2018	Level 1			000:00
000000-0016C2A3	No	2 Yearly/40000 Kms	04 Apr 2020	Level 1			000:00
	000000-	OOPS 2 Yearly/20000 Kms Drain			Non-		
000000-007D810F	00324F5A	No	Engine Oil And Filter Change (1)	04 Apr 2020	Level 1	Taskworthy	CL 000:00
000000-0016C2A4		No	Yearly/20000 Kms	08 Sep 2019	Level 1		000:00
			OOPS 2 Yearly/40000 Kms Replace				
000000-0020AF20		No	Air Cleaner Element (1)	04 Apr 2020	Level 1		000:00
			OOPS 5 Yearly Drain/Flush And				
000000-0020AF22		No	Replen Cooling System	01 Jul 2019	Level 1		000:00
000000-009B1943		No	Yearly/20000 Kms	08 Sep 2019	Level 1	Fully Fit	CL 000:00
	000000-		OOPS 2 Yearly/40000 Kms Replace			Non-	
000000-007D8126	00324F5A	No	Air Cleaner Element (1)	04 Apr 2020	Level 1	Taskworthy	CL 000:00
	000000-		OOPS 2 Yearly/20000 Kms Drain				
000000-0022F353	002DEFD7	No	Engine Oil And Filter Change (1)	04 Apr 2020	Level 1	Fully Fit	CL 000:00
	000000-					Non-	
000000-007D810D	00324F5A	No	2 Yearly/40000 Kms	04 Apr 2020	Level 1	Taskworthy	CL 000:00
000000-0043C481		No	Battery Test		Level 1		000:00
000000-0016C2A5		No	6 Monthly/10000 Kms	04 Oct 2018	Level 1		000:00
			OOPS 6 Yearly/120000 Kms				
000000-0020AF36		No	Camshaft Timing Belt (2)	17 Nov 2023	Level 2		000:00
	000000-						
000000-003CB8DF	002E7159	No	6 Monthly/10000 Kms	04 Oct 2018	Level 1	Fully Fit	CL 000:00
000000-000FC49F		No	Weekly (AR)(1)		Level 1		CL 000:00
000000-000DBEF7		No	Weekly (AR)(1)		Level 1		CL 000:00
000000-0043B3E8		No	Yearly/20000 Kms	08 Sep 2019	Level 1	Fully Fit	CL 000:00
000000-0095C95C		No	Equipment Check		Level 1		000:00
000000-004FD072		No	Battery Test		Level 1		000:00
000000-004FD073		No	Equipment Check		Level 1		000:00

000000-0093FF6C

No

Battery Test

Level 1

000:00

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
PJ98AA	2320998939963	NB50103101	LV2A/088DUM	TRUCK UTY MED (TUM HS) 4X4 SOFT TOP LANDROVER 2.5LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
06/07/1998	SALLDBA67WA154633	N/A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
PJ98AA	3		CA005A	JSCS ASHCHURCH		36158AA	06/07/1998	
PJ98AA	4	19/08/1998	A0504A	1 CG	41888A	1762	09/09/1998	
PJ98AA	4	04/05/2001	A0501A	1 GG	37	242	05/05/2001	H/T
PJ98AA	4	27/01/2003	A0900A	2 SIG REGT	270	10	20/03/2003	T71
PJ98AA	4	15/05/2003	A9112A	THEATER SIG SQN	25	86	09/06/2003	T91
PJ98AA	4	01/07/2003	A0219A	FORCE SP REAR	48	82	07/07/2003	MCR
PJ98AA	4	20/12/2006	A9121A	COQ QM DEPT	486	809	12/01/2007	Y01
PJ98AA	3	11/11/2008	CA005A	JSCS ASHCHURCH	1853	85486AA	30/01/2009	
PJ98AA	3	10/02/2009	A5969A	TFSU (UK)	92186A	898DD	23/05/2009	
PJ98AA	2	18/01/2010	A2971A	BATUS QM(T)	960D	235068	15/04/2010	
PJ98AA		10/10/2012		BATUS WRP LANDROVER ALL			11/10/2012	

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
PJ98AA		12/04/2013		BATUS VEH TP			12/04/2013	
PJ98AA		27/05/2013		BATUS OPFOR BG RECCE			01/06/2013	
PJ98AA		13/08/2013		EX PS OPFOR BG HQ			14/08/2013	
PJ98AA		09/09/2013		BATUS WRP LANDROVER ALL			09/09/2013	
PJ98AA		16/04/2014		BATUS VEH TP			17/04/2014	
PJ98AA		17/06/2014		BATUS OPFOR BG RECCE			17/06/2014	
PJ98AA		12/08/2014		EX PS OPFOR BG HQ			12/08/2014	
PJ98AA		05/10/2014		BATUS VEH TP			06/10/2014	
PJ98AA		21/10/2014		BATUS WRP LANDROVER ALL			21/10/2014	
PJ98AA		06/11/2014		SEF (UK) ASHCHURCH			02/03/2015	

Work Objects

Serial Number: PJ98AA
 NSN: 2320999087633

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Escalate Work	Repair Level	Batch Fault Group ID	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-0083D679		light cover	Closed	Limited	No	Level 2	30 Sep 2014	N/A	Closed No	TUM HS FFR			
000000-0083D678		wire under vehicle	Closed	Taskworthy	No	Level 2	30 Sep 2014	N/A	Action	4X4 SCOUT			
000000-0083D676		passenger side mirror	Closed	Taskworthy	No	Level 2	30 Sep 2014	N/A	Action	4X4 SCOUT			
000000-0083D675		drivers seatbelt	Closed	Taskworthy	No	Level 2	30 Sep 2014	N/A	Action	4X4 SCOUT			
000000-0083D677		front R/H spring	Closed	Taskworthy	No	Level 2	30 Sep 2014	N/A	Action	4X4 SCOUT			
000000-0083D674		fog lights inop	Closed	Taskworthy	No	Level 2	30 Sep 2014	N/A	Action	4X4 SCOUT			
J00433-140F4000		Renew Fuel lift pump	Closed	Taskworthy	No	Level 2	08 Sep 2014	N/A	Failure	4X4 SCOUT			
000000-0082E2E1		STARTER INOP	Closed	Taskworthy	No	Level 2	14 Aug 2014	N/A	Failure	4X4 SCOUT			
000000-0082C80C		Fit rear shock upper cases correctly	Closed	Fully Fit	No	Level 2	11 Aug 2014	N/A	Inspection	4X4 SCOUT			
000000-007FD8E4		FIRE EXTINGUISHER NOT PRESENTED ON MEI	Closed	Role	No	Level 1	01 Apr 2014	N/A	Action	4X4 SCOUT			
000000-00801294		COMPLETE 1 YEARLY SERVICE LEVEL 2 JOBS	Closed	Taskworthy	No	Level 2	01 Apr 2014	N/A	Action	4X4 SCOUT			
000000-00801293		COMPLETE 1 YEARLY SERVICE LEVEL 1 JOBS	Closed	Taskworthy	No	Level 1	01 Apr 2014	N/A	Action	4X4 SCOUT			
000000-00801291		OOPS 5 YEARLY DRAIN AND REPLEN GEARBOX OIL	Closed	Taskworthy	No	Level 1	01 Apr 2014	N/A	Action	4X4 SCOUT			
000000-0080128F		OOPS 5 YEARLY DRAIN/FLUSH AND REPLEN COOLING SYSTEM	Closed	Taskworthy	No	Level 1	01 Apr 2014	N/A	Action	4X4 SCOUT			
000000-007CE9E6		REHABILITATE VEHICLE IN ACCORDANCE WITH STANDARD REPAIR ACTIONS LISTED IN BATUS WKSP SOP 4.22(WRP 2014)	Closed	Fully Fit	No	Level 2	000000-00000E4 21 Nov 2013	N/A	Inspection	4X4 SCOUT			

000000-007AE53E	RENEW ENGINE	Closed	Non-Taskworthy	No	Level 2	23 Aug 2013	N/A	Closed No Action	TUM HS FFR 4X4 SCOUT	
000000-007A8B7C	Vehicle sentenced as per Handback job card (02/07/2013)	Closed	Non-Taskworthy	Yes	Level 2	02 Aug 2013	N/A	Closed No Action	TUM HS FFR 4X4 SCOUT	
000000-0077BFBC	ENGINE NUMBER TO BE LOCATED FOR NEXT MEI	Closed	Fully Fit	No	Level 2	01 Apr 2013	N/A	Closed No Action	TUM HS FFR 4X4 SCOUT	
000000-0077BFFB	FIT TRACK ROD PROTECTION BRKT AT AXLE	Closed	Fully Fit	No	Level 2	01 Apr 2013	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-007A2ED6	RENEW CLUTCH	Closed	Non-Taskworthy	No	Level 2	16 Jul 2013	N/A	Failure	TUM HS FFR 4X4 SCOUT	
000000-0077BFFE	VEHICLE JACK NOT PRESENTED	Closed	Role Limited	No	Level 1	01 Apr 2013	N/A	Closed No Action	TUM HS FFR 4X4 SCOUT	
000000-0077BFFD	FIRE EXTINGUISHER NOT PRESENTED	Closed	Role Limited	No	Level 1	01 Apr 2013	N/A	Closed No Action	TUM HS FFR 4X4 SCOUT	
000000-0079CEDA	INSPECT ALL TYRES	Closed	Non-Taskworthy	No	Level 2	27 Jun 2013	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-00799238	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081 24 Jun 2013	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-0079C1DE	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-0000083 25 Jun 2013	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-00732A69	RENEW BRAKE FLUID (CARRIED OUT 23/02/2012 NEXT DUE 22/03/2014) DO NOT REMOVE FAULT	Closed	Fully Fit	No	Level 2	28 Aug 2012	N/A	Closed No Action	TUM HS FFR 4X4 SCOUT	
000000-00757B92	REHABILITATE VEHICLE IN ACCORDANCE WITH STANDARD REPAIR ACTIONS LISTED IN BATUS WKSP SOP 4.22	Closed	Non-Taskworthy	No	Level 2	000000-0000059 3 12 Dec 2012	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-0074F33D	000000-002DEC65 Comms WRP Inspection	Closed	Fully Fit	No	Level 2	15 Nov 2012	N/A	Inspection	TUM HS FFR 4X4 SCOUT	ESG BATUS WKSP Comms L2
000000-00732A6A	STEERING LINKAGE	Closed	Non-Taskworthy	No	Level 2	28 Aug 2012	N/A	Inspection	TUM HS FFR 4X4 SCOUT	

Work Objects

Serial Number: PJ98AA
 NSN: 2320999087633

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work		Maintenance Event		Repair		Estimated		Working Organisation	Repair Section
	Request ID	Escalate Work	Name	Next Due Date	Level	Fault State	Work Status	Repair Time		
000000-00267BF9		No	MEI (2)	01 Apr 2015	Level 2			000:00		
000000-00267BFA		No	6 Monthly 6534 Insp	05 Mar 2015	Level 1			000:00		
000000-0037C3F3		No	6 Monthly 6534 Insp	05 Mar 2015	Level 1	Fully Fit	CL	000:00		
000000-0044844C		No	6 Monthly 6534 Insp	05 Mar 2015	Level 1			000:00		
000000-0037C465		No	MEI (2)	01 Apr 2015	Level 2	Non-Taskworthy	CL	000:00		

Work Objects

Serial Number: PJ98AA
 NSN: 2320999087633

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0026A1E6		No	First 1600 Kms (AR)		Level 2			000:00		
000000-00267BE2		No	6 Monthly/10000 Kms	27 Nov 2014	Level 1			000:00		
			OOPS 2 Yearly/40000 Kms Replace							
000000-00267BE1		No	Air Cleaner Element (1)	19 Feb 2015	Level 1			000:00		
000000-00403FFE		No	6 Monthly/10000 Kms	27 Nov 2014	Level 1			000:00		
			OOPS 5 Yearly/155000 Kms Drain							
000000-003F4484		No	And Replen Gearbox Oil (2)	27 May 2019	Level 2			000:00		
			OOPS 5 Yearly/155000 Kms Drain							
000000-0037C43D		No	And Replen Gearbox Oil (2)	27 May 2019	Level 2	Fully Fit	CL	000:00		
000000-003F44F1		No	Yearly/20000 Kms	28 May 2015	Level 1			000:00		
000000-00267BE3		No	Yearly/20000 Kms	28 May 2015	Level 1			000:00		
			OOPS 5 Yearly Drain/Flush And							
000000-0037C44E		No	Replen Cooling System	31 Mar 2019	Level 1	Fully Fit	CL	000:00		
000000-00267BE0		No	2 Yearly/40000 Kms	19 Feb 2015	Level 1			000:00		

000000-00267BF8	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	19 Feb 2015	Level 1		000:00
000000-0037C410	No	Yearly/20000 Kms	28 May 2015	Level 1	Fully Fit CL	000:00