



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk



Our Reference:
FOI2023/10361
Date:
30 August 2023

Dear

I am writing about your email of 26 August 2023, requesting the following information:

I purchased an ex-military Land Rover TUM HS 4x4 FFR (ERM – MX-92-AA) a couple of years ago and to get some history on the vehicle I recently requested a search of the MERLIN database by the RLC Archive who provided the following MERLIN excerpt:

The RLC Archive said that most of the information in MERLIN, however, has been redacted by the MoD and there also appears to be an anomaly with the vehicle's chassis number. The chassis number in the MERLIN system is SALLDBA67WA145419; but, the chassis plate on the vehicle is SALLDBA68WA145419. The NSN is also different – 2320998939966, see photo of chassis plate below:

I am therefore submitting this Freedom of Information (FoI) Request to hopefully clarify the chassis plate anomalies and provide available information on the vehicle's military:

- 1. Service/Deployment History*
- 2. Maintenance History/Records*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History (redacted)
- Annex E – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault and Modification Histories (Annexes B and D) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43

Defence Equipment & Support

concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

Under Section 16 (Advice and Assistance) I can confirm that the information on MX92AA that was released as part of the response to FOI2018/08332 did not include the unit owner history as the vehicle was still in service with the MOD at that point in time. You can view the published response to FOI2018/08332 here: <https://www.gov.uk/government/publications/foi-responses-published-by-mod-week-commencing-09-july-2018>. The information on MX92AA can be found at row 206965 in the spreadsheet named Merlin 2.0 attachment 1.

I can also confirm that the chassis number for MX92AA recorded on MERLIN appears to be in error. The 9th character of the chassis number corresponds to the type of gearbox fitted to the vehicle; a 7 corresponds to a 5-speed manual right hand drive gearbox, while an 8 corresponds to a 5-speed manual left hand drive gearbox.

The NATO Stock Number (NSN) for the vehicle recorded on the chassis plate for which you have provided a photograph, 2320-99-893-9966, corresponds to the original build standard of the vehicle, which had the associated asset code description TRUCK UTY MED (TUM HS) 4X4 GS SOFT TOP LHD LANDROVER 2.5LTR TURBO DSL (WITH EEGR). The NSN recorded on MERLIN for MX92AA, 2320-99-908-6916, has an asset code description of TRUCK UTY MED (HS) 4X4 FFR HARD TOP LHD LAND ROVER 2.5LTR TURBO DSL W/EEGR BOWMAN BF LAS. This reflects the vehicle having been modified to accept a BOWMAN communications fit at some point after entering service with the MOD.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of

Defence Equipment & Support

Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
MX92AA	2320999086916	NB50208180	LV2A/088DUM	TRUCK UTY MED (HS) 4X4 FFR HARD TOP LHD LAND ROVER 2.5LTR TURBO DSL W/EEGR BOWMAN BF LAS	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
16/07/1998	SALLDBA67WA145419	N/A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
MX92AA	3		CA005A	JSCS ASHCHURCH		36831AA	16/07/1998	
MX92AA	4	03/12/1998	A0406A	7 SIG REGT (CORPS MAIN HQ)	44147A	3486	18/01/1999	
MX92AA	4	10/03/1999	A9047A	7 UK SIG REGT	1352HT	297HT	05/06/1999	
MX92AA	4	12/07/1999	A0406A	7 SIG REGT (CORPS MAIN HQ)	137	1644A65	30/07/1999	
MX92AA	4	11/06/2004	A4062A	4 RMP	32865	34	28/06/2004	V07
MX92AA	4	09/01/2009	A2119A	4 RMP 160 PRO COY	999	999	09/01/2009	MCR
MX92AA	3	08/11/2011	A5969A	TFSU (UK)	85398	5271DD	21/11/2011	
MX92AA	2	26/07/2012	CB998C	DSG COLCHESTER PLANNED REPAIR	4395D	999	26/07/2012	
MX92AA		19/09/2013		RWXY(V)			20/09/2013	
MX92AA		27/02/2020		OSVP HOLDINGS			10/03/2020	

Work Objects

Serial Number: MX92AA
 NSN: 2320999087633

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00A1ACAC		MEI 933 - ADVISORIES - 35 - REAR TAILGATE NOT FITTED UNIT AWARE	Closed	Fully Fit	No	Level 2		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A1AC98		MEI 933 - ADVISORIES - 1 - REAR STEP NOT FITTED UNIT AWARE	Closed	Fully Fit	No	Level 2		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A40AEB		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA)	Closed	Limited Role	No	Level 2	000000-000044FD	27 Jul 2017	N/A	Closed No Action	TUM HS FFR 4X4 SCOUT			
000000-00A1ACBF		MEI 933 - ADVISORIES - 45 - NO ID MARKINGS ON VEH JACK	Closed	Fully Fit	No	Level 2		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A1ACB9		MEI 933 - ADVISORIES - 42 - MODS 38, 20 & 35 REMOVED	Closed	Fully Fit	No	Level 2		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A741E2		SERVICING FORECAST DOES NOT MATCH ACTUAL FIRST TESTABLE SERVICING DATE ON 932	Closed	Fully Fit	No	Level 2		17 Nov 2017	N/A	Closed No Action	TUM HS FFR 4X4 SCOUT			
000000-00A1AC9F		MEI 933 - ADVISORIES - 5 - EARTH BONDING CHECKS N/A UNIT AWARE	Closed	Fully Fit	No	Level 2		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A1ACA3		MEI 933 - ADVISORIES - 13 - FFR EQPT REMOVED	Closed	Fully Fit	No	Level 2		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A1ACB1		MEI 933 - ADVISORIES - 42 - MOD 42 NOT CARRIED OUT SEE I.E SNvE 00036	Closed	Fully Fit	No	Level 2		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A1ACB5		MEI 933 - ADVISORIES - 42 - OUTSTANDING MODS 44	Closed	Fully Fit	No	Level 2		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A1AC75		MEI 932 - ADVISORIES - 8.2 - WIPERS REMOVED	Closed	Fully Fit	No	Level 1		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A1AC7D		MEI 932 - ADVISORIES - 8.2 - WASHERS DISCONNECTED	Closed	Fully Fit	No	Level 1		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A1AC7F		MEI 932 - ADVISORIES - 8.3 - WINDOWS REMOVED	Closed	Fully Fit	No	Level 2		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			
000000-00A1ACCB		WORK CARRIED OUT AS PER CUSTOMER REQUEST - SALES ORDER 880134980	Closed	Fully Fit	No	Level 1		24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT			

000000-00A1B4B7	MEI 932 - ADVISORIES - 6.3 - NSN & VIN NO ON DATA PLATE DO NOT MATCH JAMES	Closed	Fully Fit	No	Level 1	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-009A9078	000000-00322197 No rear door fitted	Closed	Fully Fit	No	Level 2	29 Jun 2016	N/A	Closed No Action	TUM HS FFR 4X4 SCOUT
000000-00997ECC	fire extinguisher has passed the five year certificate date	Closed	Taskworthy	No	Level 1	26 May 2016	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1AE0D	BAAN - 144 - 1 - 6581 C+A DOOR LH LOCK INC STRIKER	Closed	Taskworthy	No	Level 2	24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1AE24	BAAN - 144 - 2 - REFIT AND SECURE STRIKER	Closed	Taskworthy	No	Level 2	24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1AE45	BAAN - 147 - 1 - 6569 C+A DOOR LH ASSY	Closed	Taskworthy	No	Level 2	24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1AE56	BAAN - 147 - 2 - 6582 RNW DOOR LH LOWER HINGE	Closed	Taskworthy	No	Level 2	24 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B033	BAAN - 147 - 3 - 6124 RNW DOOR LH UPPER HINGE	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B03C	BAAN - 150 - 1 - RENEW RH SEAT BASE STORAGE LID CATCH	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B03E	BAAN - 153 - 1 - 6142 RNW DOOR RH LOWER HINGE	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B041	BAAN - 153 - 2 - 6636 RNW DOOR RH UPPER HINGE	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B047	BAAN - 249 - 1 - 4114 RNW BATTERY POS + TERM COVER	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B04F	BAAN - 249 - 2 - REPLACE NEG COVER	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B058	BAAN - 372 - 1 - 0004 INSP INT/EXT ROAD TEST	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B05E	BAAN - 414 - 1 - 0080 SERV 24M SERVICE	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B065	BAAN - 417 - 1 - 0095 RNW OIL ENGINE	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B069	BAAN - 417 - 2 - 0109 RNW TABLE5 GEARBOX OIL	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B44E	BAAN - 417 - 3 - 0106 RNW TABLE5 COOLANT	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B455	BAAN - 417 - 4 - 0100 RNW TABLE5 AIRCLEANER ELEMENT	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B458	BAAN - 421 - 1 - 9482 TABLE 6A BEFORE USE	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B45C	BAAN - 421 - 2 - 9483 TABLE 6B AFTER USE	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B460	BAAN - 438 - 1 - 3324 RNW PANHARD ROD BUSHS	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B463	BAAN - 440 - 1 - 3478 REMOVE & REFIT FRONT STEERING GUARD	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B46A	BAAN - 440 - 2 - 3480 REMOVE & REFIT STEERING GUARD LH	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-00A1B471	BAAN - 440 - 3 - 3482 REMOVE & REFIT STEERING GUARD RH	Closed	Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT

000000-00A1B47A	BAAN - 516 - 1 - 1910 R + R WHEEL ALL ROAD	Closed	Non- Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-00A1B483	BAAN - 534 - 1 - 1825 RNW NO PLATE FRONT	Closed	Non- Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-00A1B49F	BAAN - 800 - 1 - 0002 FINAL OUT INSP/ASSESSMENT	Closed	Non- Taskworthy	No	Level 2	25 Apr 2017	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-009B0922	Equipment Ban	Closed	Non- Taskworthy	No	Level 2	000000- 00003811	18 Jul 2016	N/A	Failure Closed No Action	TUM HS FFR 4X4 SCOUT
000000-009AC94B	Carry out MEI IAW JSP930	Closed	Non- Taskworthy	No	Level 2	06 Jul 2016	N/A	Service	TUM HS FFR 4X4 SCOUT	
000000-009A969A	Carry out 12 month service	Closed	Non- Taskworthy	No	Level 2	30 Jun 2016	N/A	Service	TUM HS FFR 4X4 SCOUT	
000000-0097A9DA	REQUIRES IN-INSPECTION AND DOCS CHECK CARRY OUT 2 YRLY SERVICE LEVEL 1+2 IAW AESP	Closed	Non- Taskworthy	No	Level 2	09 Mar 2016	N/A	Failure	TUM HS FFR 4X4 SCOUT	
000000-0084FFC6	2320D128 TAB 7 COL C	Closed	Non- Taskworthy	No	Level 2	06 Nov 2014	N/A	Service	TUM HS FFR 4X4 SCOUT	
000000-0084FFCB	RENEW AIR FILTER	Closed	Non- Taskworthy	No	Level 2	06 Nov 2014	N/A	Service	TUM HS FFR 4X4 SCOUT	
000000-0084FFCE	RENEW OIL AND FILTER	Closed	Non- Taskworthy	No	Level 2	06 Nov 2014	N/A	Service	TUM HS FFR 4X4 SCOUT	
000000-0084FFD2	RENEW BRAKE FLUID	Closed	Non- Taskworthy	No	Level 2	06 Nov 2014	N/A	Service	TUM HS FFR 4X4 SCOUT	
000000-0084FFD4	CARRY OUT MEI CARRY OUT 6 MNTHLY SERVICE LEVEL 1 IAW AESP	Closed	Non- Taskworthy	No	Level 2	06 Nov 2014	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-007FA354	2320D128601 TAB 7 COL A	Closed	Non- Taskworthy	No	Level 1	26 Mar 2014	N/A	Service	TUM HS FFR 4X4 SCOUT	
000000-007FA355	CARRY OUT 6 MNTHLY SERVICE LEVEL 2 IAW AESP 2320D128601 TAB 7 COL A	Closed	Non- Taskworthy	No	Level 2	26 Mar 2014	N/A	Service	TUM HS FFR 4X4 SCOUT	
000000-007FA356	CARRY OUT 6534 INSP CARRY OUT 6 MONTHLY SERVICE IAW AESP	Closed	Non- Taskworthy	No	Level 1	26 Mar 2014	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-008185E0	2320D128601 TAB 7 COL A LEVEL 1 AND 2	Closed	Non- Taskworthy	No	Level 2	16 Jun 2014	N/A	Service	TUM HS FFR 4X4 SCOUT	
000000-008185E3	CARRY OUT 6534 INSP	Closed	Non- Taskworthy	No	Level 2	16 Jun 2014	N/A	Inspection	TUM HS FFR 4X4 SCOUT	
000000-0079B3D4	Inspect tyres for damage	Closed	Non- Taskworthy	No	Level 2	000000- 00000835	25 Jun 2013	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-007F8914	RENEW ALL TYRES Defective Land Rover HS Hub Nuts procured and fitted by DSG	Closed	Non- Taskworthy	No	Level 1	24 Mar 2014	N/A	Failure	TUM HS FFR 4X4 SCOUT	
000000-0074E583		Closed	Fully Fit	No	Level 4	13 Nov 2012	Aborted	Inspection	TUM HS FFR 4X4 SCOUT	
000000-007983CD	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Fully Fit	No	Level 1	000000- 0000081A	24 Jun 2013	N/A	Inspection	TUM HS FFR 4X4 SCOUT
000000-006DE6B1	L1 Maintenance IAW AESP 601, Table 7, Column C	Closed	Non- Taskworthy	No	Level 1	17 Nov 2011	No Effect	Salvage	TUM HS FFR 4X4 SCOUT	
000000-006DE6AF	L2 IAW AESP 601, Table 7, Column C, Serial 52. Drain & replenish brake hydraulic system	Closed	Non- Taskworthy	No	Level 2	17 Nov 2011	No Effect	Service	TUM HS FFR 4X4 SCOUT	
000000-006DE6AD	L2 Maintenance IAW AESP 601, Table 7, Column C.	Closed	Non- Taskworthy	No	Level 2	17 Nov 2011	No Effect	Service	TUM HS FFR 4X4 SCOUT	

000000-006DE6A9	Vehicle Jack Inspected IAW 2590-E-100-013 Chap 6 annex B App 7 Less Para 1	Closed	Non-Taskworthy	No	Level 2	17 Nov 2011	No Effect	Inspection	TUM HS FFR 4X4 SCOUT
000000-006DE6A5	Fire Extinguisher Inspected IAW 4210-E-110-201 Chap 3 Para 7	Closed	Non-Taskworthy	No	Level 2	17 Nov 2011	No Effect	Inspection	TUM HS FFR 4X4 SCOUT
000000-006DE6A3	L2 MEI AFG 932(b), RBT, Headlight Alignment and Emissions test IAW AESP 013 Inspection Standards.	Closed	Non-Taskworthy	No	Level 2	17 Nov 2011	No Effect	Inspection	TUM HS FFR 4X4 SCOUT
000000-006D5939	Complete L1 Maintenance IAW AESP 2320-D-128-601, Table 7, Column A.	Closed	Non-Taskworthy	No	Level 1	20 Oct 2011	No Effect	Servicing	TUM HS FFR 4X4 SCOUT
000000-006D5934	Complete L2 Maintenance IAW AESP 2320-D-128-601, Table 7, Column A	Closed	Non-Taskworthy	No	Level 2	20 Oct 2011	No Effect	Servicing	TUM HS FFR 4X4 SCOUT
000000-006D5932	Complete L1 AF B 6534 Inspection IAW AESP 2300-A-050-013 Inspection Standards	Closed	Non-Taskworthy	No	Level 1	20 Oct 2011	No Effect	Inspection	TUM HS FFR 4X4 SCOUT
000000-006AE176	Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-000002A8 22 Jun 2011	N/A	Inspection	TUM HS FFR 4X4 SCOUT



Work Objects

Serial Number: MX92AA
 NSN: 2320999087633

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-006D4D79		No	6 Monthly 6534 Insp	10 Jul 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-007EBB31	000000-00322197	No	6 Monthly 6534 Insp	10 Jul 2019	Level 1	Taskworthy	CL	000:00		
000000-0019C160		No	6 Monthly 6534 Insp	10 Jul 2019	Level 1	Taskworthy	CL	000:00		
000000-00A6048D		No	6 Monthly 6534 Insp	10 Jul 2019	Level 1	Fully Fit	CL	000:00		
000000-005357BB		No	6 Monthly 6534 Insp	10 Jul 2019	Level 1	Taskworthy	WiP	000:00		
000000-00942B27		No	MEI (2)	26 Mar 2019	Level 2	Fully Fit	CL	000:00		
000000-00781031	000000-00322197	No	MEI (2)	26 Mar 2019	Level 2	Taskworthy	CL	000:00		
000000-0088A7B9	000000-0032C84D	No	6 Monthly 6534 Insp	10 Jul 2019	Level 1	Taskworthy	CL	000:00		
000000-00481998		No	MEI (2)	26 Mar 2019	Level 2	Non-Taskworthy		000:00		
000000-0019C15F		No	MEI (2)	26 Mar 2019	Level 2	Non-Taskworthy		000:00		

000000-002E423A	No	6 Monthly 6534 Insp	10 Jul 2019	Level 1			000:00
000000-00191AC3	No	6 Monthly 6534 Insp	10 Jul 2019	Level 1			000:00
000000-0016B84E	No	MEI (2)	26 Mar 2019	Level 2			000:00
000000-0041B59D	No	6 Monthly 6534 Insp	10 Jul 2019	Level 1			000:00
000000-00942B4E	No	6 Monthly 6534 Insp	10 Jul 2019	Level 1	Fully Fit	CL	000:00
000000-009D0FAB	No	6 Monthly 6534 Insp	10 Jul 2019	Level 1	Fully Fit	CL	000:00
000000-006D4D74	No	MEI (2)	26 Mar 2019	Level 2			000:00
000000-002E4239	No	MEI (2)	26 Mar 2019	Level 2			000:00
000000-00481999	No	6 Monthly 6534 Insp	10 Jul 2019	Level 1			000:00
000000-0016B84F	No	6 Monthly 6534 Insp	10 Jul 2019	Level 1			000:00

J1026A-06EF2009	00016	Radio Battery Isolation Switch and Power Import / Export System	No	-/	RTI	Fully Fit	CL	Level 2
J1026A-06EF200C	00019	Blackout Cover for Warning Light Panel	No	-/-	UTI	Fully Fit	CL	Level 2
J1026A-06EF2012	00031	Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants	No	-/-	UTI	Fully Fit	CL	Level 2
J1026A-06EF2002	00003	Helicopter Vehicle Modification (Hard Top Only) Roof Mounted Communication Installation	No	-/	RTI	Fully Fit		
J1026A-06EF2001	00002	(Blanking Plate Only)	No	-/	RTI	Fully Fit	CL	
J1026A-06EF2000	00001	Radio Rack Fixings	No	-/	RTI	Fully Fit	CL	

Work Objects

Serial Number: MX92AA
 NSN: 2320999087633

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated		Working Organisation	Repair Section
								Repair Time	Working Organisation		
000000-002E429E		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	12 Apr 2022	Level 1			000:00			
000000-0019C144		No	OOPS 20000 Kms		Level 2			000:00			
000000-002E429F		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	13 Apr 2019	Level 1			000:00			
000000-0078104B	000000-00322197	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	13 Apr 2019	Level 1	Fully Fit	CL	000:00			
000000-0016B849		No	OOPS 2 Yearly/20000 Kms		Level 2			000:00			
000000-002E4272		No	Yearly/20000 Kms	26 Mar 2019	Level 1			000:00			
000000-0048198E		No	2 Yearly/40000 Kms	13 Apr 2019	Level 1			000:00			
000000-002E4273		No	6 Monthly/10000 Kms (1)		Level 1			000:00			

000000-006C42D8		No	6 Monthly/10000 Kms	10 Jul 2019	Level 1			000:00
000000-00481992		No	6 Monthly/10000 Kms	10 Jul 2019	Level 1			000:00
000000-0016B85E		No	OOPS 5 Yearly		Level 2			000:00
000000-007EBB82	000000-00322197	No	6 Monthly/10000 Kms	10 Jul 2019	Level 1	Fully Fit	CL	000:00
000000-007EBB83	000000-00322197	No	Yearly/20000 Kms	26 Mar 2019	Level 1	Fully Fit	CL	000:00
000000-0019C142		No	OOPS 2 Yearly/20000 Kms		Level 2			000:00
000000-0016B84C		No	6 Monthly/10000 Kms (1)		Level 1			000:00
000000-00A60490		No	6 Monthly/10000 Kms	10 Jul 2019	Level 1	Fully Fit	CL	000:00
000000-0048198F		No	Yearly/20000 Kms	26 Mar 2019	Level 1			000:00
000000-006C42D7		No	Yearly/20000 Kms	26 Mar 2019	Level 1			000:00
000000-0078104A	000000-00322197	No	2 Yearly/40000 Kms OOPS 2 Yearly/20000 Kms	13 Apr 2019	Level 1	Fully Fit	CL	000:00
000000-0078104C	000000-00322197	No	Drain Engine Oil And Filter Change (1)	13 Apr 2019	Level 1	Fully Fit Non-	CL	000:00
000000-005357BF		No	6 Monthly/10000 Kms	10 Jul 2019	Level 1	Taskworthy	WiP	000:00
000000-0016B84A		No	Yearly/20000 Kms OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element	26 Mar 2019	Level 1			000:00
000000-002E429D		No	(1)	13 Apr 2019	Level 1			000:00
000000-00942B52		No	Yearly/20000 Kms	26 Mar 2019	Level 1	Fully Fit	CL	000:00
000000-009D11FC		No	6 Monthly/10000 Kms	10 Jul 2019	Level 1	Fully Fit	CL	000:00
000000-0041B59C		No	6 Monthly/10000 Kms (1)		Level 1			000:00
000000-0019C145		No	6 Monthly/10000 Kms (1)		Level 1			000:00
000000-0016B85D		No	OOPS 6 Yearly/120000 Kms OOPS 5 Yearly/155000 Kms		Level 2			000:00
000000-00781033	000000-00322197	No	Drain And Replen Gearbox Oil (2)	12 Apr 2022	Level 2	Fully Fit	CL	000:00
000000-00191AAD		No	6 Monthly/10000 Kms (1)		Level 1			000:00

000000-0019C143	No	Yearly/20000 Kms OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox	26 Mar 2019	Level 1				000:00
000000-002E42A1	No	Oil (2)	12 Apr 2022	Level 2				000:00
000000-0019C141	No	2 Yearly/40000 Kms	13 Apr 2019	Level 1				000:00
000000-002E429C	No	2 Yearly/40000 Kms	13 Apr 2019	Level 1				000:00
000000-0016B848	No	2 Yearly/40000 Kms	13 Apr 2019	Level 1				000:00
000000-009DDF09	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	06 Jan 2025	Level 2	Fully Fit	CL		000:00
000000-002E42A0	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2) OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter	06 Jan 2025	Level 2				000:00
000000-00481991	No	Change (1)	13 Apr 2019	Level 1				000:00
000000-0016B84B	No	OOPS 20000 Kms		Level 2				000:00
000000-0019C146	No	OOPS 2 Yearly/40000 Kms		Level 2				000:00
000000-0088A7B7	000000-0032C84D	No	6 Monthly/10000 Kms	10 Jul 2019	Level 1	Non-Taskworthy	CL	000:00
000000-00942B5C	No	No	6 Monthly/10000 Kms	10 Jul 2019	Level 1	Fully Fit	CL	000:00
000000-0016B84D	No	OOPS 2 Yearly/40000 Kms OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element		Level 2				000:00
000000-00481990	No	(1)	13 Apr 2019	Level 1				000:00
000000-00781032	000000-00322197	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	12 Apr 2022	Level 1	Fully Fit	CL	000:00