



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]
[REDACTED]

Our Reference:
FOI2023/10731
Date:
08 September 2023

Dear [REDACTED]

I am writing about your email of 04 September 2023, requesting the following information:

I recently purchased an ex Military land rover and would be interested if you could please provide me with some history on it.

Where it was based who it served with , maintenance records etc.

The details are as follows:

Sentencing reference number LEOT-4314

Service number LU55AA

Land rover defender wolf (SWB)

TUL HS Hard Top

Chassis number SALLDAA7WA152911

Engine number 25LO3123A

EAC/MAC NB42203100

Date of Manufacture 7/07/1998

Date in service 7/07/1998

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History
- Annex E – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault History (Annex B) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information
Defence Equipment & Support

which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
LU55AA	2320998939742	NB42253100	LV2A/088DUM	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
07/07/1998	SALLDAA67WA152911	25L07203B		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LU55AA	3		CA005A	JSCS ASHCHURCH		36188AA	07/07/1998	
LU55AA	4	08/12/2003	A1112A	1 CS BN REME	63948A	30243	20/02/2004	
LU55AA	4	13/01/2006	A1112C	1REME-12FDROY		999	13/01/2006	MCR
LU55AA	4	15/11/2006	A2453A	QRH	31642	69728	27/11/2006	Y03
LU55AA	4	23/07/2008	A0565A	1YORKS-MUNSTER	1	90056	19/09/2008	Z582
LU55AA	2	05/08/2011	A5992D	TFSU (G)	74511	85341	10/08/2011	C18
LU55AA		04/09/2012		EQUIPMENT POOL			13/09/2012	
LU55AA		04/02/2015		SEF (UK) ASHCHURCH			22/06/2015	
LU55AA		19/01/2021		BATUK			21/01/2021	
LU55AA		02/11/2021		OSVP HOLDINGS			04/06/2022	

Work Objects

Serial Number: LU55AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Work Fault Description	Work Status	Work Fault State	Escalate Work	Repair Level	Batch Fault Group ID	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00BCD641		Carry out FFR conversion to GS (IAW 20160630 - LR FFR to GS Workshop Instruction - Draft 0.8)	Closed	Fully Fit	No	Level 2		24-Aug-20	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-00BC8D0E	0034B5F3	Rectify non stater (charge battery)	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D0D	0034B5F3	Rectify oil seepage at gear box filler plug	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D0C	0034B5F3	Renew panhard bushes	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D0B	0034B5F3	Rectify oil leak at sump	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D0A	0034B5F3	Fit miassing LHS seat adjustment knob	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D07	0034B5F3	Fit missing blower controller knob	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D06	0034B5F3	Rectify rear door lock inop	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D05	0034B5F3	Renew LHS input/output facility (missing inner lining)	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D02	0034B5F3	Straighten LHS flag mast bracket & (secure)	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D01	0034B5F3	Fit missing alternator breather cap	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8D00	0034B5F3	Rectify oil seepage at vaccum pump	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8CFE	0034B5F3	Fit missing screw at radiator grill	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BC8CFC	0034B5F3	Renew air cleaner housing valve	Closed	Taskworthy	No	Level 2		05-Aug-20	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00BBBBCD	0034B5F3	CARRY OUT 2 YRLY SERVICE	Closed	Taskworthy	No	Level 2		28-Jun-20	N/A	Servicing	HARD TOP			000:00

OFFICIAL-SENSITIVE COMMERCIAL

000000-00BBB37E		SANITARY INSPECTION CARRIED OUT - IGNATIUS KAHIGA 0783 NT SERVICING	Closed	Non-Taskworthy	No	Level 2	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00BBB374	000000-0034B5F3	FIT X2 BATTERY TERMINAL COVERS	Closed	Fully Fit	No	Level 1	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00BBB366	000000-0034B5F3	INVESTIGATE AND RECTIFY NOISE AT ENGINE PULLEYS	Closed	Fully Fit	No	Level 2	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00BBB35E	000000-0034B5F3	FIT L/H/S ROOF GROMMET	Closed	Fully Fit	No	Level 2	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00BBB35A	000000-0034B5F3	RECTIFY ROOF DAMAGED AT L/H/R SIDE NEAR DOOR SEAL	Closed	Fully Fit	No	Level 2	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00BBB353	000000-0034B5F3	RECTIFY PLAY AT REAR DOOR BOTTOM HINGES	Closed	Fully Fit	No	Level 2	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00BBB30F	000000-0034B5F3	SECURE REAR DOOR CARD	Closed	Fully Fit	No	Level 2	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00BBB30D	000000-0034B5F3	RENEW BONNET STOPPER BUSHES DETERIORATED	Closed	Fully Fit	No	Level 2	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00BBB36C	000000-0034B5F3	FIT EMERGENCY HAMMER NOT FITTED	Closed	Non-Taskworthy	No	Level 1	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00BBB36E	000000-0034B5F3	FIT WHEEL NUT INDICATOR	Closed	Non-Taskworthy	No	Level 1	24-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00B21F75	000000-0034B4AB	SNvE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B	29-Mar-19	N/A	Inspection	TUL HS FFR HARD TOP	000:00
000000-00BBA6F4	000000-0034B4AB	PLEASE CARRY OUT INSPECTION	Closed	Non-Taskworthy	No	Level 2	23-Jun-20	N/A	Inspection	TUL HS FFR HARD TOP	000:00	
000000-00B1F37E		SNvE 377 - SWIVEL HOUSING	Closed	Non-Taskworthy	No	Level 1	000000-0000697A	29-Mar-19	N/A	Closed No Action	TUL HS FFR HARD TOP	000:00
000000-00A41451		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field	Closed	Limited Role	No	Level 2	000000-0000451A	28-Jul-17	N/A	Closed No Action	TUL HS FFR HARD TOP	
000000-009621F8		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003210	20-Jan-16	N/A	Closed No Action	TUL HS FFR HARD TOP	
000000-00844134		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09-Oct-14	Degraded	Inspection No Fault	TUL HS FFR HARD TOP	
000000-006B2FA9		NIL OUTSTANDING TASKS	Closed	Fully Fit	No	Level 1	29-Jun-11	N/A	Found	TUL HS FFR HARD TOP		
000000-00798A34		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A	24-Jun-13	N/A	Quarantine	TUL HS FFR HARD TOP	
000000-0079BA16		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25-Jun-13	N/A	Inspection	TUL HS FFR HARD TOP	
000000-006C14B8		DR 17/13	Closed	Fully Fit	No	Level 1	11-Aug-11	N/A	Failure	TUL HS FFR HARD TOP	000:00	
000000-006B58EB		CARRY OUT MOD INST 37 (GLOW PLUG TIMER INTERFACE)	Closed	Fully Fit	No	Level 2	06-Jul-11	N/A	Modification	TUL HS FFR HARD TOP		
000000-006B0677		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-00000312	22-Jun-11	N/A	Inspection	TUL HS FFR HARD TOP	
000000-005F437F		RENEW R/H FRONT PANEL	Closed	Fully Fit	No	Level 2	03-May-11	N/A	Damage	TUL HS FFR HARD TOP		
000000-006018B3		CARRY OUT MEI	Closed	Fully Fit	No	Level 2	12-May-11	N/A	Inspection	TUL HS FFR HARD TOP		
000000-005EFB26		CARRY OUT 2 YEARLY VM TASKS AS PER AESP 2320-D-128-601 TABLE 7	Closed	Fully Fit	No	Level 2	07-Apr-11	N/A	Servicing	TUL HS FFR HARD TOP		

OFFICIAL-SENSITIVE COMMERCIAL

000000-005EFB0E		CARRY OUT 2 YEARLY SERVICE AS PER AESP 2320-D-128-601 TABLE 7	Closed	Fully Fit	No	Level 1	07-Apr-11 N/A	Servicing	TUL HS FFR	
000000-005E08F7		CARRY OUT 2 YEARLY BRAKE FLUID CHANGE AS PER AESP 2320-D-128-601 TABLE 7	Closed	Non-Taskworthy	No	Level 2	24-Feb-11 N/A	Servicing	HARD TOP TUL HS FFR	
000000-005D6A2D		CARRY OUT 6 MONTHLY VM TASKS AS PER AESP 2320-D-128-601	Closed	Fully Fit	No	Level 2	27-Jan-11 N/A	Servicing	HARD TOP TUL HS FFR	
000000-005D6A25		CARRY OUT 6 MONTHLY SERVICE AS PER AESP 2320-D-128-601	Closed	Fully Fit	No	Level 1	27-Jan-11 N/A	Servicing	HARD TOP TUL HS FFR	
000000-005CEF5A		INSPECT REAR SEATBELTS	Closed	Limited Role Non-	No	Level 2	08-Jan-11 N/A	Inspection	HARD TOP TUL HS FFR	000:00
000000-005D345A		carry out 6 monthly service and vm tasks	Closed	Taskworthy	No	Level 2	19-Jan-11 N/A	Servicing	HARD TOP	000:45
000000-004BEBF9	000000-002A6B15	FIT SPARE WHEEL TO VEHICLE (NOT TO BE TASKED UNTIL COMPLETED)	Closed	Limited Role	No	Level 1	22-Jan-10		TUL HS FFR HARD TOP	
000000-00374E74	000000-0027146A	FIT REAR SEAT AND SEAT BELT	Closed	Fully Fit	No	Level 1	08-Jan-09		TUL HS FFR HARD TOP	
000000-004B77ED	000000-002A358A	CARRY OUT 6534 INSPECTION	Closed	Fully Fit	No	Level 1	13-Jan-10		TUL HS FFR HARD TOP	
000000-004B77EB	000000-002A358A	Carry Out 6M Service and VM Tasks	Closed	Fully Fit	No	Level 1	13-Jan-10		TUL HS FFR HARD TOP	
000000-004972F9	000000-0029D922	Check if a Donalson Filter System is fitted (see AESP 2320-D-128-421, Instruction No4) If Filter system is	Closed	Fully Fit Non-	No	Level 1	09-Nov-09		TUL HS FFR HARD TOP	
000000-00452D6B	000000-00292684	carry out mei	Closed	Taskworthy Non-	No	Level 2	08-Jul-09		TUL HS FFR HARD TOP	
000000-00452D68	000000-00292684	carry out 1 yrly vm tasks	Closed	Taskworthy Non-	No	Level 2	08-Jul-09		TUL HS FFR HARD TOP	
000000-0041AF62		renew rear road springs & shock absorbers	Closed	Taskworthy Non-	No	Level 2	01-May-09		TUL HS FFR HARD TOP	
000000-003F7F42	000000-0028C720	Carry Out 5 Yrly OOP maint (coolant change)	Closed	Taskworthy Non-	No	Level 2	25-Mar-09		TUL HS FFR HARD TOP	
000000-003F7F38	000000-0028C720	Carry Out 5 Yrly OOP maint (Gearbox oil change)	Closed	Taskworthy Non-	No	Level 2	25-Mar-09		TUL HS FFR HARD TOP	
000000-003F7F1E		Carry Out 6 Yrly OOP maint (Cam Belt change)	Closed	Taskworthy Non-	No	Level 2	25-Mar-09		TUL HS FFR HARD TOP	
000000-003711C0	000000-0026FDEE	CARRY OUT 6M VMS	Closed	Taskworthy	No	Level 2	07-Jan-09		TUL HS FFR HARD TOP	
000000-00372700		Carry out Mod 33 (Rear Door blackout)	Closed	Fully Fit Non-	No	Level 2	08-Jan-09		TUL HS FFR HARD TOP	
000000-003711B3	000000-0026FDA2	CARRY OUT 6M SERVICE	Closed	Taskworthy	No	Level 1	07-Jan-09		TUL HS FFR HARD TOP	
000000-000BE881		FIT SEAT BELT PROTECTOR MOD	Closed	Fully Fit Non-	No	Level 1	24-Jan-08		TUL HS FFR HARD TOP	
000000-000BE883		CREW, FIT MISSING RADIO BATTERIES	Closed	Taskworthy	No	Level 1	24-Jan-08		TUL HS FFR HARD TOP	
000000-000BE87F		SECURE GPS BEHIND DRIVERS HEAD	Closed	Fully Fit Non-	No	Level 1	24-Jan-08		TUL HS FFR HARD TOP	
000000-0008D32C	000000-00272ED8	RENEW REAR BRAKE PADS	Closed	Taskworthy Non-	No	Level 2	26-Sep-07		TUL HS FFR HARD TOP	
000000-0008F455		RENEW REAR BRAKE PADS	Closed	Taskworthy	No	Level 2	01-Oct-07		TUL HS FFR HARD TOP	

OFFICIAL-SENSITIVE COMMERCIAL

000000-0008D32D		NO1 INJECTOR LEAKING	Closed	Non- Taskworthy	No	Level 2	26-Sep-07	TUL HS FFR HARD TOP
000000-0008AC9D	000000- 002727C1	CARRY OUT 6 MONTHLY SERVICING	Closed	Fully Fit	No	Level 1	17-Sep-07	TUL HS FFR HARD TOP
000000-0003BD8B		Insufficient Data	Closed	Non- Taskworthy	No	Level 1	24-Nov-06	TUL HS FFR HARD TOP
000000-000245BF	000000- 0026CAD9	REPLACE ALL DOOR LOOKS AND IGNITION BARREL	Closed	Non- Taskworthy	No	Level 2	10-Jul-06	TUL HS FFR HARD TOP
000000-00025FE0	000000- 0026D835	WIPER MOTOR SEIZED (SMOKE FROM DASH)	Closed	Non- Taskworthy	No	Level 2	18-Jul-06	TUL HS FFR HARD TOP
000000-0001BF4B		Initial Usage	Closed	Fully Fit	No	Level 1	08-Jun-06	TUL HS FFR HARD TOP
000000-0001BF52		Initial Maintenance	Closed	Fully Fit	No	Level 1	08-Jun-06	TUL HS FFR HARD TOP

Work Objects

Serial Number: LU55AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-00CB1E2E	000000-0034B5F3	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	11-Aug-22	Level 1	Fully Fit	CL	000:00		
000000-00CEC2C1		No	6 Monthly/10000 Kms	10-Feb-21	Level 1	Fully Fit	CL	000:00		
000000-00113F8D		No	6 Monthly/10000 Kms	10-Feb-21	Level 1			000:00		
000000-00BC2786		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	06-Sep-21	Level 2			000:00		
J06117-14508008		No	6 Monthly/10000 Kms	10-Feb-21	Level 1			000:00		
000000-00CEC2C3		No	Yearly/20000 Kms	11-Aug-21	Level 1	Fully Fit	CL	000:00		
000000-00BC2781		No	6 Monthly/10000 Kms	10-Feb-21	Level 1			000:00		
000000-0015AA6E		No	6 Monthly/10000 Kms	10-Feb-21	Level 1			000:00		
J06117-14508007		No	Weekly (AR)(1)		Level 1			000:00		

		OOPS 5 Yearly/155000 Kms Drain			
000000-00BC2773	No	And Replen Gearbox Oil (2)	03-Dec-22 Level 2		000:00
J06117-14508006	No	2 Yearly/40000 Kms	11-Aug-22 Level 1		000:00
000000-00BC2780	No	Yearly/20000 Kms	11-Aug-21 Level 1		000:00
000000-00BC2774	No	Yearly/20000 Kms	11-Aug-21 Level 1		000:00

		OOPS 2 Yearly/40000 Kms Replace			
J06117-1450800E	No	Air Cleaner Element (1)	11-Aug-22 Level 1		000:00
000000-00BC276B	No	6 Monthly/10000 Kms	10-Feb-21 Level 1		000:00
000000-0007EAD9	No	Yearly/20000 Kms	11-Aug-21 Level 1	CL	000:00
000000-0007EADA	No	6 Monthly/10000 Kms	10-Feb-21 Level 1	CL	000:00
000000-0007EADB	No	First 1600 Kms (AR)	Level 2	CL	000:00
000000-000DE3AA	No	Weekly (AR)(1)	Level 1	CL	000:00
000000-00078C93	No	5 Yearly/100000 Kms (1)	Level 1	CL	000:00
000000-000C3025	No	6 Monthly/10000 Kms	10-Feb-21 Level 1	CL	000:00
000000-0009CB4C	No	2 Yearly/40000 Kms	11-Aug-22 Level 1	CL	000:00
000000-0009CAB9	No	6 Monthly/10000 Kms	10-Feb-21 Level 1	CL	000:00
000000-0009CABA	No	Yearly/20000 Kms	11-Aug-21 Level 1	CL	000:00
000000-0007EC07	No	6 Yearly/120000 Kms (2)	Level 2	CL	000:00
000000-000AD3C7	No	6 Monthly/10000 Kms	10-Feb-21 Level 1	CL	000:00
000000-00018DCE	No	Yearly/20000 Kms	11-Aug-21 Level 1	CL	000:00
000000-00018DCF	No	6 Monthly/10000 Kms	10-Feb-21 Level 1	CL	000:00
000000-00036FCF	No	6 Monthly/10000 Kms	10-Feb-21 Level 1	CL	000:00
000000-000596A7	No	Weekly (AR)(1)	Level 1	CL	000:00

		OOPS 5 Yearly/155000 Kms Drain			
J06117-1450800B	No	And Replen Gearbox Oil (2)	03-Dec-22 Level 2		000:00
000000-001035F1	No	6 Monthly/10000 Kms	10-Feb-21 Level 1	CL	000:00
000000-0005B4EE	No	2 Yearly/40000 Kms	11-Aug-22 Level 1	CL	000:00
000000-000BBA9A	No	Yearly/20000 Kms	11-Aug-21 Level 1	CL	000:00
000000-000CE0F3	No	6 Monthly/10000 Kms	10-Feb-21 Level 1	CL	000:00
000000-0000D7DC	No	5 Yearly/100000 Kms (1)	Level 1	CL	000:00

000000-000098AD	No	6 Yearly/120000 Kms (2) OOPS 6 Yearly/120000 Kms	Level 2	CL	000:00
J06117-1450800A	No	Camshaft Timing Belt (2)	06-Sep-21 Level 2		000:00
000000-00BC2776	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	11-Aug-22 Level 1		000:00
000000-00CB1E2D	000000- 0034B5F3 No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	11-Aug-22 Level 1	Fully Fit CL	000:00
J06117-1450800D	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	03-Dec-22 Level 1		000:00
000000-0015AA6D	No	Yearly/20000 Kms	11-Aug-21 Level 1		000:00
000000-00CB1E22	000000- 0034B5F3 No	2 Yearly/40000 Kms OOPS 5 Yearly Drain/Flush And	11-Aug-22 Level 1	Fully Fit CL	000:00
000000-00BC2775	No	Replen Cooling System	03-Dec-22 Level 1		000:00
000000-0015AA6C	No	2 Yearly/40000 Kms	11-Aug-22 Level 1		000:00
J06117-1450800F	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	11-Aug-22 Level 1		000:00
J06117-1450800C	No	First 1600 Kms (AR)	Level 2		000:00
000000-00BC2777	No	6 Monthly/10000 Kms	10-Feb-21 Level 1		000:00
000000-00BC275D	No	2 Yearly/40000 Kms	11-Aug-22 Level 1		000:00
000000-00BC2778	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	11-Aug-22 Level 1		000:00
J06117-14508009	No	Yearly/20000 Kms	11-Aug-21 Level 1		000:00

Work Objects

Serial Number: LU55AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated
															Repair Time
000000-00771FF2	46	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-00771FF0	35	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-00771FF4	17	Introduction of Battery Retention		No	1/A	UTI				Fully Fit	CL	Level 2			000:00
000000-006F4653	17	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F695D	30	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F531D	25	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F7A92	35	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-0068DDDB	46	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-007026C4	24	Fitting of Trailer Breakaway Attachment Plate Spare Wheel Adaptor Plates; Left and Right		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-007527C2	29	Hand Installation		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-0071941D	37	Fitting Glow Plug Timer Interface Harness		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-007014B4	19	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00771FF3	25	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Fully Fit	CL	Level 2			
000000-00772005	30	Front Belt Protection Sleeves		No	1/A	UTI				Fully Fit	CL	Level 2			
000000-00629BCB	39	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-00629CDA	37	Fitting Glow Plug Timer Interface Harness		No	-/-	UTI				Fully Fit	CL	Level 2			

000000-0000B403	Input / Output Porthole for Comms / Power	8	Cable Installation	No	-/	RTI	Fully Fit	CL
000000-0000B09C	7 TUAAM Earth Bonding Improvements	7	TUAAM Earth Bonding Improvements	No	-/	RTI	Fully Fit	CL
000000-0000C0B2	Fitting Radio Frequency Radiated Hazard	12	(RADHAZ) Protection Kit	No	1/A	RTI	Fully Fit	CL
000000-0000AA54	1 Radio Rack Fixings	1	Radio Rack Fixings	No	-/	RTI	Fully Fit	CL
000000-000219AC	3 Heli-lift Vehicle Modification (Hard Top Only)	3	Heli-lift Vehicle Modification (Hard Top Only)	No	-/	RTI	Fully Fit	CL
000000-0001E98B	Fitting of Spare Wheel Tyre Inflation Valve	6	Extension	No	-/	RTI	Fully Fit	CL

Work Objects

Serial Number: LU55AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-00BC2734		No	FMT933 (W) Role Equipment (2)*	12-Nov-19	Level 2			000:00		
000000-00BC2760		No	FMT932 (W) Mandatory Equipment Inspection (2)*	12-Nov-19	Level 2			000:00		
000000-00BC2732		No	Ad Hoc Insp (AR)		Level 1			000:00		
000000-00BC2733		No	Annual Smoke Emissions Test(2)	12-Dec-19	Level 2			000:00		
000000-00166AB3		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00BC275F		No	FMT934 Functional Check (1)*	11-Oct-19	Level 1			000:00		
000000-00BC2754		No	Ad Hoc Insp (AR)		Level 1			000:00		
J06117-14508005		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00BC2757		No	FMT934 Functional Check (1)*	11-Oct-19	Level 1			000:00		
000000-0015AA75		No	MEI (2)		Level 2			000:00		
000000-000F419C		No	MEI (2)		Level 2		CL	000:00		
000000-0008EC86		No	MEI (2)		Level 2		CL	000:00		

000000-000E62CF	No	MEI (2)		Level 2	CL	000:00
000000-000D9116	No	MEI (2)		Level 2	CL	000:00
		FMT932 (W) 6 Monthly Safety				
000000-00BC2756	No	Inspection (2)	11-Oct-19	Level 2		000:00
000000-00BC2735	No	FMT931 Comms (2)*	11-Oct-19	Level 2		000:00
000000-00BC2761	No	Annual Brake Test (2)	12-Dec-19	Level 2		000:00
		FMT932 (W) 6 Monthly Safety				
000000-00BC275E	No	Inspection (2)	11-Oct-19	Level 2		000:00
		Annual Headlight Alignment				
000000-00BC2762	No	Check (2)	12-Dec-19	Level 2		000:00
000000-00BC2755	No	FMT931 Comms (2)*	11-Oct-19	Level 2		000:00
000000-0005B3CD	No	MEI (2)		Level 2	CL	000:00