

Ed Hyland (Mr)
Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

Our Reference: FOI2022/11126 Date: 12 October 2022

I am writing about your email of 27 September 2022, requesting the following information:

I have recently purchased an ex military defender 110. I have checked the release MERLIN data base and the vehicle service history is not contained in the available published MERLIN extract (the vehicle has recently just come out of service).

Therefore I submit a FOI request for the following information;

- 1) Vehicle military service history (units served etc as contained in the MERLIN/James).
- 2) Any maintenance records / work objects related to this vehicle.

Vehicle registration: HM 86 AA

VIN number: SALLDBA67VA104468

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

- Annex A Ownership History of HM86AA (redacted)
- Annex B Fault History of HM86AA (redacted)
- Annex C Inspection History of HM86AA
- Annex D Modification History of HM86AA
- Annex E Servicing History of HM86AA

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the Ownership History (Annex A) relating to sensitive units with which this vehicle served has been redacted under the qualified exemptions S26(1)(a) (Defence) and Section 38(1)(a) (Health and Safety). In addition, commercially sensitive information in the Fault History of HM86AA relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the

**Defence Equipment & Support** 

commercial interests of any person (including defence contractors and the public authority holding it).

As these exemptions are qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, releasing the information redacted under Sections 26 and 38 in the Ownership History (Annex B) would divulge information that could be used to compromise the ability of UK Armed Forces to carry out operations safely by revealing information about capabilities and actions which would assist adversaries in planning attacks against personnel and equipment. This would endanger the lives of Armed Forces personnel and disrupt or limit military operations and capabilities.

The Fault History provides details of the time taken by MOD contractors to rectify fault reports. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at https://ico.org.uk/.

Yours sincerely,

Ed Hyland

Ed Hyland (Mr) DE&S Policy Secretariat

# **VEHICLE DETAILS**

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
				TRUCK UTY MED (TUM) (HS) 4X4 FFR HARD TOP LAND	Army/NATO
HM86AA	2320998939744	NB50203100	LV2A/088DUM	ROVER 2.5 LTR TURBO DSL (WITH EEGR)	Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
19/02/1997	SALLDBA67VA104468	25L00275A		

# **VEHICLE HISTORY**

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
HM86AA	3	18/02/1997	CA005A	JSCS ASHCHURCH	CAPITA	23900AA	19/02/1997	
						ı-		
HM86AA		06/11/2020		OSVP CVS HOLDINGS			09/11/2020	

Serial Number: HM86AA NSN: 2320998939744

Criteria:

Repair Level: ALL Work Object Status: Closed Mission Impact: ALL Fault State: ALL. ALL Escalate Work:

Work Request ID:

Assigned Work Status: ALL Working Organisation: Repair Section:

						Batch Fault	: Fault						
	Work	Work		Escalate	Repair	Group ID	Occurrence	Mission		Level 3	Working	Repair	Estimated
Fault ID	Request ID Fault Description	Status	Fault State	Work	Level	Number	Date	Impact	Reason For Work	Description	Organisation	Section	Repair Time
	000000-									TUM HS FFR	14 REGT RA,	RSAPRECL	
000000-00C224A9	00355BA9 PT Reclamation Task		Fully Fit	Nο	Level 2		17 May 2021	N/A	Reclamation	HARD TOP	WKSP	AMATION	000:00
000000-00B85595	SLIGHT OIL LEAK FROM ENGINE	Closed	Fully Fit	No	Level 2		10 Dec 2019	N/A	Closed No Action	TUM HS FFR			
	MEI 933 - ADVISORIES - 1 - ENGINE BAY									TUM HS FFR			
000000-0097141A	FUSE COVER MISSING	Closed	Fully Fit	Nο	Level 1		03 Jun 2019	N/A	Failure	HARÐ TOP			000:00
	SNvE 377 - SWIVEL HOUSING NON		Non-			000000-				TUM HS FFR			
000000-00B200B0	COMPLIANT O/S/F	Closed	Taskworthy	No	Level 1	0000697A	03 Jun 2019	N/A	Inspection	HARD TOP			00:00
			Non-							TUM HS FFR			
000000-00B8553A	BAAN - R/R WHEEL R/H AXLE 1	Closed	Taskworthy	No	Level 2		20 Nov 2019	N/A	Inspection	HARD TOP			000:00
000000 00044000	WORK CARRIED OUT AS PER CUSTOMER	<b>a</b>	- 11 -11							TUM HS FFR			
000000-00B41089	REQUEST - SALES ORDER 8B0158449		Fully Fit	No	Level 2		04 Jun 2019	N/A	Inspection	HARD TOP			00:00
000000 00041005	BAAN - 280 - 0010 - STEAM CLEAN ENGI		Non-							TUM HS FFR			
000000-00B4103E	AND TRANSMISSION	Closed	•	No	Level 2		21 May 2019	N/A	Inspection	HARD TOP			000:00
000000 00041010	BAAN - 290 - 1915 - REMOVE AND REFIT	611	Non-	N4.	110		24.4			TUM HS FFR			
000000-00B4101D	WHEEL LH AXLE 2	Closea	Taskworthy	No	Level 2		21 May 2019	N/A	Inspection	HARD TOP			00:00
000000-00B41016	BAAN - 290 - 3819 - RENEW BATTERY BO	v Classi	Non-	Na	113		24 14-1-2040	NI fA	1	TUM HS FFR			
000000-00041016	BAAN - 290 - 3819 - RENEW BATTERY BC	X Closed	Taskworthy Non-	No	Level 2		21 May 2019	N/A	Inspection	HARD TOP			00:00
000000-00B41000	ITEMS	Classel	Taskworthy	No	1 1 2		24 84 2010	NI FA	1	TUM HS FFR			
000000-00841000	BAAN - 290 - 6642 - REMOVE AND REFIT	Closed	Non-	NO	Level 2		21 May 2019	N/A	Inspection	HARD TOP			00:00
000000-00B40FF2	FRONT REMUS BARS	Closed	Taskworthy	No	Level 2		21 May 2019	NI/A	1ti	TUM HS FFR HARD TOP			000.00
000000-00040112	BAAN - 280 - 4047 - RENEW TRANSFER	Cioseu	Non-	NO	Level 2		21 May 2019	N/A	Inspection	TUM HS FFR			00:00
000000-00B40FE5	BOX DIFF LOCK SWITCH	Closed	Taskworthy	No	Level 2		21 May 2019	NI/A	Inspection	HARD TOP			000:00
000000 00040123	BAAN - 280 - 0424 - RENEW WATER PUN		Non-	NO	LEVE! &		21 May 2013	IVA	mspection	TUM HS FFR			000.00
000000-00B40FDA	DRIVE BELT TENSIONER PULLEY		Taskworthy	Nο	Level 2		21 May 2019	N/A	Inspection	HARD TOP			000:00
	BAAN - 280 - 5056 - RENEW BODY LHR	3,550	Non-		2010, 2		21 11107 2015	147.1	тэрссион	TUM HS FFR			000.00
000000-00B40FB5	PANEL SILL BODY	Closed	Taskworthy	No	Level 2		21 May 2019	N/A	Inspection	HARD TOP			000:00
	BAAN - 280 - 1971 - RE-CHECK WHEEL N		Non-		J0 701 &		22 11107 2015			TUM HS FFR			000.00
000000-00B40F1D	TORQUE		Taskworthy	No	Level 2		21 May 2019	N/A	Inspection	HARD TOP			000:00
		5.5564			30701 E		11147						200.00

	BAAN - 280 - 2926 - RENEW BRAKE PIPE,		Non-						TUM HS FFR	
000000-00B40EC8	LHF CALIPER BRAKES	Closed	Taskworthy	No	Level 2	21 May 201	l9 N/A	Inspection	HARD TOP	000:00
	CARRY OUT MEI RETEST WITHIN 28 DAYS		Non-						TUM HS FFR	
000000-00B3F657	FAILED MEI 932 - 03.04.19	Closed	Taskworthy	No	Level 2	03 Apr 201	9 N/A	Inspection	HARD TOP	00:00
			Non-						TUM HS FFR	
000000-00B3F20F	MEI - 933 - DEFECTS - 1 - 4X4 LIGHT INOP	Closed	Taskworthy	No	Level 2	03 Apr 201	A/N G	Inspection	HARD TOP	000:00
	MEI - 933 - DEFECTS - 49 - UNABLE TO		Non-						TUM HS FFR	
000000-00B3F1FE	ROAD TEST DUE TO FAILED 932	Closed	Taskworthy	No	Level 2	03 Apr 201	N/A	Inspection	HARD TOP	00:00
	MEI - 933 - DEFECTS - 42 - WHEEL NUT		Non-					·	TUM HS FFR	
000000-00B3F00B	INDICATORS NOT FITTED	Closed	Taskworthy	No	Level 2	03 Apr 201	N/A	Inspection	HARD TOP	000:00
	MEI - 933 - DEFECTS - 7 - N/S REAR &		Non-			<u>-</u>	·	•	TUM H\$ FFR	
000000-0083F009	SPARE TYRE WRONG PATTERN	Closed	Taskworthy	No	Level 2	03 Apr 201	N/A	Inspection	HARD TOP	000:00
	MEI - 932 - DEFECTS - 6.1 - N/S & O/S		Non-				,		TUM HS FFR	000.00
000000-00B3EF81	FRONT CYLS CORRODED INSECURE	Closed	Taskworthy	No	Level 2	03 Apr 201	N/A	Inspection	HARD TOP	000:00
			, , , , , , , , , , , , , , , , , , , ,			00 Fibi 202	. 11,7.1	mapeetion	TIME TO	000.00
	MEI - 932 - DEFECTS - 1.1 - BOTH REAR		Non-						TUM HS FFR	
000000-00B3EEF7	BRAKE PIPES CORRODED AND INSECURE	Closed	Taskworthy	No	Level 2	03 Apr 201	N/A	Inspection	HARD TOP	000:00
	MEI - 932 - DEFECTS - 1.1 - N/S/R/ BRAKE	0.0324	Non-	****	CCVCIZ	03 Apr 201	7 11/7	mspection	TUM HS FFR	000.00
000000-00B3EEFA	CALIPER BINDING	Closed	Taskworthy	No	Level 2	03 Apr 201	9 N/A	Inconnection	HARD TOP	000.00
CCCCCC-CCCCCCC	MEI - 932 - DEFECTS - 1.1 - N/S/F METAL	Closed	Non-	140	Level Z	05 Apr 201	) N/A	Inspection		000:00
000000-00B3EEF2	BRAKE PIPE CORRODED	Classed		A1-	Lavela	02.4201			TUM HS FFR	
000000-00B3EEF2	BRAKE PIPE CORRODED	Ciosea	Taskworthy	No	Level 2	03 Apr 201	N/A	Inspection	HARD TOP	000:00
	MEI - 932 - DEFECTS - 1.1 - N/S F BRAKE		Nen						T1144114 655	
000000-00B3EEF5	·	Classed	Non-	N1 -	1 1 2	00.4 004			TUM HS FFR	
000000-0063EEF5	PIPE CLAMP CORRODED AND SNAPPED	Closea	Taskworthy	No	Level 2	03 Apr 201	₹ N/A	Inspection	HARD TOP	000:00
000000 00033500	Chi mana districti i conscisso	a	- 11 -1.		0000				TUM HS FFR	
000000-00B22C90	SNvE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1 0000	0697B 29 Mar 201	9 N/A	Inspection	HARD TOP	000:00
000000 00074444	MEI - 933 - DEFECTS - 42 - EMERGENCY		Non-						TUM HS FFR	
000000-00971411	HAMMER MISSING	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Non Specific	HARD TOP	000:00
	MEI - 932 - DEFECTS - 6.2 - O/S SEAT		Non-						TUM HS FFR	
000000-00B3EF85	FLOOR BASE CORRODED AND SPLIT	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	00:00
	MEI - 932 - DEFECTS - 6.1 - N/S & O/S/F		Non-						TUM HS FFR	
000000-00B3EF79	FLOOR PANS CORRODED AND HOLED	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	00:00
	MEI - 933 - DEFECTS - 1 - SHOVEL PAD ON		Non-						TUM HS FFR	
000000-00B3F208	BONNET U/S	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	00:00
	MEI - 933 - DEFECTS - 1 - BONNET STAY		Non-						TUM HS FFR	
000000-00B3F211	CLIP MISSING	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	000:00
	MEI - 933 - DEFECTS - 1 - FUEL & TEMP		Non-						TUM HS FFR	
000000-00B3F215	GAUGE ILLUMINATION INOP	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	000:00
			Non-						TUM HS FFR	
000000-00B3F218	MEI - 933 - DEFECTS - 1 - FAN BELT NOISY	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	000:00
	MEI - 933 - DEFECTS - 1 - FRONT TOW		Non-						TUM HS FFR	
000000-00B3F219	PINTLE MISSING	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	000:00
	MEI - 933 - DEFECTS - 1 - AIR FILTER		Non-					•	TUM HS FFR	
000000-00B3F21C	MOUNTS SPLIT	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	000:00
	MEI - 933 - DEFECTS - 5 - EARTH STRAP ON		Non-			•			TUM HS FFR	333,33
000000-00B3FQQ7	O/S/F DOOR BROKEN	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	000:00
	MEI - 933 - DEFECTS - 5 - EARTH STRAP ON		,				,	Wispediion	TUM HS FFR	250.00
000000-0089C0A1	REAR DOOR BROKEN		Fully Fit	No	Level 1	03 Apr 2019	N/A	Damage	HARD TOP	000:00
	MEI - 933 - DEFECTS - 2 - CONVOY LIGHT	J. JJC4	Non-		2040, 1	00 Abi 201:	11/1	Camage	TUM HS FFR	300.00
000000-00B3F002	INOP	Closed	Taskworthy	No	Level 2	03 Apr 2019	N/A	Inspection	HARD TOP	000:00
113000 00001 002		Cioseu	. askwoi tity	110	CEVEL Z	03 Apr 201:	/ IN/A	mapection	HARD TOP	000:00

		MEI - 932 - DEFECTS - 8.1 - EXHAUST		Non-							TUM HS FFR	
000000-00B3EF8E		CENTRE PIPE CORRODED AND SNAPPED MEI - 932 - DEFECTS - 5.3 - REAR 'A' FRAME	Closed	Taskworthy Non-	No	Level 2	03 Apr	r 2019	N/A	Inspection	HARD TOP TUM HS FFR	000;00
000000-00B3EF3F		BALL JOINT RUBBER SPLIT			No	Level 2	03 Apr	2019	N/A	Inspection	HARD TOP	00:00
		MEI - 932 - DEFECTS - 5.3 - N/S & O/S		Non-			•				TUM HS FFR	
000000-00B3EF37		RADIUS ARM BUSHES WORN	Closed	Taskworthy	No	Level 2	03 Apr	2019	N/A	Inspection	HARD TOP	00:00
		MEI - 932 - DEFECTS - 5.3 - N/S & O/S TOP								•		
		AND BOTTOM SHOCK ABSORBER BUSHES		Non-							TUM HS FFR	
000000-00B3EF32		U/S	Closed	Taskworthy	No	Level 2	O3 Apr	2019	N/A	Inspection	HARD TOP	000:00
		MEI - 932 - DEFECTS - 4.9 - HAZARD		Non-							TUM HS FFR	
000000-0083EF2C		WARNING TELL TALE INOP	Closed	•	No	Level 2	03 Apr	2019	N/A	Inspection	HARD TOP	000:00
		MEI - 932 - DEFECTS - 4.2 - O/S/F SIDE		Non-							TUM HS FFR	
000000-00B3EF27		LIGHT INOP	Closed	Taskworthy	No	Level 2	03 Apr	2019	N/A	Inspection	HARD TOP	00:00
000000 00025555		MEI - 932 - DEFECTS - 3.4 - WIPER BLADES	Ct1	Non-					****		TUM HS FFR	
000000-00B3EEFE		U/S MEI - 932 - DEFECTS - 2.1 - WRONG NUT	ciosea	Taskworthy	No	Level 2	03 Apr	2019	N/A	Inspection	HARD TOP	00:00
000000-00B3EEFD		FITTED TO N/S TRACK ROD END	Closed	Non- Taskworthy	No	Lovel 3	02 4	2010	NI /A	I	TUM HS FFR	000.00
000000-00B3EEFD		MEI - 932 - DEFECTS - 1.1 - HANDBRAKE	Ciosen	Non-	No	Level 2	03 Apr	2019	N/A	Inspection	HARD TOP	00:00
000000-0083EEEF		LEVER INSECURE	Closed	Taskworthy	No	Level 2	03 Apr	2010	N/A	Inconstian	TUM HS FFR	000.00
000000 00032221		ELVEN MOLCONE	Ciosea	Taskworthy	NO	Level 2	US Apr	2015	N/A	Inspection	HARD TOP	00:00
		WORK CARRIED OUT AS PER CUSTOMER									TUM HS FFR	
000000-00B3F65C		REQUEST - SALES ORDER 8B0158449	Closed	Fully Fit	Nο	Level 2	29 May	y 2019	N/A	Inspection	HARD TOP	000:00
		Wiring Loom Fire - Land Rover TUM (HS)						,	,,,,,	mopeonion	1000	000.00
		all variants, TUL (HS) all variants and Battle										
		Field Ambulance (8FA) post embodiment										
		instruction Mod 41 - Battery Isolation				0000	00-				TUM HS FFR	
000000-00A42107		instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	00000 Level 2 00004		2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A42107 000000-00B3F272		•		Fully Fit	No No				N/A N/A	Inspection Inspection		000:00 000:00
000000-0083F272		Switch. BAAN - 270 - INSPECTION	Closed	Fully Fit Non-	No	Level 2 00000 Level 2	451D 28 Jul 2 20 May	y 2019	-		HARD TOP	
		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S	Closed	Fully Fit Non- Taskworthy		Level 2 0000	451D 28 Jul 2	y 2019	-		HARD TOP TUM HS FFR TUM HS FFR HARD TOP	
000000-00B3F272 000000-009CBDF7		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE	Closed Closed	Fully Fit Non- Taskworthy Non-	No No	Level 2 00000- Level 2	451D 28 Jul 2 20 May 28 Sep	y 2019 2016	N/A N/A	Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR	000:00
000000-0083F272		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S	Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy	No	Level 2 00000 Level 2	451D 28 Jul 2 20 May	y 2019 2016	N/A	Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR HARD TOP	
000000-0083F272 000000-009CBDF7 000000-00981EA8		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.	Closed Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non-	No No No	Level 2 00000- Level 2 Level 2 Level 1	451D 28 Jul 2 20 May 28 Sep 30 Mar	y 2019 2016 r 2016	N/A N/A N/A	Inspection Inspection Servicing	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR HARD TOP TUM HS FFR	000:00
000000-00B3F272 000000-009CBDF7		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS	Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy	No No	Level 2 Cooperation Cooperatio	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar	y 2019 2016 r 2016	N/A N/A	Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR HARD TOP TUM HS FFR HARD TOP	000:00
000000-00B3F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA		Switch.  BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as	Closed Closed Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non-	No No No	Level 2 COOOO	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar	y 2019 2016 r 2016 r 2016	N/A N/A N/A	Inspection Inspection Servicing Servicing	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR	000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS	Closed Closed Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy	No No No	Level 2 Cooperation Cooperatio	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar	y 2019 2016 r 2016 r 2016	N/A N/A N/A	Inspection Inspection Servicing	HARD TOP TUM HS FFR TUM HS FFR HARD TOP	000:00
000000-00B3F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA		Switch.  BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as	Closed Closed Closed Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Non-	No No No No	Level 2 00000 Level 2 Level 1 Level 2 00000 Level 2 00000	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 00- 3207 19 Jan	y 2019 2016 r 2016 r 2016 2016	N/A N/A N/A N/A	Inspection Inspection Servicing Servicing Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR	000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA 000000-009615C2		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063	Closed Closed Closed Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy	No No No	Level 2 00000 Level 2 Level 1 Level 2 00000 Level 2 000000 Level 1 Level 1	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 00- 3207 19 Jan 18 Feb	y 2019 2016 r 2016 r 2016 2016	N/A N/A N/A N/A N/A N/A	Inspection Inspection Servicing Servicing Inspection Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP	000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA 000000-009615C2 000000-00971420		Switch.  BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT	Closed Closed Closed Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Non-	No No No No No	Level 2 00000 Level 2 Level 1 Level 2 00000 Level 2 00000	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 00- 3207 19 Jan 18 Feb	y 2019 2016 r 2016 r 2016 2016	N/A N/A N/A N/A N/A N/A	Inspection Inspection Servicing Servicing Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR	000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA 000000-009615C2 000000-00971420		Switch.  BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT	Closed Closed Closed Closed Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Fully Fit Non-	No No No No No	Level 2 00000 Level 2 Level 1 Level 2 00000 Level 2 000000 Level 1 Level 1	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 00- 3207 19 Jan 18 Feb	y 2019 2016 r 2016 r 2016 2016 2016 2016	N/A N/A N/A N/A N/A N/A	Inspection Inspection Servicing Servicing Inspection Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR	000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA 000000-009615C2 000000-00971420 000000-008DEDE8		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT PLEASE CARRY OUT MEI	Closed Closed Closed Closed Closed Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Fully Fit Non-	No No No No No No	Level 2	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 30- 3207 19 Jan 18 Feb 26 Nov	y 2019 1 2016 1 2016 1 2016 2016 2016 2016 2016 2015	N/A N/A N/A N/A N/A N/A N/A	Inspection Inspection Servicing Servicing Inspection Inspection Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR TUM HS FFR TUM HS FFR	000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA 000000-009615C2 000000-00971420 000000-008DEDE8		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT PLEASE CARRY OUT MEI  RENEW SERVO	Closed Closed Closed Closed Closed Closed Closed Closed Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Fully Fit Non- Taskworthy	No	Level 2	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 30 Mar 3207 19 Jan 18 Feb 26 Nov	y 2019 1 2016 1 2016 1 2016 2016 2016 2016 2016 2015 1 2015	N/A N/A N/A N/A N/A N/A N/A N/A N/A	Inspection Inspection Servicing Servicing Inspection Inspection Inspection Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP	000:00
000000-0083F272  000000-009CBDF7  000000-00981EA8  000000-00981EAA  000000-009615C2  000000-00971420 000000-008DECE8  000000-008DBC6C 000000-008BF1C9		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT PLEASE CARRY OUT MEI  RENEW SERVO CARRY OUT 2 YRLY SERVICE	Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Fully Fit Non- Taskworthy Fully Fit	No	Level 2	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 30 Mar 3207 19 Jan 18 Feb 26 Nov 18 Nov 10 Sep	y 2019 1 2016 1 2016 1 2016 2016 2016 2016 2015 2015 2015	N/A	Inspection Inspection Servicing Servicing Inspection Inspection Inspection Inspection Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR TUM HS FFR TUM HS FFR	000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA 000000-009615C2 000000-00971420 000000-008DEDE8 000000-008BF1C9 000000-008BF1CB 000000-008BF1D0		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT PLEASE CARRY OUT MEI  RENEW SERVO CARRY OUT 2 YRLY SERVICE CARRY OUT 2 YRLY L2 VM TASKS CARRY OUT 2 YRLY OOPM	Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Fully Fit Non- Taskworthy Fully Fit Fully Fit Fully Fit	No	Level 2	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 30 Mar 3207 19 Jan 18 Feb 26 Nov 18 Nov 10 Sep 10 Sep	y 2019 1 2016 1 2016 1 2016 2016 2016 2016 2015 2015 2015	N/A	Inspection Inspection Servicing Servicing Inspection Inspection Inspection Inspection Inspection Inspection Inspection Inspection Inspection Failure	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR	000:00
000000-0083F272  000000-009CBDF7  000000-00981EA8  000000-00981EAA  000000-009615C2  000000-00971420 000000-008DEC6C 000000-008BF1C9 000000-008BF1CB		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT PLEASE CARRY OUT MEI  RENEW SERVO CARRY OUT 2 YRLY SERVICE CARRY OUT 2 YRLY L2 VM TASKS	Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Fully Fit Non- Taskworthy Fully Fit Fully Fit Fully Fit Fully Fit	No	Level 2	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 30 Mar 3207 19 Jan 18 Feb 26 Nov 18 Nov 10 Sep 10 Sep	y 2019 1 2016 1 2016 1 2016 2016 2016 2016 2015 2015 2015	N/A	Inspection Inspection Servicing Servicing Inspection Inspection Inspection Inspection Inspection Inspection Inspection Inspection Inspection Failure	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR	000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA 000000-009615C2 000000-00971420 000000-008DEDE8 000000-008BF1C9 000000-008BF1CB 000000-008BF1D0		Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT PLEASE CARRY OUT MEI  RENEW SERVO CARRY OUT 2 YRLY SERVICE CARRY OUT 2 YRLY L2 VM TASKS CARRY OUT 2 YRLY OOPM  PASSENGER AIR VENT HANDLE BROKEN	Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Fully Fit Non- Taskworthy Fully Fit Fully Fit Fully Fit Fully Fit Non-	No N	Level 2 Level 2 Level 2 CO0000 Level 2 CO0000 Level 2 Cevel 1 Level 2	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 30 Mar 3207 19 Jan 18 Feb 26 Nov 18 Nov 10 Sep 10 Sep 10 Sep 03 Jun	y 2019 1 2016 1 2016 1 2016 2016 2016 2016 2015 2015 2015 2015	N/A	Inspection Inspection Servicing Servicing Inspection Inspection Inspection Inspection Inspection Inspection Inspection Inspection Inspection Failure Inspection Damage	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR	000:00 000:00 000:00 000:00 000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA 000000-009615C2 000000-00971420 000000-008DEDE8 000000-008BF1C9 000000-008BF1CB 000000-008BF1D0	000000	Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT PLEASE CARRY OUT MEI  RENEW SERVO CARRY OUT 2 YRLY SERVICE CARRY OUT 2 YRLY L2 VM TASKS CARRY OUT 2 YRLY OOPM	Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Fully Fit Non- Taskworthy Fully Fit Fully Fit Fully Fit Fully Fit Non-	No N	Level 2 Level 2 Level 2 Level 2 CO0000 Level 2 CO0000 Level 2 Level 1 Level 2	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 30 Mar 30 Mar 3207 19 Jan 18 Feb 26 Nov 18 Nov 10 Sep 10 Sep 10 Sep	y 2019 1 2016 1 2016 1 2016 2016 2016 2016 2015 2015 2015 2015	N/A	Inspection Inspection Servicing Servicing Inspection	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR HARD TOP	000:00 000:00 000:00 000:00 000:00
000000-0083F272 000000-009CBDF7 000000-00981EA8 000000-00981EAA 000000-009615C2 000000-00971420 000000-008DEDE8 000000-008BF1C9 000000-008BF1CB 000000-008BF1D0	000000-	Switch. BAAN - 270 - INSPECTION  Both Tractor Seals U/S PLEASE CARRY OUT 6 MTHLY L1 SERVICE TASKS.  CARRY OUT 6 MTHLY L2 VM TASKS Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  FIRE EXTINGUISHER REQUIRES RE-CERT PLEASE CARRY OUT MEI  RENEW SERVO CARRY OUT 2 YRLY SERVICE CARRY OUT 2 YRLY L2 VM TASKS CARRY OUT 2 YRLY OOPM  PASSENGER AIR VENT HANDLE BROKEN	Closed	Fully Fit Non- Taskworthy Non- Taskworthy Non- Taskworthy Non- Taskworthy Fully Fit Non- Taskworthy Fully Fit Fully Fit Fully Fit Fully Fit Non-	No N	Level 2 Level 2 Level 2 CO0000 Level 2 CO0000 Level 2 Cevel 1 Level 2	451D 28 Jul 2 20 May 28 Sep 30 Mar 30 Mar 30 Mar 3207 19 Jan 18 Feb 26 Nov 10 Sep 10 Sep 10 Sep 03 Jun 02 Jun	y 2019 1 2016 1 2016 1 2016 2016 2016 2016 2015 2015 2015 2015	N/A	Inspection Inspection Servicing Servicing Inspection Inspection Inspection Inspection Inspection Inspection Inspection Inspection Inspection Failure Inspection Damage	HARD TOP TUM HS FFR TUM HS FFR HARD TOP TUM HS FFR	000:00 000:00 000:00 000:00 000:00

	000000-										. TUM HS FFR
000000-00885A5A	003062E1	engine wont crank	Closed	Fully Fit	No	Level 2		31 Mar 2015	N/A	Failure	HARD TOP
							000000-				TUM HS FFR
000000-00842EEB		Towing Pintle Assembly	Closed	Fully Fit	No	Level 2	00001F58	09 Oct 2014	Degraded	Inspection	HARD TOP
		REFURB VEHICLE TO CHE ENTRY		Non-							TUM HS FFR
000000-007BB655		STANDARD	Closed	Taskworthy	No	Level 2		01 Oct 2013	N/A	Refurbishment	HARD TOP
		GOODYEAR G90 tyres manufactured in									
		South Africa cracking File Ref		Non-			000000-				TUM HS FFR
000000-007977E9		OSVP/64/40/04/09	Closed	Taskworthy	No	Level 1	0000081A	24 Jun 2013	N/A	Quarantine	HARD TOP
							000000-				TUM HS FFR
000000-0079A847		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	00000835	25 Jun 2013	N/A	Inspection	HARD TOP
000000-00406DA4		Initial Maintenance	Closed	Fully Fit	No	Level 1		29 Mar 2009			TUM HS FFR
000000-00406D9D		Initial Usage	Closed	Fully Fit	No	Level 1		29 Mar 2009			TUM HS FFR
				•							

•



Serial Number: HM86AA

NSN: 2320998939744

Criteria:

Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL
Escalate Work: ALL

Work Request ID:

Assigned Work Status: ALL

Working Organisation:

Repair Section:

								Estimated		
		Escalate	Maintenance Event	Next Due	Repair		Work	Repair	Working	Repair
Maintenance Event ID	Work Request ID	Work	Name	Date	Level	Fault State	Status	Time	Organisation	Section
000000-002F7B82		No	MEI (2)	02 Jun 2020	Level 2			00:00		
						Non-				
000000-00B0C66F		No	6 Monthly 6534 Insp	09 Jun 2020	Level 1	Taskworthy	CL	00:00		
000000-00641BED		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-002F7B84		No	6 Monthly 6534 Insp	09 Jun 2020	Level 1			00:00		
						Non-				
000000-00B06888		No	6 Monthly 6534 Insp	09 Jun 2020	Level 1	Taskworthy	CL	000:00		
000000-0049F244		No	6 Monthly 6534 Insp	09 Jun 2020	Level 1			000:00		
000000-00561778		No	6 Monthly 6534 Insp	09 Jun 2020	Level 1			000:00		
000000-00641BEC		No	6 Monthly 6534 Insp	09 Jun 2020	Level 1			000:00		

C	00000-006CF1D0	No	First Parade Insp (AR)(1)		Level 1			000:00
C	00000-0049F243	No	MEI (2)	02 Jun 2020	Level 2			000:00
C	00000-006CF1CF	No	6 Monthly 6534 Insp	09 Jun 2020	Level 1			000:00
						Non-		
C	00000-00BE2977	No	6 Monthly 6534 Insp	09 Jun 2020	Level 1	Taskworthy	CL	000:00
C	00000-003C77BD	No	6 Monthly 6534 Insp	09 Jun 2020	Level 1			000:00
C	00000-00641BEB	No	MEI (2)	02 Jun 2020	Level 2			000:00
						Non-		
C	00000-00B0C658	No	MEI (2)	02 Jun 2020	Level 2	Taskworthy	CL	000:00
						Non-		
C	00000-00B06881	No	MEI (2)	02 Jun 2020	Level 2	Taskworthy	CL	000:00

•

 Serial Number:
 HM86AA

 NSN:
 2320998939744

Criteria:

Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL
Escalate Work: ALL

Work Request ID:

Assigned Work Status: ALL

Working Organisation:

Repair Section:

	Modification		Work Request	Escalate	Production Classification/I n Service	Modification		Embody by Targe	Usage t Counter		Work	Repair	Working	Repair	Estimated Repair
Modification Event ID	Number	Modification Description FITTING OF WHEEL NUT INDICATORS TO	ID	Work	Classification	Туре	Equals	Date	Units	Fault State	Status	Level	Organisation	Section	Time
000000-00695199	00046	LAND ROVER HS PLATFORMS Fitting of a New Import/Export Box Mount		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-0060AD65	00038	Bracket Rear Door Blackout Blind (FFR Variants)		No	<b>-/</b> -	υτι				Fully Fit					
000000-0060AD4F	00033	Only Spare Wheel Adaptor Plates; Left and		No	-/-	UTI				Fully Fit					
000000-0060AD23	00029	Right Hand Installation Fitting Radio Frequency Radiated Hazard		No	-/-	UTI				Fully Fit					
000000-0060ACDF	00012	(RADHAZ) Protection Kit Input / Output Porthole for Comms /		No	1/A	RTI				Fully Fit					
000000-0060ACD7	80000	Power Cable Installation		No	-/	RTI				Fully Fit	CL				
000000-0060ACA7	00007	TUAAM Earth Bonding Improvements Heli-lift Vehicle Modification (Hard Top		No	-/	RTI				Fully Fit	CL				
000000-0060ACA9	00003	Only) Project SHOEHORN Revised Weight Data		No	-/	RTI				Fully Fit					
000000-0060AD33	00032	Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0060AD09	00028	FITTING OF REAR ANTI-ROLL BAR (RARB) Fitting of Trailer Breakaway Attachment		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0060ACF7	00024	Plate Radio Battery Isolation Switch and Power		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0060ACC9	00016	Import / Export System		No	-/	RTI				Limited Role	CL	Level 2			
000000-0060ACEF	00019	Blackout Cover for Warning Light Panel Roof Mounted Communication		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-0060AC8D	00002	Installation (Blanking Plate Only)		No	-/	RTI				Limited Role	CL	Level 2			
000000-0060AD13 000000-0060AD39	00025 00030	Fitting of Spare Wheel Lifting Aid Harness Front Belt Protection Sleeves		No No	1/A 1/A	UTI UTI				Non-Taskworthy Non-Taskworthy		Level 2 Level 2			

000000-0060AD5D	00037	Fitting Glow Plug Timer Interface Harness	No	-/	UTI	Fully Fit	CL	Level 2
000000-0060AD41	00035	Fitting of Emergency Hammer	No	1/A	UTI	Non-Taskworthy	CL	Level 2
000000-0060AC9B	00001	Radio Rack Fixings	No	-/	RTI	Limited Role	CL	Level 2
000000-0060AD01	00020	8 Metre Mast Mount Installation Kit	No	-/-	UTI	Fully Fit	CL	Level 2
		Fitting of Spare Wheel Tyre Inflation Valve						
000000-0060ACB9	00006	Extension	No	-/	RTI	Limited Role	CL	Level 2
000000-0060ACF9	00017	Introduction of Battery Retention	No	1/A	UTI	Non-Taskworthy	CL	Level 2
		Input/Output Porthole for						
		Communication Cables, Cover						
000000-0060AD1B	00027	Modification	No	-/	UTI	Fully Fit	CL	Level 2

Serial Number: HM86AA

NSN: 2320998939744

Criteria:

Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL
Escalate Work: ALL

Work Request ID:

Assigned Work Status: ALL

Working Organisation:

Repair Section:

	Work							Estimated		
	Request	Escalate		Next Due	Repair		Work	Repair	Working	Repair
Maintenance Event ID	ID	Work	Maintenance Event Name	Date	Level	Fault State	Status	Time	Organisation	Section
			OOPS 5 Yearly/155000 Kms Drain							
000000-002F7BC2		No	And Replen Gearbox Oil (2)	01 Apr 2024	Level 2			00:00		
			OOPS 2 Yearly/40000 Kms							
000000-002F7BBC		No	Replace Air Cleaner Element (1)	02 Apr 2021	Level 1			00:00		
			OOPS 5 Yearly Drain/Flush And	•		Non-				
000000-00A56426		No	Replen Cooling System	01 Apr 2024	Level 1	Taskworthy	CL	000:00		
000000-005E9F81		No	Yearly/20000 Kms	02 Apr 2020	Level 1			000:00		
			OOPS 2 Yearly/20000 Kms Drain			Non-				
000000-00A56420		No	Engine Oil And Filter Change (1)	02 Apr 2021	Level 1	Taskworthy	CL	00:00		
000000-00669417		No	Weekly (AR)(1)	•	Level 1	ŕ		000:00		
000000-00669416		No	6 Monthly/10000 Kms	20 May 2020	Level 1			000:00		

		OOPS 5 Yearly/155000 Kms Drain			Non-		
000000-00B055AC	No	And Replen Gearbox Oil (2)	01 Apr 2024	Level 2	Taskworthy	CL	000:00
000000-005612B8	No	6 Monthly/10000 Kms	20 May 2020	Level 1			000:00
000000-005E9F84	No	6 Monthly/10000 Kms	20 May 2020	Level 1			000:00
		OOPS 2 Yearly/20000 Kms Drain					
000000-005E9F83	No	Engine Oil And Filter Change (1)	02 Apr 2021	Level 1			000:00
000000-002F7BBE	No	6 Monthly/10000 Kms	20 May 2020	Level 1			000:00
		OOPS 6 Yearly/120000 Kms					
000000-002F7BBB	No	Camshaft Timing Belt (2)	01 Apr 2025	Level 2			000:00
		OOPS 2 Yearly/40000 Kms			Non-		
000000-00A56424	No	Replace Air Cleaner Element (1)	02 Apr 2021	Level 1	Taskworthy	CL	000:00
000000-0049F24A	No	6 Monthly/10000 Kms	20 May 2020	Level 1			000:00
		OOPS 6 Yearly/120000 Kms			Non-		
000000-00B0559F	No	Camshaft Timing Belt (2)	01 Apr 2025	Level 2	Taskworthy	CL	000:00
		OOPS 2 Yearly/20000 Kms Drain					
000000-002F7BC1	No	Engine Oil And Filter Change (1)	02 Apr 2021	Level 1			000:00
					Non-		
000000-00A5641C	No	2 Yearly/40000 Kms	•		Taskworthy	CL	000:00
000000-002F7BBD	No	2 Yearly/40000 Kms	02 Apr 2021	Level 1			000:00
					Non-		
000000-00BE2628	No	6 Monthly/10000 Kms	20 May 2020	Level 1	Taskworthy	CL	000:00
		OOPS 2 Yearly/40000 Kms					
000000-005E9F82	No	Replace Air Cleaner Element (1)	•	Level 1			000:00
000000-005E9F80	No	2 Yearly/40000 Kms	02 Apr 2021	Level 1			000:00
					Non-		
000000-00B054BF	No	Yearly/20000 Kms	•		Taskworthy	CL	000:00
000000-002F7BBF	No	Yearly/20000 Kms	•	Level 1			000:00
000000-0049F249	No	Yearly/20000 Kms	02 Apr 2020	Level 1			000:00

.

000000-003C77EC	No	6 Monthly/10000 Kms	20 May 2020 Leve	1 1	000:00
000000-002F7BC0	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	01 Apr 2024 Leve	el <b>1</b>	000:00
				Non-	
000000-00A56404	No	6 Monthly/10000 Kms	20 May 2020 Leve	l 1 Taskworthy CL	001:00