



Tanarife Solarium Limited home hire wooden tanning unit

Aspect	Details
Images	
Alert Number	2311-0189
Product Type	Electrical appliances and equipment - Sunbed Unit
Product Identifiers	Brand: Tanarife Solarium Limited
Product Description	A vertical, wooden tanning unit/sunbed fitted with two mains plugs.
Country of Origin	United Kingdom
Counterfeit	No
Risk Type	Fire and electric shock
Risk Description	<p>The product has been recalled as it has been identified that the poor build quality could result in fire or electric shock. One pin holder on the black mains plug was found to have loosened live pin. This could cause contact resistance between the pin and wall socket conductors, potentially resulting in the plug overheating or catching fire.</p> <p>Also, during testing, serious damage was found on the white mains plug. Therefore, protection against electric shock is not assured when operating the tanning bath. Some of the required documentation and markings were not present.</p> <p>The product does not meet the requirements of The Electrical Equipment (Safety) Regulations 2016.</p>
Corrective Measures	The authority are requiring the recall of the product from end users.
Online Marketplace	N/A
Notifier	Local Authority Trading Standards.