



Top Cowl Assembly in Mercury Marine V6 and V8 Outboard Engines

Aspect	Details
Images	
Alert Number	2312-0001
Product Type	Recreational Craft – Outboard Engine
Product Identifiers	V8 200–300 and V6 175–225 FourStroke, Pro XS®, SeaPro™ and Verado® Models - Serial Numbers V8 2B529482 to 3B430915 & V6 2B529482 to 3B421321 V8 250R, V8 300R and 300R HD Models - Serial Numbers 1E080500 to 1E091195, 2B529482 to 3B430915
Product Description	Top cowl assembly on certain models of outboard boat engines.
Country of Origin	United States
Counterfeit	No
Risk Level	Not provided
Risk Type	Injuries
Risk Description	Mercury Marine has identified the possibility for injury to occur if fingers enter the top cowl air vents on some engine models. To prevent this, Mercury Marine is offering a bezel assembly to cover the top cowl air vents. Installation of the bezel assembly is required on all sold and unsold product.
Corrective Measures	Mercury Marine have contacted all registered owners advising them of the issue and that they should contact an authorised dealer to schedule a service appointment to enable the bezel assembly to be fitted. If you need help locating a dealer, please access: https://www.mercurymarine.com/en/us/find-a-dealer/
Online Marketplace	N/A
Notifier	Local Authority Trading Standards working with the Office for Product Safety and Standards