

Product Safety Report

Wax Dissolving Lamp	
Aspect	Details
Images	
Alert Number	2312-0079
Product Type	Electrical appliances and equipment – Wax dissolving lamp
Product Identifiers	Amazon barcodes: X001QU52VN, X001TC6Y3X. Other identifier: FBA15HDB6NT8U000003.
Product Description	Black lamp for melting wax candles
Country of Origin	China
Counterfeit	No
Risk Type	Fire, electric shock
Risk Level	Serious
Risk Description	The product presents a serious risk of fire and electric shock as it's fitted with a counterfeit fuse which may not protect the product from potentially catching fire and injuring the user. The product also failed the electric strength test and there was a single insulation mains potential wiring in contact with unearthed accessible metallic parts, presenting an electric shock hazard to the user. Some of the required documentation and markings were not present. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.
Corrective Measures	The import has been rejected at the border.
Online Marketplace	Amazon
Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts