

# Air Quality and Dust Monitoring Monthly Report - November 2023

Birmingham City Council

© HS2 Ltd. gov.uk/hs2



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2021, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

### **Monthly Summary**

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of dust monitoring undertaken within Birmingham City Council (BCC) during November 2023.
- 1.1.2 Figure 1 and Figure 2 in Appendix A present the current worksites together with the dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report monthly available from <a href="www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2">www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2</a>, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figure 1 and Figure 2, include:

#### Washwood Heath (Sublot 4)

- Setup of the compound area and haulage routes; and
- Demolition and crushing of existing concrete foundations on site.

#### **Bromford East Tunnel Portal (Sublot 1B)**


- Shutters and fixing steel to wheel-washes.
- Concreting works to ducts at roundabout.
- Continue erection of fencing at Slurry Treatment Plant 1 (STP 1).
- Excavating for water supply at Articulated Dump Track (ADT) wheel wash.
- Backfilling legato blocks at North Road.
- Backfilling for Esso footpath beyond concrete path.
- Grading out grout plant access road.
- Tarmac works to wheel wash and roundabout.
- Striking shutters and backfilling cooling tower slab.
- Steel fixing at grout plant access road.
- Installing drainage at the roundabout.
- Installing screed rails at grout plant access road.
- Excavation of south access road.
- Wheel wash installation.
- 1.1.5 Five (5) dust monitors are installed around these worksites, where works are underway. These sites returned a medium dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor, presented in Figure 3. All continuous


dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.

- 1.1.7 The trigger level for  $PM_{10}$  concentrations of 190  $\mu$ g/m³, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)' has been applied.
- 1.1.8 No (0) dust trigger alerts were recorded during the monitoring period (November 2023).
- 1.1.9 Data capture was below 90% for the BETP002 monitor due to maintenance being carried out.
- 1.1.10 There were no (0) complaints received during the reporting period (November 2023).

## **Appendix A – Worksites and Monitoring Locations**

Figures 1 and 2: Worksites and Monitoring Locations within BCC





## **Appendix B - Dust Monitoring Results**

Table 1: Dust Monitoring Locations and Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM10 concentration (µg/m3)	Minimum 1-hour PM10 concentration (µg/m3)	Maximum 1- hour PM10 concentration (µg/m3)	Number of 1- hour periods exceeding trigger level of 190 µg/m3	Data capture (%)
WHD001	411221, 289245	Washwood Heath Depot, near receptors on Drews Lane	M	Yes	No	8.3	0.1	76.2	0	100.0
WHD002	410758, 289130	Washwood Heath Depot, near receptors on Common Lane	М	Yes	No	15.1	1.7	108.4	0	100.0
WHD003	410562, 288866	Washwood Heath Depot, near receptors on Warren Road	М	Yes	No	7.8	0.2	104.8	0	100.0
BETP001	416719, 290767	Bromford East Tunnel Portal, Twisted Oak Stables	M	Yes	No	8.0	0.2	69.2	0	100.0
BETP002	417406, 290605	Bromford East Tunnel Portal, Attleboro Lane	М	Yes	No	4.7	0.1	54.1	0	89.4

Figure 3: Construction dust 1-hour mean indicative PM<sub>10</sub> concentration for all dust monitors

