

Product Safety Report

| Product Safety Report | | | | | |
|----------------------------------|---|--|--|--|--|
| Astro and Canyon Guide Harnesses | | | | | |
| Aspect | Details | | | | |
| Images | ASTRO BOD FAST ASTRO SIT FAST CANYON GUIDE | | | | |
| PSD Number | 2402-0115 | | | | |
| Product Type | Personal protective equipment (PPE) - Climbing Harnesses | | | | |
| Product Identifiers | Details of affected products are attached in Annex A | | | | |
| Product Description | Three models of black coloured climbing harnesses with leg loops. | | | | |
| Country of Origin | France | | | | |
| Counterfeit | No | | | | |
| Risk Level | Not provided | | | | |
| Risk Type | Injuries | | | | |
| Risk Description | The affected products present a risk of injuries due to the detection of a defect on the gated opening attachment point of an ASTRO harness. This may lead to the unintentional opening of this attachment point and result in a life-threatening situation. The products do not meet the requirements of the Regulation (EU) 2016/425 on Personal Protective Equipment or the Personal Protective Equipment (Enforcement) Regulations 2018. | | | | |
| Corrective Measures | Petzl have launched a safety alert requesting to inspect certain harnesses. For further information, or should you wish to ascertain if your harness is affected, please access the Petzl safety notice here: https://www.petzl.com/GB/en/Professional/recalls/2023-10-25/Call-for-inspection-for-the-ASTRO-and-CANYON-GUIDE-harnesses | | | | |
| Online Marketplace | N/A | | | | |
| Notifier | Local Authority Trading Standards | | | | |

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts



Product Safety Report

Annex A – Affected Products

| Product name | Image | References | Affected serial numbers |
|--------------------------------------|-------|--|--|
| ASTRO BOD FAST european version | | C083AA00 C083AA01 C083AA02 | All serial numbers up to 23J 000000 000 included. If there is a green sticker inside your harness's plasticised label (located inside the belt), it has already been inspected. |
| ASTRO BOD FAST international version | | C083BA00 C083BA01 C083BA02 C083BA03 C083BA04 C083BA05 | All serial numbers up to 23J 000000 000 included. If there is a green sticker inside your harness's plasticised label (located inside the belt), it has already been inspected. |
| ASTRO SIT FAST | | C085AA00 C085AA01 C085AA02 | All serial numbers up to 23J 000000 000 included. If there is a green sticker inside your harness's plasticised label (located inside the belt), it has already been inspected. |
| CANYON GUIDE | | C086BA00 C086BA01 | All serial numbers up to 23J 000000 000 included. If there is a green sticker inside your harness's plasticized label (located inside the belt), it has already been inspected. |

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts