




<b>Cannondale Dave Bicycles - Model Year 2021-23</b>											
<b>Aspect</b>	<b>Details</b>										
<b>Images</b>											
<b>PSD Number</b>	2403-0078										
<b>Product Type</b>	Hobby / sports equipment - Bicycle										
<b>Product Identifiers</b>	<table border="1"> <thead> <tr> <th><b>Material</b></th> <th><b>Material number</b></th> </tr> </thead> <tbody> <tr> <td>C29101U10OS</td> <td>26 U Dave SGY OS</td> </tr> <tr> <td>C29101U20OS</td> <td>26 U Dave DTE OS</td> </tr> <tr> <td>C29201U10OS</td> <td>26 U Dave SGY OS (x)</td> </tr> <tr> <td>C29201U20OS</td> <td>26 U Dave DTE OS (x)</td> </tr> </tbody> </table>	<b>Material</b>	<b>Material number</b>	C29101U10OS	26 U Dave SGY OS	C29101U20OS	26 U Dave DTE OS	C29201U10OS	26 U Dave SGY OS (x)	C29201U20OS	26 U Dave DTE OS (x)
	<b>Material</b>	<b>Material number</b>									
	C29101U10OS	26 U Dave SGY OS									
	C29101U20OS	26 U Dave DTE OS									
	C29201U10OS	26 U Dave SGY OS (x)									
C29201U20OS	26 U Dave DTE OS (x)										
<b>Product Description</b>	Model Year 2021 through 2023 Cannondale 26" Dave bicycles. The bicycles were sold in deep teal and stealth grey colours. "Dave" is printed on the bicycle frame top-tube. "Cannondale" is printed on the downtube.										
<b>Country of Origin</b>	Taiwan										
<b>Counterfeit</b>	No										
<b>Risk Level</b>	Low										
<b>Risk Type</b>	Injuries										
<b>Risk Description</b>	CSG has received reports of damage to the bicycle headtube/downtube weld, resulting in the downtube detaching from the bicycle frame. The bicycles have a weld securing the bicycle down tube to the bicycle fork. The bottom of the bicycle down tube and the gusset are both supposed to be welded to the head tube. In affected frames, only the bicycle gusset is welded to the bicycle head tube, resulting in only one lower weld to the bicycle head tube and a resultant decrease in the strength the bicycle head tube to down tube junction. This can lead to the downtube detaching when the bicycle is being used, presenting a risk of falls injuries to the user.										
<b>Corrective Measures</b>	CSG have recalled the product from end users, and have notified customers and distributors. Please access the Cannondale website for further information: <a href="https://www.cannondale.com/en-gb/safety-and-recalls">https://www.cannondale.com/en-gb/safety-and-recalls</a> .										
<b>Online Marketplace</b>	N/A										
<b>Notifier</b>	Office for Product Safety and Standards										