



Telescopic Ladder	
Aspect	Details
Images	
PSD Number	2309-0029
Product Type	Other – Telescopic Ladder
Product Identifiers	Carton number: 881044
Product Description	Telescopic ladder with black sides and red rungs.
Country of Origin	China
Counterfeit	No
Risk Level	Serious
Risk Type	Injuries
Risk Description	<p>The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling.</p> <p>The product does not meet the requirements of the General Product Safety Regulations 2005.</p>
Corrective Measures	The import has been rejected at the border and destroyed.
Online Marketplace	N/A
Notifier	Local Authority Trading Standards