

## **Product Recall**

Black Diamond Equipment Neve Strap Crampons (green 2024 version)	
Aspect	Details
Images	
PSD Number	2405-0119
Product Type	Personal protective equipment (PPE) - Aluminium crampons
Product Identifiers	Brand: Black Diamond Equipment Style: #400073 Affected date codes: 01-2021, 05-2022, 07-2023, 01-2024, and SS1271 SKU: BD4000733011ALL1 Sales period of affected products: January 2024 to May 2024
Product Description	Green aluminium crampons for snow travelling.
Country of Origin	Unknown
Counterfeit	No
Risk Level	High
Risk Type	Injuries
Risk Description	The product presents a high risk of injuries as the screws which connect the plastic heel cup to the aluminium heel unit of the Neve Strap Crampon can loosen. This could result in the heel cup detaching from the crampon, posing a fall or injuries hazard.  The product does not meet the requirements of the Regulation (EU) 2016/425 on Personal Protective Equipment or the Personal Protective Equipment (Enforcement) Regulations 2018.
Corrective Measures	The product has been recalled from end users. For further information, please access the Black Diamond Equipment recall site here: <a href="https://www.blackdiamondequipment.com/en_EU/content/neve-strap-recall/">https://www.blackdiamondequipment.com/en_EU/content/neve-strap-recall/</a>
Online Marketplace	N/A
Notifier	Office for Product Safety and Standards.

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <a href="https://www.gov.uk/guidance/product-recalls-and-alerts">https://www.gov.uk/guidance/product-recalls-and-alerts</a>