

## **Product Safety Report**

Images   Details	Product Safety Report		
Images  2406-0004  Product Type Product Identifiers Product Description  Country of Origin  Counterfeit Risk Level Risk Type  The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling.  The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Online Marketplace  Amazon  At 2406-0004  Double 1- Telescopic Ladder  Amazon  A 3.8m extending telescopic ladder.  Cointry of Origin  China  China  The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling.  The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Amazon	MLHY 3.8m Telescopic Ladder		
Images  2406-0004  Product Type  Product Identifiers  Product Description  Country of Origin  Counterfeit  Counterfeit  Counterfeit  Counter The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling.  The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Online Marketplace  Amazon	Aspect	Details	
Product Type	Images	IF ASS. AS EXEMPTED ON	
Product Identifiers  Brand: MLHY Amazon product identifiers: X001ZGP6XH, FBA15HW6DRK6U000045. SKU: Ladder-3.8m.  A 3.8m extending telescopic ladder.  Country of Origin  Counterfeit  Unknown  Risk Level  Serious  The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling. The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Online Marketplace  Amazon	_	2406-0004	
Amazon product identifiers: X001ZGP6XH, FBA15HW6DRK6U000045. SKU: Ladder-3.8m.  Product Description  Country of Origin  China  Counterfeit  Unknown  Risk Level  Risk Type  Injuries  The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling. The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Online Marketplace  Amazon		·	
Country of Origin  China  Counterfeit  Unknown  Risk Level  Serious  The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling.  The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Amazon  Amazon		Amazon product identifiers: X001ZGP6XH, FBA15HW6DRK6U000045.	
Counterfeit Unknown  Risk Level Serious  Risk Type Injuries  The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling. The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Online Marketplace  Amazon		A 3.8m extending telescopic ladder.	
Risk Type Injuries  The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling. The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Online Marketplace  Amazon		China	
Risk Type  The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling.  The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Online Marketplace  Amazon	Counterfeit	Unknown	
The product presents a serious risk of injuries as the ladder could not hold the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling. The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  Online Marketplace  Amazon	Risk Level	Serious	
the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling. The product does not meet the requirements of the General Product Safety Regulations 2005.  Corrective Measures  The import has been rejected at the border and destroyed.  Amazon	Risk Type	Injuries	
Measures  Online Marketplace  Amazon		the claimed weight without collapsing. If the ladder were to collapse while in use, the user could fall and receive serious injuries. The dimensions of the ladder were noncompliant, and the ladder allowed different distances between rungs while in use. There is also no protection in place to prevent squeezing when the ladder is being collapsed. The product also requires improvements to marking and labelling.  The product does not meet the requirements of the General Product Safety	
Marketplace Amazon		The import has been rejected at the border and destroyed.	
Notifier Local Authority Trading Standards		Amazon	
	Notifier	Local Authority Trading Standards	

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <a href="https://www.gov.uk/guidance/product-recalls-and-alerts">https://www.gov.uk/guidance/product-recalls-and-alerts</a>