





**DE&S Policy Secretariat** 

DESSEC-PolSecLE-JSC-WPNS@mod.gov.uk

Defence Equipment & Support Maple 0a #2043 MOD Abbey Wood Bristol BS34 8JH

Reference: FOI2024/15433

23 August 2024

I am writing about your email of 20 August 2024, requesting the following information:

I am researching the history of an ex army 90 Landrover Registration number 65 KF 20 which was classified as beyond repair on 8th July 2009 from Camp Bastion ,Operation Herrick The chassis number is SALLDVAC7AA262011 I have owned this from about 2010

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD) and some information about your vehicle has been located. Some of the information identified relating to this vehicle is attached, as follows:

- Annex A Fault History
- Annex C Inspection History
- Annex D Servicing History

Some of the information you have requested has previously been published; Section 21(1) of the FOI Act provides that information is exempt if it is reasonably available by other means. The MERLIN archive was released as part of a previous FOI request and can be accessed at the Government publications website via the following link:

https://www.gov.uk/government/publications/foi-responses-published-by-mod-week-commencing-09-july-2018

Under Section 16 (Advice and Assistance) of the FOI Act, I can advise you that the MERLIN database in the above link is split into seven spreadsheets. The first has a list of vehicles, while spreadsheets 2 through 7 include the vehicle service histories. To search for a vehicle, you must press Ctrl + F on your computer keyboard, then type in the vehicle registration number (65KF20) and press 'enter'. For ease of reference, the published information concerning your vehicle is available from MERLIN 2.0 attachment 1, Row 128-53, and MERLIN 2.0 attachment 4, Rows 118108 – 118119.

You may wish to note that when the MERLIN database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the data may be inaccurate.

I can advise that no other information on this vehicle is held.

**Defence Equipment & Support** 

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at https://ico.org.uk/.

Yours sincerely,

**DE&S Policy Secretariat** 

Work Objects

Serial Number:

65KF20

NSN:

2320998938029

Criteria:

Repair Level:

ALL Closed

Work Object Status: Mission Impact:

ALL

Fault State:

ALL Escalate Work: ALL

Work Request ID:

Assigned Work Status: ALL

Working Organisation: Repair Section:

|                 |            |                      |        |                |          |         | Batch Fault | Fault       |         |                |                 |              |         |             |
|-----------------|------------|----------------------|--------|----------------|----------|---------|-------------|-------------|---------|----------------|-----------------|--------------|---------|-------------|
|                 | Work       |                      | Work   |                | Escalate | Repair  | Group ID    | Occurrence  | Mission | Reason         |                 | Working      | Repair  | Estimated   |
| Fault ID        | Request ID | Fault Description    | Status | Fault State    | Work     | Level   | Number      | Date        | Impact  | For Work Level | l 3 Description | Organisation | Section | Repair Time |
|                 | 000000-    |                      |        |                |          |         |             |             |         |                |                 |              |         |             |
| 000000-00009FC5 | 0026AC7C   | DVR SEATBELT MISSING | Closed | Non-Taskworthy | No       | Level 1 |             | 03 Feb 2006 |         | TUL (          | GS SOFT TOP     |              |         |             |
| 000000-00007317 |            | Initial Usage        | Closed | Fully Fit      | No       | Level 1 |             | 11 Jan 2006 |         | TUL (          | GS SOFT TOP     |              |         |             |
| 000000-0000731C |            | Initial Maintenance  | Closed | Fully Fit      | No       | Level 1 |             | 11 Jan 2006 |         | TUL (          | GS SOFT TOP     |              |         |             |
|                 |            |                      |        |                |          |         |             |             |         |                |                 |              |         |             |

## Work Objects

Serial Number:

65KF20

NSN:

2320998938029

Criteria:

Repair Level:

ALL

Work Object Status:

Closed

Mission Impact:

ALL

Fault State:

ALL

Escalate Work:

ALL

Work Request ID:

Assigned Work Status: ALL

Working Organisation:

Repair Section:

|                      | Work       | Escalate | Maintenance       |               | Repair  |             | Work   | Estimated   | Working      |                |
|----------------------|------------|----------|-------------------|---------------|---------|-------------|--------|-------------|--------------|----------------|
| Maintenance Event ID | Request ID | Work     | <b>Event Name</b> | Next Due Date | Level   | Fault State | Status | Repair Time | Organisation | Repair Section |
| 000000-00072E31      |            | No       | MEI (2)           | 07 Mar 2008   | Level 2 |             | CL     | 00:00       |              |                |
| 000000-0007D788      |            | No       | MEI (2)           | 07 Mar 2008   | Level 2 |             | CL     | 000:00      |              |                |

## Work Objects

Serial Number:

65KF20

NSN:

2320998938029

Criteria:

Repair Level:

ALL

Work Object Status:

Closed

Mission Impact:

ALL

Fault State:

ALL

Escalate Work:

ALL

Work Request ID:

Assigned Work Status: ALL

Working Organisation:

Repair Section:

|                      | Work       | Escalate | Maintenance Event  |               | Repair  | Fault | Work   | Estimated   | Working      | Repair  |
|----------------------|------------|----------|--------------------|---------------|---------|-------|--------|-------------|--------------|---------|
| Maintenance Event ID | Request ID | Work     | Name               | Next Due Date | Level   | State | Status | Repair Time | Organisation | Section |
| 000000-00072DF2      |            | No       | 2 Yearly/40000 Kms | 17 Jan 2008   | Level 1 |       | CL     | 00:00       |              |         |