




Gazelle Makki Cargo Bike with Electrical Support	
Aspect	Details
Images	
PSD Number	2108-0063
Product Type	Hobby / Sports Equipment – Cargo Bike
Product Identifiers	Not provided
Product Description	Gazelle Makki cargo bike with electrical support/assistance.
Country of Origin	The Netherlands
Counterfeit	No
Risk Level	Serious
Risk Type	Injuries
Risk Description	The product presents a risk of injuries because the threaded bolt, positioned at the ball joint that forms part of the steering rod, can break under exceptional circumstances. The failing ball joint will lead to a complete loss of steering control at the front wheel on the cargo bike. In such a scenario, most riders would instinctively bring the bike to an emergency stop, in doing so causing them to fall. The product does not meet the requirements of the Supply of Machinery (Safety) Regulations 2008.
Corrective Measures	The product has been recalled from end users by the manufacturer.
Online Marketplace	N/A
Notifier	Office for Product Safety and Standards