

Air Quality and Dust Monitoring Monthly Report - September 2025

West Northamptonshire District Council



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2025, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v3.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/ version/3 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of dust monitoring undertaken in the West Northamptonshire District (WNDC) during September 2025.
- 1.1.2 Figure 1 and Figure 2 in Appendix A present the current worksites together with the dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figure 1 and Figure 2, include:

Twyford to Greatworth

Radstone and Hall Farm

- Bulk Excavation
- Stockpile Management
- BSC Topsoil laying on batters
- Site Access Road/ Haul Road use and maintenance
- Drainage
- Works associated with the permanent diversion of Radstone Road.
- Works associated with the temporary diversion of Radstone Road.
- AX15 wingwalls construction
- AX18 maintenance stairs construction and highways works
- Brackley Culvert backfilling and waterproofing.

Greatworth Hall


- Crushing and screening
- Bulk Excavation
- Stockpile Management
- Site Access Road/ Haul Road use and maintenance
- Excavate and replace at Greatworth South Cutting
- Main excavation works at Greatworth South Cutting
- Drainage works
- AN37 Approach parapets
- AN14 maintenance stairs and platforms construction
- Stockpile management.


Greatworth To Southam

- Earthworks
- Highways
- A361 road realignment
- Boddington highways
- Greatworth Tee
- Utilities
- A361 weekend works on newly laid gas main connections.
- 1.1.5 Ten (10) dust monitors are installed around these worksites, where works are underway. These sites returned a medium dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor, presented in Figure 3. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level for PM₁₀ concentrations of 190 μg/m³, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)' has been applied.
- 1.1.8 Details of the trigger alert investigations and remediations are presented in Appendix B, Table 2.
- 1.1.9 There were no (0) complaints received during the reporting period (September 2025).

Appendix A - Worksites and Monitoring Locations

Figures 1 and 2: Worksites and Monitoring Locations within WNDC





Appendix B - Dust Monitoring Results

Table 1: Dust Monitoring Locations and Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (μg/m³)	Minimum 1- hour PM ₁₀ concentration (μg/m³)	Maximum 1- hour PM ₁₀ concentration (μg/m³)	Number of 1- hour periods exceeding trigger level of 190 µg/m ³	1-hour data capture (%)
Chipping Warden – RAMAC	449600, 249755	Chipping Warden, West Northamptonshire	М	Yes	Yes	4.4	1.0	15.0	0	98.9
CW Village	450000, 249367	Chipping Warden, West Northamptonshire	М	Yes	Yes	5.0	1.0	27.0	0	99.9
Lower Boddington	447997, 251865	Lower Boddington, West Northamptonshire	М	Yes	Yes	5.0	1.0	82.0	0	99.7
Fir Tree Nursery	447283, 252421	Fir Tree Nursery, West Northamptonshire	М	Yes	Yes	4.5	1.0	15.0	0	98.8
Radstone	458712, 240454	Radstone Road, Brackley, West Northamptonshire	М	Yes	Yes	22.5	1.0	3274.0	8	100.0
Greatworth Village	455551, 242992	Greatworth Village, Helmdon Road,	М	Yes	Yes	4.1	1.0	16.0	0	98.6
Lower Thorpe	453553, 245334	Banbury Lane, Lower Thorpe	М	Yes	Yes	4.3	1.0	15.0	0	99.6
Greatworth Hall	456179, 242763	Greatworth Hall, Greatworth	М	Yes	Yes	4.4	1.0	16.0	0	99.0
Blackgrounds	450846, 248413	Blackgrounds, West Northamptonshire	М	Yes	Yes	4.3	1.0	51.0	0	99.6

Table 2: Summary of exceedances during period (September 2025)

Monitoring Site ID	Period of trigger alert & Concentration	Investigation	Outcomes / Resolution / Remedial measures
	recorded		implemented
	06/09/2025 04:01 – 05:00; 332 μg/m³ 05:01 – 06:00; 442 μg/m³		
	09/09/2025 05:01 – 06:00; 3274 μg/m ³		
Radstone	27/09/2025 04:01 – 05:00; 453 μg/m³ 05:01 – 06:00; 1535 μg/m³	Erroneous data.	Disregarded. Checking for blockages and changing out dust receptor 30/09/2025. None found on original unit.
	29/09/2025 04:01 – 05:00; 221 µg/m³		
	30/09/2025 03:01 – 04:00; 909 µg/m ³ 04:01 – 05:00; 279 µg/m ³		

Figure 3: Continuous dust 1-hour mean indicative PM₁₀ concentration for all monitors

