

Property History List

Stoke Lodge Shirehampton Road

Development Control

66/03334/U_U Erect a pavilion.

Date Closed 24 October 1966 NOOBJ

10/05069/VP Reduce by 50% a semi-mature Oak tree located on eastern perimeter of fields (abutting Parrys Lane). (Tree is protected by Tree Preservation Order 451 (T4))

Date Closed 7 November 2011 WITH

11/00076/VP Fell a semi-mature Oak tree located on eastern perimeter of fields (abutting Parrys Lane). (Tree is protected by Tree Preservation Order 451 (T4))

Date Closed 1 March 2011 PER

12/01215/VP T3 Fraxinus excelsior - decay present - Fell tree and replace with a tree of similar mature stature. T1 Quercus cerris - reduce distal portion of branch affected by fungus to just above 2nd lateral from fungal fruiting body. Reduce remaining laterals by 20% - T4 Populus x nigra - remove hyperextended branch at 6m with excessive end loading leading to possible failure and T5 Quercus robur - reduce upright branch above historic branch failures by 20%. G1- Remove deadwood in canopies where necessary. - Protected by tree preservation order 1192.

Date Closed 10 May 2012 PER

12/01269/VC T2 - Prunus avium - Fell tree with decay and replace with a tree of similar mature stature.

Date Closed 2 May 2012 NOTPO

12/02586/VP TPO 1192. Woodland group G2 & G4. Remove Ash tree with extensive canopy dieback & Armillaria infection. Crown lift all trees impacting on adjacent properties & highways. See from for details of other work to be carried out.

Date Closed 2 August 2012 PER

14/02251/VP G4 - Quercus Ilex - Remove. Crataegus Monogyna - Prune. Acer Pseudoplatanas - Crown lift. Trim and thin tree saplings within G4. TPO 1192

Date Closed 4 July 2014 PER

14/03899/VD English Oak on site boundary in north west corner of site. One of three main branches has failed leaving large wound. Dismantle other two branches as unstable. Main stem approx 4m high to be left. Tree subject to Tree Preservation Order no. 1192. (5-Day Notice.)

Date Closed 8 August 2014 PER

14/06337/VP Crown lift canopies of trees to provide 5.5m over roads and 2.5m over pavements. (Trees protected by Tree Preservation Orders 1192, 1236 and 451).

Date Closed 28 February 2015 PER

15/02681/VP Tree 100048 Cedar of Lebanon. Dying, decline monitored over several years. Main stem and larger branches to be sculpted (Design to be chosen by local community) (Protected by Tree Preservation Order 1236).

Date Closed 25 July 2015 PER

15/03766/VP Clear growth around base of trees and remove Ivy from lower stems to enable access and inspection of the trees. (Protected by Tree Preservation Orders 451, 1192 and 1236).

Date Closed 14 September 2015 PER

16/06304/F New perimeter fence to playing fields.

Date Closed 2 March 2017 WITH

17/00864/F Replacement changing room building and associated works (Use Class D2).

Date Closed 28 July 2017 REF

18/05206/A Retrospective application for installation of sign.

Date Closed 20 December 2018 REF

18/06369/VP T1 - Acer platanoides, T2 - Acer pseudoplatanus, T3 - Fagus sylvatica and T4 -
Acer platanoides: reduce in length the lower branches by 3m (for all four trees up to a
height of 8m) or to a suitable pruning point remaining within property boundary. Trees all
subject of TPO 1192.

Date Closed 5 February 2019 REF

19/02046/VD White Poplar - fell -TPO 1192.

Date Closed 1 May 2019 PG

19/04039/VP Ash (T8) Remove the lowest 6 branches on the south side of the tree and
crown lift by removing secondary laterals to give a minimum clearance of 1.5m branches
above to clear both the side and the top of tower to allow for the installation of CCTV
cameras. TPO 1192

Date Closed 30 August 2019 WITH

20/01826/F Works are to install a CCTV pole and camera adjacent to the gate behind the
neighbouring Stoke Lodge Adult Learning Centre.

Date Closed 23 February 2023 REF

20/02228/VP Norway Maple "Crimson King" (NW1) Norway Maple (NW2) -light crown-lift and reduction (2m maximum) of the NE lower face of crown. TPO 1192.

Date Closed 24 July 2020 PG

20/03288/VP Ash (T8 on plan, part of G7 on TPO 1192) Crown lift to 8m on the Pavilion side . Remove the basal shoot and any hanging branches or deadwood in the crown. Remove the three lowest limbs that overhang the footpath outside of the playing fields.

Date Closed 15 October 2020 PER

20/03697/VD T3 - English Oak - Reduce storm damaged limb. (See Associated Photograph) TPO 1192

Date Closed 18 August 2020 PER

20/05068/VP Beech (B) - Light crown-lift and reduction (2m maximum) of the NE lower face of crown (lower 4m North East quadrant of crown and no higher).

Date Closed 11 January 2021 PG

20/05387/VP T11 Oak - Fell dead tree. TPO 1192

Date Closed 6 January 2021 REF

20/05776/VP See attached document; Stoke Lodge TPO application identification of trees and description of works TPO 451, 1192, 1236.

Date Closed 4 January 2021 PG

23/03588/VD Pine - Make fallen section safe and fell remaining tree - 5 Day Notice (TPO 1192).

Date Closed 14 September 2023 PG

00/01985/LA Internal alterations including new staircase and installation of lift (wheel chair access); provision of 6 no. rooflights, all to enable conversion of stable block to arts studio.

Date Closed 22 May 2001 PG

01/01653/FB Installation of velux roof lights to newly converted stable block.

Date Closed 18 July 2001 PG

77/01735/P_U Erection of temporary office building.

Date Closed 18 August 1977 PG

79/00321/P_N Proposed extension to temporary relocatable elliott office building.

Date Closed 1 March 1979 PG

05/01500/LA Refurbishment of the Gazebo to its original form including making safe structurally, replacing missing elements and applying new finishes.

Date Closed 18 July 2005 PG

17/00864/F Replacement changing room building and associated works (Use Class D2).

Date Closed 28 July 2017 REF

17/06665/F Erection of new changing room building and associated works to replace existing building.

Date Closed 25 June 2018 REF

20/05068/VP Beech (B) - Light crown-lift and reduction (2m maximum) of the NE lower face of crown (lower 4m North East quadrant of crown and no higher).

Date Closed **11 January 2021** **PG**

20/05185/LA Installation of new fire alarm, emergency lighting and upgrade of fire compartmentation and non-original doors.

Date Closed **14 December 2020** **PG**

20/05776/VP See attached document; Stoke Lodge TPO application identification of trees and description of works TPO 451, 1192, 1236.

Date Closed **4 January 2021** **PG**

21/01390/VP Please see attached Ross Consulting ALMS Method Statement TPO1192

Date Closed **16 March 2021** **WITH**

21/01509/VP T8 Ash - Sympathetic Excavation of the trench and removal of stumps supervised by an Arboricultural Consultant. Installation of path for disabled access. All works including potential root pruning in line with BS 5837:2012 Trees in relation to design, demolition and construction -Recommendations and Industry best practice. The application addresses the worst case scenario as the client is exploring the possibilities of repair work requiring only minor excavations.

Date Closed **28 April 2021** **PG**

22/04219/VP G4 T1 Ash (*Fraxinus excelsior*) - Fell. G1 T2 (Holm oak (*Quercus ilex*)) - Reduce height of growth to approx. 1.2m and continue to manage as a hedge. T3 yew (*Taxus baccata*) - Crown lift canopy to 5m over access road. T4 Walnut (*Juglans regia*) - Sensitive crown lift to a single branch extending over access road to prevent impact damage from passing machinery. Reduce back from outbuilding to prevent any damage to guttering. T6 Black pine (*Pinus nigra*) - Large dead limb extending SW over fence line. Smaller dead branch at crown break. Shorten large limb back to an upright structure, leaving habitat potential. Smaller branch to be removed. T7 Ginkgo (*Ginkgo biloba*) - Create

a 2m halo around tree. T8 (Black pine) *Pinus nigra* - Fell. T9 Beech (*Fagus sylvatica*) crown lift to 5 m to allow for vehicle access.

Date Closed **24 October 2022** **PER**

23/00131/VP T6 - Beech - Reduce northwest primary limb at 4m by approx. 2.5-3m, reduce northeast primary limb at 7m by approx. 2m, reduce southwest primary limb at 7m by approx. 2m, reduce lateral growth on northwest to southwest aspects to restore natural flowing canopy outline. (TPO 1192)

Date Closed **7 March 2023** **PER**

25/13944/VD 5 Day Notice - Copper Beech (dangerous) - Remaining stem to be removed to 2m above the failure point. (TPO 1236)

Date Closed **12 September 2025** **PG**

25/14288/VD 5 Day Notice: Sycamore (Dead) - Fell. Norway Maple (Dead) - Fell. (TPO 1192).

Date Closed **1 October 2025** **PG**